

Cecilia

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003718

AXA INSURANCE PTE LTD

8 Shenton Way #B1-01

AXA Tower (S) 068811

ATTENTION:

CONTACT: -

FAX NO: 68804838

DATE: 09/04/2018
ACCIDENT DATE: 09/04/2018 12/4/18
VEHICLE NO: SLP3842R
CHASSIS/ENG.NO:
VEHICLE MODEL: TOYOTA COROLLA
CLAIM NO:
POLICY NO:
REMARK: 3842 AXA TP AGAINST SLV7893K

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
------	-----	------	-------------	-------	--------	-------------	-----------

** LIST PRICE **

1	1	PC	REAR BUMPER	561.45	25	421.09 DE	421.09
2	1 PC	PC	REAR BUMPER SIDE RETAINER	132.25 66.12	25	49.59 19.99	198.38
3	1	PC	REAR BUMPER SPONGE	182.10	25	136.57 ? Xan	136.57

SUB-TOTAL: 756.04

470.68 \$619.47

** SPECIAL NETT PRICE **

1	1	PC	REAR BUMPER REVERSE SENSOR	180.00	S/N	180.00 ? Xan	180.00
---	---	----	----------------------------	--------	-----	--------------	--------

SUB-TOTAL 180.00

\$180

** WORK LABOUR **

TO CHECK WIRING	30.00	30.00
TO APPLY ANTI RUST COATING	100.00 X	100.00
TO KNOCK REAR END PANEL, WELD, REMOVE & REPLACE ABOVE PARTS	550.00 200	550.00
TO PUTTY & RESPRAY PAINTING ON RR BUMPER, REAR END PANEL AND AFFECTED AREAS	600.00 200	600.00
	0.00	0.00

SUB-TOTAL 1,280.00

\$430

total \$1814.47
Partly part
ok? p/h paint.
Shawn
11/8/18

Rare
H92000068
2 days
P/P

10/04/18 1345

Reg by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____
Date: _____

Supplementary
① Rear boot lock - \$385- Xan
② Rear Bumper Reinforcement \$395- bt

JOYCE

PAGE: 1 of 1

SUB-TOTAL: S\$ 2,216.04

ADD 7% GST. S\$ 155.12

GRAND TOTAL: S\$ 2,371.16

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3 Pioneer Road North #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Our Ref:

Date : 9/4/2018

ATTN: THE MOTOR CLAIMS DEPT
AXA INSURANCE SINGAPORE PTE LTD
143 CECIL STREET
#01-01
GB BUILDING
SINGAPORE 069542

SUPPLEMENTARY ESTIMATE COST OF REPAIR

Vehicle Reg No.	SLP3842R	Model / Year	TOYOTA COROLLA ALTIS
Date of Accident	09-Apr-18	Policy No.	
Type of Claim	TP AXA	Prepared By	SHARON
Survey By		Chassis No.	

S/NO Description

- 1 REAR BUMPER REINFORCEMENT *34*
- 2 REAR BOOT LID LOCK *X answer*

Qty	Unit Price	Amount
1	\$ 395.00	\$ 395.00
1	\$ 385.00	\$ 385.00
		\$ 780.00
	LESS 25%	\$ 195.00
		\$ 585.00

395
25%
98.75
296.25

This is a computer printout no signature is required.

P - 470.68
S/L - 180.00
L - 430.00
Suppl - 296.25
T - 1376.93
2 days