

INS. CASE OWNER:

LKK:

IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

13/3/18

Date / Time:

13/3/18

Registered in Merimen:

14/3/18

Pre-assign / CCU / FTE:



Insured Vehicle No.:

SLA ABOUT

Name of Insured:

Um SIEW Kim RUBY

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

6/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

TAN WITH WIFE

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

5377244456

Policy No.:

200453463

Make / Model:

EIA

Place of Accident:

Rye

OI GIA REPORT: YES / NO

YES

TP GIA REPORT: YES / NO

YES

Insured Liability:

%

Final? Yes / No

574 374

INSRS:
WSP:
Tel:
Liability:
RMKS:Um
TanINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

16/3/18

2PM

14022983

11am

Spoke to QD (Mr Tan) - confirmed accident details and OIC rear-ended TP OI will send out additional photos via email. Informed abt TP calling a/c of NCD 1400 and agree to settle. Send letter to OI.

RECEIVED 10 MAY 2018

STAGE	DATE / PIC
Non-Reporting Itr (1st):	
Non-Reporting Itr (2nd):	
Non-Reporting Itr (Final):	
Notification Itr (if non-pickup):	
Call OI:	17022983
After call Itr to OI:	16/3/18
Documentation Check List: Handler Typist	
Notification Itr (if non-pickup)	☒
After call Itr to OI	☒
Authorisation To Act:	☒
Release Voucher:	☒
Final Repair Bill:	☒
Car Rental Invoice:	☒
Towing Invoice:	☒
LTA / GBA:	☒
Medical Bill:	☒
PIR:	☒
Mandate/Reject Instruction:	☒
LOD:	☒
Payment Breakdown Form:	
Post-Repair Photos:	☐
Others:	☐

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	SS	days)	Reduction:
FINAL SETTLEMENT		Date/Time:	Confirm with:
Final Liability:	SS 100	(Agreed / Assessed)	BOLA S/N No.:
Repair Cost:	SS 3,075.02		
Loss of Rental (LOR):	SS 360.00	x 3 days)	120
Loss of Use (LOU):	SS X	(S x days)	
Loss of Income (LOI):	SS X	(S x days)	
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
GIA/LTA Search:	SS 7.45		
Medical:	SS X		
Disbursement:	SS X	(e.g. Tow/ Independent)	
Legal Cost:	SS X		
Total:	SS 3,442.47	Global Sum SS:	
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	SS 3,442.47	Name 1:	LIM TAN MOICR PTE LTD
Payee 2: (Strikes if N/A)		CC	Name 2:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/AIG18004841/Kkb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 14-03-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLA 9803T	Veh. Inspected	SJY 37U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	14/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	06/03/2018	Inspection Date	13/03/2018
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



ESTIMATE TO REPAIR

VEHICLE NO. : SJY 37 U
 MAKE : B.M.W.
 MODEL : 730LI AT ABS D/AB 2WD 4DR NAV HID SF
 YEAR : 2009
 CHASSIS NO : WBAKB22090CN74121

SURVEYOR NAME :
 DATE OF SURVEY : 13 MAR 2012
 TIME OF SURVEY :

DATE : 12-Mar-18
 DATE OF ACCIDENT : 6-Mar-18
 THIRD PARTY REF : SLA 9803 T / AIG

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper			cm Bu	\$ 1,571.15 ✓
1 pc	Rear Bumper Lower Lid			cm	\$ 224.45 ✓
2 pcs	Rear Bumper Sensor		\$ 236.85	nd	\$ 437.70 ✓
1 pc	Rear Bumper Reinforcement			sa	\$ 800.80 ✓
1 pc	N/S Tail Lamp			nc (cm)	\$ 721.50 ✓
1 pc	Rear Boot "730LI" Emblem			na	\$ 62.55 ✓
					\$ 3,818.15
	To putty & spray painting.			400	\$ 450.00
	To check rear wiring and replace sensor.			600	\$ 120.00
	Labour Charges.			1250	\$ 300.00
TG-RA/-					\$ 4,688.15

Not Authorized
 11/12/18
 Repairing After Repair
 3 days

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation



SUPPLEMENTARY TO REPAIR

VEHICLE NO. : SJY 37 U
 MAKE : B.M.W.
 MODEL : 730LI AT ABS D/AB 2WD 4DR NAV HID SF
 YEAR : 2009
 CHASSIS NO : WBAKB22090CN74121

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

DATE : 15-Mar-18
 DATE OF ACCIDENT : 6-Mar-18
 THIRD PARTY REF : SLA 9803 T / AIG

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper Reinforcement Outer Foam			CM \$	68.85 ✓
TG-RA/-					\$ 68.85

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel:65-64520883 Fax:65-64589127 Website: www.LTM.sg
 Co Reg No: 199307777D GST Reg No: M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0000D
Vehicle Details	
Vehicle No.:	SJY37U
Vehicle to be Exported:	Yes
Intended De-registration Date:	07 Mar 2018
Vehicle Make:	B.M.W.
Vehicle Model:	730LI AT ABS D/AB 2WD 4DR NAV HID SR
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	70304598N52B30AF
Chassis No.:	WBAKB22090CN74121
Maximum Power Output:	190.0 kW (254 bhp)
Open Market Value:	\$82,739.00
Original Registration Date:	01 Apr 2010
First Registration Date:	01 Apr 2010
Transfer Count:	0
Actual ARF Paid:	\$82,739.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Mar 2020
PARF Rebate Amount:	\$49,643.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2020
COE Category:	E - Open Category



LIM TAN MOTOR

Date: 30-Apr-18

(WITHOUT PREJUDICE)

Your Ref: CC4/AIG18004841/Kjb3
Our Ref: LTP032018026 (SJV 37 U)

Attention To : Ms Joy Irene [From LNK Auto Consultants Pte Ltd]
Insurance Company : AIG ASIA PACIFIC INSURANCE PTE LTD

Dear Sir/Idm,

RE THE MATTER OF ACCIDENT INVOLVING EJY27U & SLA883T ON 06.03.2017

We refer to the above matter.

We are instructed and authorised by our client to quantify, to act and negotiate settlement in relation to the above road traffic accident that was caused by your insured.

All supporting documents are enclosed herewith:-

[x] Authorization To Act [x] Original Tax Invoice no. 89033513
[x] Original Rental Receipt and Agreement [x] LTA search receipt
[] Letter Of Discharge []

Survey was done by Insurance instruction and was surveyed by Mr Kenneth on 13-Mar-18

As a result of the accident, our client's vehicle was damaged and has been put to loss and Expenses, particulars of which are as follows:-

1] Cost of repair (inclusive of 7% GST)	\$ 3,075.02
2] Rental of Vehicle	\$ 600.00
3] LTA Search fee	\$ 7.45
	<u>\$ 3,682.47</u>

Please acknowledge receipt of this letter within 14 days. If you agreeable to the above, please forward your payment. Payment to be issued directly to LIM TAN MOTOR PTE LTD within 4 weeks. Should there be any injury related to this matter, any settlement agreed is WITHOUT PREJUDICE to the related injury claim.

Your faithfully

Mandy Lim

Email: mandy@ltn.sg

LTA Roadblock Case No. LTA

File # 79-001 (Copy 1) per 400000 Service of Documents (Singapore) 2002/2
Tel: 65-64222883 Fax: 65-64218112
Website: www.LTA.sg
LTA Roadblock Case No. LTA

This document is intended for the addressee only. If you are not the addressee, you should not disseminate, distribute or copy this document. If you have received this document in error, please inform the sender immediately by e-mail or by phone. Thank you for your cooperation.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/AIG18004841/Kkb3

19 MARCH 2018

LIM SIEW KIM RUBY
BLOCK 525 CHOA CHU KANG STREET 51
#04-293
SINGAPORE 680525

Dear Sir/Madam,

ACCIDENT INVOLVING SLA 9803T AND SJY 37U ON 06.03.2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,


Zaini
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: Zaini@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

To Whom It May Concern

AUTHORIZATION TO ACT

I/We, NG HUNG KOON ('the third party Claimant') of BLK 35 BUKIT BATOK EAST AVENUE 6 #06-23 SINGAPORE 659765 (Address) owner of SJY37U (vehicle number) hereby authorize LIM TAN MOTOR PTE LTD ('the workshop') to act for me with respect to my/our claim for repair costs and/or rental and/or Loss of use ('claim') for my/our vehicle number SJY37U that was damaged pursuant to the accident which occurred on 06-Mar-18 (date) Along AYE TOWARDS TUAS (NEAR EXIT 8) (locate on) involving vehicle number SLA9803T (the accident').

I/We further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive Payment further to settlement of my claim with payment cheque/s being made In favour of the workshop.

Dated this 13th (day) of March (month) 2018 (year)



Signed By ' the third party claimant '





Signed By ' the workshop'

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, LIM TAN MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for SS 3,075.02 (Repair Cost), SS 360.00 (Rental Fee), SS 7.45 (Disbursement) for vehicle no. SJY 37 U that was damaged pursuant to the accident which occurred on 06 MARCH 2017 (date) along AYE TOWARDS TUAS (NEAR EXIT 8) (location) involving vehicle no/s SLA 9803 T. This is pursuant to the inspection conducted on 13 MARCH 2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner NG HUNG KOON ("the third party claimant") of vehicle no. SJY 37 U make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJY 37 U (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 9th (day) of MAY (month) 2018 (year)



RSC

Signed by appointed surveyor



Signed by "the workshop" (with chop)



LIM TAN MOTOR PTE LTD
林陳摩哆私人有限公司

Company's Registration No: 199307277D
GST Registration No: M2 0119088-0

Branch
(Warranty and Performance) Blk 9 Sector C #01-38/40/42
Sin Ming Industrial Estate, Singapore 575644
Tel: +65 6452 2135 Fax: +65 6452 2159

Blk 17 Sector A #01-65
Sin Ming Industrial Estate, Singapore 575675

Main Office / Workshop
Blk 176 Sin Ming Drive #03-09/10/06
Sin Ming Autocare Singapore 575721

Tel: +65 6452 0893 (24Hrs)
Fax: +65 6458 9127
Email: sales@l.t.m.sg

WWW.LTM.SG

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIMS DEPT
TEL :
FAX :
A/C NO. : 30A0/097

MILEAGE :
W.O NO. : SO34226
CAR NO. : SJY37U
MAKE : BMW
MODEL : 730LI

TAX INVOICE

NO : INV33513
DATE : 17-04-2018
TERMS : CASH
PAGE : 1

	DESCRIPTION	QTY	U.PRICE	DIS	AMOUNT
1	REAR BUMPER	1 PCS	1,571.15		1,571.15
2	REAR BUMPER LOWER LID	1 PCS	224.45		224.45
3	REAR BUMPER SENSOR	1 PCS	236.85		236.85
4	REAR BOOT "730LI" EMBLEM	1 PCS	62.55		62.55
5	REAR BUMPER REINFORCEMENT OUTER FOAM	1 PCS	68.85		68.85
6	TO PUTTY & SPRAY PAINTING	1 UNIT	400.00		400.00
7	TO CHECK REAR WIRING AND REPLACE SENSOR	1 UNIT	60.00		60.00
8	LABOUR CHARGES	1 UNIT	250.00		250.00

SINGAPORE DOLLARS : THREE THOUSAND SEVENTY FIVE AND TWO CENTS ONLY

REMARKS: DATE OF ACCIDENT: 06.03.2018
REF: DREF5721729994SG-003

TOTAL QTY: 8.00

SUBTOTAL	2,873.85
DISCOUNT	0.00
TOTAL	2,873.85
GST 7 %	201.17
NET	3,075.02
Deposit	0.00
Balance	3,075.02



AUTHORISED SIGNATURE(S)

CUSTOMER NAME / SIGNATURE / DATE

Customer Acknowledgement

I/We confirm that I/We incurred the repair costs herein and will observe my/our Agreement with the repairer. I/We declare the repair for the above vehicle have been completed to my/our satisfaction

CHIN HUI CAR RENTAL

BLK 7, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-76,
SINGAPORE 575642. TEL: 6453 4680
REGN. NO.: 53090791K

VEHICLE RENTAL AGREEMENT

NO: 8079

HIRER'S PARTICULAR		Vehicle No. S616526 B		Mileage Out: 837km			
Hirer: Ng Hung Koon		Make & Model: Toyota Camry		Auto / Manual: ☒ Auto			
NRIC / Passport No: S1630000 D		Date of Birth: 03.07.1964		OUT - Date: 13-3-2018			
Address: 81K 35 Bukit Batok East Avenue 6		Replace Veh No:		Mileage Out:			
#06-23 Singapore 659765		OUT - Date:		OUT - Time:			
Driving Licence No: S1630000 D		Pass Date: 03.04.1982					
Contact Number: 9137 6388							
DRIVERS PARTICULARS (If different from Hirer)		CHARGES					
Appointed Driver:		Daily 3 @ \$200/-	per day	600.00			
NRIC / Passport No:		Weekly @ \$	per week				
Address:		Monthly @ \$	per month				
Driving Licence No:		Hours @ \$	per hour				
Contact Number:		Others @ \$					
		SUB-TOTAL \$ 600.00					
New Insurance Policy Terms & Conditions as at 08-12-2010 1. NOT PERMITTED TO DRIVE - Not Covered Driver Age 22 years old and below Driver above Age 70 years old Driver less than 2 years Driving Experience 2. ADDITIONAL EXCESS - S\$3000.00 Driver Age 23 to 25 years old with 2 years driving experience Driver Age 65 to 70 years old with 2 years driving experience		PETROL LEVEL					
		Out	E	1/4	1/2	3/4	F
		In	E	1/4	1/2	3/4	F
		TOTAL CHARGES \$ 600.00					
REMARKS LP032018/02G (STY 31 U)		IMPORTANT! FOR SINGAPORE USE ONLY					
		Excess Liability: S\$2500.00					
		Malaysia Excess (With Prior Consent):					
		Hirer's Signature: 					
		Addition Driver's Signature:					

I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given CHIN HUI CAR RENTAL in connection with this agreement is true.

* IMPORTANT

- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER, AND ADMINISTRATIVE CHARGE WILL BE LEVED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY CHIN HUI CAR RENTAL.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURY, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.

RETURN OF VEHICLE: THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO CHIN HUI CAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY
16/3/18	1:20 pm	84011 km	

SIGNATURE OF HIRER / DRIVER



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 07 Mar 2018 / 15:58:10

Receipt Date/Time : 07 Mar 2018 / 15:58:10

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180307-001617

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Result of Insurance Enquiry - SLA9803T				
As at 06 Mar 2018/17:25:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLA9803T Enquiry Fee 20180307155709682002	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx7458	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Mar 2018 Edit Reg		13 Mar 2018 00:00 Edit Adj Rpt	S\$2,873.85 Edit Estimates	S\$2,873.85 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Lim Siew Kim Ruby , ID: S1475121A									
Main Claimant: NG HUNG KOON , ID: S1630000D									
Vehicle Reg. No.: SJY37U		Date of Loss: 06/03/2018 17:00 - :59 [95 Months and 5 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 57217299945G		Policy/Cover Note No.: 2100457463 (Comprehensive) Coverage: 24/03/2017 - 23/03/2018							
Vehicle Reg. No. (Insured): SLA9803T		Policy No. (Claimant): 80246224							
Excess:									
Repairer: Lim Tan Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care, 575721 Sin Ming - Tel: 6452 0893									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Mohd-Rasheed, Rashidah - 64191767] Rashidah.Mohamedrasheed@aig.com									
Claimant's Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 23/03/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJY37U (5721729994SG)
[SLA9803T]

TP
NG HUNG KOON
Mar 6 2018 5:00PM
[Lim Siew Kim Ruby]
Lim Tan Motor Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
------------------	---------------	--------------------	--------------	--------------	------	-----------------

Letters/Correspondences				1 per page	☒
No	Finalized On			Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1	Edit	

Assessment Reports				1 per page	☒
No	Finalized On			Thumbnail	Print
1	15/03/18 12:26	Accident Statement From: OD - Reg. No: SLA9803T, Claimant: LIM SIEW KIM RUBY	1	Load HTM	

Photos/Images				3 per page	☒
No	Relabel/Reorder			Thumbnail	Print
1	09/05/18 16:53	General View	1	Load JPG	☒
2	09/05/18 16:53	General View	1	Load JPG	☒
3	09/05/18 16:53	General View	1	Load JPG	☒
4	09/05/18 16:53	General View	1	Load JPG	☒
5	09/05/18 16:53	General View	1	Load JPG	☒
6	09/05/18 16:53	General View	1	Load JPG	☒
7	09/05/18 16:53	General View	1	Load JPG	☒
8	09/05/18 16:53	General View	1	Load JPG	☒
9	09/05/18 16:53	General View	1	Load JPG	☒
10	09/05/18 16:53	General View	1	Load JPG	☒
11	09/05/18 16:53	General View	1	Load JPG	☒
12	09/05/18 16:53	General View	1	Load JPG	☒
13	09/05/18 16:53	General View	1	Load JPG	☒
14	09/05/18 16:53	General View	1	Load JPG	☒
15	09/05/18 16:53	General View	1	Load JPG	☒

Documentation				1 per page	☒
No	Relabel/Reorder			Thumbnail	Print
1	14/03/18 15:15	EMAIL FROM AIG DD 12032018	1	Load PDF	
2	14/03/18 15:15	TP GIA REPORT	1	Load PDF	
3	14/03/18 18:06	TP ESTIMATE- MARKED	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLA9803T (Insd veh)	Model:	BMW 730LI 3.0 AT ABS D/AB
	SJY37U (TP veh)		2WD 4DR NAV HID SR (A)
Date of Accident:	06/03/2018		

Global Sum Settlement	:	☐ Yes	☒ No		
Repair Estimate	:	\$	5,089.99		
Final Repair Cost	:	\$	3,075.02		
Loss of Use	:	\$		days at \$0.00 per day	
Rental (if any)	:	\$	360.00	3	days
LTA / GIA Search Fee	:	\$	7.45		
Others:	:	\$	0.00		
	:	\$			
Final Settlement Sum	:	\$	3,442.47		

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Lim Tan Motor Pte Ltd	: \$	3,442.47
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

15 May
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18004841/KJB3Q2

Date: 15/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100457463
Claimant Vehicle No : SJY37U **Insured Vehicle No :** SLA9803T
 Date of Loss: 06/03/2018 Nature of Claim: TP Claim No: 5721729994SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJY37U**
 Make & Model: BMW 730Li, 3.0 AT ABS D/AB 2WD 4DR NAV HID SR (A) Engine No: 70304598N52B30AF
 Reg. Date: 01/04/2010 (Man. Year: 2009) Chassis No: WBAKB22090CN74121
 Colour: Metallic Dark Grey Odometer: 198588 km
 Engine Capacity: 2996 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/45 R19 Rear Tyre Size: 275/40 R19
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,887.00	2,163.85	1,723.15	44.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	870.00	710.00	160.00	18.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,757.00	2,873.85	1,883.15	39.59
+ GST 7.00/7.00% (S\$)	332.99	201.17	131.82	39.59
Nett Amount (S\$)	5,089.99	3,075.02	2,014.97	39.59
+ Car Rental (3.0 x S\$120.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,442.47		

INSPECTION

Date of Assignment: 13/03/2018
 Date Inspected: 13/03/2018 Inspected At: Lim Tan Motor Pte Ltd (HQ)
 Blk 176 Sin Ming Drive #03-09/10, Sin
 Ming Auto Care
 Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,571.15 F	*1,571.15 F
2	1		*REAR BUMPER LOWER LID	Scratched	224.45 F	*224.45 F
3	1		*REAR BUMPER SENSOR (2 PCS)	Dented (1 PCS ONLY)	437.70 F	*236.85 F
4	1		*REAR BUMPER REINFORCEMENT	Repair	800.80 F	*- F
5	1		*N/S TAIL LAMP (CRACKED)	Not Consistent With The Impact	721.50 F	*- F
6	1		*REAR BOOT 730LI EMBLEM	Necessary	62.55 F	*62.55 F
7	1		*REAR BUMPER REINFORCEMENT OUTER FOAM	Cracked	68.85 F	*68.85 F

F=Franchise part.

Total Parts (S\$)	3,887.00	2,163.85
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY & SPRAY PAINTING	New	450.00	400.00
2	TO CHECK REAR WIRING AND REPLACE SENSOR	New	120.00	60.00
3	LABOUR CHARGES	New	300.00	250.00
Gross Labour Cost (S\$)			870.00	710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >