

Send 13/3

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
Halcyon 2, S'pore 577200
Tel No. : 6451 3933 Fax No. : 6455 7576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL ST #04-05 IOB BUILDING
049711

Attention : Motor Claim Department
Contact : 6223 8122

Estimate : ES005797

Date : 12/03/2018
Vehicle Num. : SLQ 9849C(LCR)
Make/Model : TOYOTA PRIUS HYBRID 1.8S
Chassis/Eng# :
Accident Date : 09/03/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	LIST ITEMS :		
2.	1	REAR BUMPER ✓ Deform.		423.90
3.	1	REAR BUMPER REINFORCEMENT ? X		318.80
3.	1	REAR BUMPER LOWER COVER ✓ Deform.		552.30
		List TotalS\$:		1,295.00
		25.00% Discount S\$:		323.75
				971.25
1.	1 SET	SPECIAL NETT ITEMS :		
		REVERSE SENSOR ? X		280.00
		Special Nett Total S\$:		280.00
		LABOUR :		
		LABOUR TO RENEW REAR BUMPER AND KNOCK OUT END PANEL		
		ALIGN REAR BUMPER.		400.00 300.
		SPRAY PAINT TO REAR BUMPER,REAR BOOT ETC(PEAL WHITE)		480.00 250.
		Labour Total S\$:		880.00

E. & O.E.

Total S\$: 2,131.25
=====

for WORLD AUTO PTE LTD

Sebastian.
14/3/18.

- Part by part repair.
- Question Mark Item
- Photo
- Photo Before Paint

3 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: