



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

Vehicle No : SKF5697U
Make & Model : MERCEDES BENZ, C 180
KOMPRESSOR, WDD2040452A716510
Year of Manufacture : 2012

TP FWD
Asher

ESTIMATION REPORT

Estimation No. : E18030042
DOA : 13/03/2018

WDD2040452A716510.

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bumper <i>shd</i>	1.00	1,672.00	1,672.00 1448
2	Rear bumper clip <i>m</i>	10.00	5.00	50.00
3	Rear bumper retainer (LH) <i>me n</i>	1.00	76.00	76.00
4	Rear bumper retainer (RH) <i>m</i>	1.00	76.00	76.00
5	Rear bumper bracket (RH) <i>me n</i>	1.00	45.00	45.00
6	Rear bumper chrome piece <i>m</i>	3.00	379.00	1,137.00 445
7	Tail lamp (RH)	1.00	684.00	684.00
8	Tail lamp clip (RH)	10.00	5.00	50.00
9	Tail lamp bracket (RH)	1.00	0.00	0.00
10	Tail lamp panel (RH)	1.00	210.00	210.00
11	Rear fender (RH) <i>Painted</i>	1.00	2,300.00	2,300.00 1975
12	Rear fender cowl (RH)	1.00	220.00	220.00
13	Rear fender cowl clip (RH)	10.00	5.00	50.00
14	Rear fender inner trim (RH)	1.00	45.00	45.00
15	Rear fender inner trim clip (RH)	10.00	5.00	50.00
16	Rear door (RH) <i>Repair</i>	1.00	2,150.00	2,150.00
17	Rear door weather strip (RH)	1.00	375.20	375.20
18	Rear door chrome protector (RH)	1.00	512.00	512.00
19	Rear door window moulding (RH)	1.00	240.00	240.00
20	Rear door window chrome piece (RH)	2.00	314.00	628.00
21	Rear door lock (RH)	1.00	0.00	0.00
22	Rear rim	1.00	0.00	0.00
23	Rear tyre	1.00	0.00	0.00
24	Rear absorber	1.00	606.00	606.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKF5697U
Make & Model : MERCEDES BENZ,C 180
KOMPRESSOR,WDD2040452A716510
Year of Manufacture : 2012

Estimation No. : E18030042
DOA : 13/03/2018

No	Description	Qty	U/P	Amt
25	Rear bearing	1.00	390.00	390.00
26	Rear kunckle	1.00	1,804.00	1,804.00
27	Rear lower arm	1.00	275.60	275.60
28	Rocker panel	1.00	0.00	0.00
Amt				S\$ 13,645.80
Discount (0.00%)				S\$ 0.00
Subtotal				S\$ 13,645.80

Section: Special Nett Items

29	Rear fender sealant	1.00	80.00	80.00
Amt				S\$ 80.00
Discount (0.00%)				S\$ 0.00
Subtotal				S\$ 80.00

Section: Labour Items

30	To R&R accident affected areas	1.00	1,250.00	1,250.00
31	To putty & respray accident affected areas	1.00	1,000.00	1,000.00
32	To rust proof accident affected areas	1.00	60.00	60.00
33	To R&R rear luggage compartment	1.00	200.00	200.00
34	To R&R rear bumper reverse sensor & check function	1.00	80.00	80.00
35	To check wiring layout of tail lamp	1.00	80.00	80.00
36	To R&R rear door mechanism	1.00	80.00	80.00
37	To R&R rear under carriage	1.00	300.00	300.00
38	To check for water seepage	1.00	100.00	100.00
39	To do wheel alignment	1.00	180.00	180.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Continue on next page...

Adrian Lj
w/s 15/03/18
05 Apr.

Veron Chen (LKKAuto)

From: Torque 5 Assessment <assessment@torque5.com>
Sent: Monday, 17 June 2019 10:47 AM
To: Adrian Ling (LKKAuto); Veron Chen (LKKAuto)
Cc: 'Torque 5 Assessment'; claims@torque5.com; sam.chang@torque5.com
Subject: RE: SKF 5697 U - Mercedes Benz C180

Importance: High

Dear Adrian,




We hereby confirm the final amount of L/S \$4,250 (before GST @ 5 repair days).
Thank you.

Warmest Regards,
Stephanie Teo
Assessor | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com



From: Torque 5 Assessment [mailto:assessment@torque5.com]
Sent: Thursday, 30 May, 2019 10:54 AM
To: 'Adrian Ling (LKKAUTO)'
Cc: 'Torque 5 Assessment'
Subject: SKF 5697 U - Mercedes Benz C180
Importance: High

**** URGENT ****

Dear Adrian,

Kindly refer to the attached for the damages part of the above mentioned vehicle for your consideration.



Do revert if we can close this case at L/S \$4,770 @ 5 repair days.

Warmest Regards,
Stephanie Teo
Assessor | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com

