

INS. CASE OWNER

CC 3/CTI1800

4864, F/A 18/12

LKK

IDAC

Surveyor

Fenneth

DOI:

ASSIGNMENT

13/3/18

Date / Time

13/3/18

Registered in Meriton

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLN 35414

Name of Insured:

UENH HADONG

Insured Tel No.:

HP: 913 81486

Excess Sec II :SS

D.O.A: 10/3/18

Is driver the owner?

(YES) / NO

Nature of Accident:

Claim No.:

GNM150013410X

Policy No.:

DMP66N173231700

Make / Model:

NORDA

Place of Accident:

MURRAY WEST ACTING SG
SPORTS CENTRE

If SG, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final? Yes / No

SHD 897M



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans
Cab

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

16/3/18
TH

SHD 897M - F

SLN 35414 - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

10/04/18 - Summary

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

28/6/18

Called OI to inform TP claim

21-10-18

TP ALSO SHOULD TAKE 25% DEGREE OF BLAME FOR NOT
TAKING ANY EVASIVE ACTION TO AVOID THE COLLISION
(SEE COMMENTS)

29-11-18

PLS INITIATE YOUR OFFER FROM 80% SLOWLY INCREASE IF
SITUATION NEED TO -

5/3/2020

Init PMJ To move to close

PRELIMINARY ADVICE Date/Time:

14/3/18

Sent By:

Phe

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

26/3/2020

Confirm with:

Amuda

Email

Call

Final Liability:

%

80

(Agreed / Assessed) BOLA S/N No.:

NIL

Repair Cost:

SS

1296.84

OI REVERSE AND HIT

Loss of Rental (LOR):

SS

187.20

(

3

days) x 478

TP

Loss of Use (LOU):

SS

-

(5

x

days)

Loss of Income (LOI):

SS

120.00

(5

x

3

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

GLA / T Search:

SS

-

Medical:

SS

-

Disbursement:

SS

-

Legal Cost:

SS

-

Total:

SS

1604.04

Global Sum SS: 1600.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

1600.00

Name 1:

Trans - Cab Auto Services Pte Ltd

Payee 2 (Strike if N.A.):

SS

Name 2:

Payee 3 (Strike if N.A.):

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

5400

COPY SENT
16/3/2020

ASS. REC. BY:

REF: 0721

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 1/2 days Res.: Yes or No

Lum Sum: 1.8.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 897M Yr Regn: 07 17

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi / Prime Mover /

Truck / Traller or _____

Make: Perant Longitude c.c. 1895

Colour: White 1Pw A/C: Insured / Std / NI / NA

Sp. Reading: 82015 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF1A3L15AUC 283481

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 10/3/18

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

14/3	1515.00 - 11P (Red \$24103.37 947.)
------	-------------------------------------

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18004864/Kub3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 14-03-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLN 3541U	Veh. Inspected	SHD 897M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	14/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	10/03/2018	Inspection Date	13/03/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 CUBA AVE. #02-25 PAYA LEBU INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI18004864/Kub3

Date: 14.03.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD897M

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13.03.2018 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	25,618.37
Revised Estimate Amount	: S\$	1,515.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S Body



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2.5 days

Yours faithfully,

KENNETH KONG

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD897M
Vehicle to be Exported:	Yes
Intended De-registration Date:	12 Mar 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	M9R8839C003199
Chassis No.:	VF1ABL15AUC283481
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	10 Jul 2017
First Registration Date:	10 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Jul 2025
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	

COE Expiry Date:	09 Jul 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$38,560.00
COE Rebate Amount:	\$30,848.00
Total Rebate Amount:	\$45,846.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Mar 2018

OK

Shu Pei (LKKAUTO)

From: Angie Foo <angie.foo@sg.cntaiping.com>
Sent: Thursday, 15 March 2018 4:43 PM
To: Shu Pei (LKKAUTO)
Cc: Chong Boon Sen; Thin Thin (LKKAUTO); Admin A; Claims Dept of CTI
Subject: OUR REF: SNM18D01341C02/1/LKKDS & YR REF: (TP : LKK REF - CC3/CTI18004864/Kub3) on 10.03.2018
Attachments: MSAT18033707-SLN3541U.pdf, SNM18D01341C02 20180315 TO INSURED -SLN3541U-LKKDirectSettlementAccidentNotReportedLtr.pdf

Dear Shu Pei,

We refer to your email of 14th March 2018.

We attached our Insured's SAS Report and Assignment Letter for your necessary action

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co.Reg.No.200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, 14 March, 2018 5:57 PM
To: Claims Dept of CTI
Cc: Chong Boon Sen; Thin Thin (LKKAUTO); Admin A
Subject: Direct Settlement - Accident Involving SLN3541U (OI : CTI - TBA) and SHD897M (TP : LKK REF - CC3/CTI18004864/Kub3) on 10.03.2018

WITHOUT PREJUDICE

Dear Sir/ Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHD 897M at M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

Thank You.

Best Regards,

Shu Pei | Admin

L&K Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkauto.com | fax: 6741-4108

8th Fl, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Our Reference: **SNM18D01341/C02/1**Date: **15 MARCH 2018**

via Ordinary & Registered Mail

CHENG HAIDONG
BLK 656C JURONG WEST STREET 61
#04-315
SINGAPORE 643656

Dear Sir / Madam

ACCIDENT INVOLVING SLN3541U AND SHD897M ON 10 MARCH 2018
ALONG JURONG WEST ACTIVE SG SPORTS CENTRE

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHD897M**, is filing a third party property claim against your vehicle.We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will soon contact you for more information about the accident. Kindly render your assistance and co-operation accordingly.We understand that you or your driver has not filed an accident report within 24 hours as per Motor Claims Framework. We would urge you to comply with the condition to file your accident report with your vehicle (whether damaged or not) to us IMMEDIATELY through **LKK Auto Consultants Pte Ltd** or any of our authorized workshops. You may log onto our website www.sg.cntaiping.com for location of the respective workshops.We regret to advice that we and/or **LKK Auto Consultants Pte Ltd** will not be handling the third party claim and your NO CLAIM DISCOUNT will be penalized upon renewal of your policy if you fail to comply with the condition of reporting.Yours truly,
Claims Department*(This is a computer generated letter and no signature is required.)*CC: **LKK Auto Consultants Pte Ltd**
Attn : **THIN THIN**
Ref : **TP : LKK REF - CC3/CT118004864/Kub3**
Contact No : **6841 2360**
via Email : **thinthin@lkkauto.com**

CC: Agent - (AN0420A) - INXPRESS INSURANCE AGENCY PTE LTD

F02/LKKDSANR-2013

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL.NO. 6287 6666 FAX NO. 6257 1330

GO/GST REG NO. 201019626G

SHD897M - CHINA TAIPING**AAD1803-092**

Not Authorised
Reserving B4 pair 81515-00

Vehicle No.:	SHD897M - CANDY
Chassis No.:	VF1ABL15AUC283481
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	10.03.2018
Third Party Insurer :	CHINA TAIPING

PART			LIST	
1	1	BUMPER COVER REAR	\$	1,108.46
2	1	BUMPER LOWER REAR	\$	768.84
3	1	BUMPER BRACKET CTR REAR	\$	113.47
4	1	BUMEP R BRACKET SIDE RH REAR	\$	135.97
5	1	BUMEP R RETAINER RH REAR	\$	44.99
6	1	BUMPER REFLECTOR RH	\$	43.61
7	1	BUMEP R BRACKET SIDE LH REAR	\$	135.97
8	1	BUMEP R RETAINER LH REAR	\$	44.99
9	1	ROCKER PANEL OUTER RH	\$	987.49
10	1	FENDER PANEL REAR RH	\$	3,299.13
11	1	WHEELARCH REAR RH	\$	543.47
12	1	TAILLAMP RH	\$	552.55
13	1	TAILLAMP PANEL RH	\$	986.70
14	1	DOOR PANEL REAR RH	\$	2,844.66
15	1	DOOR GUIDE REAR RH	\$	176.82
16	1	DOOR HINGE UPPER RH	\$	274.50
17	1	DOOR HINGE LOWER RH	\$	300.55
18	1	DOOR CHECK REAR RH	\$	203.06
19	1	DOOR GRAB HANDLE REAR RH	\$	210.96
20	1	DOOR HANDLE OUTER REAR RH	\$	126.49
21	1	DOOR HANDLE CAP REAR RH	\$	35.52
22	1	DOOR HANDLE SEAL REAR RH	\$	7.89
23	1	DOOR HANDLE COVER REAR RH	\$	13.22
24	1	DOOR HANDLE MODULE REAR RH	\$	133.60
25	1	DOOR FINISHER REAR RH	\$	423.10
26	1	DOOR WHEATHESTRIIP REAR RH	\$	410.66
27	1	DOOR SEAL REAR RH	\$	162.02
28	1	DOOR WAIST SEAL OUTER REAR RH	\$	334.69
29	1	DOOR MOULDING REAR RH	\$	176.82
30	1	DOOR PANEL FRT RH	\$	2,844.66

TOTAL	\$	17,444.86
10%	\$	1,744.49
	\$	15,700.37

TRANS-CAB AUTO SERVICES PTE LTD**AAD1803-092**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL.NO. 6287 6666 FAX NO. 6257 1330

GO/GST REG NO. 201019626G

SHD897M - CHINA TAIPING**Specical Nett**

1	1SET	PARKING AID	\$	Sm	700.00	}	X
2	1SET	REAR BUMPER CLIP	\$	nn	66.00		
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00		
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	nn	10.00		
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	nn	20.00		
6	1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00		
7	1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00		
8	1	TAILLAMP CLIP RH	\$	nn	5.00		
9	1SET	WHEELARCH CLIP RR RH	\$	nn	66.00		
10	2	REAR WINDSCREEN SELANT	\$	nn	80.00		
11	1	WINDSCREEN MOULDING	\$	nn	100.00	}	
12	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00		
13	1	CAP HUB RH RR	\$	Sm	35.00		
14	1	RIM RH RR	\$	Sm	385.00		
15	1	TYRE RH RR	\$	Sm	330.00	}	
16	1	DOOR STICKER "Trans-cab"	\$	nn	80.00		
17	1	DOOR STICKER "Classic"	\$	nn	30.00		
18	1	DOOR STICKER "6555-3333"	\$	nn	80.00	}	

TOTAL	\$	2,208.00
TOTAL PARTS	\$	17,908.37

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	Spd
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	50d
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
Towing Fees	\$	nn 120.00	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1803-092**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL.NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD897M - CHINA TAIPING

To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	nn 170.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X

TOTAL	\$	7,710.00
Over All Total	\$	25,618.37

(PARTS BY PARTS)**Repair Days****10 Days***24 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To re-survey before/after spray painting
- To display damaged part(s) during re-survey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be re-surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18004864/Kda3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 09-03-2020		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLN 3541U	Veh. Inspected	SHD 897M	
Policy No.	DMPCSN1732331700	Coverage (\$)	0.00	
Claim No.	SNM18D01341C02/1	Excess (\$)	0.00	
Assign From		Assign Date	13/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VF1ABL15AUC283481	Colour	METALLIC WHITE / RED	
Odometer	82015	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GOODYEAR	7 mm	
L/H Front Tyre	215/60 R16	GOODYEAR	7 mm	
R/H Rear Tyre	215/60 R16	GOODYEAR	8 mm	
L/H Rear Tyre	215/60 R16	GOODYEAR	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/03/2018	Inspection Date	13/03/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2.500 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 897M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER REAR	TO REPAIR SEE LABOUR	1,108.46	-
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	ROCKER PANEL OUTER RH	TO REPAIR SEE LABOUR	987.49	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR GUIDE REAR RH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR RH	SERVICEABLE	203.06	-
1	DOOR GRAB HANDLE REAR RH	SERVICEABLE	210.96	-
1	DOOR HANDLE OUTER REAR RH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR RH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR RH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR RH	SERVICEABLE	133.60	-
1	DOOR FINISHER REAR RH	SERVICEABLE	423.10	-
1	DOOR WEATHERSTRIP REAR RH	SERVICEABLE	410.66	-

Report Ref No. CC3/CT118004864/Kda3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR SEAL REAR RH	SERVICEABLE	162.02	-
1	DOOR WAIST SEAL OUTER REAR RH	SERVICEABLE	334.69	-
1	DOOR MOULDING REAR RH	SERVICEABLE	176.82	-
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,844.66	-
	LESS 10% DISCOUNT		-1,744.49	-
			15,700.37	-
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	66.00	-
1	SET BUMPER BRACKET CTR CLIP (SN)	NOT NECESSARY	33.00	-
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	66.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	SET WHEELARCH CLIP RR RH (SN)	NOT NECESSARY	66.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	CAP HUB RH RR (SN)	SERVICEABLE	35.00	-
1	RIM RH RR (SN)	SERVICEABLE	385.00	-
1	TYRE RH RR (SN)	SERVICEABLE	330.00	-
1	DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	DOOR STICKER "CLASSIC" (SN)	NECESSARY	30.00	15.00
1	DOOR STICKER "6555-3333" (SN)	NECESSARY	80.00	60.00
			2,208.00	135.00
	<u>LABOUR</u>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	880.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER COVER REAR,ROCKER PANEL OUTER RH,FENDER PANEL REAR RH,TAILLAMP PANEL RH,DOOR PANEL REAR RH,DOOR HINGE UPPER RH,DOOR HINGE LOWER RH AND DOOR PANEL FRT RH.		2,800.00	500.00
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
			7,710.00	1,380.00
	GRAND TOTAL		25,618.37	1,515.00
RECOMMENDED COST OF REPAIRS				1,515.00

Report Ref No. CC3/CT118004864/Kda3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.