

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL.NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD897M - CHINA TAIPING**AAD1803-092**

Not Authored
Reserving B4 paid \$1515.00

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD897M - CANDY

VF1ABL15AUC283481

RENAULT

LATITUDE

10.03.2018

CHINA TAIPING**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>R</i> 1,108.46
2	1	BUMPER LOWER REAR	\$	<i>S</i> 768.84
3	1	BUMPER BRACKET CTR REAR	\$	<i>S</i> 113.47
4	1	BUMEP R BRACKET SIDE RH REAR	\$	<i>S</i> 135.97
5	1	BUMEP R RETAINER RH REAR	\$	<i>S</i> 44.99
6	1	BUMPER REFLECTOR RH	\$	<i>S</i> 43.61
7	1	BUMEP R BRACKET SIDE LH REAR	\$	<i>S</i> 135.97
8	1	BUMEP R RETAINER LH REAR	\$	<i>S</i> 44.99
9	1	ROCKER PANEL OUTER RH	\$	<i>R</i> 987.49
10	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13
11	1	WHEELARCH REAR RH	\$	<i>S</i> 543.47
12	1	TAILLAMP RH	\$	<i>S</i> 552.55
13	1	TAILLAMP PANEL RH	\$	<i>R</i> 986.70
14	1	DOOR PANEL REAR RH	\$	<i>R</i> 2,844.66
15	1	DOOR GUIDE REAR RH	\$	<i>S</i> 176.82
16	1	DOOR HINGE UPPER RH	\$	<i>R</i> 274.50
17	1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55
18	1	DOOR CHECK REAR RH	\$	<i>S</i> 203.06
19	1	DOOR GRAB HANDLE REAR RH	\$	<i>S</i> 210.96
20	1	DOOR HANDLE OUTER REAR RH	\$	<i>S</i> 126.49
21	1	DOOR HANDLE CAP REAR RH	\$	<i>S</i> 35.52
22	1	DOOR HANDLE SEAL REAR RH	\$	<i>S</i> 7.89
23	1	DOOR HANDLE COVER REAR RH	\$	<i>S</i> 13.22
24	1	DOOR HANDLE MODULE REAR RH	\$	<i>S</i> 133.60
25	1	DOOR FINISHER REAR RH	\$	<i>S</i> 423.10
26	1	DOOR WHEATHESTRIIP REAR RH	\$	<i>S</i> 410.66
27	1	DOOR SEAL REAR RH	\$	<i>S</i> 162.02
28	1	DOOR WAIST SEAL OUTER REAR RH	\$	<i>S</i> 334.69
29	1	DOOR MOULDING REAR RH	\$	<i>S</i> 176.82
30	1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66

TOTAL	\$	17,444.86
10%	\$	1,744.49
	\$	15,700.37

TRANS-CAB AUTO SERVICES PTE LTD**AAD1803-092**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL.NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD897M - CHINA TAIPING**Special Nett**

1	1SET	PARKING AID	\$	Sn	700.00	}	X
2	1SET	REAR BUMPER CLIP	\$	nn	66.00		
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00		
4	1SET	BUMEP R BRACKET SIDE CLIP RH RR	\$	nn	10.00		
5	1SET	BUMEP R RETAINER RH CLIP RR	\$	nn	20.00		
6	1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00		
7	1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00		
8	1	TAILLAMP CLIP RH	\$	nn	5.00		
9	1SET	WHEELARCH CLIP RR RH	\$	nn	66.00		
10	2	REAR WINDSCREEN SELANT	\$	nn	80.00		
11	1	WINDSCREEN MOULDING	\$	nn	100.00	}	X
12	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00		
13	1	CAP HUB RH RR	\$	Sn	35.00		
14	1	RIM RH RR	\$	Sn	385.00		
15	1	TYRE RH RR	\$	Sn	330.00		
16	1	DOOR STICKER "Trans-cab"	\$	nn	80.00		
17	1	DOOR STICKER "Classic"	\$	nn	30.00		
18	1	DOOR STICKER "6555-3333"	\$	nn	80.00		

TOTAL	\$	2,208.00
TOTAL PARTS	\$	17,908.37

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	Spd
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	Spd
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
Towing Fees	\$	nn 120.00	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1803-092**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL.NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD897M - CHINA TAIPING

To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X

TOTAL	\$	7,710.00
Over All Total	\$	25,618.37

(PARTS BY PARTS)**Repair Days**~~10 Days~~*21 day*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: