

ASS. REC. BY:

REF: CS / SMO18 004865 / Kad3⁰²

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Irene Henry

of SMO

Date/Time: 14/3/18 @ 11:05am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLL3482S

Insured:

FBM 6111G

at Workshop m/s

K. Kim Hin Auto

Tel:

64527018

of

160 Sin Ming Drive #02-20

Policy No:

Claim No:

CMTD1801133

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/3/18

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

12:44pm @ 14/3/18

Person Contacted:

Shuman

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLL3482S - X

FBM6111G - X

15/3/18 @ 2:16pm revised to Irene Henry by email.

15/5 @ 8:33:59.12 Confirmed by email (Red \$ 2108.92, 34%.)

ASS. REC. BY:

REF: SMO/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s KCKHIN

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 1.3.1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLL34825 Yr Regn: 02, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Honda 1498 c.c.

Colour: m. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 23812 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMGK5750HX 202393

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 13/3/18

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 14/3/18

Survey held at _____

Des. of Damages: Nil / Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/3 File pass to Kenneth

RECEIVED 18 MAY 2018

Date/Time, File Pass to?

: Prell. Report

1) 18/5 transfer

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

250

Report Format: TP

Lump Sum / I.B.I. (\$) 3359.12



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18004865/Kqd3	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 14-03-2018	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBM 6111G	Veh. Inspected	SLL 3482S
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801133	Excess (\$)	0.00
Assign From	IRENE HENRY	Assign Date	14/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	13/03/2018	Inspection Date	14/03/2018
Survey held at	160 SIN MING DRIVE #02-20		
Repairer	K KIM HIN AUTOMOTIVE PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD18001133/RE

Date: 15th March 2018

Our Ref: CS/SMO18004865/Kqd3

Without Prejudice

The Motor Claims Department
Sompo Insurance

Attn: Irene

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SLL 3482S


We thank you for the instruction on 14/03/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/03/2018 at the premises of M/s K KIM HIN and have the following to report:-

Workshop Estimate Amount	: S\$	<u>5,467.84</u>
Revised Estimate Amount	: S\$	<u>3,336.72</u>
"Check" Items Amount	: S\$	<u>288.56</u>
Market Value	: S\$	<u>-</u>
LTA Reimbursement Value	: S\$	<u>-</u>
Nett Value	: S\$	<u>-</u>

Description of Damage:

The vehicle sustained damages at the n/s rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 6 days.

We have NOT authorize repair.

Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

Nivitha (LKK Auto)

From: Henry, Irene James <irene.henry@sompo.com.sg>
Sent: Wednesday, 14 March 2018 11:05 AM
To: service@kkimhin.com.sg
Cc: sandrakhong@gmail.com; admin1@kkimhin.com.sg; simon@kkimhin.com.sg; survey@kkimhin.com.sg; Chan, Shu Hui Agnes; assignments; Nivitha (LKK Auto)
Subject: SOMPO REF: CMTD1801133/RE: Accident Involving SLL 3482 S and FBM 6111G on13 Mar 2018
Attachments: GIA REPORT.PDF

Our Claim Reference: CMTD1801133

WITHOUT PREJUDICE

Hi,

We refer to the above matter.

We regret to inform that we are still unable to revert on liability for direct settlement as we have yet to receive our insured's accident report.

As spoken, we shall proceed to assign LKK AUTO CONSULTANTS as agreed on the "SJE" to conduct the motor survey on a "without Prejudice" basis.

Aside to LKK AUTO,

Kindly assist to arrange to conduct the motor survey.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: service@kkimhin.com.sg [mailto:service@kkimhin.com.sg]

Sent: Tuesday, 13 March, 2018 7:02 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>; Teo, See Ling <seeling.teo@sompo.com.sg>

Cc: sandrakhong@gmail.com; admin1@kkimhin.com.sg; simon@kkimhin.com.sg; survey@kkimhin.com.sg

Subject: Accident Involving SLL 3482 S and FBM 6111G on 13 Mar 2018

Your Ref: FBM 6111 G

Our Ref: SLL 3482 S

Dear Survey Team/ Officer

Good day to you.

Enclosed the GIA report of our client SLL 3482 S who was hit by your insured FBM 6111 G on 13 Mar 2018.

Vehicle is in our workshop.

Please kindly arrange for survey and advise liability.

Many thanks.

Regards

Sandra

64527018

K. Kim Hin Auto Pte Ltd

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 15 March 2018 2:16 PM
To: 'Henry, Irene James'
Cc: 'Chan, Shu Hui Agnes'; SUR
Subject: RE: SOMPO REF: CMTD1801133/RE: Accident Involving SLL 3482 S and FBM 6111G on13 Mar 2018
Attachments: CSSMO18004865Kqd3.pdf

Dear Irene,

Enclosed herewith preliminary advice of SLL 3482S.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 14 March 2018 1:01 PM
To: 'Henry, Irene James' <irene.henry@sompo.com.sg>
Cc: 'Chan, Shu Hui Agnes' <agnes.chan@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SOMPO REF: CMTD1801133/RE: Accident Involving SLL 3482 S and FBM 6111G on13 Mar 2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Henry, Irene James [<mailto:irene.henry@sompo.com.sg>]
Sent: Wednesday, 14 March 2018 11:05 AM
To: service@kkimhin.com.sg
Cc: sandrakhong@gmail.com; admin1@kkimhin.com.sg; simon@kkimhin.com.sg; survey@kkimhin.com.sg; Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; assignments <assignments@lkkauto.com>; Nivitha (LKK Auto) <admin-d@lkkauto.com>
Subject: SOMPO REF: CMTD1801133/RE: Accident Involving SLL 3482 S and FBM 6111G on13 Mar 2018

Our Claim Reference: CMTD1801133

WITHOUT PREJUDICE

Hi,

We refer to the above matter.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 1155R

Vehicle Details

Vehicle No.: SLL3482S

Vehicle to be Exported: Yes

Intended De-registration Date: 13 Mar 2018

Vehicle Make: HONDA

Vehicle Model: JAZZ 1.5 VTIR M/T ABS D/AIRBAG 2WD

Primary Colour: Silver

Manufacturing Year: 2017

Engine No.: L15B31200009

Chassis No.: JHMGK5750HX202393

Maximum Power Output: 96.0 kW (128 bhp)

Open Market Value: \$16,460.00

Original Registration Date: 22 Feb 2017

First Registration Date: 22 Feb 2017

Transfer Count: 0

Actual ARF Paid: \$16,460.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 21 Feb 2027

PARF Rebate Amount: \$12,345.00

Intended COE Rebate Details

COE Expiry Date: 21 Feb 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$48,000.00

COE Rebate Amount: \$38,400.00

Total Rebate Amount: \$50,745.00

The information contained herein is correct as at 13 Mar 2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/03/2018 16:41
Date Of Accident	13/03/2018 10:25
Exact Location Of Accident	BUKIT BATOK WEST AVE 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL3482S
Insured/Policyholder	
Name Of Registered Owner	BUKIT BATOK DRIVING CENTRE LTD
Co Reg No	198801155R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65611233

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ 1.5 VTIR M/T ABS D/AIRBAG 2WD
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	0073346186-14
Cover Note Number	

Driver

Name of Driver	TEE ZHONGCHENG
NRIC No	S8307945B
Date Of Birth	13/03/1983
Occupation	INDOOR
Date Of Driving Pass	13/03/2018
Driving Experience	0 YEAR AND 0 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96814821
Fax Number	
Contact Number	
EEmail Address	TEEZC83@GMAIL.COM

Address BLK 358 BUKIT BATOK STREET 31 #10-383
 Postcode 650358
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - LEARNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : DRIVING INSTRUCTOR
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 21 BUKIT BATOK EAST AVE 4 , POSTCODE: 659840 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-6659999 - FAX NO: 66655793
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBM6111G
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category MOTORCYCLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number FP8691Y
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category MOTORCYCLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name RIDER
Approximate Age
Injuries Sustain
Injured person in which vehicle? FBM6111G
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

DETAILS OF INJURED PERSON 2

Name RIDER
Approximate Age
Injuries Sustain
Injured person in which vehicle? FP8691Y
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

BUKIT BATOK DRIVING CENTRE LTD
 1233 BUKIT BATOK WEST AVENUE 3
 SINGAPORE 680035
 1233 FAX: 6862 9777

Policyholder's Signature
 Date & Time:


Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



Shuman
 13/3/18 @
 4.40pm

Sketch Plan Pg. 2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Waiting for a right turn, Then motorcycles bang me from the rear.
That's all.

DECLARATION DRIVING CENTRE LTD
 I/We declare the facts and circumstances are true in every respect.
 SINGAPORE 650085
 TEL: 6561 1233 FAX: 6569 0777

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



Shum

13/3/18 @
 4:40pm



**SINGAPORE
POLICE FORCE**



T/20180313/2052

2 of 3

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

Report No. T/20180313/2052

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TEE ZHONGCHENG	ID No.	S8307945B
Related Vehicle	SLL3482S (Car)	Contact No.	96814821
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 13/03/2018 at about 1026hrs, I am having my driving Practical Test when the accident happened and my tester is namely, Ahmad Redzuan Bin Masod. When I was waiting for traffic to clear along Bukit Batok West Ave 5 towards Bukit Batok Central in my vehicle of reg: SLL3482S, Model: Honda Jazz: Colour: Silver to make a right turn into Bukit Batok Driving Centre in lane 1. Suddenly, a motorcycle of reg: FBM6111G, Model: YAMAHA, Colour: Blue hit onto the left rear of my vehicle. After the rider of reg: FBM6111G hit onto my vehicle, he steered towards his left and hit onto another motorcycle of reg: FP8691Y, RXZ Colour: White. Traffic Police came to scene. Both of the riders were injured and conveyed to hospital by ambulance. Both my passenger who is my tester and I do not have injuries. The left rear bumper, fender and tier light of my vehicle of reg: SLL3482S are all damaged. Both of the motorcycles of reg: FBM6111G and FP8691Y were seriously damaged. There was no government property damaged.



SINGAPORE
POLICE FORCE



T/20180313/2052

3 of 3

Report No. T/20180313/2052

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J/ Sr Staff Sgt MARY CHYE SIEW PING	
Signature Of Interpreter: Not applicable	
Officer In Charge Of Case: TP / GIT / SSI TAN CHIN YONG Contact No.: 65476178	

Signature Of Informant:	
Date/Time: 13/03/2018 12:38	
Classification Of Case:	

Authentication Stamp

 Singapore Police Force

TP
 BBDC

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
 Sin Ming AutoCity, Singapore 575722
 Tel: 6452 7018 Fax: 6458 3895
 Email: service@kkinhin.com.sg

No. : 29622

Vehicle Insured : FBM 6111 G
 Accident Date : 13-Mar-2018

Date : 14-Mar-2018

Our Ref : 180190 (SOMPO) / SHUMAN

PAGE : 1

BUKIT BATOK DRIVING CENTRE LTD
 Singapore

Not Authorized
Resurvey B & PAIN
 83359.12
 6 days

ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.5 VTIR M/T ABS (2017) SLL3482S
 =====

1 pc	tailgate "JAZZ" emblem		NA	32.90	X
1 pc	rear bumper		Bu	492.60	✓
1 pc	n/s rear bumper side retainer		CRS	28.00	—
10 pcs	rear bumper clips	@ S\$ 3.80	NA	38.00	—
1 pc	n/s rear bumper side garnish		SN	38.00	X
1 pc	n/s rear bumper inner shield		SN	165.00	X
1 pc	n/s taillamp assy		CRS	228.00	✓
1 pc	n/s taillamp panel		R	332.70	✓
1 pc	n/s taillamp clips		NA	3.80	—
1 pc	n/s rear fender		Bu	610.90	—
1 pc	n/s rear fender top glass		NA	28.00	✓
	moulding				
1 pc	n/s rear fender inner shield		SN	165.00	X
1 pc	n/s rear rim		PD	819.60	✓
1 pc	n/s rear wheel bearing		NA	289.80	X
				3,272.30	
		Less 20% :		-654.46	
				-----	2,617.84
2 pcs	tailgate "7" & "2" sticker	@ S\$ 10.00	NA	20.00	sn X
1 pc	tailgate company advertisement sticker		NA	250.00	sn X
1 pc	n/s rear bumper "L" plate		his	120.00	sn ✓
1 pc	n/s rear bumper "L" plate bracket		PD	80.00	sn ✓
1 pc	n/s rear fender top glass sealant		NA	40.00	sn 30sn
1 pc	n/s rear fender top glass damping seal		NA	20.00	sn ✓

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : FBM 6111 G
Our Ref : 180190

Page : 2
No. : 29622

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.	900.00	<i>600</i>
To focus taillamps. To check rear wiring and lighting operation.	50.00	<i>20</i>
To apply undersealing.	120.00	<i>30</i>
To dismantle and check rear under- carriage. To replace affected portions.	<i>nn</i> 150.00	<i>X</i>
To conduct rear wheel alignment test.	100.00	<i>60</i>
To putty and respray on affected portions.	1,000.00	<i>800</i>
	<hr/>	
	Total :	S\$ 5,467.84
		<hr/>

Singapore Dollars Five Thousand Four Hundred
and Sixty Seven and Cents Eighty Four Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18004865/Kqd3n2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 18-05-2018	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh. FBM 6111G	Veh. Inspected	SLL 3482S
	Policy No.	Coverage (\$)	0.00
	Claim No. CMTD1801133	Excess (\$)	0.00
	Assign From IRENE HENRY	Assign Date	14/03/2018
2. Vehicle Particulars & Condition			
	Make & Model HONDA JAZZ (M)	c.c	1498
	Engine No. HIDDEN	Year of Reg.	2017
	Chassis No. JHMGK5750HX202393	Colour	METALLIC GREY
	Odometer 23812	Steering	IN ORDER
	Brakes IN ORDER	Modification	STANDARD ALLOY RIM
	General GOOD		
3. Conditions of Tyres			
		Size	Make
	R/H Front Tyre	185/55 R16	DUNLOP
	L/H Front Tyre	185/55 R16	DUNLOP
	R/H Rear Tyre	185/55 R16	DUNLOP
	L/H Rear Tyre	185/55 R16	DUNLOP
			Balance
			8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
	Accident Date 13/03/2018	Inspection Date	14/03/2018
	Survey held at 160 SIN MING DRIVE #02-20		
	Repairer K KIM HIN AUTOMOTIVE PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 3482S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE "JAZZ" EMBLEM	NOT NECESSARY	32.90	-
1	REAR BUMPER	BUCKLED	492.60	492.60
1	N/S REAR BUMPER SIDE RETAINER	CRACKED	28.00	28.00
10	REAR BUMPER CLIPS @\$3.80	NECESSARY	38.00	38.00
1	N/S REAR BUMPER SIDE GARNISH	SERVICEABLE	38.00	-
1	N/S REAR BUMPER INNER SHIELD	SERVICEABLE	165.00	-
1	N/S TAILLAMP ASSY	CRACKED	228.00	228.00
1	N/S TAILLAMP PANEL	TO REPAIR SEE LABOUR	332.70	-
1	N/S TAILLAMP CLIPS	NECESSARY	3.80	3.80
1	N/S REAR FENDER	BENT	610.90	610.90
1	N/S REAR FENDER TOP GLASS MOULDING	NECESSARY	28.00	28.00
1	N/S REAR FENDER INNER SHIELD	SERVICEABLE	165.00	-
1	N/S REAR RIM	DENTED	819.60	819.60
1	N/S REAR WHEEL BEARING	NOT NECESSARY	289.80	-
	LESS 20% DISCOUNT		-654.46	-449.78
			2,617.84	1,799.12
<u>SPECIAL NETT ITEMS</u>				
2	TAILGATE "7" & "2" STICKER @\$10.00 (SN)	NOT NECESSARY	20.00	-
1	TAILGATE COMPANY ADVERTISEMENT STICKER (SN)	NOT NECESSARY	250.00	-
1	N/S REAR BUMPER "L" PLATE (SN)	MISSING	120.00	120.00
1	N/S REAR BUMPER "L" PLATE BRACKET (SN)	DENTED	80.00	80.00
1	N/S REAR FENDER TOP GLASS SEALANT (SN)	NECESSARY	40.00	30.00
1	N/S REAR FENDER TOP GLASS DAMPING SEAL (SN)	NECESSARY	20.00	20.00
			530.00	250.00
<u>LABOUR</u>				
	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF N/S TAILLAMP PANEL.		900.00	600.00
	TO FOCUS TAILLAMPS. TO CHECK REAR WIRING AND LIGHTING OPERATION.		50.00	20.00

Report Ref No. CS/SMO18004865/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY UNDERSEALING.	NOT NECESSARY	120.00	30.00
	TO DISMANTLE AND CHECK REAR UNDER-CARRIAGE. TO REPLACE AFFECTED PORTIONS.		150.00	-
	TO CONDUCT REAR WHEEL ALIGNMENT TEST.		100.00	60.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		1,000.00	600.00
			2,320.00	1,310.00
	GRAND TOTAL		5,467.84	3,359.12
RECOMMENDED COST OF REPAIRS				3,359.12

Report Ref No. CS/SMO18004865/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.