

ASS. REC. BY:

REF: CS/FCI18004872/Kqd3/n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Irene Lee of FCI

Date/Time: 13/3/18 @ 6:31pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBD 7223H

Insured: SHD 6729B

at Workshop m/s R. Kim Hin Auto

Tel: 64527018

of 160 Sin Ming Drive #02-20

Policy No: Claim No: D18002069 MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 12/3/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

17-04-2018

H.O.D. Endorsement:

Date/Time: 10:04am @ 14/3/18 Person Contacted: Shumein

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBD 7223H-X
	SHD 6729B - CC4/AXA 15011301/H140342
10/4/18 @ 4:32pm	vised to Elvan Lee by email.
	Kenneth finalised final by 8/1090, 3 days.
	(Red 8/1900, 642.)

REF: F11

ASSIGNMENT

From: Date: 17042018

Estimated Cost:

OD / ☒ PWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: QBD 7223H

at Workshop m/s K Kim Hin

of 160 Sin Ming Drive #02-20

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 853/c

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: QBD 7223H Yr Regn: 04 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Trace C.C. 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 114879 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KD11 20 10149036

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: ☒ S/Rim / STD A/Rim or

Tyre Size: F: 195 R15x8

R:

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 2 mm

Rear

R/Bal. 2 mm

L/Bal. 2 mm

L/Bal. 2 mm

D.O.A. 12/13/18

D.O.I. 17/18/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/4 File pass to Catherine

arrange survey on 16-04-2018 but nivitha miss out, we arrange survey on 17-04-2018

RECEIVED 18 JUN 2018

Date/Time, File Pass to?

18/6 11/18/18

Date/Time, File Return to?

2)

Report Format: 7P

Lump Sum / I.B.I. (\$) 1090

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

110

50

50

12

222

MOTOR SURVEY ASSIGNMENT

Date	13-03-2018	Our Ref No. D18002009MFSH
Accident Date	12-03-2018	Claim Type. Third Party
Insured Vehicle	SHD6729B	Third Party Vehicle. GBD7223H
Survey Location	160 Sin Ming Drive #02-20SIN MING AUTOCITY	
Contact Person.	SHUMAN	
Contact No.	64527018/ 0	Fax No. 64583895
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED / NO EST. PROVIDED	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	K. KIM HIN AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235880)



PRI Documents



Close



PRI Header Details

Claim No	D18002069MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & K. KIM HI AUTO PTE LTC
Workshop Name	K. KIM HIN AUTO PTE LTD (Contact Person : SHUMAN)	Survey Location & Contact Details	160 Sin Ming Drive #02-20SIN MING AUTOCITY Mobile: 0 , Phone: 64527018 , Fax: 64583895 EmailId: ADMIN1@KKIMHIN.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED / NO		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD6729B	TP Vehicle No	GBD7223H
PRI Recieved Date	13-03-2018 05:43:10 PM	Surveyor Appointed Date	13-03-2018 06:30:28 PM	Surveyor Accept Date	14-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	14-03-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 19 April 2018 4:37 PM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR;
EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: RE: SURVEY ASSESSMENT - D18002363MFSH/1
Attachments: CSFCI18004872Kqd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of GBD 7223H.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 14 March 2018 10:11 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002069MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 13 March 2018 6:30 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002069MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002363MFSH

Date: 19 April 2018

Our Ref: CS/FCI18004872/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBD 7223H.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 17/04/2018 at the premises of M/s K KIM HIN AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,990.00</u> .
Revised Estimate Amount	: S\$ <u>1,090.00</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the n/s rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2120M
Vehicle Details	
Vehicle No.:	GBD7223H
Vehicle to be Exported:	No
Intended De-registration Date:	13 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE 3.0 DX DIESEL TURBO M/T 2WD 5DR
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	1KD2440307
Chassis No.:	KDH2010149036
Maximum Power Output:	-
Open Market Value:	\$30,752.00
Original Registration Date:	02 Apr 2015
First Registration Date:	02 Apr 2015
Transfer Count:	1
Actual ARF Paid:	\$1,538.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	01 Apr 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$39,920.00
COE Rebate Amount:	\$28,148.00
Total Rebate Amount:	\$28,148.00

The information contained herein is correct as at 13 Mar 2018

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 29635

Vehicle Insured : SHA 7158 H
Accident Date : 12-Mar-2018

Date : 16-Mar-2018

Our Ref : 180188 (FIRST) / SHUMAN

PAGE : 1

PAS AUTO PTE LTD
Singapore

Not Authorised
Resurvey After Paint 1.B.1 3days

ESTIMATED COST OF REPAIR FOR TOYOTA HIACE 3.0 DX DIESEL (2015) GBD7223H

1 pc rear bumper	<i>nd/wt</i> 400.00 ✓
1 pc n/s rear bumper side retainer	<i>nn</i> 30.00 ✓
10 pcs rear bumper clips	@ S\$ 5.00 <i>nn</i> 50.00 ✓
1 pc n/s rear body panel	<i>n</i> 1,400.00 X
	1,880.00
	Less 25% : -470.00
	1,410.00
1 pc n/s rear body panel top glass sealant	<i>nn</i> 40.00 sn X
1 pc n/s rear body panel top glass damping seal	<i>nn</i> 20.00 sn X
To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.	700.00 <i>480</i>
To remove and refix n/s rear body panel top glass and conduct water leak test.	<i>nn</i> 120.00 X
To putty and respray on affected portions.	700.00 <i>250</i>
	Total : S\$ 2,990.00

Singapore Dollars Two Thousand Nine Hundred and Ninety Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722,
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 29635

Vehicle Insured : SHA 7158 H
Accident Date : 12-Mar-2018

Date : 16-Mar-2018

Our Ref : 180188 (FIRST) / SHUMAN

PAGE : 1

PAS AUTO PTE LTD
Singapore

Not Authorised
1.B.1
Respray After Paint 3days

ESTIMATED COST OF REPAIR FOR TOYOTA HIACE 3.0 DX DIESEL (2015) GBD7223H
=====

1 pc rear bumper
1 pc n/s rear bumper side retainer
10 pcs rear bumper clips
1 pc n/s rear body panel

Puller 400.00 ✓
na 30.00 ✓
@ S\$ 5.00 *na* 50.00 ✓
R 1,400.00 X

1,880.00
Less 25% : -470.00

1,410.00

1 pc n/s rear body panel top glass
sealant
1 pc n/s rear body panel top glass
damping seal

480.00
-25%

na 40.00 sn X
na 20.00 sn X

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

360.00
+730.00

700.00 *4 days*

To remove and refix n/s rear body
panel top glass and conduct water
leak test.

\$1090.00 ✓ ok

na 120.00 X

To putty and respray on affected
portions.

700.00 *2.5 days*

Total : S\$ 2,990.00
=====

Singapore Dollars Two Thousand Nine Hundred and
Ninety Only

3 days

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18004872/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-06-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 7158H	Veh. Inspected	GBD 7223H
	Policy No.	D-18088936MFSH	Coverage (\$)	0.00
	Claim No.	D18002363MFSH	Excess (\$)	0.00
	Assign From	SERENE	Assign Date	13/03/2018
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	KDH2010149036	Colour	SILVER
	Odometer	114879	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15X8	BRIDGESTONE	8 mm
	L/H Front Tyre	195 R15X8	BRIDGESTONE	8 mm
	R/H Rear Tyre	195 R15X8	BRIDGESTONE	8 mm
	L/H Rear Tyre	195 R15X8	BRIDGESTONE	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	12/03/2018	Inspection Date	17/04/2018
	Survey held at	K KIM HIN AUTOMOTIVE PTE LTD BLK 34 SIN MING DRIVE, #01-114, SINGAPORE 575708		
5a. Remarks				
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 7223H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED / CUT	400.00	400.00
1	N/S REAR BUMPER SIDE RETAINER	NECESSARY	30.00	30.00
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	N/S REAR BODY PANEL	TO REPAIR SEE LABOUR	1,400.00	-
	LESS 25% DISCOUNT		-470.00	-120.00
			1,410.00	360.00
SPECIAL NETT ITEMS				
1	N/S REAR BODY PANEL TOP GLASS SEALANT (SN)	NOT NECESSARY	40.00	-
1	N/S REAR BODY PANEL TOP GLASS DAMPING SEAL (SN)	NOT NECESSARY	20.00	-
			60.00	-
LABOUR				
	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF N/S REAR BODY PANEL.		700.00	480.00
	TO REMOVE AND REFIX N/S REAR BODY PANEL TOP GLASS AND CONDUCT WATER LEAK TEST.	NOT NECESSARY	120.00	-
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		700.00	250.00
			1,520.00	730.00
GRAND TOTAL			2,990.00	1,090.00
RECOMMENDED COST OF REPAIRS				1,090.00

Report Ref No. CS/FC118004872/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.