

Spark Car Care

Page 1

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62815767

Spare Parts

Vehicle No : SDQ2219L

Case Owner : BRENDA NG

Make & Model : BMW 520I

Year Manufacture : 2013

Chassis No : WBA5A320X0D789300

Engine No : B2010700N20B20B

Sales Order : _____

Supplier : _____

Order By : _____

Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
1	FRONT BUMPER	1	✓ def	\$1,277.55		
2	FRONT BUMPER RETAINER - RH	1	✓ dis	\$12.45		
3	HEADLAMP ASSY - RH	1	✓ ex	\$2,631.00		
4	HEADLAMP PANEL - RH	1	✓ ex	\$128.00		
5	FRONT FENDER - RH	1	✓ d	\$863.00		
6	FRONT FENDER UNDERSHIELD- RH	1	✓ ex	\$127.00		
7	FRONT FENDER UNDERSHIELD CLIPS	10	✓	\$25.00		
8	FRONT FENDER CHROME PROTECTOR -RH	1	out	\$78.00		
9	FRONT DOOR - RH	1	✓ ex	\$1,731.00		
10	FRONT DOOR CHROME HANDLE - RH	1	✓ ex	\$574.00		
11	REAR DOOR - RH	1	✓ ex	\$1,731.00		
12	FRONT RIM - RH (225/55/R17)	1	✓ ex	\$1,600.00	\$250 S/N	
13	FRONT TYRE - RH (PIRELLI CINTIRATO 225/55/R17)	1		✓ ex		\$380.00
14	0	1				
15	0	1				
16	0	1				
17	0	4				
18	0	0				
19	0	1				
20	0	0				
21	0	1				
22	0	1				
23	0	1				
24	0	1				
25	0	1				
26	0	1				
27	0	1				
28	0	0				
29	0	0				
30		0				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

10:12 AM

ComfortDelGro Engineering Pte Ltd

Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No. : **SDQ2219L**

: **BRENDA NG**

: 2013

[illegible]

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Supplementary 1

Vehicle No : SDQ2219L Case Owner : BRENDA NG
Make & Model : BMW 520I Year Manufacture : 2013
Chassis No : WBA5A320X0D789300 Engine No : B2010700N20B20B
Sales Order : 0 Supplier : 0
Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Item	S/N	Disposition By Surveyor
1	Driver door lock mechanism	1		\$284.50			
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge