

ComfortDelGro Engineering

205 Braddell Road S(579701)

200 Braddell Moad Of		REPAIR ESTIMATES	
Our Ref:			
Type of Claim :	TP	Vehicle No.	SDQ2219L
Type of olaim		Make & Model	BMW 520I
		Year of Manufacture	2013
		Chassis No.	WBA5A320X0D789300
Ins Company :A	XA VS AXA	Engine No.	B2010700N20B20B
Excess :		Policy No.	P1552481
Date of Accident :	9/3/2018	Time of Accident	1930
Suggested Days of Repair :		In-house Vehicle Assess	sor
Repair Estimates		Case Owner	BRENDA NG
		Signature	:- <u></u>
Parts (a) Cost / List Price Items	\$10,778.00	Contact No	
Plus/Less5%	\$538.90	onital Ho	63837466 - Patrick
Total of Cost / List	\$10,239.10		patricktia@sparkcarcare.co
(b) Nett Price Items	\$-	63837890 – Eric ericppg@sparkcarcare.com	63838115 – WILLIAM
Less		63837362 - EZEL	63837656 - Ngo
Total of Nett Item			ngotw@cdge.com.sg
(c) Special Nett Items	\$380.00	63837730 - Brenda Ng	
Total Parts Cost (Appendix A)	\$10,619.10		
Labour (Appendix B)	\$2,350.00		
Total Repair Cost	\$12,969.10		
The above total will be subjected to	to 7% G.S.T.		
	Maria Line		
Name of Surveyor	· ·		
Company			
Survey conducted on		at	
Remarks By Surveyor			
(a) The repair of this vehicle is	authorized / is not auth	orized until further notice.	
(b) Recommended Days of Re	pair :	day(s)	
(c) Resurvey	: Required / N	lot Required	

Date:

(d) Excess

(e) Signature of surveyor

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No	SDQ2219L	Case Owner : BRENDA NG	_
Make & Model	: BMW 520I	Year Manufacture : 2013	
Chassis No	WBA5A320X0D789300	Engine No : B2010700N20B20B	_
Sales Order	:	Supplier :	
Order By		Type of Claim : TP	

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
1	FRONT BUMPER	1	Vdet	\$1,277.55	Price	S/N
	FRONT BUMPER RETAINER – RH	1	dic	\$1,277.55		
	HEADLAMP ASSY – RH	1	avex	\$2,631.00		
	HEADLAMP PANEL – RH	1	Suc y	\$128.00		
	FRONT FENDER – RH	1	de	\$863.00		
	FRONT FENDER UNDERSHIELD- RH	1	Sur V	\$127.00		
	FRONT FENDER UNDERSHIELD CLIPS	10	hu	\$25.00		
	FRONT FENDER CHROME PROTECTOR -RH	1	aux -	\$78.00		
	FRONT DOOR – RH	1	A. V	\$1,731.00		
	FRONT DOOR CHROME HANDLE – RH	1	RY	\$574.00		
	REAR DOOR - RH	1	PX	\$1,731.00		
	FRONT RIM - RH (225/55/R17)	1	DX	\$1,600.00		
	FRONT TYRE – RH (PIRELLI CINTIRATO 225/55/R1	1	* 1	ave	N A	\$380.00
14		1		7,0	4. 1	ψοσο.σο
15		1				
16		1				
	0	4				
	0	0				
	0	1				
	0	0				
	0	1				
	0	1				
23	0	1				
24	0	1				
	0	1				
	0	1				
	0	1				
	0	0				
29	0	0				
30		0				

Spark Car Care ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax: 62815767

Labour

Vehicle No. :	SDQ2219L	Case Owner	:	BRENDA NG	
Make & Model:	BMW 520I	Year of Manufacture	:	2013	

S/No	Labour Description		Esimated Price	Adjusted Price	
1	TO KNOCK,STRAIGHTEN AND RENEW ACCIDENT AREA S	UCH AS	\$800.00	- Acop	
	FRONT BUMPER, HEADLAMP, FRONT RH FENDER, FRONT			,,-,	
	AND REAR RH DOOR.				
2	TO PUTTY AND RESPRAY FRONT BUMPER , FRONT RH F	ENDER,	\$900.00	800 -	
	FRONT RH DOOR AND REAR RH DOOR .				
3	TO TRANSFER PARTS TO NEW DOOR		\$150.00	x n/m	
4	TO CHECK LIGHTING AND WIRING		\$80.00	50/2	
5	TO DO WHEEL ALIGNMENT		\$120.00	80	
6	TO PERFORM PROGRAMMING		\$300.00	X	
	Not Sullary. PP Depen. Sufare Faint Abor.				
	1913/3018	LKK Auto Cons	ultants hence no	otify	
	14th Suto Chine,	the Repairer of	the following:		
	<u>Swidays</u>	 To display dama 	re/after spray painting ged part(s) during re	survey	
		Parts prices are Third party supplements	subject to confirmati v is on a "Without P	on rejudice" basis	
		 No illegal modific 	cation(s) is allowed		
		 Supplementary is subject to final 	tem(s) must be result approval from Insur	veyed <u>and</u> ance Company	
		Acknowledged by			
		Signature:	i region or		
		Date:			