



ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim :	TP	Vehicle No. :	SDQ2219L
Ins Company :	AXA VS AXA	Make & Model :	BMW 520i
Excess :		Year of Manufacture :	2013
Date of Accident :	9/3/2018	Chassis No. :	WBA5A320X0D789300
Suggested Days of Repair :		Engine No. :	B2010700N20B20B
		Policy No. :	P1552481
		Time of Accident :	1930
		In-house Vehicle Assessor	

**Repair Estimates**

Parts (a) Cost / List Price Items	\$10,778.00
Plus/Less 5%	\$538.90
Total of Cost / List	\$10,239.10
(b) Nett Price Items	\$-
Less	
Total of Nett Item	
(c) Special Nett Items	\$380.00
<b>Total Parts Cost (Appendix A)</b>	<b>\$10,619.10</b>
<b>Labour (Appendix B)</b>	<b>\$2,350.00</b>
<b>Total Repair Cost</b>	<b>\$12,969.10</b>

Case Owner :	BRENDA NG
Signature :	

Contact No	63837466 – Patrick <a href="mailto:patricktia@sparkcarcare.com">patricktia@sparkcarcare.com</a>
------------	--

63837890 – Eric <a href="mailto:ericppg@sparkcarcare.com">ericppg@sparkcarcare.com</a>
---

63838115 – WILLIAM

63837362 – EZEL

63837656 - Ngo  
[ngotw@cdge.com.sg](mailto:ngotw@cdge.com.sg)

63837730 – Brenda Ng

The above total will be subjected to 7% G.S.T.

Name of Surveyor :	
Company :	
Survey conducted on :	at

**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor : Date:

# Spark Car Care

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road S (579701)  
Tel: 63837168 / 63837466 Fax:62815767

## Spare Parts

Vehicle No	: <u>SDQ2219L</u>	Case Owner	: <u>BRENDA NG</u>
Make & Model	: <u>BMW 520I</u>	Year Manufacture	: <u>2013</u>
Chassis No	: <u>WBA5A320X0D789300</u>	Engine No	: <u>B2010700N20B20B</u>
Sales Order	: _____	Supplier	: _____
Order By	: _____	Type of Claim	: <u>TP</u>

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
1	FRONT BUMPER	1		\$1,277.55		
2	FRONT BUMPER RETAINER – RH	1		\$12.45		
3	HEADLAMP ASSY – RH	1		\$2,631.00		
4	HEADLAMP PANEL – RH	1		\$128.00		
5	FRONT FENDER – RH	1		\$863.00		
6	FRONT FENDER UNDERSHIELD- RH	1		\$127.00		
7	FRONT FENDER UNDERSHIELD CLIPS	10		\$25.00		
8	FRONT FENDER CHROME PROTECTOR -RH	1		\$78.00		
9	FRONT DOOR – RH	1		\$1,731.00		
10	FRONT DOOR CHROME HANDLE – RH	1		\$574.00		
11	REAR DOOR – RH	1		\$1,731.00		
12	FRONT RIM - RH (225/55/R17)	1		\$1,600.00		
13	FRONT TYRE – RH (PIRELLI CINTIRATO 225/55/R17)	1				\$380.00
14	0	1				
15	0	1				
16	0	1				
17	0	4				
18	0	0				
19	0	1				
20	0	0				
21	0	1				
22	0	1				
23	0	1				
24	0	1				
25	0	1				
26	0	1				
27	0	1				
28	0	0				
29	0	0				
30		0				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

13/03/2018

10:12 AM

**ComfortDelGro Engineering Pte Ltd**  
205 Braddell Road S (579701)  
Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No.	: <u><b>SDQ2219L</b></u>	Case Owner	: <u><b>BRENDA NG</b></u>
Make & Model	: <u><b>BMW 520i</b></u>	Year of Manufacture	: <u><b>2013</b></u>

[illegible]