

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5045C -**AAD1803-071***Not Withheld
11/12/8 1500*

Vehicle No.:

SHC5045C - JHOW

Chassis No.:

VF1ABL15AUC276053

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

07.03.2018

Third Party Insurer :

AIG**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Sn</i>	1,259.42	} X
2	1	BUMPER ABSORBER FRT	\$	<i>Sn</i>	394.68	
3	1	BUMPER BEAM FRT	\$	<i>R</i>	914.08	
4	1	BUMPER SPOILER FRT	\$	<i>Sn</i>	181.75	
5	1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i>	266.80	
6	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i>	207.22	
7	1	BUMPER RETAINER FRT RH	\$	<i>Sn</i>	151.41	
8	1	BUMPER SUPPORT FRT RH	\$	<i>Sn</i>	123.88	
9	1	BUMPER RETAINER FRT LH	\$	<i>Sn</i>	151.41	
10	1	BUMPER SUPPORT FRT LH	\$	<i>Sn</i>	123.88	
11	1	HEADLAMP RH	\$	<i>Sn</i>	1,184.43	
12	1	HEADLAMP PANEL FRT RH	\$	<i>R</i>	152.15	
13	1	FENDER PANEL FRT RH	\$	<i>R</i>	783.83	
14	1	FENDER INSULATOR RH	\$	<i>Sn</i>	130.84	
15	1	FENDER BRACKET FRT RH	\$	<i>R</i>	13.02	
16	1	FENDER WHEELARCH FRT RH	\$	<i>Sn</i>	278.84	
17	1	FENDER PANEL BRACKET FRT RH	\$	<i>R</i>	177.41	
18	1	RADAIOR GRILLE	\$	<i>Sn</i>	1,707.78	
19	1	RADAIOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i>	173.36	
20	1	RADAIOR GRILLE FRAME	\$	<i>Sn</i>	1,353.75	} X
21	1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i>	615.90	
22	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i>	89.79	
23	1	BONNET	\$	<i>R</i>	1,941.63	
24	1	BONNET INSULATOR	\$	<i>Sn</i>	405.73	
25	1	DOOR MIRROR RH	\$	<i>cm</i>	1,483.40	
26	1	DOOR MIRROR GLASS RH	\$	<i>Sn</i>	242.33	
27	1	DOOR MIRROR BACK COVER RH	\$	<i>Sn</i>	218.46	
28	1	DOOR MIRROR LAMP RH	\$	<i>Sn</i>	194.18	
29	1	DOOR PANEL FRT RH	\$	<i>R</i>	2,844.66	

TOTAL	\$	17,766.04
10%	\$	1,776.60
	\$	15,989.43

TRANS-CAB AUTO SERVICES PTE LTD

AAD1803-071

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5045C -**Specical Nett**

1	1SET	FRONT BUMPER CLIP	\$	na	66.00	} X
2	1SET	WHEELARCH CLIP RH	\$	na	66.00	
3	1	TOW COVER FRT	\$	su	14.50	
4	1	CAP HUB RH FRT	\$	su	35.00	
5	1	RIM RH FRT	\$	su	385.00	
6	1	TYRE RH FRT	\$	su	330.00	
7	1	DOOR SEAL CLIP FRT RH	\$	na	4.68	} X
8	1	DOOR STICKER "Trans-cab"	\$	na	80.00	
9	1	DOOR STICKER "Classic"	\$	na	30.00	} X
10	1SET	BUMPER SUPPORT FRT CLIP RH	\$	na	9.80	
11	1SET	BUMEPR RETAINER FRT CLIP RH	\$	na	12.50	} X

TOTAL	\$	1,033.48
TOTAL PARTS	\$	17,022.91

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,800.00 2001

To Check Electrical Lighting Concerned.

\$ 170.00 201

Putty and spray painting of the affected portion.

\$ 3,000.00 2601

To rust-proofing of the affected areas.

\$ na 170.00 X

To check steering geometry and computer wheel alignment

\$ na 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ na 170.00 X

Towing fees

\$ na 120.00 X

To transfer of door fittings, attachment and perform water seepage test.

\$ na 170.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ na 380.00 X

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.

\$ na 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1803-071**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5045C -

To Remove And Refit Front W/Screen Glass To
Facilitate Bodywork Repair.

\$ *na* 170.00 X

TOTAL	\$	7,540.00
Over All Total	\$	24,562.91

(PARTS BY PARTS) Repair Days*10 Days**2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Win/Lose" basis
- No illegal modifications, is allowed
- Supplementary items must be approved by LKK
is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: