

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Authorised

ESTIMATE

1.9.1

Reserve 84 parts

4 days

Ex B66d

For ref

25

Allied World Assurance Company, Ltd

60 Anson Road

#08-01 Mapletree Anson

Singapore 079914

Attn: Motor Claims Department

Date :

13/03/2018

Vehicle No :

GP5588X

Veh Make/Model :

Toyota Dyna 1.5 M

YOM :

2014

Chassis No :

JTFAT35Y10K204099

Date of Accident :

13/03/2018

Fax: 62564315

No	Qty	Description	Amount \$
Cost Items:-			
1	1	Front bumper	\$ 150.00
2	1	Front bumper reinforcement	\$ 100.00
3	1	LH headlamp	\$ 220.00
4	1	Front grille	\$ 150.00
5	4	Front grille clip	\$ 7.20
6	1	Front grille logo	\$ 35.00
7	1	Front LH door assy	\$ 560.00
8	1	Air-con condenser and fan assy (complete)	\$ 420.00
Total - Cost Item			\$ 1,642.20
Add 10%			\$ 164.22
Total			\$ 1,806.42
Special Nett Items:-			
1	1	Front number plate	\$ 30.00
2	1	Front LH door ROC sticker	\$ 30.00
Total - SN Item			\$ 60.00
Labour Charges:-			
1		Spray painting on all affected area.	\$ 600.00
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 500.00
3		To apply anti rust treatment.	\$ 80.00
4		To check wiring system & light.	\$ 60.00
5		To remove and replace air-con condenser, fan assy & etc. and top up gas.	\$ 300.00
Total - L/C			\$ 1,540.00
Sub-Total			\$ 3,406.42
7% GST			\$ 238.45
Total			\$ 3,644.87