

22/03/2002

ASS. REC. BY:

REF: CS/ALG18004883/A1d3⁰²

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Abu Kessim of ALG Date/Time: 14/3/18 @ 9:59am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKF9950L Insured: SLL8154Gat Workshop m/s Autobay Tel: 93716693of J kaki Bkt Ave 6 #02-11 AutobayPolicy No: _____ Claim No: 9277976430SG003

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 9/3/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement: _____

Date/Time: 12:31pm @ 14/3/18 Person Contacted: Victor Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SKF9950L-x</u>
	<u>SLL8154G-x</u>
	<u>Lump Sum \$4300 (Red: 7362.99; 63%)</u>

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKF9950L Yr Regn: 2009, Jan.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Suzuki Grand Vitara 2383Colour: Black A/C: Insured / Std / NI / NASp. Reading: 158004 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JSATJDA4V00113642Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/60R18R: 225/60R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 21/03/18Survey held at AutobayDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ALG.MV: 211CPV: 13.9KNet: 7.1K

RECEIVED 14 MAY 2018

Date/Time, File Pass to?

☐ : Preli. Report1) 15 Typist☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 6Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 250Transportation: 20

S + RS: \$ _____

Photos

Others

TOTAL

270Report Format: TPLump Sum / I.B.I: (\$ 4300/-)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG18004883/Atd3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 14-03-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLL 8154G	Veh. Inspected	SKF 9950L
Policy No.		Coverage (\$)	0.00
Claim No.	9277976430SG003	Excess (\$)	0.00
Assign From	ABU KASSIM MARIA	Assign Date	14/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	09/03/2018	Inspection Date	
Survey held at	AUTOBAY PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-11 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Nivitha (LKK Auto)

From: Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>
Sent: Wednesday, 14 March 2018 9:59 AM
To: 'assignments@lkkauto.com'; 'admin-a@lkkauto.com'
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene; Chin, Lee-Ying
Subject: AIGENCRYPT - Pre repair inspection request - SKF9950L VS SLL8154G (OI) DOA 09/03/2018
Attachments: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLL81... (53.5 KB); SLL8154G.TIF

Hi,

Please refer to the enclosed request from **Catherine Lim LLC**

Claim no : 9277976430SG003
Case Owner : Justin Wong

If you have any queries/concerns, please let us know.
Kindly assist to assign Adrian Ling as Single Joint Expert as requested.

Thank you.

Best Regards,

Mariesa Abu Kassim (Mariesa)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services
AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012202 | Fax +6 03 2685 5898

NoorMariesa.AbuKassim@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

CHEAPEST CAR INSURANCE RENEWAL



Choice of
\$0 excess

Option of any
workshop

GET A CHEAPER QUOTE NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Year Coe Renewal Honda Stream 1.8A RSZ



\$2800 Downpayment Monthly
From \$738 Onwards, Lowest
3.68% P.A. @ GV Cars Financing
GV Credit Pte Ltd StarAd

PRIME MOTOR & LEASING
(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)
With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.





Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

4 vehicles

Grand Vitara 2.4A

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Grand Vitara 2.4A	Any	Any	2009	Any	Any	Any	Available
	Suzuki Grand Vitara 2.4A	\$23,800	\$12,390 /yr	15-Jan-2009	2,393 cc	-	SUV	Available
Monthly At \$500 Plus Only! Almost New Tyres! Multi-mode 4WD System! Come With Sunroofs, Well Maintained SUV, Designed To Give You Excellent Off-road Capabilities And Its A Great Choice As Family Car T...								
Dickson Automobile								
Posted: 17-Mar-2018 Tags: 2009 Suzuki Grand, Suzuki Grand, Suzuki, Grand, Used Suzuki								
	Suzuki Grand Vitara 2.4A	\$21,800	\$9,720 /yr	22-Jan-2009	2,393 cc	129,426 km	SUV	Available
New 6 Months Road Tax! Very High PARF With Lowest Depreciation In The Market! Loan Can Be Arranged! Call/Sms To Arrange For Viewing!								
Posted: 09-Feb-2018 Tags: 2009 Suzuki Grand, Suzuki Grand, Suzuki, Grand, Used Suzuki								
	Suzuki Grand Vitara 2.4A	\$24,688	\$11,220 /yr	16-Mar-2009	2,393 cc	110,000 km	SUV	Available
Superb Condition At This Age, Tastefully Done Up 4X4 For Short Term Or COE Renewal When Time Comes, You Will Never Get Another 4X4 At This Depreciation, Wonder Why This Model Is The Most Popular 4X4 S...								
Posted: 27-Feb-2018 Tags: 2009 Suzuki Grand, Suzuki Grand, Suzuki, Grand, Used Suzuki								
	Suzuki Grand Vitara 2.4A	\$25,800	\$10,300 /yr	18-Jun-2009	2,393 cc	110,356 km	SUV	Available
CNY Special Buy. Rare 4X4 Vitara With Agent Service Excellent Condition. High PARF Value. Contact/SMS Our Professional Friendly Sales Executives Directly For Viewing And Testing Immediately!								
Posted: 09-Mar-2018 Tags: 2009 Suzuki Grand, Suzuki Grand, Suzuki, Grand, Used Suzuki								

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Grand Vitara 2.4A, Grand Vitara 2.4A Singapore, used Grand Vitara 2.4A Singapore, used Grand Vitara 2.4A, used vehicles Singapore or even buy used Grand Vitara 2.4A Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool &

- About Us
- Careers
- Contact Us
- Sitemap

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3911N
Vehicle Details	
Vehicle No.:	SKF9950L
Vehicle to be Exported:	Yes
Intended De-registration Date:	21 Mar 2018
Vehicle Make:	SUZUKI
Vehicle Model:	GRAND VITARA 2.4 5DOOR 4WD AT ABS AIRBAG
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	J24B1026691
Chassis No.:	JSAJTDA4V00113642
Maximum Power Output:	122.0 kW (163 bhp)
Open Market Value:	\$27,300.00
Original Registration Date:	15 Jan 2009
First Registration Date:	15 Jan 2009
Transfer Count:	4
Actual ARF Paid:	\$27,300.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jan 2019
PARF Rebate Amount:	\$13,650.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jan 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$3,089.00
COE Rebate Amount:	\$251.00
Total Rebate Amount:	\$13,901.00

The information contained herein is correct as at 21 Mar 2018

OK

TPAIG Denise

Regn No : SKF9950L

Vehicle Make & Model : Suzuki Grand Vitara

ITEM NO	DESCRIPTION OF ITEMS	QUANTITY (Piece/Set)	UNIT PRICE (S\$)	AMOUNT (S\$)
List Items:				
1	Spare Wheel Cover - Inner <i>excluded</i>	1	\$ 321.85	\$ 321.85 ✓
2	Spare Wheel Cover - Outer <i>excluded</i>	1	\$ 581.75	\$ 581.75 ✓
3	Spare Wheel Bracket	1	\$ 106.15	\$ 106.15 +
4	Rear Tailgate <i>Painted new</i>	1	\$ 812.65	\$ 812.65 ✓
5	Rear Tailgate Emblem - "SUZUKI" <i>2</i>	1	\$ 28.85	\$ 28.85 ✓
6	Rear Tailgate Emblem - "GRAND" <i>1</i>	1	\$ 26.80	\$ 26.80 ✓
7	Rear Tailgate Emblem - "VITARA" <i>1</i>	1	\$ 30.25	\$ 30.25 ✓
8	Tailgate Outer Handle <i>new</i>	1	\$ 89.95	\$ 89.95 +
9	Tailgate Inner Lock <i>new</i>	1	\$ 160.95	\$ 160.95 +
10	Tailgate Inner Board <i>new</i>	1	\$ 199.85	\$ 199.85 +
11	Tailgate Lock Striker <i>new</i>	1	\$ 41.50	\$ 41.50 +
12	Tailgate Damper <i>3 not</i>	1	\$ 131.50	\$ 131.50 ✓
13	Tailgate Hinges <i>1</i>	2	\$ 81.50	\$ 163.00 +
14	Tailgate Weatherstrip <i>new</i>	1	\$ 110.45	\$ 110.45 +
15	Taillamps <i>Left cut</i>	2	\$ 241.65	\$ 483.30 <i>241.65</i>
16	Taillamp Filter Panels <i>Repair</i>	2	\$ 203.50	\$ 407.00 +
17	Rear Bumper <i>excluded</i>	1	\$ 681.60	\$ 681.60 ✓
18	Rear Bumper Reflectors <i>new</i>	2	\$ 28.05	\$ 56.10 +
19	Rear Bumper Clips	6	\$ 4.50	\$ 27.00 ✓
20	Rear Bumper Side Retainers <i>3</i>	2	\$ 28.85	\$ 57.70 ✓
21	Rear End Panel <i>Painted</i>	1	\$ 361.50	\$ 361.50 ✓
22	Rear End Panel Inner Member <i>Repair</i>	1	\$ 265.45	\$ 265.45 +
23	Rear End Panel Inner Trim <i>Painted</i>	1	\$ 68.85	\$ 68.85 ✓
24	Rear Exhaust Silencer <i>new</i>	1	\$ 512.60	\$ 512.60 +
25	Rear Exhaust Insulator <i>3</i>	1	\$ 82.65	\$ 82.65 +
26	Rear Exhaust Mountings <i>3</i>	2	\$ 18.50	\$ 37.00 ✓
27	Rear Floor Board <i>3</i>	1	\$ 245.50	\$ 245.50 +
28	Rear Floor Panel <i>3</i>	1	\$ 541.50	\$ 541.50 +
29	Rear Fender <i>Painted</i>	1	\$ 481.95	\$ 481.95 +
30	Rear Fender Inner Boards <i>Left excluded</i>	2	\$ 411.65	\$ 823.30 <i>823.30</i>
31	Rear Fender Inner Shields <i>new</i>	2	\$ 48.15	\$ 96.30 +
32	Rear Licence Lamps <i>3</i>	2	\$ 19.05	\$ 38.10 +
33	Rear Licence Lamp Bracket <i>3</i>	1	\$ 18.85	\$ 18.85 +
			Sub-total	\$ 8,091.75
Less			15%	\$ 1,213.76
List Items			Total	\$ 6,877.99

3498.45

2973.68

Special Nett Items:

1	Rear Windscreen Sealant <i>me</i>	1	\$	80.00	\$	80.00 730
2	Rear Windscreen Foam Tape <i>me</i>	1	\$	65.00	\$	65.00 730
3	Rear Number Plate with Holder <i>new</i>	1	\$	120.00	\$	120.00 *
4	Reverse Camera <i>2nd</i>	1	\$	450.00	\$	450.00 380
5	Reverse Sensor <i>2nd</i>	1	\$	280.00	\$	280.00 200
		S/Nett Items	Total		\$	995.00

640

Labour Charge Items:

1	Towing charges		\$	180.00	x.	
2	To remove, refix rear windscreen		\$	180.00	2120	
3	To check rear electrical wiring systems		\$	80.00	30	
4	To remove, refix interior upholstery to facilitate repair works	1770	\$	120.00	40	
5	To remove, refix reverse sensor and camera		\$	200.00	80	
6	To remove and refix rear exhaust silencer		\$	80.00	460	
7	To repray undercoating		\$	150.00	240	
8	To respray painting & etc		\$	1,200.00	600.	
9	Panel beating, cut, weld, remove and replacing above parts		\$	1,600.00	800.	
			Labour Charge	Total	\$	3,790.00

Estimate Parts & Labour**Grand total \$ 11,662.99**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
w/s 21/03/18
04-06/18

total: 5383.68
w/s: 4.3K
06 Days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18004883/ATD3N2

Date: 17/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994827
 Claimant Vehicle No: SKF9950L Insured Vehicle No: SLL8154G
 Date of Loss: 09/03/2018 Nature of Claim: TP Claim No: 9277976430SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKF9950L
 Make & Model: SUZUKI GRAND VITARA, 2.4 (A) Engine No: J24B1026691
 Reg. Date: 15/01/2009 (Man. Year: 2008) Chassis No: JSAJTDA4V00113642
 Colour: Black Odometer: 154004 km
 Engine Capacity: 2393 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60R18 Rear Tyre Size: 225/60R18
 Front Left Side: Maxxis 6 mm Rear Left Side: Maxxis 6 mm
 Front Right Side: Maxxis 6 mm Rear Right Side: Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,872.99	3,613.68	4,259.31	54.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,790.00	1,770.00	2,020.00	53.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,662.99	5,383.68	6,279.31	53.84
Approved Total (Overridden) (\$\$)		4,300.00		
Nett Amount (\$\$)	11,662.99	4,300.00	7,362.99	63.13

INSPECTION

Date of Assignment: 14/03/2018
 Date Inspected: 21/03/2018 Inspected At: Autobay Pte Ltd (kaki Bukit) (HQ)
 1 KAKI BUKIT AVE 6, #02-11
 Singapore 417883
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SPARE WHEEL COVER-INNER	Cracked	321.85 FL	*321.85 FL
2	1		*SPARE WHEEL COVER-OUTER	Deformed	581.75 FL	*581.75 FL
3	1		*SPARE WHEEL BRACKET	Not Necessary	106.15 FL	*- FL
4	1		*REAR TAILGATE	Dented	812.65 FL	*812.65 FL
5	1		*REAR TAILGATE EMBLEM-SUZUKI	Necessary	28.85 FL	*28.85 FL
6	1		*REAR TAILGATE EMBLEM-GRAND	Necessary	26.80 FL	*26.80 FL
7	1		*REAR TAILGATE EMBLEM-VITARA	Necessary	30.25 FL	*30.25 FL
8	1		*TAILGATE OUTER HANDLE	Not Necessary	89.95 FL	*- FL
9	1		*TAILGATE INNER LOCK	Not Necessary	160.95 FL	*- FL
10	1		*TAILGATE INNER BOARD	Not Necessary	199.85 FL	*- FL
11	1		*TAILGATE LOCK STRIKER	Not Necessary	41.50 FL	*- FL
12	1		*TAILGATE DAMPER	Not Necessary	131.50 FL	*- FL
13	2		*TAILGATE HINGES	Not Necessary	163.00 FL	*- FL
14	1		*TAILGATE WEATHERSTRIP	Not Necessary	110.45 FL	*- FL
15	1		*TAILLAMPS	N/s Cut	483.30 FL	*241.65 FL
16	2		*TAILLAMP FILTER PANELS	Repair	407.00 FL	*- FL
17	1		*REAR BUMPER	Deformed	681.60 FL	*681.60 FL
18	2		*REAR BUMPER REFLECTORS	Not Necessary	56.10 FL	*- FL
19	6		*REAR BUMPER CLIPS	Necessary	27.00 FL	*27.00 FL
20	2		*REAR BUMPER SIDE RETAINERS	Necessary	57.70 FL	*57.70 FL
21	1		*REAR END PANEL	Dented	361.50 FL	*361.50 FL
22	1		*REAR END PANEL INNER MEMBER	Repair	265.45 FL	*- FL
23	1		*REAR END PANEL INNER TRIM	Dented	68.85 FL	*68.85 FL
24	1		*REAR EXHAUST SILENCER	Not Necessary	512.60 FL	*- FL
25	1		*REAR EXHAUST INSULATOR	Not Necessary	82.65 FL	*- FL
26	2		*REAR EXHAUST MOUNTINGS	Not Necessary	37.00 FL	*- FL
27	1		*REAR FLOOR BOARD	Not Necessary	245.50 FL	*- FL
28	1		*REAR FLOOR PANEL	Not Necessary	541.50 FL	*- FL
29	1		*REAR FENDER	Not Necessary	481.95 FL	*- FL
30	1		*REAR FENDER INNER BOARDS	N/s Deformed	823.30 FL	*258.00 FL
31	2		*REAR FENDER INNER SHIELDS	Not Necessary	96.30 FL	*- FL
32	2		*REAR LICENCE LAMPS	Not Necessary	38.10 FL	*- FL
33	1		*REAR LICENCE LAMP BRACKET	Not Necessary	18.85 FL	*- FL
34	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS
35	1		*REAR WINDSCREEN FOAM TAPE	Necessary	65.00 FS	*30.00 FS
36	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	120.00 FS	*- FS
37	1		*REVERSE CAMERA	Damaged	450.00 FS	*380.00 FS
38	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,086.75	4,138.45
- List Item Discount on L Items 15.00/15.00% (\$\$)	1,213.76	524.77
Total Parts (\$\$)	7,872.99	3,613.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING CHARGES	New	180.00	-
2	TO REMOVE,REFIX REAR WINDSCREEN	New	180.00	120.00
3	TO CHECK REAR ELECTRICAL WIRING SYSTEMS	New	80.00	30.00
4	TO REMOVE,REFIX INTERIOR UPHOLSTERY TO FACILITATE REPAIR WORKS	New	120.00	40.00
5	TO REMOVE,REFIX REVERSE SENSOR AND CAMERA	New	200.00	80.00
6	TO REMOVE AND REFIX REAR EXHAUST SILENCER	New	80.00	60.00
7	TO REPRAY UNDERCOATING	New	150.00	40.00
8	TO RESPRAY PAINTING & ETC	New	1,200.00	600.00
9	PANEL BEATING,CUT,WELD,REMOAVE AND REPLACING ABOVE PARTS	New	1,600.00	800.00
Gross Labour Cost (\$\$)			3,790.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >