

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
Halcyon 2, S'pore 577200
Tel No. : 6451 3933 Fax No. : 6455 7576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL ST #04-05 IOB BUILDING
049711

Attention : Motor Claim Department
Contact : 6223 8122

Estimate : ES005797

Date : 13/03/2018
Vehicle Num. : SLK 8951C (LCR)
Make/Model : HONDA VEZEL
Chassis/Eng# :
Accident Date : 12/03/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	FRT BUMPER ✓ DT		495.00
3.	1	FRT BUMPER REINFORCEMENT ? ✓ DT		445.00
4.	1	FRT BUMPER RETAINER R/H ? ✓ CRK.		75.00
5.	1	HEADLAMP ASSY RH ✓ SCR.		1,850.00
6.	1	L/F FENDER ✓ BT		499.60
7.	1	L/F FENDER WHEEL ARCH MOULDING ✓ cut		152.80
7.	1	L/F FENDER INNER SHIELD X		144.60

List Total S\$:	3,662.00
20.00% Discount S\$:	732.40
	2,929.60

1.	SPECIAL NETT ITEMS :		
	FRT BUMPER CLIP ✓ NEC.	40.00	30.
	Special Nett Total S\$:	40.00	

LABOUR :		
LABOUR TO REPLACE FRT BUMPER, FENDER, HEADLAMP AND KNOCK OUT R/F FENDER INNER PANEL, HEADLAMP PANELS ETC.	480.00	400.
SPRAY PAINT TO FRT ACCIDENT AREAS INCLUDE FENDER INNER PANEL, R/F DOOR AND HEADLAMP SUPPORT PANEL ETC	600.00	400.
Labour Total S\$:	1,080.00	

E. & O.E.	Total S\$:	4,049.60
		=====

for WORLD AUTO PTE LTD

Sebastian.
14/3/18.
- Part by part repair.
- Question Mark Item
Photo
- Photo Before Painting

4 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: