

22/03/2002

ASS. REC. BY:

REF: CS/TCS 10004896 / Avb n2

Special Instruction:

Survivor

ASSIGNMENT (Office)

From (Person): Janice Goh of TCS Date/Time: 19/03/2018 9:02am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLG 6235X Insured: GBF 4279 Gat Workshop m/s Kai Motor Tel: _____of Blk 3007 Ubi Rd 1 #01-434Policy No: _____ Claim No: DMCV18000164

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 07/03/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: Kym Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLG 6235X - X</u>
	<u>GBF 4279 G - X</u>
<u>11/4/18</u>	<u>Adrian confirmed \$ 5328.49 (Real 1154.44, 18/3)</u> <u>7 11/4</u>

Surveyor

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLG6235x Yr Regn: 2016 oct

Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Harrier c.c 1986

Colour: Black A/C: Insured / Std / NI / NA

Sp.Reading: 44988 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2SU600070699

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55R18

R: 235/55R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 12/03/18

Survey held at 1ccr motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
TP ECICS.

RECEIVED 12 APR 2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
Date/Time, File Return to?

2) 12/4 - typist

Report Format : menmen

Lump Sum / I.B.I: (\$) 5328.49

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation: _____

Photos

Others

TOTAL

250

10

260



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS/ICS18004896/Avb

7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
SINGAPORE 038987

Date : 14-03-2018



Code : ICS

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 4279G	Veh. Inspected	SLG 6235X
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JANICE GOH	Assign Date	09/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/03/2018	Inspection Date	12/03/2018
Survey held at	KAI MOTOR TRADING BLK 3007 UBI ROAD 1 #01-434 SINGAPORE 408701		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Veron Chen (LKKAuto)

From: Janice Goh Siew Geok (ECICS, Claims) <Janice_Goh@ecics.com.sg>
Sent: Wednesday, 11 April 2018 11:10 AM
To: Veron Chen (LKKAuto)
Subject: RE: ACCIDENT INVOLVING VEHICLE NO SLG 6235 X & GBF 4279 G on 07/03/2018

Dear Veron

Our claim no DMCV1800016H.
Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, 11 April, 2018 10:35 AM
To: Janice Goh Siew Geok (ECICS, Claims)
Subject: FW: ACCIDENT INVOLVING VEHICLE NO SLG 6235 X & GBF 4279 G on 07/03/2018

Dear Janice,

Please provides us the claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kai Motor [mailto:kaimotor@gmail.com]
Sent: Wednesday, 14 March 2018 5:26 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Subject: Fwd: ACCIDENT INVOLVING VEHICLE NO SLG 6235 X & GBF 4279 G on 07/03/2018

----- Forwarded message -----

From: **motorsurvey** <motorsurvey@ecics.com.sg>

Date: 9 March 2018 at 09:02

Subject: RE: ACCIDENT INVOLVING VEHICLE NO SLG 6235 X & GBF 4279 G on 07/03/2018

To: kaimotor <kaimotor@gmail.com>, "assignments@lkkauto.com" <assignments@lkkauto.com>

Cc: motorsurvey <motorsurvey@ecics.com.sg>

Without Prejudice

Dear Kym

Thank you for your email.

We will appoint LKK for the survey.

Aside to LKK

Please assist to arrange for TP PRI.

Thank you.

Regards,

Janice Goh

Claims Division

DID: +65 6303 0182

FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

*****Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.*****

From: kaimotor [mailto:kaimotor@gmail.com]

Sent: Thursday, 8 March, 2018 6:04 PM

To: motorsurvey

Subject: Re: ACCIDENT INVOLVING VEHICLE NO SLG 6235 X & GBF 4279 G on 07/03/2018

Sent from my Samsung Galaxy smartphone.

----- Original message -----

From: kaimotor <kaimotor@gmail.com>

Date: 8/3/18 6:02 PM (GMT+08:00)

To: motorsurvey@ecics.com.sg

Subject: Re: ACCIDENT INVOLVING VEHICLE NO SLG 6235 X & GBF 4279 G on 07/03/2018

Sent from my Samsung Galaxy smartphone.

----- Original message -----

From: Kai Motor <kaimotor@gmail.com>

Date: 8/3/18 4:18 PM (GMT+08:00)

To: motorsurvey@ecics.com.sg

Subject: ACCIDENT INVOLVING VEHICLE NO SLG 6235 X & GBF 4279 G on 07/03/2018

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1
#01-440, SINGAPORE 408701
TEL: 67474006 FAX: 67437591
E-mail : kaimotor@gmail.com
REG NO: 44223100L

Date : 08/03/2018

Attn: The Motor Claims Department

ECICS Limited

Attn: Motor Claim Dep
7 Temasek Boulevard,
#10-01
Suntec Tower One
Singapore 038987

WITHOUT PREJUDICE

(By Email Only)

Phoebe Phone: 6337 4779
motorsurvey@ecics.com.sg

Dear Sir / Madam

ACCIDENT INVOLVING VEHICLE NO SLG 6235 X & GBF 4279 G on 07/03/2018

We are writing on behalf of Mr Tee Chee Siong the registered owner of SLG 6235 X which was involved on the above mentioned accident between GBF 4279 G.

Investigation reveals that the motor vehicle number GBF 4279 G was insured with you at the material time of the said accident.

As a result of the accident was caused solely and completely by the negligence of your insured vehicle number GBF 4279 G. Therefore, our client is holding you liable for the repair costs and other consequential loss which was sustained by him/her/them.

Kindly arrange your representative to survey our client's vehicle at **KAI MOTOR TRADING** Blk 3007, Ubi Road 1, #01-440, Singapore 408701 within two (2) days from the date hereof as to avoid further losses incur.

We enclosed hereby the GIA report of SLG 6235 X for your kind attention.

Failing which, our client have no alternative but to proceed with the necessary repairs and the bill will be forward to you for reimbursement.

Yours faithfully,

--

Thank you.

Ms Kym

Kai Motor Trading

Blk 3007 Ubi Rd 1 #01-440

Singapore 408701

Telephone: 6747 4006

follow us on  facebook  follow us on twitter  visit our website ecics.com.sg 

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

--

Thank you.

Ms Kym

Kai Motor Trading

Blk 3007 Ubi Rd 1 #01-440

Singapore 408701

Telephone: 6747 4006

Catherine Chong (LKK Auto)

From: Kai Motor <kaimotor@gmail.com>
Sent: Wednesday, 14 March, 2018 5:26 PM
To: Catherine Chong (LKK Auto)
Subject: Fwd: ACCIDENT INVOLVING VEHICLE NO SLG 6235 X & GBF 4279 G on 07/03/2018

----- Forwarded message -----

From: **motorsurvey** <motorsurvey@ecics.com.sg>
Date: 9 March 2018 at 09:02
Subject: RE: ACCIDENT INVOLVING VEHICLE NO SLG 6235 X & GBF 4279 G on 07/03/2018
To: kaimotor <kaimotor@gmail.com>, "assignments@lkkauto.com" <assignments@lkkauto.com>
Cc: motorsurvey <motorsurvey@ecics.com.sg>

Without Prejudice

Dear Kym

Thank you for your email.

We will appoint LKK for the survey.

Aside to LKK

Please assist to arrange for TP PRI.

Thank you.

Regards,

Janice Goh

Claims Division

DID: +65 6303 0182

FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg

directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: kaimotor [<mailto:kaimotor@gmail.com>]

Sent: Thursday, 8 March, 2018 6:04 PM

To: motorsurvey

Subject: Re: ACCIDENT INVOLVING VEHICLE NO SLG 6235 X & GBF 4279 G on 07/03/2018

Sent from my Samsung Galaxy smartphone.

----- Original message -----

From: kaimotor <kaimotor@gmail.com>

Date: 8/3/18 6:02 PM (GMT+08:00)

To: motorsurvey@ecics.com.sg

Subject: Re: ACCIDENT INVOLVING VEHICLE NO SLG 6235 X & GBF 4279 G on 07/03/2018

Sent from my Samsung Galaxy smartphone.

----- Original message -----

From: Kai Motor <kaimotor@gmail.com>

Date: 8/3/18 4:18 PM (GMT+08:00)

To: motorsurvey@ecics.com.sg

Subject: ACCIDENT INVOLVING VEHICLE NO SLG 6235 X & GBF 4279 G on 07/03/2018

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1
#01-440, SINGAPORE 408701
TEL: 67474006 FAX: 67437591

E-mail : kaimotor@gmail.com

REG NO: 44223100L

Date : 08/03/2018

Attn: The Motor Claims Department

ECICS Limited

Attn: Motor Claim Dep
7 Temasek Boulevard,
#10-01
Suntec Tower One
Singapore 038987

WITHOUT PREJUDICE

(By Email Only)

Phoebe Phone: 6337 4779
motorsurvey@ecics.com.sg

Dear Sir / Madam

ACCIDENT INVOLVING VEHICLE NO SLG 6235 X & GBF 4279 G on 07/03/2018

We are writing on behalf of Mr Tee Chee Siong the registered owner of SLG 6235 X which was involved on the above mentioned accident between GBF 4279 G.

Investigation reveals that the motor vehicle number GBF 4279 G was insured with you at the material time of the said accident.

As a result of the accident was caused solely and completely by the negligence of your insured vehicle number GBF 4279 G. Therefore, our client is holding you liable for the repair costs and other consequential loss which was sustained by him/her/them.

Kindly arrange your representative to survey our client's vehicle at **KAI MOTOR TRADING** Blk 3007, Ubi Road 1, #01-440, Singapore 408701 within two (2) days from the date hereof as to avoid further losses incur.

We enclosed hereby the GIA report of SLG 6235 X for your kind attention.

Failing which, our client have no alternative but to proceed with the necessary repairs and the bill will be forward to you for reimbursement.

Yours faithfully,

--

Thank you.




Ms Kym

Kai Motor Trading

Blk 3007 Ubi Rd 1 #01-440

Singapore 408701

Telephone: 6747 4006

		
---	---	---

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

--

Thank you.

Ms Kym

· Kai Motor Trading

Blk 3007 Ubi Rd 1 #01-440

Singapore 408701

Telephone: 6747 4006



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 08/03/2018

Attn: The Motor Claims Department
ECICS Limited

Attn: Motor Claim Dep
7 Temasek Boulevard,
#10-01
Suntec Tower One
Singapore 038987

LKK
Adrian 96893735
WITHOUT PREJUDICE

(By Email Only)

Phoebe Phone: 6337 4779
motorsurvey@ecics.com.sg

Dear Sir / Madam

Estimate Cost repair Bill To Toyota Harrier No SLG 6235 X & GBF 4279 G on 07/03/2018

To Supply :-

1pc	Front bumper <i>replaced</i>	5877.90	\$ 1,475.00	✓
1pc	Front head lamp unit.RH Led <i>ut.</i>	4408.42	\$ 3,450.30	✓
1pc	Front fender RH <i>Dented</i>		\$ 1,215.30	✓
1pc	Front fender inner liner RH <i>NE Nec</i>		\$ 436.50	✓
			\$ 6,577.10	
		less	25%	\$ 1,644.28
				\$ 4,932.83

To dismanlte & replace damage parts,panel beat where necessary.

\$ 600.00 *400*

To putty,apply primer & spray paint on the affecte portion.

830 \$ 750.00 *400*

To check wiring functions.

\$ 80.00 *30*

6482.93

\$ 6,362.83

Supplementary: 90.07

Adrian Ling
12/03/18
OA says

total 5328.49
CP/P.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



凱 摩 哆 服 務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.

TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com

BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 13/03/2018

Attn: The Motor Claims Department

ECICS Limited

Attn: Motor Claim Dep
7 Temasek Boulevard,
#10-01
Suntec Tower One
Singapore 038987

WITHOUT PREJUDICE

(By Email Only)

Phoebe Phone: 6337 4779
motorsurvey@ecics.com.sg

Dear Sir / Madam

Supplementary Cost repair Bill To Toyota Harrier No SLG 6235 X & GBF 4279 G on 07/03/2018

To Supply :-

1pc	Front bumper side retainer RH <i>cracked</i>	\$ 120.10 ✓
-----	--	-------------

Adrian Lj
15/03/18
sls

120.10
90.07

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18004896/AVBN2

Date: 16/04/2018

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SLG6235X	Insured Vehicle No :	GBF4279G
Date of Loss:	07/03/2018	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG6235X	Engine No:	3ZRB716508
Make & Model:	TOYOTA HARRIER, 2.0 (A)	Chassis No:	ZSU600070699
Reg. Date:	06/10/2016 (Man. Year: 2015)	Odometer:	44988 km
Colour:	Black		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R18	Rear Tyre Size:	235/55R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,052.92	4,498.49	554.43	10.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,430.00	830.00	600.00	41.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,482.92	5,328.49	1,154.43	17.81
+ GST 7.00/7.00% (S\$)	453.80	372.99	80.81	17.81
Nett Amount (S\$)	6,936.72	5,701.48	1,235.24	17.81

INSPECTION

Date of Assignment:	09/03/2018	
Date Inspected:	12/03/2018	Inspected At:
		KAI MOTOR TRADING (HQ) BLK 3007 UBI ROAD 1, #01-440 Singapore 408701

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Apr 2018)
Parts: M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLG6235X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,475.00 FL	*1,475.00 FL
2	1		*FRONT HEAD LAMP UNIT,RH LED	Cut	3,450.30 FL	*3,450.30 FL
3	1		*FRONT FENDER RH	Dented	1,215.30 FL	*952.60 FL
4	1		*FRONT FENDER INNER LINER RH	Not Necessary	436.50 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINER RH	Cracked	120.10 FS	*90.07 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					6,697.20	5,967.97
- List Item Discount on L Items 25.00/25.00% (S\$)					1,644.28	1,469.48
Total Parts (S\$)					5,052.92	4,498.49

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGE PARTS,PANEL BEAT WHERE NECESSARY	New	600.00	400.00
2	TO PUTTY,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	750.00	400.00
3	TO CHECK WIRING FUNCTIONS	New	80.00	30.00
Gross Labour Cost (S\$)			1,430.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >