



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : GBF2709X
Make & Model : MITSUBISHI,CANTER FEA01BR1SDEB
 (CBU),FEA01BA20268
Year of Manufacture : 2016

Estimation No. : E18030043
DOA : 13/03/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Roof <i>Repair</i>	1.00	0.00	0.00 ✗
2	Front windscreen <i>could</i>	1.00	0.00	0.00 ✓ 1300.00
3	Front windscreen moulding <i>cut</i>	1.00	0.00	0.00 ✓ 472.80
4	Side mirror assy (LH) <i>new</i>	1.00	0.00	0.00 ✗ 233.00
5	Side mirror cover (LH) <i>cut</i>	1.00	0.00	0.00 ✓ 30.00
6	Side mirror ^{stay} panel (LH) <i>Bent</i>	1.00	0.00	0.00 ✓ 150.00
7	Signal lamp (LH) <i>could</i>	1.00	0.00	0.00 ✓ 381.70
8	Signal lamp clip (LH) <i>new</i>	1.00	0.00	0.00 ✗ 10.00
9	Head lamp (LH) <i>?</i>	1.00	0.00	0.00 ? 699.20
10	Head lamp clip (LH) <i>new</i>	1.00	0.00	0.00 ✗ 10.00
11	Front bumper <i>cut new</i>	1.00	0.00	0.00 ✗ 790.00
12	Front bumper clip <i>new</i>	1.00	0.00	0.00 ✗ 10.00
13	Front bumper retainer (LH) <i>new</i>	1.00	0.00	0.00 ✗ 73.60
14	Front bumper retainer (RH) <i>new</i>	1.00	0.00	0.00 ✗ 73.60
15	Door pillar 'A' <i>Repair Dented</i>	1.00	0.00	0.00 ✓ 791.80
16	Front door (LH) <i>dented</i>	1.00	0.00	0.00 ✓ 1385.20
17	Front door hinge-up (LH) <i>new</i>	1.00	0.00	0.00 ✗ 191.50
18	Front door hinge-down (LH)	1.00	0.00	0.00 ✗ 191.50
19	Front door weather strip (LH) <i>new</i>	1.00	0.00	0.00 ✗ 271.70
20	Front door inner weather strip (LH) <i>new</i>	1.00	0.00	0.00 ✗ 183.60
21	Front door lock (LH) <i>new</i>	1.00	0.00	0.00 ✗ 281.70
22	Front door window moulding (LH) <i>new</i>	1.00	0.00	0.00 ✗ 102.20
23	Front door window garnish (LH) <i>new</i>	1.00	0.00	0.00 ✗ 98.30
24	Front door power window gear (LH) <i>new</i>	1.00	0.00	0.00 ✗ 316.70
25	Front door power window motor (LH)	1.00	0.00	0.00 ✗ 423.60

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : GBF2709X
 Make & Model : MITSUBISHI,CANTER FEA01BR1SDEB (CBU),FEA01BA20268
 Year of Manufacture : 2016

Estimation No. : E18030043
 DOA : 13/03/2018

No	Description	Qty	U/P	Amt
26	Front door step garnish (LH) <i>new</i>	1.00	0.00	0.00
27	Front door arch garnish (LH) <i>new</i>	1.00	0.00	0.00
28	Door pillar 'B' <i>Ry's</i>	1.00	0.00	0.00
				Amt S\$ 0.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 0.00

189.90
210.70
630.50

Section: Special Nett Items

29	Front door sticker - company details (LH) <i>new</i>	1.00	40.00	40.00 30
30	Front door sticker - DUONIC (LH) <i>an</i>	1.00	50.00	50.00 ✓
31	Front door window sticker (LH) <i>new</i>	1.00	80.00	80.00 +
32	Rear box <i>Fridge</i> Panel LH.	1.00	18,000.00 1800	18,000.00 1200 <i>4500?</i>

<i>Rear Box</i>				Amt S\$
<i>Rear Fridge Door LH. Painted</i>				18,170.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 18,170.00

5000

Section: Labour Items

33	To R&R accident affected areas	1.00	2,500.00	2,500.00 900
34	To putty & respray accident affected areas	1.00	1,300.00	1,300.00 800
35	To rust proof accident affected areas	1.00	120.00	120.00 +
36	To R&R rear cooler box	1.00	2,000.00	2,000.00 300
37	To R&R front door mechanism	1.00	80.00	80.00 ✓
38	To check for water seepage	1.00	100.00	100.00 +
39	To do wheel alignment	1.00	180.00	180.00 60

P: 5220.70 - 25%
= 3915.53
EN: 4580.00

Adrian Ling
15/03/19

Amt S\$ 6,280.00
 Discount (0.00%) S\$ 0.00
 Subtotal S\$ 6,280.00

1 = 2240.00
10435.53

07 Days.

List Items Subtotal S\$ 0.00
 Special Nett Items S\$
 Subtotal 18,170.00
 Labour Items Subtotal S\$ 6,280.00
 Total S\$ 24,450.00

+ 45 \$ 8590.00
7 repair days