



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : GBF2709X
Make & Model : MITSUBISHI,CANTER FEA01BR1SDEB (CBU),FEA01BA20268
Year of Manufacture : 2016

Estimation No. : E18030043
DOA : 13/03/2018

No	Description	Qty	U/P	Amt
26	Front door step garnish (LH) <i>new</i>	1.00	0.00	0.00
27	Front door arch garnish (LH) <i>new</i>	1.00	0.00	0.00
28	Door pillar 'B' <i>new</i>	1.00	0.00	0.00
				Amt S\$ 0.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 0.00

Section: Special Nett Items

29	Front door sticker - company details (LH) <i>new</i>	1.00	40.00	40.00 <i>30</i>
30	Front door sticker - DUONIC (LH) <i>new</i>	1.00	50.00	50.00 ✓
31	Front door window sticker (LH) <i>new</i>	1.00	80.00	80.00 ✓
32	Rear box ^{Fridge} Panel LH.	1.00	18,000.00 ¹⁸⁰⁰	18,000.00 ¹⁸⁰⁰ <i>4500? 1200</i>
				Amt S\$ 18,170.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 18,170.00

Section: Labour Items

33	To R&R accident affected areas	1.00	2,500.00	2,500.00 <i>900</i>
34	To putty & respray accident affected areas	1.00	1,300.00	1,300.00 <i>800</i>
35	To rust proof accident affected areas	1.00	120.00	120.00 ✓
36	To R&R rear cooler box	1.00	2,000.00	2,000.00 <i>300</i>
37	To R&R front door mechanism	1.00	80.00	80.00 ✓
38	To check for water seepage	1.00	100.00	100.00 ✓
39	To do wheel alignment	1.00	180.00	180.00 <i>60</i>

P: 5220.70 - 25%
 = 3915.53

RM: 4580.00

L: 2240.00

10735.53

+ 45 \$ 8590.00
 7 repair days

Adrian Lij
 13/03/18

07 Days.

Amt S\$ 6,280.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 6,280.00

List Items Subtotal S\$ 0.00
Special Nett Items S\$
Subtotal 18,170.00
Labour Items Subtotal S\$ 6,280.00
Total S\$ 24,450.00



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : GBF2709X
 Make & Model : MITSUBISHI,CANTER FEA01BR1SDEB
 (CBU),FEA01BA20268
 Year of Manufacture : 2016

Estimation No. : E18030043
 DOA : 13/03/2018

No	Description	Qty	U/P	Amt
<u>Section: List Items</u>				
1	Roof <i>Ryris</i>	1.00	0.00	0.00 ✗
2	Front windscreen <i>could d.</i>	1.00	0.00	0.00 ✓ 1300.00
3	Front windscreen moulding <i>cut</i>	1.00	0.00	0.00 ✓ 472.80
4	Side mirror assy (LH) <i>new</i>	1.00	0.00	0.00 ✗
5	Side mirror cover (LH) <i>lit</i>	1.00	0.00	0.00 ✓ 30.00
6	Side mirror ^{stay} panel (LH) <i>Bent</i>	1.00	0.00	0.00 ✓ 150.00
7	Signal lamp (LH) <i>could</i>	1.00	0.00	0.00 ✓ 381.70
8	Signal lamp clip (LH) <i>new</i>	1.00	0.00	0.00 ✗ 10.00
9	Head lamp (LH) <i>?</i>	1.00	0.00	0.00 ? 699.20
10	Head lamp clip (LH) <i>new</i>	1.00	0.00	0.00 ✗ 10.00
11	Front bumper <i>cut new</i>	1.00	0.00	0.00 ✗ 790.00
12	Front bumper clip <i>new</i>	1.00	0.00	0.00 ✗ 10.00
13	Front bumper retainer (LH) <i>new</i>	1.00	0.00	0.00 ✗
14	Front bumper retainer (RH) <i>new</i>	1.00	0.00	0.00 ✗
15	Door pillar 'A' <i>Ryris Dented</i>	1.00	0.00	0.00 ✓ 791.80
16	Front door (LH) <i>dented</i>	1.00	0.00	0.00 ✓ 1385.20
17	Front door hinge-up (LH) <i>new</i>	1.00	0.00	0.00 ✗ 191.50
18	Front door hinge-down (LH)	1.00	0.00	0.00 ✗ 191.50
19	Front door weather strip (LH) <i>new</i>	1.00	0.00	0.00 ✗ 271.70
20	Front door inner weather strip (LH) <i>new</i>	1.00	0.00	0.00 ✗
21	Front door lock (LH) <i>new</i>	1.00	0.00	0.00 ✗ 281.70
22	Front door window moulding (LH) <i>new</i>	1.00	0.00	0.00 ✗
23	Front door window garnish (LH) <i>new</i>	1.00	0.00	0.00 ✗
24	Front door power window gear (LH) <i>new</i>	1.00	0.00	0.00 ✗
25	Front door power window motor (LH)	1.00	0.00	0.00 ✗

Continue on next page...