

12/05/2008

ASS. RFC. BY:

REF: CS/ASM18004918/Atbez

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Yvonne Ang

of

ASM

Date/Time:

14/3/18

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGV 4090P

Insured:

at Workshop m/s

SME MOTOR

Tel:

6747 6106

of

1 Kaki Bkt Ave 6 # 02-15

Policy No:

Claim No:

S8M00AMR

Sum Insured:

Excess:

\$ 2600.00

Make of Veh:

D.O.A.

10/03/2018

(Client's Record)

15/3/18

CA / ☒ REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3:40pm 14/3/18

Person Contacted:

Pei Ying

Vehicle ☒ IN / ☐ OUT

Date/Time

Action/Instruction

(✓)

Estimate

Pending investigation.

16/3

Revert via Smart claims

Sebastian agree lump sum \$8.5k

23/3 - 3

3pm authorise repair by Yvonne

26/3 @

10am inform Jane authorise repair excess \$2600/-

ASM

ASSIGNMENT

14/06/07

2007 June

Date 15/3/18

Estimated Cost

② 1/25/TP RES / CO RES / EVA / INV / MY

To: 100000000000

SGV 4090P

at Workshop

SME Motor

1 Kaki Bkt Ave 6 # 02-15

Insured

Policy No

Claim No

Sum Insured

Excess

\$2,600.00

Claims Record

Make of Van

Policy Condition

Remark: The van had commenced its repair at the time of inspection.

NS	OS

Ball on/Wheel Value

D/C Accident Room Consistent? Yes or No

D/A PR Seen Consistent? Yes or No

Est. Repair days Res: Yes or No

Lift Sum by 3 val: Yes or No

CA ② REP 24 HRS

Date Person Contacted

Vehicle IN / OUT

Vehicle SGV 4090P

Type ② Midsize Euro Van Lorry Taxi (Prime Motor)

Track Trailers

Make Mrt Lances

1584

Color Blue

No. Reg. 252520

TP Res Insured Ed N / N/A

Engine

C/K

JmYSNCS.3A74008562

Gear Conn Good Fair/Poor Burnt

Steering Jammed Leaked Burnt

Brake Jammed Leaked Burnt

Mod N/A STD A/B

Tyre Size

195/50R15

195/50R15

BS / DUN EXNOVA GY PS LQA MID CHTEL / PR SLM

② TOYO YOKO

Front

Rear

R/S

06

R/S

06

L/S

06

L/S

06

D/C

D/C

15/03/18

Survey Notes

SME

Des. of Damages Fr. Rear OS NS LC Reached by

Front o/s.

The U/C Chassis frame Body Structure offered least support

Date/Time Action/Instruction

00 AXA.

COE Expiry: 13/06/22

lump sum \$ 8500 (Red: 10-162: 55%)

my: 30k

PV: 21.5k

Nett: 8.5k

RECEIVED 29 OCT 2010

Cost Time Fee Paid



Prelim. Report

26/10 Typist



Final Report

Cost Time Fee Paid

Days Of Repair

14

Resurvey No. of Trip

1

Site Fee

240

Add Fee

Storage

Cleaning

Towing

Access

Report Format

OD

Lump Sum

8500

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18004918/Atb

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 15-03-2018



Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SGV 4090P
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00AMR	Excess (\$)	2,600.00
Assign From	SMART CLAIM (YVONNE ANG)	Assign Date	14/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	10/03/2018	Inspection Date	15/03/2018
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 26 October 2018 3:53 PM
To: 'ying@smemotor.com.sg'
Subject: RE: SGV4090P PENDING FOR FINALISE *LKK REF: CS/ASM18004918/Atb

Dear Ying,

Confirm on lump sum \$8500/- as agree with Sebastian.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ying@smemotor.com.sg <ying@smemotor.com.sg>
Sent: Thursday, 20 September 2018 11:03 AM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: Re: SGV4090P PENDING FOR FINALISE *LKK REF: CS/ASM18004918/Atb

hi Dennise,

Photos sent.

thanks
ying

From: Denise Tay (LKKAuto)
Sent: Thursday, September 6, 2018 4:57 PM
To: ying@smemotor.com.sg
Subject: RE: SGV4090P PENDING FOR FINALISE *LKK REF: CS/ASM18004918/Atb

Dear Ying,

Any photo?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Service Address

1 Kaki Bukit Ave 6 #02-15, , 417883

Primary Contact/Insured

SAINI MUHAMMAD KHAIRUL ANWAR BIN
BLK 237 PASIR RIS STREET 21, #05-17, 510237, Singapore
98587052

Claim Handler

ANG Yvonne
6568804461
yvonne.ang@axa.com.sg

Additional Instructions
EXCESS 2600 PENDING INVESTIGATION

Messages Invoices History Documents Assessment Metrics Notes

New Message

TYPE ?

SENT 3/23/18 3:33 PM

FROM ANG Yvonne

SUBJECT Re:RE: IA UPLOADED OF SGV 4090P

BODY Please confirm Lump sum repair \$8500 and 14 days ...



TYPE ?

SENT 3/16/18 2:43 PM

FROM LKK AUTO CONSULTANTS PTE LTD (OD)



GS Automobiles Pte Ltd

Posted: 15-Mar-2018 Tags: 2007 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Used Mitsubishi

**Mitsubishi Lancer 1.6A GLX Sports (COE till 05/2022)****\$30,800****\$7,390 /yr****15-May-2007****1,584 cc****137,000 km****Sedan****Available**

"One Year In House Warranty!" With Official Warranty Certificate (Peace Of Mind), Fully Refurbished, New Paintwork, Accident Free, Wear And Tear Replaced, \$485 Low Monthly Instalment, 10% Down Payment...

Carway

Posted: 14-Mar-2018 Tags: 2007 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Used Mitsubishi

**Mitsubishi Lancer 1.6M GLX (COE till 05/2022)****\$55,000****\$5,990 /yr****22-May-2007****1,584 cc****98,000 km****Sedan****Available**

Low Mileage, Low Depreciation, Interior Excellent Condition, New Aircon Compressor, New Brake Rotors, No Modifications Done Before.

CREDIT OWNER

Posted: 01-Feb-2018 Tags: 2007 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Used Mitsubishi

**Mitsubishi Lancer 1.6A GLX (COE till 06/2022)****\$34,800****\$8,130 /yr****25-Jun-2007****1,584 cc****-****Sedan****Available**

\$5000 To \$7000 Drive Away! 1 To 1 Exchange Available! Monthly From \$594. Guaranteed Approval! All Our Cars Have Undergone A Workshop Check. Buy With Trust And Assurance! Expect Only Honest Deals! Call...

Posted: 13-Mar-2018 Tags: 2007 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Used Mitsubishi

**Insurance renewal at cheaper price!**

We'll find you the cheapest car insurance quotes from over 10 insurers. Make your choice on zero excess and own workshop. Everything done at the comfort of your own home. Roadside assistance & claims support completely free.

Find out more!

**Mitsubishi Lancer 1.6A (OPC) (COE till 06/2022)****\$28,500****\$6,660 /yr****26-Jun-2007****1,584 cc****97,707 km****Sedan****Available**

1 Careful Owner, Original Paint, Low Mileage Done, Car In Excellent Condition, Car Can Convert Back To Normal Plate. Please Call For Appointment To View.

Posted: 22-Feb-2018 Tags: 2007 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Used Mitsubishi

**Mitsubishi Lancer EX 1.5A GLS (New 5-yr COE)****\$36,838****\$7,360 /yr****19-Nov-2007****1,499 cc****-****Sedan****Available**

Tip Top Condition, 100% In House Loan, Low Down Payment, Don't Need Guarantors. 2 Years Free Servicing. 100% Worth Buy. Don't Miss It. Call Now To Enquire For More Detail, Act Fast Or Else Sure Gone. ...

Posted: 09-Mar-2018 Tags: 2007 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Used Mitsubishi

**Mitsubishi Lancer 1.6A GLX (OPC) (New 5-yr COE)****\$33,800****\$6,760 /yr****26-Nov-2007****1,584 cc****120,000 km****Sedan****Available**

Posted: 03-Mar-2018 Tags: 2007 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Used Mitsubishi

**Mitsubishi Lancer EX 1.5A GLS (COE till 01/2023)****\$36,888****\$7,590 /yr****22-Jan-2008****1,499 cc****108,000 km****Sedan****Available**

2 Years Warranty On Engine And Gearbox! Down Payment \$2000! 100% Loan Approval! Bank And In House Loan Available! Low Down Payment. Available! No Gimmicks! Trade In Welcome! Priced Lowest In The Market...

JDM Cars

Posted: 11-Mar-2018 Tags: 2008 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Used Mitsubishi

**Mitsubishi Lancer EX 1.5A GLS (COE till 01/2023)****\$36,000****\$7,410 /yr****23-Jan-2008****1,499 cc****96,331 km****Sedan****Available**

Extremely Sporty And One Of A Kind Diamond Base Matte Custom Paintwork. Well Maintained At Every Servicing Interval With Lots Of New Parts Changed Prior To Renewal. Parts Include New Genuine Engine Mo...

CREDIT OWNER

Posted: 18-Feb-2018 Tags: 2008 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Used Mitsubishi

**Mitsubishi Lancer EX 1.5A GLS (New 5-yr COE)****\$34,500****\$6,900 /yr****30-Jan-2008****1,499 cc****125,000 km****Sedan****Available**

Low Mileage. Car In Very Good Condition Interior And Exterior, No Repairs Needed. Trade In Welcome, Bank Loan And In-House Loan Available. Call Us For An Appointment Today.

Posted: 05-Mar-2018 Tags: 2008 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Used Mitsubishi

Mitsubishi Lancer 1.6M GLX (OPC) (New 5-yr COE)**\$31,800****\$6,360 /yr****18-Feb-2008****1,584 cc****88,259 km****Sedan****Available****CREDIT OWNER**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5325Z
Vehicle Details	
Vehicle No.:	SGV4090P
Vehicle to be Exported:	Yes
Intended De-registration Date:	15 Mar 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 M
Primary Colour:	Grey
Manufacturing Year:	2007
Engine No.:	4G18JC2295
Chassis No.:	JMYSNCS3A7U008562
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$10,843.00
Original Registration Date:	14 Jun 2007
First Registration Date:	14 Jun 2007
Transfer Count:	3
Actual ARF Paid:	\$11,288.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jun 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,313.00
COE Rebate Amount:	\$21,494.00
Total Rebate Amount:	\$21,494.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 15 Mar 2018



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S8M00AMR

Our Ref: CS/ASM18004918/Atb

Date: 16/3/2018

The Motor Claims Department
M/s AXA Insurance Singapore Pte Ltd

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO SGV 4090P

We thank you for the instruction on 16/3/2018

Please be informed that we had conducted the inspection of the abovementioned vehicle on 15/3/2018 at the premises of M/s SME MOTOR and have the following to report: -

Workshop Estimate Amount	: S\$	<u>18,342.00</u>
Revised Estimate Amount	: S\$	<u>8,604.00</u>
"Check" Items Amount	: S\$	<u>5,840.00</u>
Total	: S\$	<u>14,444.00</u>
Market Value	: S\$	<u>30,000.00</u>
LTA Reimbursement Value	: S\$	<u>21,481.00</u>
Nett Value	: S\$	<u>8,519.00</u>

Description of Damage:

The vehicle sustained damages at the
Front o/s portion.

Comments/ Present Status:

Damages Consistent


Repair cost economical

We did NOT authorized repair

Repair Days: 14

Yours Faithfully,

Adrian
Automotive Assessor



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5325Z
Vehicle Details	
Vehicle No.:	SGV4090P
Vehicle to be Exported:	No
Intended De-registration Date:	16 Mar 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 M
Primary Colour:	Grey
Manufacturing Year:	2007
Engine No.:	4G18JC2295
Chassis No.:	JMYSNCS3A7U008562
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$10,843.00
Original Registration Date:	14 Jun 2007
First Registration Date:	14 Jun 2007
Transfer Count:	3
Actual ARF Paid:	\$11,288.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jun 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,313.00
COE Rebate Amount:	\$21,481.00
Total Rebate Amount:	\$21,481.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 16 Mar 2018




Service Request Details

Claim

S8M00AMR

Reference

None 

Loss Date

March 10, 2018

Request Date

March 14, 2018

Due Date

March 21, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

2-40pm
Wh. /
paying
15/3/18

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SGV4090P

Make

MITSUBISHI

Service Address

1 Kaki Bukit Ave 6 #02-15, . . 417883

Primary Contact/Insured

SAINI MUHAMMAD KHAIRUL ANWAR BIN
BLK 237 PASIR RIS STREET 21, #05-17, 510237, Singapore
98587052

Claim Handler

ANG Yvonne
6568804461
yvonne.ang@axa.com.sg

Additional Instructions

EXCESS 2600 PENDING INVESTIGATION

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

[+ Upload Documents](#)

NAME

 Accident Statement

TYPE

Reports & Statement

SUB-TYPE

AUTHOR

Merimen

DATE UPLOADED

NAME

 SGV4090P ESTIMATE.pdf

TYPE


Reports & Statement

SUB-TYPE

GIA Report

AUTHOR

SME MOTOR PTE LTD

NAME	 SGV4090P.pdf
TYPE	Reports & Statement
SUB-TYPE	GIA Report
AUTHOR	SME MOTOR PTE LTD
DATE UPLOADED	March 14, 2018

NAME	 SGV4090P INSD GIA.PDF
TYPE	Reports & Statement
SUB-TYPE	GIA Report
AUTHOR	NIKAM Santosh Pandurang
DATE UPLOADED	March 13, 2018

Denise Tay (LKKAUTO)

From: ANG Yvonne <yvonne.ang@axa.com.sg>
Sent: Tuesday, 20 March 2018 1:52 PM
To: Denise Tay (LKKAUTO)
Subject: S8M00AMR / SGV4090P MUHAMMAD KHAIRUL ANWAR BIN SAINI
Attachments: Servicing Invoice - 18 December 2017.jpg

Hi Denise

As spoken, attached the servicing invoice from insured
Please advise any mechanic issue upon surveying the vehicle

*The invoice only describe items
used for routine servicing.*

Regards

Yvonne Ang
Assistant Manager
Motor (Property) Claims

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg
Email: yvonne.ang@axa.com.sg
DID: 1800 880 4888



redefining / insurance

AXA's Values at Work:



Customer
First



Integrity



Courage



ONE
AXA

Please consider the environment before printing this email

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited.
If you are not the intended recipient of the message, please notify the sender immediately.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

M/S 86V 4090 P

No. 400255

日期
Date

18.10.2017

No	詳細 PARTICULARS BUTIR-BUTIR	数量 QUANTITY Kuantiti	单价 UNIT PRICE HARGA	金额 AMOUNT NILAI
1	Engine Oil			140-00
2	Mounting			150-00
3	Coolant			80-00
4	Spray Engine casing			150-00
5	Oil filter			25-00
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
			TOTAL / 总额 JUMLAH	608-00

GT PERFORMANCE MOTOR SPORT
No. 0618954-P)1st GROUND FLOOR,
JALAN TAN ABDUL RAZAK, SUSUR 4,
86000 JOHOR BAHRU, JOHOR.

HP: +6012-732-8233, +6012-732-3555 Signature / Tandatangan / 经手人



redefining / insurance

LETTER OF UNDERTAKING/ AUTHORIZATION FOR LUMP SUM REPAIR

MUHAMMAD KHAIROL ANWAR BIN SAINI

1. I, [Name] [NRIC] (S90353252) the owner/ authorized driver of vehicle [Registration No.] SAV4090P ("Vehicle") do hereby authorize the [Workshop/Insurer] to repair the Vehicle on a lump sum basis instead of part by part.
2. The [Workshop/Insurer] has explained to me the difference between lump sum repair and part by part repair and the consequences of my authorization for lump sum repair for the Vehicle.
3. I understand that with lump sum repair, the Workshop may use a mixture of genuine parts, original equipment manufacturer (OEM) parts, reconditioned and second hand parts to carry out the repair and I note that the [Workshop/Insurer] will not be furnishing a detailed breakdown of parts or price for such lump sum repair.
4. I am aware that AXA Insurance Pte Ltd ("AXA Insurance") does not encourage lump sum repair as AXA Insurance strongly recommends repairs for vehicles on a part by part basis for transparency reasons. I confirm that I will hold AXA Insurance harmless from any claims arising from the lump sum repair of the Vehicle which I have authorized.
5. * To be applicable where person authorizing is the authorized driver.
I confirm that I have the authority from the owner of the Vehicle to authorize the lump sum repairs and that I have duly notified the owner of the Vehicle of the contents of this Letter of Authorization.

Signed and acknowledged by:

Signature of policyholder/ authorized driver* and company stamp (where applicable)

Date:



Sebastian

Name and signature of workshop personnel including workshop stamp

Date: 16/03/2018

*authorized driver to either the named drivers as per motor insurance policy or in the case of commercial vehicles, permitted drivers who are permitted to drive the insured Vehicle.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/03/2018 12:51
Date Of Accident	10/03/2018 16:50
Exact Location Of Accident	JOHOR BAHRU
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGV4090P
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD KHAIRUL ANWAR BIN SAINI
NRIC No	S9035325Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98587052
Alternative Phone No	OFFICE-98587052

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER-1.6 (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA221646
Cover Note Number	

Driver

Name of Driver	MUHAMMAD KHAIRUL ANWAR BIN SAINI
NRIC No	S9035325Z
Date Of Birth	24/09/1990
Occupation	INDOOR
Date Of Driving Pass	19/01/2010
Driving Experience	8 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98587052
Fax Number	
Contact Number	OFFICE-98587052
Email Address	NOEMAIL

Address	BLK 237 PASIR RIS ST 21 #05-17
Postcode	510237
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	QS1386G (PRIVATE CAR)
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : MUHAMMAD FIRDAUS BIN MUSTAFA KAMAL GENDER: : MALE
Passenger 2	NAME: : MUHD SALIHIN BIN ABDUL RAHIM GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BEDOK SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 CHAI CHEE DRIVE , POSTCODE: 469045 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2448999 - FAX NO: 62446558
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT: G/20180312/2093.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QS1386G
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MUHAMMAD KHAIRUL ANWAR BIN SAINI

Approximate Age

Injuries Sustain

Injured person in which vehicle? SGV4090P

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name MUHAMMAD FIRDAUS BIN MUSTAFA KAMAL

Approximate Age

Injuries Sustain

Injured person in which vehicle? SGV4090P

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 3

Name MUHD SALIHIN BIN ABDUL RAHIM

Approximate Age

Injuries Sustain

Injured person in which vehicle? SGV4090P

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/VIN No.:



DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature: _____
Date & Time: _____

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:



redefining / Insurance

Date: 13/03/2018

To: Owner of Vehicle Number: 3EIV 4090P

The following has been advised to you via your workshop, SME MOTOR PTECTA through their staff.

Please tick the applicable box if you had been advice on the content as seen below:

☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

☒ You had been advised by the workshop on the liability and merits of the case accordingly.

☒ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.

☐ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.

☒ There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.

☐ The estimated waiting time for the spare parts to arrive is _____. The estimated arrival time does not include the repair period.

☐ You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.

☒ For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.

For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using any combination of genuine original parts and/or original equipment manufacturer (OEM) parts.

☒ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.

☐ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.

☐ Others _____

Signed and acknowledge by:

X [Signature]
Name and signature of policyholder/authorized driver

Name and signature of workshop personnel including company stamp



**SINGAPORE
POLICE FORCE**



G/20180312/2093

1 of 2

POLICE REPORT (NP299)

Report No. G/20180312/2093

Police Station Of Origin
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

Date/Time Report Made 12/03/2018 14:14		Vide Report No.		Station Diary No. 23	
Name Of Informant MUHAMMAD KHAIRUL ANWAR BIN SAINI		Address APT BLK 237 PASIR RIS STREET 21 #05-17 SINGAPORE 510237			
ID Type / ID No. NRIC NO / S9035325Z		Contact No. Home/Office Mobile 98587052			
Nationality SINGAPORE CITIZEN		Email Address			
Occupation POWERGRID		Sex Male	Age 27	Date of Birth 24/09/1990	Race Boyanesse
Institution/School Name		Language English			
Date/Time Of Incident 10/03/2018 16:50		Location Of Incident Johor Bahru MALAYSIA			

Brief details.

On 10/03/2018 at about 1650hrs, I was driving vehicle SGV4090P Mitsubishi Lancer Blue in colour together with my three friends along Jalan Tun Abdul Razak at Johor Bahru turning right to going to Singapore. While I was driving, I spotted one Toyota Grey registration number believe QS1386G but I am unsure as after the incident there was a lot of crowd at the said location that was making things difficult for me to settle the matter.

Signature Of Officer Recording The Report:

G / Staff Sgt MUHAMMAD AL-ADHA BIN ABDUL GHANI

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
G / Bedok Police Divisional Investigation Branch /
Staff Sgt MUHAMMAD FADLI BIN SALIM
Contact No.: 62440000

Authentication

SINGAPORE
POLICE FORCE

SIGNATURE

Signature Of Informant:

Date/Time:
12/03/2018 14:14

Classification Of Case:



**SINGAPORE
POLICE FORCE**



G/20180312/2093

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20180312/2093

When I saw the said vehicle coming to my lane, I swerve to my left and the said vehicle had hit my front right side which make my vehicle stop at the at the opposite direction. I wish to state that after the incident occurred my vehicle was seriously damaged and unable to move.

I also discovered that the other vehicle was slight damaged however the driver does not wish to communicate with me. As I was trying to engage him, I was stopped by the crowd who then told me that I was at fault. I wish to state that I was trying to avoid him as he had come to my lane and however my effort had gone to waste as I could not avoid being hit. After The said driver was standing far from his vehicle and the crowd was making things difficult for me.

Traffic police came to scene and advise to proceed police station to lodge a report and settle via insurance claim. I did make a police report at Johor Bahru Police Station. After the incident, I then towed my vehicle to my insurance workshop located at Singapore and was also advice to make a police report.


I wish to include that I did went for my medical at Mount Alvernia and was given 8 days MCs from 11/03/2018 to 18/03/2018. Both of my friend, Muhammad Firdaus Bin Mustafa Kamal, S8923643F was given MCs from 11/03/2018 to 17/03/2018 and Muhd Salihin Bin Abdul Rahim S9229712H was given MCs from 12/03/2018 to 14/03/2018.

I am making this report as instructed by my insurance company to facilitate in the claim.

Signature Of Officer Recording The Report: G / Staff Sgt MUHAMMAD AL-ADHA BIN ABDUL GHANI
Signature Of Interpreter: Not applicable
Officer In-Charge Of Case: G / Bedok Police Divisional Investigation Branch / Staff Sgt MUHAMMAD FADLI BIN SALIM Contact No.: 62440000

Signature Of Informant:
Date/Time: 12/03/2018 14:14
Classification Of Case:

Authentication Stamp



VEHICLE NO.: SGV4090P
 MAKE: MITSUBISHI
 MODEL: LANCER
 YEAR OF MAKE: 2007
 CHASSIS NO.: JMYSNCS3A7U008562
 SUPPLIERS : HEXING

S/N	Parts Description	QTY	Remarks
1	FRT WINDSCREEN <i>Cracked</i>	1	\$550.00 ✓
2	FRT WINDSCREEN MOULDING <i>new</i>	1	\$45.00 ✓
3	FRT BONNET <i>Twisted</i>	1	\$395.00 ✓
4	FRT BONNET LOCK <i>Bent</i>	1	\$38.00 ✓
5	FRT BONNET HINGE <i>Bent</i>	2	\$75.00 ✓
6	FRT BONNET LOCK CABLE <i>new</i>	1	\$35.00 ✓ X
7	FRT GRILLE <i>cut</i>	1	\$325.00 ✓
8	FRT GRILLE CLIP <i>new</i>	4	\$8.00 ✓
9	FRT BUMPER <i>Distorted</i>	1	\$400.00 ✓
10	FRT BUMPER RETAINER <i>new</i>	2	\$60.00 ✓
11	FRT BUMPER CLIP <i>new</i>	10	\$20.00 ✓
12	FRT BUMPER LOWER GRILLE <i>Distorted</i>	1	\$85.00 ✓
13	FRT BUMPER LOWER OUTER GARNISH <i>new new</i>	2	\$70.00 X X
14	FRT BUMPER LOWER SPOILER <i>new</i>	1	\$800.00 X X
15	FOG LAMP GARNISH RH <i>Missing</i>	1	\$25.00 ✓
16	FOG LAMP RH <i>Missing</i>	1	\$380.00 ✓
17	HEADLAMP <i>LH cracked, RH smashed</i>	2	\$590.00 ✓
18	HEADLAMP SUPPORT PANEL <i>Distorted</i>	1	\$400.00 ✓
19	AIRCON CONDENSER <i>Distorted</i>	1	\$190.00 ✓
20	RADIATOR <i>Cracked</i>	1	\$290.00 ✓
21	AIRCON FAN MOTOR ASSY <i>Cracked</i>	1	\$180.00 ? ✓
22	RADIATOR MOTOR COWLING <i>Cracked</i>	1	\$75.00 ? ✓
23	RADIATOR MOTOR <i>Bent</i>	1	\$165.00 ? ✓
24	RADIATOR FAN BLADE <i>Bent</i>	1	\$35.00 ? X
25	RADIATOR SPARE TANK <i>new</i>	1	\$38.00 X X
26	RADIATOR TOP HOSE <i>twisted</i>	1	\$20.00 ✓
27	RADIATOR LOWER HOSE <i>Not new</i>	1	\$25.00 ? X
28	RADIATOR TOP BRACKET <i>Bent</i>	2	\$22.00 ✓
29	AIRCON COOLING PIPE <i>Bent</i>	1	\$155.00 ✓
30	AIRCON DISCHARGE PIPE <i>Bent</i>	1	\$155.00 ✓
31	AIRCON SUCTION PIPE <i>Bent</i>	1	\$155.00 ✓
32	WASHER TANK <i>Distorted</i>	1	\$75.00 ✓
33	WASHER TANK MOTOR <i>new</i>	1	\$85.00 X X
34	AUTO OIL <i>new</i>	1	\$48.00 ✓
35	POWER STEERING TANK <i>Cracked</i>	1	\$80.00 ✓
36	POWER STEERING PUMP <i>Bent</i>	1	\$850.00 ? ✓
37	POWER STEERING PUMP BRACKET <i>Bent</i>	1	\$125.00 ? ✓
38	ALTERNATOR <i>Distorted</i>	1	\$850.00 ? X
39			

40	AIRCON COMPRESSOR	Alfa	1	\$650.00	?	✓
41	WATER PUMP	3/4" 1/2"	1	\$160.00	?	✓
42	WATER PUMP PULLEY	1/2" 1/2"	1	\$75.00	?	X
43	FAN BELT	1/2" 1/2" Snapped	1	\$55.00	?	
44	FRT ENGINE MOUNTING	Torn	1	\$85.00	?	✓
45	REAR ENGINE MOUNTING	Torn	1	\$85.00	?	✓
46	RH ENGINE MOUNTING	Torn	1	\$135.00	?	✓
47	LH ENGINE MOUNTING	Torn	1	\$135.00	?	✓
48	FRT RH WHEEL HOUSING PANEL	Distorted	1	\$900.00	?	✓
49	FRT RH CHASSISMEMBER	Rear	1	\$950.00	?	✓
50	FRT RH FENDER	Distorted	1	\$295.00	?	✓
51	FRT FENDER INNER COWLING	Torn	2	\$156.00	?	✓
52	INNER COWLING CLIP	1/2"	20	\$40.00	?	✓
53	FRT RH FENDER SIGNAL LAMP	1/2"	1	\$25.00	?	X
54	POWER STEERING PIPE	2" ? not in	1	\$175.00	?	X
55	POWER STEERING HOSE	2" ? not in	1	\$75.00	?	X
56	FRT FENDER TOP CORNER GARNISH RH	Missing	1	\$25.00	?	✓
57	FRT SHOCK ABSORBER RH	1/2" 1/2"	1	\$225.00	?	X
58	FRT KNUCKLE ARM RH	1/2" 1/2"	1	\$250.00	?	X
59	FRT KNUCKLE ARM BEARING RH	1/2" 1/2"	1	\$120.00	?	X
60	FRT LOWER ARM RH	1/2" 1/2"	1	\$195.00	?	X
61	FRT CENTER CROSSMEMBER	1/2" 1/2"	1	\$215.00	?	X
62	ENGINE UNDER COVER	Torn	2	\$116.00	?	✓
63	UNDER COVER CLIP	1/2"	10	\$20.00	?	✓
64	ENGINE SIDE COVER RH	Torn	1	\$55.00	?	✓
65	SIDE COVER CLIP	1/2"	6	\$12.00	?	✓
66	WIPER GARNISH	1/2"	1	\$100.00	?	✓
67	WIPER CORNER GARNISH RH	1/2"	1	\$28.00	?	✓
68	GRILLE LOGO	1/2"	1	\$20.00	?	✓
69						
70	TOTAL:			\$13,297.00		
71						
72						
73						
74						
75						
76						

VEHICLE NO.: SGV4090P
 MAKE: MITSUBISHI
 MODEL: LANCER
 YEAR OF MAKE: 2007
 CHASSIS NO.: JMYSNCS3A7U008562
 SUPPLIERS : HEXING

S/N	Item Description	QTY	Remarks
1			
2	SPECIAL NETT:		
3	FRT WINDSCREEN GUM <i>Free</i>		\$65.00 ✓
4	RADIATOR COOLANT		\$25.00 ✓
5	HEADLAMP BULB <i>smashed</i>		\$30.00 <i>20</i>
6	SMALL LAMP BULB		\$25.00 <i>15</i>
7	SIGNAL LAMP BULB		\$20.00 <i>15</i>
8	POWER STEERING OIL <i>an</i>		\$25.00 ✓
9			
10			
11	TOTAL:		\$190.00
12			
13			
14	LABOUR:		
15	WIRE CHECKING		\$20.00 ✓ ✓
16	REMOVE & REFIX AIRCON AND GAS		\$100.00 ✓ ✓
17	REMOVE & REFIX FRT WINDSCREEN		\$120.00 ✓ ✓
18	REMOVE & REFIX ENGINE		\$350.00 ✓ ✓
19	REMOVE & REFIX POWER STEERING PUMP, ALTERNATOR &		\$180.00 ✓ ✓
20	AIRCON COMPRESSOR		
21	REMOVE & REFIX 1 SET ENGINE MOUNTING		\$150.00 ✓ ✓
22	REMOVE & REFIX FRT UNDERCARRIAGE		\$250.00 X X
23	WHEEL ALIGNMENT		\$65.00 ✓ X
24	REPAIR WIRE HARNESS		\$120.00 X X
25	LABOUR CHARGE		\$2,000.00 <i>1500</i>
26	SPRAY PAINTING		\$1,500.00 <i>1200</i>
27			
28	TOTAL:		\$4,855.00
29			
30			
31			
32	TOTAL:		\$18,342.00
33	7% GST:		\$1,283.94
34			\$19,625.94
35			

Adrian Lij
L/S - 15/03/18.

Excess: \$2600
Not Authorised.

14 Days.

19262

VEHICLE NO.: SGV4090P

MAKE: MITSUBISHI

MODEL: LANCER

YEAR OF MAKE: 2007

CHASSIS NO.: JMYSNCS3A7U008562

SUPPLIERS : HEXING

S/N	Parts Description	QTY	Remarks
1	FRT WINDSCREEN <i>cracked</i>	1	\$550.00 ✓
2	FRT WINDSCREEN MOULDING <i>m</i>	1	\$45.00 ✓
3	FRT BONNET <i>ruled</i>	1	\$395.00 ✓
4	FRT BONNET LOCK <i>2nd</i>	1	\$38.00 ✓
5	FRT BONNET HINGE <i>Bent</i>	2	\$75.00 ✓
6	FRT BONNET LOCK CABLE <i>new</i>	1	\$35.00 ✓
7	FRT GRILLE <i>cut</i>	1	\$325.00 ✓
8	FRT GRILLE CLIP <i>m</i>	4	\$8.00 ✓
9	FRT BUMPER <i>Dislodged</i>	1	\$400.00 ✓
10	FRT BUMPER RETAINER <i>m</i>	2	\$60.00 ✓
11	FRT BUMPER CLIP <i>m</i>	10	\$20.00 ✓
12	FRT BUMPER LOWER GRILLE <i>ruled</i>	1	\$85.00 ✓
13	FRT BUMPER LOWER OUTER GARNISH <i>new m</i>	3	\$70.00 ✓
14	FRT BUMPER LOWER SPOILER <i>new</i>	1	\$600.00 ✓
15	FOG LAMP GARNISH RH <i>Missing</i>	1	\$25.00 ✓
16	FOG LAMP RH <i>Missing</i>	1	\$380.00 ✓
17	HEADLAMP <i>LH cracked & RH smashed</i>	2	\$590.00 ✓
18	HEADLAMP SUPPORT PANEL <i>Distorted</i>	1	\$400.00 ✓
19	AIRCON CONDENSER <i>Dislodged</i>	1	\$190.00 ✓
20	RADIATOR <i>cracked</i>	1	\$290.00 ✓
21	AIRCON FAN MOTOR ASSY ?	1	\$180.00 ?
22	RADIATOR MOTOR COWLING ?	1	\$75.00 ?
23	RADIATOR MOTOR ?	1	\$165.00 ?
24	RADIATOR FAN BLADE ?	1	\$35.00 ?
25	RADIATOR SPARE TANK <i>new</i>	1	\$35.00 ✓
26	RADIATOR TOP HOSE <i>twisted</i>	1	\$20.00 ✓
27	RADIATOR LOWER HOSE ?	1	\$25.00 ✓
28	RADIATOR TOP BRACKET <i>Bent</i>	2	\$22.00 ✓
29	AIRCON COOLING PIPE <i>Bent</i>	1	\$155.00 ✓
30	AIRCON DISCHARGE PIPE <i>Bent</i>	1	\$155.00 ✓
31	AIRCON SUCTION PIPE <i>Bent</i>	1	\$155.00 ✓
32	WASHER TANK <i>Dislodged</i>	1	\$75.00 ✓
33	WASHER TANK MOTOR <i>new</i>	1	\$35.00 ✓
34	AUTO OIL <i>m</i>	1	\$48.00 ✓
35	POWER STEERING TANK <i>cracked</i>	1	\$80.00 ✓
36	POWER STEERING PUMP ?	1	\$850.00 ?
37	POWER STEERING PUMP BRACKET ?	1	\$125.00 ?
38	ALTERNATOR ?	1	\$600.00 ?
39			

SME MOTOR PTE LTD

40	AIRCON COMPRESSOR	?	1	\$650.00	?
41	WATER PUMP	?	1	\$180.00	?
42	WATER PUMP PULLEY	?	1	\$75.00	?
43	FAN BELT	?	1	\$55.00	?
44	FRT ENGINE MOUNTING	?	1	\$85.00	?
45	REAR ENGINE MOUNTING	?	1	\$85.00	?
46	RH ENGINE MOUNTING	?	1	\$135.00	?
47	LH ENGINE MOUNTING	?	1	\$135.00	?
48	FRT RH WHEEL HOUSING PANEL	?	1	\$900.00	?
49	FRT RH CHASSIS MEMBER	Repair	1	\$950.00	?
50	FRT RH FENDER	Disbld	1	\$295.00	✓
51	FRT FENDER INNER COWLING	ton	2	\$155.00	✓
52	INNER COWLING CLIP	u	20	\$40.00	✓
53	FRT RH FENDER SIGNAL LAMP	sta	1	\$25.00	✓
54	POWER STEERING PIPE	ps ?	1	\$175.00	?
55	POWER STEERING HOSE	?	1	\$75.00	?
56	FRT FENDER TOP CORNER GARNISH RH	Missing	1	\$25.00	✓
57	FRT SHOCK ABSORBER RH	?	1	\$225.00	?
58	FRT KNUCKLE ARM RH	?	1	\$250.00	?
59	FRT KNUCKLE ARM BEARING RH	?	1	\$120.00	?
60	FRT LOWER ARM RH	?	1	\$195.00	?
61	FRT CENTER CROSSMEMBER	?	1	\$215.00	?
62	ENGINE UNDER COVER	ton	2	\$115.00	✓
63	UNDER COVER CLIP	sta	10	\$20.00	✓
64	ENGINE SIDE COVER RH	ton	1	\$55.00	✓
65	SIDE COVER CLIP		8	\$12.00	✓
66	WIPER GARNISH	Disbld	1	\$100.00	✓
67	WIPER CORNER GARNISH RH	Disbld	1	\$28.00	✓
68	GRILLE LOGO	u	1	\$20.00	✓
69					4000
70	TOTAL:			\$13,297.00	
71	TIMMING COVER TOP	- \$85			
72	TIMMING COVER LOWER	- \$85			
73	FRT EXHAUST MANIFOLD	- \$750			
74					
75					
76					

VEHICLE NO.: SGV4090P
 MAKE: MITSUBISHI
 MODEL: LANCER
 YEAR OF MAKE: 2007
 CHASSIS NO.: JMYSNCS3A7U008562
 SUPPLIERS : HEXING

S/N	Item Description	QTY	Remarks
1			
2	SPECIAL NETT:		
3	FRT WINDSCREEN GUM <i>Free</i>		\$65.00 ✓
4	RADIATOR COOLANT		\$25.00 ✓
5	HEADLAMP BULB <i>2 smashed</i>		\$30.00 20
6	SMALL LAMP BULB		\$25.00 15
7	SIGNAL LAMP BULB		\$20.00 15
8	POWER STEERING OIL <i>an</i>		\$25.00 ✓
9			165
10			
11	TOTAL:		\$190.00
12			
13			
14	LABOUR:		
15	WIRE CHECKING		\$20.00 ✓
16	REMOVE & REFIX AIRCON AND GAS		\$100.00 ✓
17	REMOVE & REFIX FRT WINDSCREEN		\$120.00 100
18	REMOVE & REFIX ENGINE		\$350.00 ?
19	REMOVE & REFIX POWER STEERING PUMP, ALTERNATOR &		\$180.00 ? 1
20	AIRCON COMPRESSOR		
21	REMOVE & REFIX 1 SET ENGINE MOUNTING		\$150.00 ?
22	REMOVE & REFIX FRT UNDERCARRIAGE		\$250.00 7
23	WHEEL ALIGNMENT		\$65.00 ✓
24	REPAIR WIRE HARNESS		\$120.00 7
25	LABOUR CHARGE		\$2,000.00 1500
26	SPRAY PAINTING		\$1,500.00 1200
27			
28	TOTAL:		\$4,855.00
29			3665
30			
31			
32	TOTAL:		\$18,342.00
33	7% GST:		\$1,283.94
34			\$19,625.94
35			

Adrian Lij
L/S: 15/03/18.

Excess: \$2600
Not Authorised.

14 Days. 26/3/18 @ 10am authorised repair

VEHICLE NO.:

SGV4090P

MAKE:

MITSUBISHI

MODEL:

LANCER

YEAR OF MAKE:

2007

CHASSIS NO.:

SUPPLEMENTARY

SUPPLIERS :

HEXING

[illegible]

parts 10,959

SN 165

LC 3665

14,789.

Us 11,850

17/04/2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18004918/Atbe2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN : YVONNE ANG

Date : 14-11-2018

Code : ASM



1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SGV 4090P
Policy No.	GA221646	Coverage (\$)	0.00
Claim No.	S8M00AMR	Excess (\$)	2,600.00
Assign From	YVONNE ANG	Assign Date	14/03/2018

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI LANCER	c.c	1584
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JMYSNCS3A7U008562	Colour	BLUE
Odometer	252920	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/50 R15	TOYO	6 mm
L/H Front Tyre	195/50 R15	TOYO	6 mm
R/H Rear Tyre	195/50 R15	TOYO	6 mm
L/H Rear Tyre	195/50 R15	TOYO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/03/2018	Inspection Date	15/03/2018
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		

5a. Remarks

A)THE MARKET VALUE IS S\$30,000.00(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	14 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGV 4090P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT WINDSCREEN (CONSISTENT)	CRACKED	550.00	550.00
1	FRT WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	45.00	45.00
1	FRT BONNET (CONSISTENT)	BUCKLED	395.00	395.00
1	FRT BONNET LOCK (CONSISTENT)	DAMAGED	38.00	38.00
2	FRT BONNET HINGE (CONSISTENT)	BENT	76.00	76.00
1	FRT BONNET LOCK CABLE (CONSISTENT)	NOT NECESSARY	35.00	-
1	FRT GRILLE (CONSISTENT)	CUT	325.00	325.00
4	FRT GRILLE CLIP (CONSISTENT)	NECESSARY	8.00	8.00
1	FRT BUMPER (CONSISTENT)	DISTORTED	400.00	400.00
2	FRT BUMPER RETAINER (CONSISTENT)	NECESSARY	60.00	60.00
10	FRT BUMPER CLIP (CONSISTENT)	NECESSARY	20.00	20.00
1	FRT BUMPER LOWER GRILLE (CONSISTENT)	DEFORMED	85.00	85.00
2	FRT BUMPER LOWER OUTER GARNISH (CONSISTENT)	NOT NECESSARY	70.00	-
1	FRT BUMPER LOWER SPOILER (CONSISTENT)	NOT NECESSARY	800.00	-
1	FOG LAMP GARNISH RH (CONSISTENT)	MISSING	25.00	25.00
1	FOG LAMP RH (CONSISTENT)	MISSING	380.00	380.00
2	HEADLAMP (CONSISTENT)	N/S CRACKED / O/S SMASHED	590.00	590.00
1	HEADLAMP SUPPORT PANEL (CONSISTENT)	DISTORTED	400.00	400.00
1	AIRCON CONDENSER (CONSISTENT)	DISTORTED	190.00	190.00
1	RADIATOR (CONSISTENT)	CRACKED	290.00	290.00
1	AIRCON FAN MOTOR ASSY (CONSISTENT)	CRACKED	180.00	180.00
1	RADIATOR MOTOR COWLING (CONSISTENT)	CRACKED	75.00	75.00
1	RADIATOR MOTOR (CONSISTENT)	DAMAGED	165.00	165.00
1	RADIATOR FAN BLADE (CONSISTENT)	CUT	35.00	35.00
1	RADIATOR SPARE TANK (CONSISTENT)	NOT NECESSARY	38.00	-
1	RADIATOR TOP HOSE (CONSISTENT)	TWISTED	20.00	20.00
1	RADIATOR LOWER HOSE (CONSISTENT)	NOT NECESSARY	25.00	-
2	RADIATOR TOP BRACKET (CONSISTENT)	BENT	22.00	22.00
1	AIRCON COOLING PIPE (CONSISTENT)	BENT	155.00	155.00
1	AIRCON DISCHARGE PIPE (CONSISTENT)	BENT	155.00	155.00

Report Ref No. CS/ASM18004918/Atbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIRCON SUCTION PIPE (CONSISTENT)	BENT	155.00	155.00
1	WASHER TANK (CONSISTENT)	DISTORTED	75.00	75.00
1	WASHER TANK MOTOR (CONSISTENT)	NOT NECESSARY	85.00	-
1	AUTO OIL (CONSISTENT)	NECESSARY	48.00	48.00
1	POWER STEERING TANK (CONSISTENT)	CRACKED	80.00	80.00
1	POWER STEERING PUMP (CONSISTENT)	DAMAGED	850.00	850.00
1	POWER STEERING PUMP BRACKET (CONSISTENT)	BENT	125.00	125.00
1	ALTERNATOR (CONSISTENT)	NOT NECESSARY	850.00	-
1	AIRCON COMPRESSOR (CONSISTENT)	NOT NECESSARY	650.00	-
1	WATER PUMP (CONSISTENT)	DAMAGED	160.00	160.00
1	WATER PUMP PULLEY (CONSISTENT)	NOT NECESSARY	75.00	-
1	FAN BELT (CONSISTENT)	SNAPPED	55.00	55.00
1	FRT ENGINE MOUNTING (CONSISTENT)	TORN	85.00	85.00
1	REAR ENGINE MOUNTING (CONSISTENT)	TORN	85.00	85.00
1	RH ENGINE MOUNTING (CONSISTENT)	TORN	135.00	135.00
1	LH ENGINE MOUNTING (CONSISTENT)	TORN	135.00	135.00
1	FRT RH WHEEL HOUSING PANEL (CONSISTENT)	DISTORTED	900.00	900.00
1	FRT RH CHASSISMEMBER (CONSISTENT)	TO REPAIR SEE LABOUR	950.00	-
1	FRT RH FENDER (CONSISTENT)	DISTORTED	295.00	295.00
2	FRT FENDER INNER COWLING (CONSISTENT)	TORN	156.00	156.00
20	INNER COWLING CLIP (CONSISTENT)	NECESSARY	40.00	40.00
1	FRT RH FENDER SIGNAL LAMP (CONSISTENT)	NOT NECESSARY	25.00	-
1	POWER STEERING PIPE (CONSISTENT)	NOT NECESSARY	175.00	-
1	POWER STEERING HOSE (CONSISTENT)	NOT NECESSARY	75.00	-
1	FRT FENDER TOP CORNER GARNISH RH (CONSISTENT)	MISSING	25.00	25.00
1	FRT SHOCK ABSORBER RH (CONSISTENT)	NOT NECESSARY	225.00	-
1	FRT KNUCKLE ARM RH (CONSISTENT)	NOT NECESSARY	250.00	-
1	FRT KNUCKLE ARM BEARING RH (CONSISTENT)	NOT NECESSARY	120.00	-
1	FRT LOWER ARM RH (CONSISTENT)	NOT NECESSARY	195.00	-
1	FRT CENTER CROSSMEMBER (CONSISTENT)	NOT NECESSARY	215.00	-
2	ENGINE UNDER COVER (CONSISTENT)	TORN	116.00	116.00
10	UNDER COVER CLIP (CONSISTENT)	NECESSARY	20.00	20.00

Report Ref No. CS/ASM18004918/Atbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ENGINE SIDE COVER RH (CONSISTENT)	TORN	55.00	55.00
6	SIDE COVER CLIP (CONSISTENT)	NECESSARY	12.00	12.00
1	WIPER GARNISH (CONSISTENT)	DEFORMED	100.00	100.00
1	WIPER CORNER GARNISH RH (CONSISTENT)	DEFORMED	28.00	28.00
1	GRILLE LOGO (CONSISTENT)	NECESSARY	20.00	20.00
1	TIMING COVER TOP (CONSISTENT) (ADDITIONAL)	CRACKED	85.00	85.00
1	TIMING COVER LOWER (CONSISTENT) (ADDITIONAL)	CRACKED	85.00	85.00
1	FRT EXHAUST MANIFOLD (CONSISTENT) (ADDITIONAL)	DENTED	750.00	750.00
			14,217.00	9,359.00
	<u>SPECIAL NETT ITEMS</u>			
1	FRT WINDSCREEN GUM (SN) (CONSISTENT)	NECESSARY	65.00	65.00
1	RADIATOR COOLANT (SN) (CONSISTENT)	NECESSARY	25.00	25.00
1	HEADLAMP BULB (SN) (CONSISTENT)	SMASHED	30.00	20.00
1	SMALL LAMP BULB (SN) (CONSISTENT)	SMASHED	25.00	15.00
1	SIGNAL LAMP BULB (SN) (CONSISTENT)	SMASHED	20.00	15.00
1	POWER STEERING OIL (SN) (CONSISTENT)	NECESSARY	25.00	25.00
			190.00	165.00
	<u>LABOUR</u>			
	WIRE CHECKING.		20.00	20.00
	REMOVE & REFIX AIRCON AND GAS.		100.00	100.00
	REMOVE & REFIX FRT WINDSCREEN.		120.00	100.00
	REMOVE & REFIX ENGINE.		350.00	350.00
	REMOVE & REFIX POWER STEERING PUMP, ALTERNATOR & AIRCON COMPRESSOR.		180.00	180.00
	REMOVE & REFIX 1 SET ENGINE MOUNTING.		150.00	150.00
	REMOVE & REFIX FRT UNDERCARRIAGE.	NOT NECESSARY	250.00	-
	WHEEL ALIGNMENT.		65.00	65.00
	REPAIR WIRE HARNESS.	NOT NECESSARY	120.00	-
	LABOUR CHARGE. INCLUSIVE OF THE REPAIR OF FRT RH CHASSISMEMBER.		2,000.00	1,500.00
	SPRAY PAINTING.		1,500.00	1,200.00
			4,855.00	3,665.00
	GRAND TOTAL		19,262.00	13,189.00

Report Ref No. CS/ASM18004918/Atbe2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,500.00
---	--	--	----------

Report Ref No. CS/ASM18004918/Atbe2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.