

[illegible]

	AFFECTED AREAS.			
4	TO TRANSFER WINDOW MECHANISM FROM DAMAGE DOOR TO NEW DOOR & CHECK FUNCTION ABILITY	NETT		\$ 780.00 ✓
5	TO CHECK STEERING GEOMETRY & CONDUCT WHEEL ALIGNMENT ACCORDING TO SPECIFICATIONS.	NETT		\$ 680.00 X
6	TO REMOVE / REPLACE TYRES & RIMS @ \$60/-			\$ 60.00 X
7	TO SUPPLY 1 PCS TYRE \$980.00 ea			\$ 980.00 X
8	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES AFTER ACCIDENT REPAIR.	NETT		\$ 600.00 ✓
9	TO SUPPLY 1 PC NO PLATE \$70.00 EA	NETT		\$ 70.00 X
10	SUNDRIES.			\$ 100.00
		TOTAL LABOUR		\$ 12,110.00
		TOTAL PARTS		\$ 5,822.88
		GRAND TOTAL		\$ 17,932.88

Please note that this is **only an estimate**, base on our visual inspection. However should there be any additional work be found necessary in the course of repair and thus additional parts, materials and labor cost will be deem necessary, you will be inform accordingly prior to any action taken. In view of this, expected delays will be indivertible and therefore additional working days will be required. As such the loss of use and other incidentals will be adjusted accordingly.

Prepared By

Acknowledge By

Sebastian.
15/3/18.

- Part by part repair.
- Question Mark Item
Photo
- Photo Before Paint
Excess : \$2000
Authorized.

6 days.

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--

9003614

sebastianyang@lkkauto.com