

CO. REG. NO: 199402370D

GST NO: M2-0123250-3

KIM HIN AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkimhin.com.sg

No. : 29631

Your Reference : GA125994

Accident Date : 13-Mar-2018

Date : 15-Mar-2018

Our Ref : 180199 / SHUMAN

PAGE : 1

HO JIE SHENG JASON (MR)
C/O AXA INSURANCE PRIVATE LIMITED
8 SHERENTON WAY
#24-01 AXA TOWER
Singapore 068811

Not Authorised
61 Rps 8?
Putting After Paint
5 days
Ex @ 4000

ESTIMATED COST OF REPAIR FOR TOYOTA WISH 1.8 A (2006) SGN5145B

1 pc	front bumper		<i>Rh</i>	195.00	c	✓
1 pc	front bumper side retainer-LH		<i>DR</i>	25.00	c	✓
1 pc	front bumper side retainer-RH		<i>DR</i>	25.00	c	✓
1 pc	front bumper sponge			50.00	c	?
1 pc	front bumper reinforcement		<i>Rh</i>	95.00	c	✓
1 pc	front bumper reinforcement bracket-LH			35.00	c	?
1 pc	front bumper reinforcement bracket-RH			35.00	c	?
10 pcs	front bumper clips	@ S\$ 1.50	<i>Rh</i>	15.00	c	✓
1 pc	front bumper fog cover-LH		<i>Rh</i>	20.00	c	✓
1 pc	front bumper fog cover-RH		<i>Rh</i>	20.00	c	✓
1 pc	front bumper centre lower grille			55.00	c	?
1 pc	front grille		<i>Rh</i>	50.00	c	✓
1 pc	front grille side rubber stopper-LH		<i>Rh</i>	12.00	c	✓
1 pc	front grille side rubber stopper-RH		<i>Rh</i>	12.00	c	✓
1 pc	headlamp assy-LH		<i>my cm</i>	265.00	c	✓
1 pc	headlamp assy-RH		<i>cm</i>	265.00	c	✓
1 pc	front support panel		<i>Rh</i>	420.00	c	✓
1 pc	front brace panel		<i>Rh</i>	55.00	c	✓
2 pcs	horn	@ S\$ 60.00		120.00	c	?
1 pc	aircon condenser			240.00	c	?
1 pc	aircon liquid pipe		<i>Rh</i>	215.00	c	✓

Con't Page 2 ...

CO. REG. NO: 199402370D

GST NO: M2-0123250-3

KIM HIN AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkimhin.com.sg

Your Reference : GA125994

Our Ref : 180199

Page : 2

No. : 29631

1 pc aircon discharge pipe
 1 pc radiator
 1 pc radiator top hose
 1 pc radiator fan cowling
 1 pc radiator fan blade
 1 pc radiator fan motor
 1 pc bonnet
 1 pc bonnet lock
 1 pc bonnet outer chrome
 1 pc bonnet insulation
 8 pcs bonnet insulation clips @ S\$ 2.00
 1 pc bonnet hinges-LH
 1 pc bonnet hinges-RH
 1 pc front fender-LH
 1 pc front fender-RH
 1 pc front fender inner shield-LH
 1 pc front fender inner shield-RH
 16 pcs front fender inner shield clip @ S\$ 1.50
 1 pc front number plate
 1 pc radiator coolant

Sn 185.00 eX
 480.00 e 7
 Sn 35.00 eX
 95.00 e 7
 55.00 e 7
 135.00 e 7
 Bux 185.00 e ✓
 D11 45.00 e ✓
 Wap 85.00 e ✓
 Sn 115.00 eX
 16.00 eX
 35.00 eX
 35.00 eX
 R 185.00 eX
 R 185.00 eX
 Sn 65.00 eX
 Sn 65.00 eX
 24.00 eX
 40.00 sn ✓
 48.00 sn 20sn

To remove, cut out damaged parts,
 panel beating, welding, align,
 refix and to renew affected parts.

750.00 6001

To remove aircon condenser, pipes
 and driers. Vacuum and recharge gas

100.00 ✓

To putty and respray on affected
 portions.

950.00 6001

To focus headlamps. To check front
 wiring and lighting operation.

50.00 201

Total : S\$ 6,187.00

=====

Singapore Dollars Six Thousand One Hundred and
 Eighty Seven Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.