



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLS1342P
Date of Accident : 26 January 2018

Messrs Tan Hock Bee

Date : 19 March 2018

Estimate To Repair GBB5331C - Toyota Hiace Manual
Chassis No : JTFHT02P700043035

S/No	Quantity	Description	Amount
07		<u>LABOUR & MISC. CHARGES</u> To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 11 250.00
			\$ 2,980.00
		Total	\$ 7,926.15