

AIG Building
78 Shenton Way #07-16
Singapore 079120

3RD PARTY CLAIM ESTIMATION

Vehicle number	SLJ4293A
Make / Model	TOYOTA/ALTIS
Chassis number	MR053REH104560569
Accident date	12 March 2018
Reference	1803-12

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	REAR RH DOOR PANEL <i>enc</i>	751.35 ✓
1	REAR RH TOP MOULDING <i>src</i>	171.58 X
1	REAR RH DOOR INNER TRIM <i>mounty crack</i>	698.40 ✓
1	REAR RH DOOR LOCK ASSY <i>Down</i>	325.44 ✓
1	REAR RH DOOR REGULATOR ASSY <i>St</i>	198.40 686.52 ✓
1	REAR RH FENDER <i>enc</i>	1173.60 ✓
1	REAR RH FENDER INNER TRIM <i>MM</i>	422.40 X
1	REAR RH FENDER INNER SHIELD <i>MM</i>	110.00 X
1	REAR WINDSCREEN MOULDING <i>enc</i>	93.60 ✓
1	REAR BUMPER <i>enc</i>	582.00 X
2	REAR BUMPER BRACKET <i>src</i>	78.00 X
2	REAR BUMPER RETAINER <i>src</i>	104.00 X
1	REAR RH KNUCKLE <i>distorted</i>	697.20 ✓
1	REAR RH WHEEL HUB BEARING <i>Down</i>	281.90 ✓
1	REAR RH LOWER ARM <i>MS</i>	332.52 X
		4219.89
		3164.91
	Less 25 %	6508.51
	Subtotal	1627.12
		4881.39
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
	Balance B/F	4881.39
1	RIM <i>enc</i>	600.00 350/-
1 SET	REAR BUMPER CLIP <i>src</i>	60.00 X
1 SET	REAR FENDER INNER TRIM CLIP <i>MM</i>	50.00 X
1	JOINT SEALANT <i>enc</i>	150.00 40/-
1	WINDSCREEN SEALANT <i>enc</i>	150.00 40/-
1	BRAKE FLUID <i>MM</i>	50.00 X
		430.00
	Subtotal	1060.00
	Balance C/F	5941.39
LABOUR AND MISCELLANEOUS CHARGES		
	Balance B/F	5941.39
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 MM
2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	150.00 80/-
3	REMOVE AND REFIT REAR WINDSCREEN	150.00 120/-
4	TRANSFER PART, ATTACHEMENT FROM OLD REAR DOOR TO NEW	200.00 60/-
5	CHECK REAR WHEEL ALIGNMENT	150.00 60/-
6	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS <i>1710.00</i>	200.00 150/-
7	PANEL BEATING ON AFFECTED AREAS	1400.00 600/-
8	SPRAY PAINTING ON AFFECTED AREAS	1500.00 600/-
9	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40/-
	Subtotal	3960.00
	Grand total	9901.39

5304.91

14/03/2018 e 1100hrs
Mr Anthony
LKK Auto

Supp 2059.35
7364.26
1/5 5800/-



TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
ROC: 201015366H

3RD PARTY CLAIM ESTIMATION

Vehicle number	SLJ4293A
Make / Model	TOYOTA/ALTIS
Chassis number	MR053REH104560569
Accident date	12 March 2018
Reference	1803-12

AIG Building
78 Shenton Way #07-16
Singapore 079120

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	REAR RH DOOR OUTER HANDLE <i>distorted</i>	150.00 ✓
1	REAR RH SHOCK ABSORBER <i>distorted</i>	204.00 ✓
1	REAR CROSS MEMBER <i>distorted</i>	2850.00 ✓
		3204.00
Less 25 %		801.00
Subtotal		2403.00

2391.80

[Signature]
LKK Auto

2745.80

2059.35

[Signature]