



# 創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,  
Spray-Painting, Mechanical Repair And Customizing of Cars  
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724  
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723  
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg  
Bus. Reg. No. 251513/00M

DA/FWD (SKJ5437H)  
DOA: 08/03/2018@080

FWD SINGAPORE PTE LTD

14/3/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM  
ESTIMATE COST OF REPAIR FOR VEHICLE NO:  
SGP 5599 S - FORD FOCTA4  
CHASSIS NO: WF04XXWPD45B46767 (04/2006)

1 pc	Rear boot logo	\$	65.00	rel
1 pc	Rear boot 'FOCUS' emblem	\$	66.00	rel
1 pc	Rear bumper	\$	920.00	de
1 pc	Rear bumper protector LH	\$	125.00	de
1 pc	Rear bumper protector CTR	\$	230.00	de
1 pc	Rear bumper protector RH	\$	125.00	?
1 pc	Rear bumper reinforcement	\$	408.00	?
		\$	1,939.00	
	LESS 20%	\$	387.80	
		\$	1,551.20	

1 set Reverse Sensor \$ 200.00 nu ✓

Remove necessary parts: jacking, panel beating, repair and  
straighten rear inner panel, rear end panel, rear boot and  
rear bumper.

\$ 500.00

Putty and respray rear inner panel, rear end panel, rear  
boot and rear bumper.

\$ 500.00

ADD 7% GST

\$ 2,751.20

\$ 192.58

\$ 2,943.78

Note: The above is an estimate only. IF other parts requested  
during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

LIK Auto Consultants hence notify  
the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tayfun 97495749  
- WOP  
21/3/18 2:57pm

4 days  
happy  
ready after repair  
sure@whatsapp