



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE S'PORE PTE LTD	Document No.	: SQT18000871	Page	1
	8 SHENTON WAY	Date	: 28. Feb 2018		
	#27-01 AXA TOWER	Customer No.	: WZA006		
	SINGAPORE 068811	Svc Advisor	:		
Registration No	: SJS448Z	Engine No	: K24Z98502567		
Chassis No	: MRHRM3850GP000114	Date Time	: 28. Feb 2018 6:46:23 PM		
Model	: CRV 2.4L 2016 MODEL (EURO 4)	Surveyor Name	:		
Owner's Name	: CLARENCE LOW	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 23/2/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: LOW CLARENCE						
	OWNER INSURER: TOKIO MARINE						
	ACC DATE: 23/02/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: LIBERTY INSURANCE						
	TP VEH: SHB9552J						
BOSUN	SUNDRIES	1	50.00 ³⁰		50.00	3.50	53.50
BOJSE	SEALANT FOR TAILGATE	1	80.00 ✓		80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE WINDSCREEN	2	100.00 ✓		200.00	14.00	214.00
BOJSE	SEALANT FOR REAR END PANEL	1	80.00 ?		80.00	5.60	85.60
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	2250.00	20	1800.00	126.00	1926.00
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	280.00 ✓	20	224.00	15.68	239.68
BKB01K	REMOVE/REFIT BOOT TRIMS TO ASSIST REPAIR (N)	1	225.00 ✓	20	180.00	12.60	192.60
BKBOR	REMOVE/REINSTALL TAILGATE REVERSE CAMERA	1	180.00 ✓	20	144.00	10.08	154.08
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00 ✓	20	64.00	4.48	68.48
BA02R	REMOVE/REFIT RR BUMPER SENSORS	1	100.00 ✓	20	80.00	5.60	85.60
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2200.00	20	1760.00	123.20	1883.20
			2100				
				Sum Labor	4662.00	326.34	4,988.34
RS-4CS	4PCS CORNER SENSOR W DISPLAY	1	272.00 ✓		272.00	19.04	291.04
65741-T0A-A00ZZ	CROSS MEMBERRR.FLOOR UPPER	1	108.80 ?	35	70.72	4.95	75.67
66100-T0A-J00ZZ	PANEL COMPRR.	1	470.00 ?	35	305.50	21.39	326.89
75717-SNB-E01	STICKER I-VTEC	1	12.40 ✓	35	8.06	0.56	8.62
91501-S70-003	FASTENER BW/SHIELD	4	3.20 ✓	35	8.32	0.58	8.90
91502-S70-003	FASTENER B	2	4.90 ✓	35	6.37	0.45	6.82
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50 ✓	35	4.55	0.32	4.87



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SJS448Z
Chassis No : MRHRM3850GP000114
Model : CRV 2.4L 2016 MODEL (EURO 4)
Owner's Name : CLARENCE LOW
Ins Policy No :
Date of Accident : 23/2/2018

Document No. : SQT18000871
Date : 28. Feb 2018
Customer No. : WZA006
Svc Advisor :
Engine No : K24Z98502567
Date | Time : 28. Feb 2018 6:46:23 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
73226-SZW-000	DAMPERSTD 5X5	3	8.30 <i>nd</i>	35	16.18	1.13	17.31
74895-T0N-T01ZJ	GARNISH ASSYTAILGATE NSE	1	274.90 <i>de</i>	35	178.68	12.51	191.19
68100-T0Y-E50ZZ	TAILGATECOMP	1	781.90 <i>bt</i>	35	508.23	35.58	543.81
74440-T0A-J01	WEATHERSTRIPTAILGATE	1	100.70 <i>nd</i>	35	65.45	4.58	70.03
74890-TFA-U10	GARNISH ASSYRR.LICENSE	1	236.40 ?	35	153.66	10.76	164.42
75722-T0N-T00	EMBLEMRR.	1	20.30 <i>nd</i>	35	13.19	0.92	14.11
04715-T1W-A00ZZ	FACERR.BUMPER	1	609.40 <i>de</i>	35	396.11	27.73	423.84
33505-T1W-A01	REFLECTOR ASSYRR.RR.	1	54.00 <i>dis</i>	35	35.10	2.46	37.56
33555-T1W-A01	REFLECTOR ASSYL.RR.	1	54.00 X	35	35.10	2.46	37.56
71502-TFA-T00	FACERR.R.BUMPER LOWER	1	64.50 <i>det</i>	35	41.92	2.93	44.85
71507-TFA-T00	FACERR.L.BUMPER LOWER	1	64.50 X	35	41.92	2.93	44.85
71510-TFA-T20	GARNISHRR.BUMPER LOWER	1	144.80 <i>de</i>	35	94.12	6.59	100.71
71593-T1W-A01	SPACERR.RR.BUMPER SIDE	1	13.40 <i>nd</i>	35	8.71	0.61	9.32
71598-T1W-A01	SPACERL.RR.BUMPER SIDE	1	13.40 <i>nd</i>	35	8.71	0.61	9.32
91505-TM8-003	CLIPBUMPER	15	2.00 ?	35	19.50	1.37	20.87
Sum Item					2292.10	160.46	2,452.56

Survey By *Tanpin 97495749*

Date & Time *21/3/18 @ 1115*

Excess *wp*

Status

Signature *[Signature]*

Total Amount 6,954.10 486.80 7,440.90

Total (Inclusive of GST) 7,440.90

*6-8 days
Repair before paint
sur @ lkk auto wun.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 1/3/2018 11:34:49 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)