

REPAIR ESTIMATE*

VEHICLE NO : SH 6678M

DATE 14/3/2018 15:21

MAKE :

MODEL : HYUNDAI i40

LKR/Kalwai

P6yP

Like

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Wheel Rim (LH) X			\$ 297.10
	Front Wheel Hub Cap(LH) ✓			\$ 150.70
	Front Wheel Bearing ?			\$ 258.50
	Front Shock Absorber (Assy) (LH) ?			\$ 212.65
	Front Shock Absorber Mounting (LH) ?			\$ 75.10
	Front Drive Shaft (LH) ?			\$ 1,069.55
	Rack & Pinion Assy ?			\$ 2,184.00
	STG Tie End ?			\$ 69.50
	Stabilizer Bar ?			\$ 222.50
	Stabilizer Bar Bush (LH) ?			\$ 13.50
	Stabilizer Bar Link ?			\$ 81.70
	Stabilizer Bracket ?			\$ 24.00
	Front Suspension Lower Arm (LH) ?			\$ 715.10
	Knuckle Arm (LH) ?			\$ 582.95
	SUB TOTAL			\$ 5,956.85
	LESS 20%			\$ 1,191.37
	DISCOUNTED TOTAL			\$ 4,765.48
	Front Rear Fender Advertisement Logo (LH) ✓			\$ 100.00
	Front Tyre (LH) X			\$ 216.00
				\$ 316.00
	Labour Charge			
	Panel Beating- Repair Bumper			\$ 250.00
	Spray Painting Charge- Bumper/Fender			\$ 500.00
	Tuff Kote			\$ 50.00
	Remove/Refix Undercarriage (FRT)			\$ 400.00
	FRT Wheel Alignment			\$ 120.00
	TOTAL LABOUR			\$ 1,320.00
	ESTIMATE TOTAL			\$ 6,401.48
	LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged parts during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - Supplementary item(s) are reserved and is subject to final approval by LKK Auto Consultants Company Acknowledge by Repairer Signature: <i>15/3/18</i> Date: <i>2 PIP Ashu Ram photo</i>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				