

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: AXA INSURANCE	DATE	: 14/03/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SGP3407Z		
MODEL	: TOYOTA WISH 1.8A	Vic	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 14-Mar-18
		TIME	: 14:40HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented,</i>	1	\$ 1,588.30	\$ 1,588.30
2	TAIL GATE HINGE <i>new</i>	2	\$ 69.00	\$ 138.00
3	TAILGATE DAMPER <i>new</i>	2	\$ 244.30	\$ 488.60
4	TAIL GATE TOP LOCK <i>new</i>	1	\$ 468.40	\$ 468.40
5	TAIL GATE LOWER CATCH <i>new</i>	1	\$ 62.00	\$ 62.00
6	TAIL GATE INNER TRIM <i>new</i>	1	\$ 422.00	\$ 422.00
7	TAILGATE WEATHER STRIP <i>cut</i>	1	\$ 366.20	\$ 366.20
8	TAILGATE DETECTOR <i>new</i>	1	\$ 112.20	\$ 112.20
9	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 165.00	\$ 165.00
10	REAR BUMPER <i>Dented</i>	1	\$ 688.30	\$ 688.30
11	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 72.00	\$ 144.00
12	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 52.00	\$ 104.00
13	REAR BUMPER STAY <i>Dented</i>	2	\$ 74.50	\$ 149.00
14	TAILLAMP <i>new</i>	2	\$ 411.20	\$ 822.40
15	REAR END PANEL <i>Dented,</i>	1	\$ 568.00	\$ 568.00
16	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 255.30	\$ 255.30

4908.60

TOTAL PRICE \$ 6,541.70

3681.45

LESS 25% \$ 1,635.43

SUB TOTAL PRICE

\$ 4,906.28

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Not on</i>	1	\$ 50.00	\$ 50.00
2	TAIL GATE SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
3	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
4	TAILGATE WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00
5	TAILGATE INNER TRIM BOARD CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
6	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
7	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 35.00	\$ 35.00
8	REAR END PANEL TOP GARNISH CLIPS (SET)	1	\$ 50.00	\$ 50.00
9	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00
10	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00
		380	TOTAL	\$ 745.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	800	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	800	
3	WIRING CHECK	\$ 150.00	30	
4	TUFF COAT	\$ 200.00	50	
5	REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIR	\$ 180.00	60	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 180.00	50	
7	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	100	
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$180.00	X	
9	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 150.00	X	
10	TRANSFER TAILGATE MECHANISM	\$ 180.00	80	

TOTAL

\$4,940.00

1970

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,651.28

TOTAL LABOUR COST : \$ 4,940.00

TOTAL REPAIR COST : \$ 10,591.28

APPROVED DETAILS

EXCESS :

NO. OF WORKING DAYS :

RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :

SURVEYED BY :

CONTACT NUMBER :

FAX NUMBER :

Admin by
H/S 14/03/18
06 days.

total: 6031.45

H/S: 4.8K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: