

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

14-Mar-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6019 Y

1 pc	Rear bumper ✓	\$ 696.00
1 pc	Rear bumper lower cover ✓	\$ 206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 ?	\$ 58.00
1 pc	Rear bumper inner sponge ?	\$ 114.00
1 pc	Rear bumper reinforcement ✓	\$ 607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 ?	\$ 106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ?	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ?	\$ 36.00
	<i>Rear Bmt 1-3 "CR02" ✓</i>	\$ 1,859.00
	Less 10%	\$ 185.90
		<u>\$ 1,673.10</u>

S/NETT

1 set	Rear bumper clips ✓	\$ 48.00
1 set	Reverse sensor <i>Bootlid Striker ✓ \$100</i>	\$ 280.00 200
	Sundry	\$ 50.00 20
	To dismantle / replace/test reverse sensor to new bumper and reset to the same	\$ 120.00 20
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 50
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel	\$ 650.00 400
	To putty and spray painting on rear bumper, bootlid, bootlid lower garnish, end panel <i>X</i>	\$ 800.00 360
	To apply rustproofing on the repaired and replaced panels.	\$ 200.00 X
		<u>\$ 4,001.10</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES

- As a Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kahar Ucy
14/3/18 1504
3 Apr.
4/5
After Repair photo