

INS. CASE OWNER:

WINNIE

CC

4 ASM
/AXA1800

4953, R1 W635

LKK:

IDAC:

Surveyor:

RASHI

DOI:

15/03/18

Date / Time:

15/3/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKH 1250R

Name of Insured:

UM SHEN

Insured Tel No.:

HP:

Excess Sec II :\$

D.O.A.:

12/3/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

JOSEPH UM JUNIOR

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

S8M00APH / 34759

Policy No.:

UN80452

Make / Model:

TOYOTA

Place of Accident:

PAYA LEBAR RD 7 QUINEMARK RD

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKH 30862



INSRS:

WSP:

Tel:

Liability:

RMKS:

Ding
Auto

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

16/3/18
v/c

SKH 30862 - X

SKH 1250R - F

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others: 100% STRAIGHT

20/03/18 @
11:57 AMcall OI. NO RESPONSE. STOKES TO OI.
OI was his wife. He confirmed
accident details in KUALA LUMPUR TP.
INFORMED TP CALL 4 NCD. He
agreed to talk to his wife/son.
DAD 9297 1503

@ 12:00 N

9000 to OI DAD. INFORMED STOKES.
NO INFO. SEND LETTER to BUNAL to OI.
BUNAL WILL NOT CLASH
MINALIZED
to LOD IN BY BUNAL

23/04/18

TYPE REPORT FOR WASTE APPROVAL

06/06/18

REPORT DONE.
9000 WASTAGE TO AXA BY SHARIF CHANG
AXA APPROVED WASTAGE.

PRELIMINARY ADVICE

Date/Time: 16/03/18

Sent By: LS

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

US

SS 5,000.00

(9 days)

Reduction:

59 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

20/06/18

Confirm with:

NICHOLAS

Email ☐ Call ☐

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

(w/term)

SS 5,243.00

(e.g. 4,900.00)

COID (BOLA - BOLA TP)

Loss of Rental (LOR):

SS

-

(days)

Loss of Use (LOU):

SS

600.00

x 10

(days)

Loss of Income (LOI):

SS

300.00

x 10

(days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$350.00

Total:

SS 6,340.00

Global Sum SS:

6,340.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

6,340.00

Name 1:

DING AUTO PTE LTD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

a/z)

[illegible]

(2/2)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18004953/R1hb3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 15-03-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKH 1250R	Veh. Inspected	SLH 3086Z	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	15/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/03/2018	Inspection Date		
Survey held at	DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

DING AUTO PTE LTD
Blk 10 Sin Ming Industrial Estate Sector C
#01-20

Singapore 575645

TO :

Tel: 6452 1208 Fax: 6452 0614

FAX NO:

ESTIMATE REPORT

1ST Quotation

14/03/2018 11:40

JOB-NO: 85008190

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD

CONTACT: 0

Page 1 of 2

ADDRESS: 50 UBI AVENUE 3

#01-12

SINGAPORE 408866

0

NIL

VEHICLE DETAILS

LICENSE NO: SLH3086Z

TRANS: AUTO

CHASSIS: MR053REH104559092

MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)

ENGINE: 1ZRY335873

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR DISP	REV PRICE
<u>LABOUR</u>							
1 R & R SEAT & CARPET TO ASSIT REPAIR	1.00	120.00	0.00	120.00		Y	60
2 R & R BOOT LID COMPARTMENT	1.00	100.00	0.00	100.00		Y	60
3 TO CHECK & REPAIR WIRING SYSTEM	1.00	100.00	0.00	100.00		Y	30
4 TO APPLY RUSTPROOFING / TUFFICOATING TREATMENT TO REPLACED	1.00	120.00	0.00	120.00		Y	60
5 R & R REAR BUMPER REVERSE SENSOR	1.00	150.00	0.00	150.00		Y	60
6 LABOUR CHARGE - TO REMOVE & REPLACE THE LISTED DAMAGED PARTS, KNOCK OUT DENTS ON THE AFFECTED PORTION, ADJUST & REALIGN TO THE SAME.	1.00	2,000.00	0.00	2,000.00		Y	2220 8000 10000
7 TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS. ETC BOOT LID INNER & OUTER, REAR BUMPER, LHS & RHS REAR FENDER, REAR END PANEL & REAR SPARE TYRE COMPARTMENT.	1.00	1,800.00	0.00	1,800.00		Y	1000

TOTAL:

4,390.00

0.00

4,390.00

MATERIALS

1 REAR BUMPER	1.00	535.00	133.75	401.25 ✓	L	Y	DE ✓
2 REAR BUMPER SIDE RETAINER (LONG)	2.00	210.00	52.50	157.50 ✓	L	Y	NE ✓
3 REAR BUMPER SIDE RETAINER (SHORT)	2.00	160.00	40.00	120.00 ✓	L	Y	NE ✓
4 REAR BUMPER CLIPS	10.00	40.00	10.00	30.00 ✓	L	Y	NE ✓
5 REAR BUMPER REFLECTORS	10.00	140.00	35.00	105.00 ✓	L	Y	SC ✓
6 REAR BUMPER REINFORCEMENT	1.00	385.00	96.25	288.75 ✓	L	Y	BT ✓
7 REAR BUMPER REINFORCEMENT ARM	2.00	210.00	52.50	157.50 ✓	L	Y	T BT ✓
8 REAR BUMPER SPONGE	1.00	95.00	23.75	71.25 ✓	L	Y	X SC ✓
9 BOOT LID	1.00	885.00	221.25	663.75 ✓	L	Y	BT ✓
10 BOOT LID "TOYOTA" EMBLEM	1.00	68.00	17.00	51.00 ✓	L	Y	NE ✓
11 BOOT LID "COROLLA" BADGE	1.00	64.00	16.00	48.00 ✓	L	Y	NE ✓
12 BOOT LID "ALTIS" BADGE	1.00	64.00	16.00	48.00 ✓	L	Y	NE ✓
13 BOOT LID HINGES	2.00	190.00	47.50	142.50 ✓	L	Y	X SC ✓
14 BOOT LID LOCK	1.00	355.00	88.75	266.25 ✓	L	Y	BT ✓
15 BOOT LID OUTER CHROME GARNISH	1.00	225.00	56.25	168.75 ✓	L	Y	X SC ✓
16 BOOT LID LICENCE PLATE LAMPS	2.00	34.00	8.50	25.50 ✓	L	Y	X SC ✓
17 REAR END PANEL	1.00	705.00	176.25	528.75 ✓	L	Y	BT ✓
18 REAR END PANEL TOP GARNISH	1.00	345.00	86.25	258.75 ✓	L	Y	DE ✓
19 REAR END PANEL TOP GARNISH CLIPS	10.00	35.00	8.75	26.25 ✓	L	Y	NE ✓

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP.	REV. PRICE
20 REAR END PANEL WEATHERSTRIP	1.00	185.00	46.25	138.75	L	Y	185
21 REAR END PANEL INNER CENTER TRIM	1.00	245.00	61.25	183.75	L	Y	245
22 REAR SPARE TYRE COMPARTMENT	1.00	785.00	196.25	588.75	L	Y	785
23 REAR SPARE TYRE COMPARTMENT FLOOR BOARD	1.00	415.00	103.75	311.25	L	Y	415
24 TAILLAMP OUTER	2.00	770.00	192.50	577.50	L	Y	770
25 TAILLAMP INNER	2.00	590.00	147.50	442.50	L	Y	590
26 TAILLAMP CLIPS	6.00	18.00	4.50	13.50	L	Y	18
27 REAR FENDERS	2.00	2,170.00	542.50	1,627.50	L	Y	2170
28 REAR FENDER INNER SHIELD CLIPS	20.00	70.00	17.50	52.50	L	Y	70
29 REAR REVERSE SENSORS	2.00	260.00	0.00	260.00	S	Y	260
30 REAR NO PLATE & CASING	1.00	60.00	0.00	60.00	S	Y	60
TOTAL:		10,313.00	498.25	7,814.75			
TOTAL PARTS & LABOUR:		14,703.00	2,498.25	12,204.75			

EXCESS/LOADING: \$ 0.00

No. Of Day: _____

RE-SURVEY: BEFORE AFTER PAINTING
PART-BY-PART OR LUMP SUM \$DATE OF SURVEY: 15 / 03 / 18 @ 1420SURVEYED BY: RASULCONTACT NO: 90010068 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

3828
200
2270
6298
206
5038.40

Rasul
Hr 90010068

7 days

48

15/03/18 @ 1420

Reay after rep

415-5000

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Service Request Details

Claim

S8M00APH

Reference

None

Loss Date

March 12, 2018

Request Date

March 14, 2018

Due Date

March 21, 2018

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

14/03/2018 @ 2:13pm
Ding Auto
249 Jln Boon Lay
Ravi

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLH3086Z

Make

TPVD TOYOTA

Service Address

...

Primary Contact/Insured

LIM SHEA

BLK 7 HAIG ROAD, #14-439, 430007, Singapore

Claim Handler

HO Winnie

6568804833

winnie.ho@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Vic (LKKAUTO)

From: Michelle <accounts@dingauto.sg>
Sent: Wednesday, 20 June, 2018 4:12 PM
To: Vic (LKKAUTO)
Cc: Kenneth Ding; Kelly Ding; Ding Ding Auto; Sales Ding Auto; Alex; You jingfeng
Subject: Re: (REF : CC4/ASM18004953/R1hb3) BILLING FOR SLH3086Z TP CLAIMS AGAINST SKH1250R ON 12/3/2018 LKK REF CC4/ASM18004953/R1hb3
Attachments: SLH3086Z (DV).pdf; SLH3086Z (REPAIR INVOICE).pdf

Dear Vic,

Please view attached file for signed DV and repair invoice.
We will also mail both DV and invoice to your office.

Kindly revert back regarding payment as soon as possible.
*NOTE : Payment is to be made to Ding Auto Pte Ltd

Thank you so much

Yours sincerely
Michelle Fang
92934128
Ding Auto Pte Ltd

On 20/6/2018 2:50 PM, Vic (LKKAUTO) wrote:

Without Prejudice

Dear Michelle,

We refer to your below email.

On a without prejudice basis and purely for an amicable settlement on a without admission of liability to our Insured's part, we have our principal's mandate and we offer to settle your client's claim at a global sum of **\$6,340.00** (all in).

If agreeable, kindly let the owner chop and sign the attached DV and forward back to us a copy together with the **FINAL REPAIR INVOICE** for our Principal to process the payment.

The above amount is to be made payable to **DING AUTO PTE LTD**.

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."



Accounts Ding Auto <accounts@dingauto.sg>

85008190 / SLH3086Z - FINALIZE AMOUNT

Rasul (LKKAuto) <Rasul@lkkauto.com>

Tue, Apr 3, 2018 at 10:09 AM

To: Kenneth Ding <kenneth.ding@dingauto.sg>, Accounts Ding Auto <accounts@dingauto.sg>, Kelly Ding <kelly.ding@dingauto.sg>

Cc: "Vic (LKKAuto)" <vicalpeh@lkkauto.com>, Vivian <vivian.tan@dingauto.sg>, yvonne wong <yvonne.wong@dingauto.sg>, You jingfeng <jingfeng@dingauto.sg>

Hi Kenneth,

Finalised amount is \$ 5,000.00 / 8 days lump sum

Kindly confirm

Best Regards,

Rasul | Assessor**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK
CONSULTANTS
PTE LTD*Save the Earth. Print only when necessary.*

From: Kenneth Ding [mailto:kenneth.ding@dingauto.sg]**Sent:** Wednesday, 28 March, 2018 5:20 PM**To:** 'Accounts Ding Auto'; Rasul (LKKAuto); 'Kelly Ding'**Cc:** Vic (LKKAuto); 'Vivian'; 'yvonne wong'; 'You jingfeng'**Subject:** RE: 85008190 / SLH3086Z - FINALIZE AMOUNT

[Quoted text hidden]

DING AUTO PTE LTD
Blk 10 Sin Ming Industrial Estate Sector C
#01-20

Singapore 675645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

14/03/2018 11:40

JOB-NO: 85008190

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD

CONTACT: 0

Page 1 of 2

ADDRESS: 50 UBI AVENUE 3

0

#01-12

NIL

SINGAPORE 408866

VEHICLE DETAILS

LICENSE NO: SLH3086Z

TRANS: AUTO

CHASSIS: MR053REH104559092

MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)

ENGINE: 1ZRY335873

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 R & R SEAT & CARPET TO ASSIT REPAIR	1.00	120.00	0.00	120.00	Y		60
2 R & R BOOT LID COMPARTMENT	1.00	100.00	0.00	100.00	Y		60
3 TO CHECK & REPAIR WIRING SYSTEM	1.00	100.00	0.00	100.00	Y		30
4 TO APPLY RUSTPROOFING / TUFFICOATING TREATMENT TO REPLACED	1.00	120.00	0.00	120.00	Y		60
5 R & R REAR BUMPER REVERSE SENSOR	1.00	150.00	0.00	150.00	Y		60
6 LABOUR CHARGE - TO REMOVE & REPLACE THE LISTED DAMAGED PARTS, KNOCK OUT DENTS ON THE AFFECTED PORTION, ADJUST & REALIGN TO THE SAME.	1.00	2,000.00	0.00	2,000.00	Y		2000
7 TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS. ETC BOOT LID INNER & OUTER, REAR BUMPER, LHS & RHS REAR FENDER, REAR END PANEL & REAR SPARE TYRE COMPARTMENT.	1.00	1,800.00	0.00	1,800.00	Y		1000
TOTAL:		4,390.00	0.00	4,390.00			

MATERIALS

1 REAR BUMPER	1.00	535.00	133.75	401.25	L	Y	DE
2 REAR BUMPER SIDE RETAINER (LONG)	2.00	210.00	52.50	157.50	L	Y	NE
3 REAR BUMPER SIDE RETAINER (SHORT)	2.00	160.00	40.00	120.00	L	Y	NE
4 REAR BUMPER CLIPS	10.00	40.00	10.00	30.00	L	Y	NE
5 REAR BUMPER REFLECTORS	1.00	140.00	35.00	105.00	L	Y	SC/4/24x
6 REAR BUMPER REINFORCEMENT	1.00	385.00	96.25	288.75	L	Y	BT
7 REAR BUMPER REINFORCEMENT ARM	2.00	210.00	52.50	157.50	L	Y	
8 REAR BUMPER SPONGE	1.00	95.00	23.75	71.25	L	Y	X
9 BOOT LID	1.00	885.00	221.25	663.75	L	Y	BT
10 BOOT LID "TOYOTA" EMBLEM	1.00	68.00	17.00	51.00	L	Y	NE
11 BOOT LID "COROLLA" BADGE	1.00	64.00	16.00	48.00	L	Y	NE
12 BOOT LID "ALTIS" BADGE	1.00	64.00	16.00	48.00	L	Y	NE
13 BOOT LID HINGES	2.00	190.00	47.50	142.50	L	Y	X
14 BOOT LID LOCK	1.00	355.00	88.75	266.25	L	Y	BT
15 BOOT LID OUTER CHROME GARNISH	1.00	225.00	56.25	168.75	L	Y	X
16 BOOT LID LICENCE PLATE LAMPS	2.00	34.00	8.50	25.50	L	Y	X
17 REAR END PANEL	1.00	705.00	176.25	528.75	L	Y	BT
18 REAR END PANEL TOP GARNISH	1.00	345.00	86.25	258.75	L	Y	DE
19 REAR END PANEL TOP GARNISH CLIPS	10.00	35.00	8.75	26.25	L	Y	NE

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
20 REAR END PANEL WEATHERSTRIP	1.00	185.00	46.25	138.75	L	Y	185 ✓
21 REAR END PANEL INNER CENTER TRIM	1.00	245.00	61.25	183.75	L	Y	245 ✓
22 REAR SPARE TYRE COMPARTMENT	1.00	785.00	196.25	588.75	L	Y	785 ✓
23 REAR SPARE TYRE COMPARTMENT FLOOR BOARD	1.00	415.00	103.75	311.25	L	Y	415 ✓
24 TAILLAMP OUTER	2.00	770.00	192.50	577.50	L	Y	770 ✓
25 TAILLAMP INNERS	2.00	590.00	147.50	442.50	L	Y	590 ✓
26 TAILLAMP CLIPS	6.00	18.00	4.50	13.50	L	Y	18 ✓
27 REAR FENDERS	2.00	2,170.00	542.50	1,627.50	L	Y	2170 ✓
28 REAR FENDER INNER SHIELD CLIPS	20.00	70.00	17.50	52.50	L	Y	70 ✓
29 REAR REVERSE SENSORS	2.00	260.00	0.00	260.00	S	Y	260 ✓
30 REAR NO PLATE & CASING	1.00	60.00	0.00	60.00	S	Y	60 ✓
TOTAL:		10,313.00	498.25	7,814.75			
TOTAL PARTS & LABOUR:		14,703.00	2,498.25	12,204.75			

EXCESS/LOADING:SS 0.00

No. Of Day: _____

RE-SURVEY: BEFORE AFTER PAINTING
PART-BY-PART OR LUMP SUM:SSDATE OF SURVEY: 15 / 03 / 18 @ 1420SURVEYED BY: RASULCONTACT NO: 90010068 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

0413 0962

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Accounts Ding Auto <accounts@dingauto.sg>

RE: UPDATE LIABILITY FOR ACCIDENT INVOLVING SLH3086Z & SKH1250R ON 12/03/2018 LKK REF CC4/ASM18004953/R1hb3

Vic (LKKAuto) <vicalpeh@lkkauto.com>

Tue, Mar 20, 2018 at 12:07 PM

To: Accounts Ding Auto <accounts@dingauto.sg>

Cc: Kenneth Ding <kenneth.ding@dingauto.sg>, You jingfeng <jingfeng@dingauto.sg>, yvonne wong <yvonne.wong@dingauto.sg>, Vivian <vivian.tan@dingauto.sg>, Admin A <admin-a@lkkauto.com>, "Vic (LKKAuto)" <vicalpeh@lkkauto.com>, "Asher Sng (LKKAuto)" <AsherSng@lkkauto.com>

WITHOUT PREJUDICE

Dear Michelle,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is clear.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle and admission of any liability to our Insured's part. The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Kindly forward the LOD and all supporting documents to us if available to proceed with the settlement.

Thank you.


Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Auto
Consultants
Pte Ltd*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Accounts Ding Auto [mailto:accounts@dingauto.sg]**Sent:** Tuesday, 20 March, 2018 9:28 AM**To:** Vic (LKKAuto)**Cc:** Kenneth Ding; You jingfeng; yvonne wong; Vivian**Subject:** UPDATE LIABILITY FOR ACCIDENT INVOLVING SLH3086Z & SKH1250R ON 12/03/2018

Satisfaction Voucher

Date: 24/03/2018

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Attention: CLAIMS DEPT

Dear Sir/Madam

Ahmad Hasan bin Zulkifli

I/We hereby acknowledge having received from Singapore Technologies Kinetics

Ltd., 249 Jalan Boon Lay, Singapore 619523, my/our vehicle number SLH3086Z

which has been repaired to my/our satisfaction and acceptance. I/We admit that

the payment of SGD _____ account for such repairs is in full discharge

of my/our claim upon the corporation under the policy number 999995417

reference claim number 85008190 in respect of the damage caused to the

said vehicle in an accident that occurred thereto or about the 12/03/2018

at PAYA LEBAR ROAD

Dated this day of _____, 201 _____

Signature: 

NRIC No: S9540278Z

Name: LION CITY RENTALS PTE.
LTD (FLEET)

Address: 50 UBI AVENUE 3
#01-12
SINGAPORE 408866

Company Stamp if applicable



SEEK MANDATE APPROVAL

Type

🔗 Question

Message

Hi Vic, pls revise to TP as below :- 1) COR to LS-\$4800 to \$4900 2) Loss of Use - \$60 x 10 days (recommend 8 days repair + sat & sun) 3) loss of income - \$50 x 10 days

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKH 1250R (Insd veh)	Model:	TOYOTA
	SLH 3086Z (TP veh)		COROLLA ALTIS CLASSIC
Date of Accident:	12/03/2018		1.6 CVT

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	13,059.08
Final Repair Cost	:	\$	5,243.00
Loss of Use	:	\$	600.00
Loss of Income	:	\$	500.00
LTA / GIA Search Fee	:	\$	2.00

Others: : \$

: \$

Final Settlement Sum (GLOBAL SUM) : \$ 6,340.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ 100 _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____	

Payment Instruction: Payee's Breakdown		
1)	DING AUTO PTE LTD	: \$ 6,340.00

NUR SHAQILAH BTE ABDOL
WAHAB

25/06/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

SERVICE REQUESTS

MESSAGES

CLAIMS

<<

Service Request Details

Claim	S8M00APH
Reference	
CC4/ASM18004953/R11663	Date
March 12, 2018	Request Date
March 14, 2018	Due Date
March 14, 2019	Vendor Name
LKK AUTO CONSULTANTS PTE Loss LTD (TP)	Type of
Third Party Vehicle Damage	Services

Vehicle Information	
Incident Vehicle	SLH3086Z
Registration #	TPVD TOYOTA
Make	COROLLA ALTIS-1.6
Model	CLASSIC CVT (A)
Primary Contact/Insured	
LIM SHEA	
BLK 7 HAIG ROAD, #14-439, 430007, Singapore	
Claim Handler	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 5, 2018
GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 5, 2018
WEEKLY EARNINGS.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 5, 2018
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	June 5, 2018
TP ESTIMATE-MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	March 16, 2018
Preliminary Advice.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	March 16, 2018
SKH1250R INSD GIA.PDF	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	March 14, 2018
EMAIL FROM WORKSHOP.msg	Letters and Correspondence	Workshop	NIKAM Santosh Pandurang	March 14, 2018

SERVICE REQUESTS MESSAGES CLAIMS

<< Service Request Details

Claim	S8M00APH	Vehicle Information	
Reference CC4/ASM18004953/R11b58  Date	Next Step	Incident Vehicle	SLH3086Z
		Registration #	TPVD TOYOTA
		Make	COROLLA ALTIS-1.6
		Service Address	CLASSIC CVT (A)
March 12, 2018	Request Date	Primary Contact/Insured	
March 14, 2018	Due Date	LIM SHEA	
March 14, 2019	Vendor Name	BLK 7 HAIG ROAD, #14-439,	
		430007, Singapore	
LKK AUTO CONSULTANTS PTE LOSS LTD (TP)	Type of	Claim Handler	
Third Party Vehicle Damage	Services		

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SLH3086Z

Purchase Date
mm/dd/yyyy

Registration State

SINGAPORE

Registration Date *

10/28/2016

Mileage

108296

Age of Vehicle

1

CATEGORY

Manufacturing Year

Driver Details

POLICY INFORMAT...

CATEGORY Driver Name

ASSESSMENT INFO...

2016

FNOL INFORMATI... HASAN BIN ZULKIFLI AHMAD

CATEGORY

Make

POST SURVEY INF...

CATEGORY	Engine No
POLICY INFORMAT ...	
ASSESSMENT INFO...	1ZRY335873
CATEGORY	Engine Capacity
POLICY INFORMAT ...	
ASSESSMENT INFO...	1598 cc
CATEGORY	Sum Insured
POLICY INFORMAT ...	
ASSESSMENT INFO...	0
CATEGORY	Market Value
POLICY INFORMAT ...	
ASSESSMENT INFO...	0

FNOL INFORMATI...	0
POST SURVEY INF...	
CATEGORY	Driver License #
FNOL INFORMATI...	
POST SURVEY INF...	
CATEGORY	License Type
FNOL INFORMATI...	
POST SURVEY INF...	
CATEGORY	License Issue Date
FNOL INFORMATI...	
POST SURVEY INF...	mm/dd/yyyy
CATEGORY	License Expiration Date
FNOL INFORMATI...	
POST SURVEY INF...	mm/dd/yyyy
CATEGORY	Address



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Front left side

TRIANGLE 5mm

Front right side

TRIANGLE 5mm

Rear left side

TRIANGLE 5mm

Rear right side

TRIANGLE 5mm

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details			Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	Parts			
EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
	1	1			REAR BUMPER			Deformed	535		25		401.25
	2	2			REAR BUMPER SIDE RETAINER (LONG)			Necessary	105		25		157.5
	3	2			REAR BUMPER SIDE RETAINER (SHORT)			Necessary	80		25		120
	4	10			REAR BUMPER CLIPS			Necessary	4		25		30
	5	2			REAR BUMPER REFLECTORS (1PC ONLY)			Damaged	35		25		52.5
	6	1			REAR BUMPER REINFORCEMENT			Bent	385		25		288.75
	7	2			REAR BUMPER REINFORCEMENT ARM			Bent	105		25		157.5
	8	1			REAR BUMPER SPONGE			Serviceable	0		25		0
	9	1			BOOT LID			Bent	885		25		663.75

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/STTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
	23	1			REAR SPARE TYRE COMPARTMENT FLOOR BOARD			Serviceable	0		25		0
	24	2			TAILLAMP OUTER			Cracked	385		25		577.5
	25	2			TAILLAMP INNERS			Serviceable	0		25		0
	26	6			TAILLAMP CLIPS			Necessary	3		25		13.5
	27	2			REAR FENDERS			Repair	0		25		0
	28	20			REAR FENDER INNER SHIELD CLIPS			Serviceable	0		25		0
Labour													
EDIT	SR NO	REPAIR/REPLACE (LABOUR)			PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)		COMMENT		
	1				R&R SEAT & CARPET TO ASSIST REPAIR.	60	0	0	Reviewing				
	2				TO R&R BOOT LID COMPARTMENT.	60	0	0	Reviewing				
	3				TO CHECK & REPAIR WIRING SYSTEM.	30	0	0	Reviewing				
	4				TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED.	60	0	0	Reviewing				
	5				R&R REAR BUMPER REVERSE SENSOR.	60	0	0	Reviewing				
	6				LABOUR CHARGE - TO REMOVE & REPLACE THE LISTED DAMAGES PARTS. KNOCK OUT DENTS ON THE AFFECTED PORTION, ADJUST & REALIGN TO THE SAME.	1000	0	0	Reviewing				

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐	1	DAYS OF REPAIR	Reviewing	8		
☐	2	REAR REVERSE SENSORS	Reviewing	200	NOT WORKING	
☐	3	REAR NO PLATE & CASING	Reviewing	0	SERVICEABLE	

SERVICE REQUESTS MESSAGES CLAIMS

<< **Assessment Details**

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary	Claim Amount	\$6,298.00	Claim Amount	\$6,298.00	

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$2,270.00	\$2,270.00
Miscellaneous	\$200.00	\$200.00

Submit for Review

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Add

Approve

Deny

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
------	-------	------	--------	--------	---------	--------

		1	FINAL LUMP SUM	Reviewing	4900	
--	--	---	----------------	-----------	------	--