

DING AUTO PTE LTD
Blk 10 Sin Ming Industrial Estate Sector C
#01-20

Singapore 675645

TO : Tel: 6452 1208 Fax: 6452 0614

FAX NO:

14/03/2018 11:40

JOB-NO: 85008190

ESTIMATE REPORT 1ST Quotation

Page 1 of 2

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD CONTACT: 0
ADDRESS: 50 UBI AVENUE 3 0
#01-12 NIL
SINGAPORE 408866

VEHICLE DETAILS

LICENSE NO: SLH3086Z TRANS: AUTO CHASSIS: MR053REH104559092
MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A) ENGINE: 1ZRY335873
OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.
JOB-CODE: TP SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 R & R SEAT & CARPET TO ASSIT REPAIR	1.00	120.00	0.00	120.00		Y	60
2 R & R BOOT LID COMPARTMENT	1.00	100.00	0.00	100.00		Y	60
3 TO CHECK & REPAIR WIRING SYSTEM	1.00	100.00	0.00	100.00		Y	30
4 TO APPLY RUSTPROOFING / TUFFICOATING TREATMENT TO REPLACED	1.00	120.00	0.00	120.00		Y	60
5 R & R REAR BUMPER REVERSE SENSOR	1.00	150.00	0.00	150.00		Y	60
6 LABOUR CHARGE - TO REMOVE & REPLACE THE LISTED DAMAGED PARTS, KNOCK OUT DENTS ON THE AFFECTED PORTION, ADJUST & REALIGN TO THE SAME.	1.00	2,000.00	0.00	2,000.00		Y	800/1000
7 TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS. ETC BOOT LID INNER & OUTER, REAR BUMPER, LHS & RHS REAR FENDER, REAR END PANEL & REAR SPARE TYRE COMPARTMENT.	1.00	1,800.00	0.00	1,800.00		Y	1000
TOTAL:		4,390.00	0.00	4,390.00			

MATERIALS

1 REAR BUMPER	1.00	535.00	133.75	401.25	L	Y	DE
2 REAR BUMPER SIDE RETAINER (LONG)	2.00	210.00	52.50	157.50	L	Y	NE
3 REAR BUMPER SIDE RETAINER (SHORT)	2.00	160.00	40.00	120.00	L	Y	NE
4 REAR BUMPER CLIPS	10.00	40.00	10.00	30.00	L	Y	NE
5 REAR BUMPER REFLECTORS	1/2	140.00	35.00	105.00	AGREED	Y	SCA/WH/PA
6 REAR BUMPER REINFORCEMENT	1.00	385.00	96.25	288.75	L	Y	BT
7 REAR BUMPER REINFORCEMENT ARM	2.00	210.00	52.50	157.50	L	Y	?
8 REAR BUMPER SPONGE	1.00	95.00	23.75	71.25	L	Y	X
9 BOOT LID	1.00	885.00	221.25	663.75	L	Y	BT
10 BOOT LID "TOYOTA" EMBLEM	1.00	68.00	17.00	51.00	L	Y	NE
11 BOOT LID "COROLLA" BADGE	1.00	64.00	16.00	48.00	L	Y	NE
12 BOOT LID "ALTIS" BADGE	1.00	64.00	16.00	48.00	L	Y	NE
13 BOOT LID HINGES	2.00	190.00	47.50	142.50	L	Y	X
14 BOOT LID LOCK	1.00	355.00	88.75	266.25	L	Y	PA
15 BOOT LID OUTER CHROME GARNISH	1.00	225.00	56.25	168.75	L	Y	X
16 BOOT LID LICENCE PLATE LAMPS	2.00	34.00	8.50	25.50	L	Y	X
17 REAR END PANEL	1.00	705.00	176.25	528.75	L	Y	PA
18 REAR END PANEL TOP GARNISH	1.00	345.00	86.25	258.75	L	Y	DE
19 REAR END PANEL TOP GARNISH CLIPS	10.00	35.00	8.75	26.25	L	Y	NE

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
20 REAR END PANEL WEATHERSTRIP	1.00	185.00	46.25	138.75	L	Y	na ✓
21 REAR END PANEL INNER CENTER TRIM	1.00	245.00	61.25	183.75	L	Y	X
22 REAR SPARE TYRE COMPARTMENT	1.00	785.00	196.25	588.75	L	Y	X
23 REAR SPARE TYRE COMPARTMENT FLOOR BOARD	1.00	415.00	103.75	311.25	L	Y	X
24 TAILLAMP OUTER	2.00	770.00	192.50	577.50	L	Y	CRA ✓
25 TAILLAMP INNERS	2.00	590.00	147.50	442.50	L	Y	X
26 TAILLAMP CLIPS	6.00	18.00	4.50	13.50	L	Y	na ✓
27 REAR FENDERS	2.00	2,170.00	542.50	1,627.50	L	Y	R
28 REAR FENDER INNER SHIELD CLIPS	20.00	70.00	17.50	52.50	L	Y	X
29 REAR REVERSE SENSORS	2.00	260.00	0.00	260.00 200	S	Y	na ✓
30 REAR NO PLATE & CASING	1.00	60.00	0.00	60.00	S	Y	X
TOTAL:		10,313.00	498.25	7,814.75			
TOTAL PARTS & LABOUR:		14,703.00	2,498.25	12,204.75			

EXCESS/LOADING:\$ 0.00

No. Of Day:

RE-SURVEY: BEFORE AFTER PAINTING
PART-BY-PART OF LUMP SUM \$

DATE OF SURVEY: 15 / 03 / 18 @ 1420

SURVEYED BY: RASUL

CONTACT NO: 90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
7 days
4/3
15/03/18 @ 1420
Resay after rep