

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : **BP 3594**
Date Estimated : **14/03/2018**
Prepared By : **Wong Guo Xiang**

Page No. : **1 of 1**

- ESTIMATE REPAIR FOR -

Lim Mae-Lynn(Lin Meiling)
103 Spottiswoode Park Road
#09-104

Singapore 080103

- ACCOUNT - **2000**

CASH - Sale service
.

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLT7523P	VF3LPHNYWHS153323	10/11/2017	3081.2 Allure17	0

DESCRIPTION	VALUE
SUNDRIES	150.00
REPLACE / REPAIR REAR RHS FENDER,REAR BUMPER	1,200.00
RESPRAY REAR RHS FENDER,REAR BUMPER	1,800.00
WIRING CONNECTION & CHECK (NETT)	150.00
REMOVE & REFIX REAR LIGHTIN G SYSTEM (NETT)	150.00
REMOVE & REFIX REVERSE SENSOR (NETT)	150.00
TUFF KOTE @ \$60 PER PANEL	60.00
TO CONDUCT ECU COMPUTER DIAGNOSTIC INCLUDING CLEAR FAULT CODE (NETT)	600.00

Total Labour 1: **4,260.00**

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
1610767180	REAR BUMPER - TO BE PAINTED	1	700.00	10.00	630.00
1610767480	RR BUMPER SIDE BRACKET SET	1	60.00	10.00	54.00
9677817580	REAR WING LIGHT RH	1	206.00	10.00	185.40

Total Parts : **869.40**

Customer Service Officer

Contact

Labour 1	:	4,260.00
Parts	:	869.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	359.06
Grand Total	:	5,488.46

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.