

Signature:

REF:

NS/INC18004965/Srbor

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____


Insured: SJM 542RPolicy No. 3095768189 16.11.17 - 15.11.18Claims No. MT/0985967-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHF 7E Yr Regn: 17/12/1017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius 4 C.C. 1798Colour Maroon A/C: Insured / Std / NI / NASp. Reading 10873 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 370EB 3FH 603550707

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modt: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 13/3/18 D.O.I. 14/3/18Survey held at SMART

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time / Action / Instruction

SHF 7E - NS/INC18004965/Srbor

NA: 050516

TAX/03/18/2064

SJM 542R - X

CIC

NTUC

Confirm \$4284.50, 5 days

Red: \$2099.60, 65%

SJM 542R

RECEIVED 22 APR 2018

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 51) typist
Date/Time, File Return to?☒ : Final ReportResurvey No. of Trip: 3Survey Fee: 160

2) _____

Add Fee: ☐ : Site Insp (\$ _____) S+RS. \$☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Orders☐ : Weekend (\$ _____)Report Format: TPLump Sum / I.B.I.: (\$ 4284.50)

TOTAL

16039199

TP Claims against NTUC Income: Follow-Through Survey

Date : 04/04/2018

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/0984098-002	SMRT TAXIS PTE LTD	SHB 5366G	SKA 7181D	28/02/2018	\$ 7,797.23	\$ 2,550.00
2	MT/0988982-001	SMRT TAXIS PTE LTD	SHC 4926S	SJK 1772Y	19/03/2018	\$ 2,842.70	\$ 550.00
3	MT/0988428-002	COMFORTDELGRO	SHA 4969D	SCE 4477U	02/04/2018	\$ 1,303.30	\$ 480.00
4	MT/0988889-002	COMFORTDELGRO	SH 6484E	SIG 4840K	31/03/2018	\$ 2,381.58	\$ 1,050.00
5	MT/0984196-002	SMRT TAXIS PTE LTD	SHC 4004C	GU 9556K	01/03/2018	\$ 10,777.84	\$ 3,750.00
6	MT/0987457-002	SMRT TAXIS PTE LTD	SHB 5197C	SLK 4501U	16/03/2018	\$ 5,230.50	\$ 920.00
7	MT/0981513-002	SMRT BUS	SMB 5057P	SLU 2644B	06/02/2018	\$ 1,540.00	\$ 700.00
8	MT/0981716-002	SMRT BUS	SG 5494M	SIG 6853K	08/02/2018	\$ 1,927.00	\$ 1,590.00
9	MT/0985967-002	SMRT TAXIS PTE LTD	SHF 7E	SJM 542R	13/03/2018	\$ 12,384.10	\$ 4,284.50

Claim received from LKK Auto



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18004965/Srb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 Date: 15-03-2018



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJM 542R	Veh. Inspected	SHF 7E
Policy No.	5095968189	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	14/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	13/03/2018	Inspection Date	14/03/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No. (For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	S095968189	SHABUDIN BIN AHMAD	S1593688C	GCV	Third Party, Fire & Theft	SJM542R	SJM542R	16/11/2017	15/11/2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/03/2018 11:33
Date Of Accident	13/03/2018 17:55
Exact Location Of Accident	BKE TOWARDS WOODLANDS (BEFORE MANDAI EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF7E
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

Driver

Name of Driver	LIM CHENG HIONG
NRIC No	S1623556C
Date Of Birth	15/10/1963
Occupation	OUTDOOR
Date Of Driving Pass	01/12/1997
Driving Experience	20 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address 08-484
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - RELIEF
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : UNKNOWN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS STATIONARY ALONG BKE TOWARDS WOODLANDS (BEFORE MANDAI EXIT) WITH ONE PASSENGER (CHINESE FEMALE) ON BOARD AS ALL THE VEHICLES STOPPED. A VEHICLE SJM542R WHICH WAS BEHIND MY TAXI SLOWED DOWN TO STOP AS WELL. SUDDENLY A VEHICLE YP8333G WHICH WAS BEHIND SJM542R FAILED TO STOP AND COLLIDED ONTO SJM542R THE IMPACT PUSHED SJM542R TO COLLIDED ONTO THE REAR OF MY TAXI.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FIEL TOO BIG
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJM542R
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver SHABUDINBIN AHMAD
 NRIC/Passport Number S1598688C
 Contact Number
 Address
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

YP8333G

Vehicle Make/Model/Colour

Details Of Properties

LEO ONG CONSTRUCTION PTE LTD

Vehicle Category

GOODS VEHICLE

Name of Driver

GOVINDHARASU KANNAN

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

BRE towards Woodlands (Before Mandai Exit)

C-YP8333G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Cheng
Driver's Signature
(If driver is not the policyholder)
Date & Time:

14/3/2018
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


SMRT Accident Vehicle Repair Estimates

NTUC

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF7E
 Ref. No : TAX/03/18/2064
 Reg. Date : 19/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : LIM CHENG HIONG
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 13/03/2018 05:56:00 PM
 Accident Reported Date / Time : 14/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 13/03/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095044
 Special Instruction to ARC, if any :
 TOWED \$40 / SJM542R - NTUC IDAC
 Prepared Date : 14/03/2018 12:06:13 PM



Sebastian
 14/3/18.
 - Part by part repair.
 - Question Mark Item Photo
 - Photo Before Paint

 27/3/18

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU603580707


Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	600.00
Total Spray Painting Charges	: 1,854.00	900.00
Total Material Charges	: 4,240.25 8576.10	2,524.50
Other Charges	: 940.00	260.00
TOTAL	: 8,048.25 12384.10	4,284.50
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 7.00	5.00
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 14/03/2018 01:58:31 PM	14/03/2018 02:53:47 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 14/03/2018 01:58:31 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1803-0557

Invoice No :

Quotation Date : 23/3

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 3/14/2018 1:58:54 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	600.00 /
Total Labour	1,014.00	600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00
TO RESPRAY BUMPER BEAM	180.00	100.00 /
TO RESPRAY REAR PANEL	180.00	100.00 /
TO RESPRAY TAIL GATE	378.00	200.00 /
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100.00 /
TO RESPRAY REAR FENDER RH	378.00	200.00 /
Total Spray Painting & Panel Beating	1,854.00	900.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30.00 /
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120.00 /
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50.00 /
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	940.00	260.00

11550.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52159479 13			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No ✓
			PIXEL STICKER	2	60.00 (11.9)	0.00	120.00	Replace	Replace	No ✓
52462470 30			PAD, RR BUMPER, RH & LH, 1	2	3.80 (2.67)	25.00	5.70	Replace	Check	No X
52462470 20			PAD, RR BUMPER, RH & LH, 2	2	3.80 (2.60)	25.00	5.70	Replace	Check	No X
52462470 10			PAD, RR BUMPER, RH & LH, 3	2	3.80 (2.60)	25.00	5.70	Replace	Check	No X
52191470 30			SEAL, RR BUMPER ARM, RH & LH	2	11.00 (2.2)	25.00	16.50	Replace	Check	No X
52575470 40			RETAINER, RR BUMPER, RH	0	112.70	25.00	0.00	Replace	Not given	No X
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace S	No ✓
52453470 10			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No ✓
52169470 20			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace S	No ✓
52461470 10			PAD, RR BUMPER, CTR	3	2.20 (6.6)	25.00	4.95	Replace	Check	No X
52565479 00			FILLER, RR BUMPER, RH	1	119.90	25.00	89.93	Replace	Replace S	No ✓
52161160 10			CLIPS PIECE, FRT & RR BUMPER	10	1.50 (15)	25.00	11.25	Replace	Replace	No ✓
81551472 81			LENS & BODY, REAR COMBINATION LAMP, RH	1	438.10	10.00	394.29	Replace	Check	No X
81581470 10			LENS & BODY ASSY, RR BUMPER, RH	1	486.80	10.00	438.12	Replace	Check	No X
52591470 50			SEAL, RR BUMPER, RH	1	85.20	25.00	63.90	Replace	Check	No X
52023470 30			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace	No ✓
58398470 50			COVER, REAR FLOOR UNDER, RH	1	169.50	25.00	127.13	Replace	Check	No X
66259470 10			COVER, REAR FLOOR UNDER CENTER	1	222.60	25.00	166.95	Replace	Check	No X
89997301 00			ANTENNA, ELECTRICAL KEY	1	60.30	10.00	54.27	Replace	Check	No X
58307470 90			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	100.00	0.00	Replace	Repair	No R
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No ✓
58386470 20			BRACKET, REAR BUMPER COVER	2	17.10 (34.2)	25.00	25.65	Replace	Check	No X
67005474 40			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Replace	No ✓
56117501 40			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	2	27.90 (55.8)	25.00	41.85	Replace	Replace	No ✓
75571470 10			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	25.00	22.27	Replace	Replace	No ✓
75574470 40			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, LH	1	29.90	25.00	22.42	Replace	Replace	No ✓

51.30

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
75573471 10			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, RH	1	29.90	25.00	22.42	Replace	Replace	No
75575470 51			TAIL GATE MOULDING LOWER GLASS, BACK DOOR	1	19.70	25.00	14.77 14.76	Replace	Replace	No
68810470 61			TAIL GATE BACK DOOR HINGE ASSY, RH & LH	0	59.10	25.00	0.00	Replace	Not given	No X
69350470 50			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	10.00	406.89	Replace	Check	No X
76801471 10A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	100.00	0.00	Replace	Repair	No R
	REAR		NUMBER PLATE	0	30.00	0.00	0.00	Replace	Not given	No X
			NUMBER PLATE FRAME	1	25.00	0.00	25.00	Replace	Replace	No
75441470 90			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No
75442471 30			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No
75403480 10			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace	No
			STICKER SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
	COMMO N		SEALANT W/SCREEN	3	37.00 (111)	0.00	111.00	Replace	Replace	No
61601471 50			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	100.00	0.00	Replace	Repair	No R
TOTAL MATERIALS					2623.10		4,240.30	2,524.50		
TOTAL MATERIALS(Discounted)							4,240.25	2,524.50		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

2524.50
 + 600.00
 + 1160.00

 4284.50

Seby Simon
 27/3/18



SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

20-3-18/10:53

20-3-18/14:53

SMRT Accident Vehicle Repair Estimates

14-3-18/14:53

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF7E
Ref. No : TAX/03/18/2064
Reg. Date : 19/12/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : LIM CHENG HIONG
Type of Accident : CHAIN COLLISION
Date / Time of Accident : 13/03/2018 05:56:00 PM
Accident Reported Date / Time : 14/03/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Sebastian
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 13/03/2018
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024095044
Special Instruction to ARC, if any :



TOWED \$40 / SJM542R - NTUC IDAC p18
BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK)
& Email : sebastianyeang @lkkauto.com HP:90036121

Prepared Date : 14/03/2018 12:06:13 PM

20/3/18 12:18 P455

Recording Camera

☐ ☒

Radio Antenna

☐ ☒1st witness

Date 14-3-18

2nd witness

Date

30873

1 1 1 1
1/4 2 3/4

30936

Supplementary
Refer to the Supplementary part 1st

LEE SHENG AUTO PTE LTD

Vehicle Return Date:

20-3-2018

Vehicle Return Time:

10:10 am

SMRT staff sign:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU603580707

Mileage :

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,854.00	0.00
Total Material Charges	: 6,202.76	6,202.76
Other Charges	: 1,020.00	0.00
TOTAL	: 10,090.76	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 7.00	0.00
Prepared / Adjusted By	:	5 days
Arc / Surveyor Sing Off Date	: 14/03/2018 01:58:31 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 14/03/2018 01:58:31 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 3/14/2018 1:58:54 PM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	0.00 600
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00 X
TO RESPRAY BUMPER BEAM	180.00	0.00 100
TO RESPRAY REAR PANEL	180.00	0.00 100
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 100
TO RESPRAY REAR FENDER RH	378.00	0.00 200
Total Spray Painting & Panel Beating	1,854.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 X
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00 120
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 50
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,020.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159479 13			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
52462470 30			PAD, RR BUMPER, RH & LH, 1	2	3.80	25.00	5.70	Replace	Replace	No
52462470 20			PAD, RR BUMPER, RH & LH, 2	2	3.80	25.00	5.70	Replace	Replace	No
52462470 10			PAD, RR BUMPER, RH & LH, 3	2	3.80	25.00	5.70	Replace	Replace	No
52191470 30			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace	No
52575470 40			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.52	Replace	Replace	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No
52453470 10			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No
52169470 20			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace	No
52461470 10			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Replace	No
52565479 00			FILLER, RR BUMPER, RH	1	119.90	25.00	89.92	Replace	Replace	No
52161160 10			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace	No
81551472 81			LENS & BODY, REAR COMBINATION LAMP, RH	1	438.10	10.00	394.29	Replace	Replace	No
81581470 10			LENS & BODY ASSY, RR BUMPER, RH	1	486.80	10.00	438.12	Replace	Replace	No
52591470 50			SEAL, RR BUMPER, RH	1	85.20	25.00	63.90	Replace	Replace	No
52023470 30			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace	No
58398470 50			COVER, REAR FLOOR UNDER, RH	1	169.50	25.00	127.12	Replace	Replace	No
66259470 10			COVER, REAR FLOOR UNDER CENTER	1	222.60	25.00	166.95	Replace	Replace	No
89997301 00			ANTENNA, ELECTRICAL KEY	1	60.30	10.00	54.27	Replace	Replace	No
58307470 90			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Replace	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No
58386470 20			BRACKET, REAR BUMPER COVER	2	17.10	25.00	25.65	Replace	Replace	No
67005474 40			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Replace	No
56117501 40			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	2	27.90	25.00	41.85	Replace	Replace	No
75571470 10			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	25.00	22.27	Replace	Replace	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
75574470 40			TAIL GATE MOULDING LOWER GLASS , BACK DOOR , LH	1	29.90	25.00	22.42	Replace	Replace	No
75573471 10			TAIL GATE MOULDING LOWER GLASS , BACK DOOR , RH	1	29.90	25.00	22.42	Replace	Replace	No
75575470 51			TAIL GATE MOULDING LOWER GLASS , BACK DOOR	1	19.70	25.00	14.77	Replace	Replace	No
68810470 61			TAIL GATE BACK DOOR HINGE ASSY, RH & LH	2	59.10	25.00	88.65	Replace	Replace	No
69350470 50			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	10.00	406.89	Replace	Replace	No
76801471 10A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace	No
	REAR		NUMBER PLATE	1	30.00	0.00	30.00	Replace	Replace	No
			NUMBER PLATE FRAME	1	25.00	0.00	25.00	Replace	Replace	No
75441470 90			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No
75442471 30			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No
75403480 10			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace	No
			STICKER SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
	COMMO N		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace	No
61601471 50			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	25.00	618.60	Replace	Replace	No
TOTAL MATERIALS								6,202.82	6,202.76	
TOTAL MATERIALS(Discounted)								6,202.76	6,202.76	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHF7E
Vehicle to be Exported:	No
Intended De-registration Date:	15 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR8297250
Chassis No.:	JTDKB3FU603580707
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	19 Dec 2017
First Registration Date:	19 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2025

PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	18 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$33,125.00
Total Rebate Amount:	\$36,875.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 15 Mar 2018

OK



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham escribe

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18004965/Srbe2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 12-04-2018



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJM 542R	Veh. Inspected	SHF 7E
Policy No.	5095968189	Coverage (\$)	0.00
Claim No.	MT/0985967-002	Excess (\$)	0.00
Assign From		Assign Date	14/03/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU603580707	Colour	MAROON
Odometer	30873	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/03/2018	Inspection Date	14/03/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 7E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER, RR BUMPER ASSY (DISC 25%)	CRACKED	423.90	317.92
1	GUARD, RR BUMPER, LOWER (DISC 25%)	DEFORMED	558.30	418.72
1	COVER, GUARD RR BUMPER LOWER (DISC 25%)	MISSING	14.80	11.10
1	FILLER, RR BUMPER, RH (DISC 25%)	CRACKED	119.90	89.93
10	CLIPS PIECE, FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	REAR BUMPER REINFORCEMENT (DISC 25%)	BENT	318.80	239.10
1	TAIL GATE PANEL SUB-ASSY, BACK DOOR (DISC 25%)	DENTED	929.60	697.20
2	TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE @\$27.90 (DISC 25%)	NECESSARY	55.80	41.85
1	TAIL GATE MOULDING GLASS, BACK DOOR (DISC 25%)	NECESSARY	29.70	22.27
1	TAIL GATE MOULDING LOWER GLASS, BACK DOOR, LH (DISC 25%)	NECESSARY	29.90	22.42
1	TAIL GATE MOULDING LOWER GLASS, BACK DOOR, RH (DISC 25%)	NECESSARY	29.90	22.42
1	TAIL GATE MOULDING LOWER GLASS, BACK DOOR (DISC 25%)	NECESSARY	19.70	14.76
1	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.22
1	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.22
1	EMBLEM SUB-ASSY REAR (DISC 25%)	NECESSARY	46.30	34.72
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
1	SEALANT SIKAFLEX (SN)	NECESSARY	37.00	37.00
1	NUMBER PLATE FRAME (SN)	CUT	25.00	25.00
1	STICKER SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
3	SEALANT W/SCREEN @\$37.00 (SN)	NECESSARY	111.00	111.00
2	PAD, RR BUMPER, RH & LH, 1 @\$3.80	NOT NECESSARY	7.60	-
2	PAD, RR BUMPER, RH & LH, 2 @\$3.80	NOT NECESSARY	7.60	-
2	PAD, RR BUMPER, RH & LH, 3 @\$3.80	NOT NECESSARY	7.60	-
2	SEAL, RR BUMPER ARM, RH & LH @\$11.00	NOT NECESSARY	22.00	-

Report Ref No. NS/INC18004965/Srbe2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RETAINER, RR BUMPER, RH	NOT NECESSARY	112.70	-
3	PAD, RR BUMPER, CTR @\$2.20	CRACKED	6.60	-
1	LENS & BODY, REAR COMBINATION LAMP, RH	NOT NECESSARY	438.10	-
1	LENS & BODY ASSY, RR BUMPER, RH	NOT NECESSARY	486.80	-
1	SEAL, RR BUMPER, RH	NOT NECESSARY	85.20	-
1	COVER, REAR FLOOR UNDER, RH	NOT NECESSARY	169.50	-
1	COVER, REAR FLOOR UNDER CENTER	NOT NECESSARY	222.60	-
1	ANTENNA, ELECTRICAL KEY	NOT NECESSARY	60.30	-
2	BRACKET, REAR BUMPER COVER @\$17.10	NOT NECESSARY	34.20	-
1	TAIL GATE BACK DOOR HINGE ASSY, RH & LH	NOT NECESSARY	59.10	-
1	TAIL GATE LOCK ASSY, BACK DOOR	NOT NECESSARY	452.10	-
1	NUMBER PLATE	NOT NECESSARY	30.00	-
1	END PANEL SUB-ASSY, BODY LOWER BACK	TO REPAIR	629.80	-
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	TO REPAIR	891.20	-
1	PANEL SUB-ASSY, FENDER REAR RH	TO REPAIR	824.80	-
			7,746.40	2,524.50
	LABOUR			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		1,694.00	830.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		1,954.00	930.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			3,808.00	1,760.00
	GRAND TOTAL		11,554.40	4,284.50
RECOMMENDED COST OF REPAIRS (CONFIRMED)				4,284.50

Report Ref No. NS/INC18004965/Srbe2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.