

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 諭輝

Date : 14/03/2018
TP Vehicle No. : GX - 941-A
To : **AIG ASIA PACIFIC INSURANCE PTE LTD**
Attn : **Motor Claim Department**

IVAN TEO
ABWIN SERVICE PTE LTD
DID: 67139416
Fax: 67139415
HP: 86680608

Owner : SAPHAD SERVICES
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5085358448-01
Vehicle No. : GBF-4488-U
Make & Model : TOYOTA HIACE 3.0 DX M

Accident Date: 23/02/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	LEFT SLIDING DOOR	\$1,412.70	Ry
1	LEFT REAR FENDER	\$1,321.70	bt✓
	Sub Total	\$2,734.40	
	Discount 25% on Parts	(\$683.60)	
		\$2,050.80	

Special Nett

1	DOOR GLASS SEALANT	\$80.00	X
1	FENDER GLASS SEALANT	\$80.00	new
	Sub Total	\$160.00	

Labour & Misc

LABOUR TO FACILITATE REPAIR	\$1,000.00	700
TO SPRAY PAINT ON AFFECTED AREAS	\$1,000.00	600 700
TO RUST PROOF AFFECTED AREA	\$150.00	60
TO TRANSFER & REFIX REAR DOOR FIXTURE & FITTING	\$150.00	X
Sub Total	\$2,300.00	

Sub Total \$4,510.80
GST 7% \$315.76
Total \$4,826.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

62563561 office
Taufiq 97495749
wp
15/3/18 C1015
sur@lkhauto.com
6 days
Resurvey before/after repair paint