

ASS. REC. BY: Adrian King

REF: CC3/ALH18001981/Arber

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. 1800012222
 Claims No. 314651580156
 Sum Insured: _____ Excess: 8600
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 125K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 08/8/18 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLW2857T Yr Regn: 2018 / Feb.
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Audi A3 SB c.c. 999
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 20061 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WAUZZZ8V1JA072456
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55R16
 R: 205/55R16
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 15/03/18
 Survey held at Premium
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

08/08/18

Report in Merimen
Authorise repair & inform repairer by email.

Confirm \$20835.08 @ 8 days
Red. \$24062.92, 541.

RECEIVED 03 JUL 2018

Date/Time, File Pass to? ☐ : Preli. Report
 1) typist ☒ : Final Report

Date/Time, File Return to?

2) _____

Report Format: 00
 Lump Sum / I.B.I. (\$) 20,835.08

Days Of Repair: 8
 Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee: 200
 Transportation: _____
 \$ + RS. SI
 Photos: _____
 Others: 10

TOTAL

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18004981/Arb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 15-03-2018



Code : AIG

Policy Particulars :- OWN DAMAGE

1.	Insured Veh.	Veh. Inspected	SLW 2857T
	Policy No. 1800012222	Coverage (\$)	0.00
	Claim No.	Excess (\$)	0.00
	Assign From	Assign Date	15/03/2018

Vehicle Particulars & Condition

2.	Make & Model	c.c	0
	Engine No. HIDDEN	Year of Reg.	
	Chassis No.	Colour	
	Odometer -	Steering	
	Brakes	Modification	
	General		

Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

Description of Damages

4.

General Information

5.	Accident Date	13/03/2018	Inspection Date	15/03/2018
	Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		

Remarks

5a.

- A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 16 Mar 2018

Preliminary Advice

Vehicle No	: SLW2857T	Accident Date	: 13/03/2018
Make	: AUDI A3	Policy No.	: 1800012222
Assignment Date	: 15/03/2018	Excess	: S\$0.00
Date of Inspection	: 15/03/2018	Est. Duration of Repair	: 8.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 44,822.00
Revised Amount	:S\$ 23,561.00
Check Items (Estimated)	:S\$ 7,312.00
Total	:S\$ 30,873.00

30949

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 125,000.00
COE / PARF Rebate	:S\$ 55,836.00
Salvage Value	:S\$
Margin for Repair	:S\$ 69,164.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Monday, March 19, 2018 11:42 AM
To: 'claims@premiumauto.com.sg'
Cc: SUR
Subject: SLW 2857T AIG OD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLW 2857T (excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 0319I

Vehicle Details

Vehicle No.: SLW2857T

Vehicle to be Exported: No

Intended De-registration Date: 16 Mar 2018

Vehicle Make: AUDI

Vehicle Model: A3 SPORTBACK 1.0 TFSI S TRONIC (LED)

Primary Colour: Grey

Manufacturing Year: 2017

Engine No.: CHZ640416

Chassis No.: WAUZZZ8V1JA072156

Maximum Power Output: 85.0 kW (113 bhp)

Open Market Value: \$24,162.00

Original Registration Date: 05 Feb 2018

First Registration Date: 05 Feb 2018

Transfer Count: 0

Actual ARF Paid: \$25,827.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 04 Feb 2028

PARF Rebate Amount: \$19,370.00

Intended COE Rebate Details

COE Expiry Date: 04 Feb 2028

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$36,890.00

COE Rebate Amount: \$36,466.00

Total Rebate Amount: \$55,836.00

The information contained herein is correct as at 16 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/03/2018 16:27
Date Of Accident	13/03/2018 18:00
Exact Location Of Accident	ALONG CTE BEF ANG MO KIO AVE 1 EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW2857T
Insured/Policyholder	
Name Of Registered Owner	SEOW DONG JIE, PATRICK
NRIC No	S8510319I
Email Address	AVANTIS01@GMAIL.COM
Mobile Phone No	(LOCAL) +65-82682791
Alternative Phone No	OTHERS-82682791

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SB 1.0 TF
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800012222
Cover Note Number	

Driver

Name of Driver	SEOW DONG JIE, PATRICK
NRIC No	S8510319I
Date Of Birth	01/04/1985
Occupation	INDOOR
Date Of Driving Pass	05/06/2006
Driving Experience	11 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82682791
Fax Number	
Contact Number	OTHERS-82682791
Email Address	AVANTIS01@GMAIL.COM

Address	BLK 965 HOUGANG AVE 9
	#09-646
Postcode	530965
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

HEAD TO REAR COLLISION OCCURED BETWEEN 3 VEHICLES, SLW2857T (HEAD) TO GBC265M (REAR). ACCIDENT HAPPENED ALONG CTE, BEFORE ANG MO KIO AVE 1 EXIT, AT ABOUT 18:00 PM ON 13/03/2018.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC265M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHA9233K
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: L. W. K. K. K.
NRIC/FIN No.: C88025678

Sketch Plan #2

SKETCH PLAN

A: SLW 2857 T
B: GBC 265 M
C: SHA 9233 K



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Head-to-head collision occurred between 3 vehicles, SLW 2857 T (Front) to GBC 265 M (Rear). Accident happened along UTE, before Ang Mo Kio Ave 1 exit, at about 18:00 pm on 13-Mar-2018.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: LIM EOE SENG
NRIC/FIN No: G94552564M

Accident Photo



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S85103191**

Name: **SEOW DONG JIE, PATRICK (XIAO DONGJIE)**

Birth Date: **01 Apr 1985**

Issue Date: **05 Jun 2006**

001423253K



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S85103191**



Name:

SEOW DONG JIE, PATRICK (XIAO DONGJIE)

蕭 东 杰

Race:

CHINESE

Date of birth:

01-04-1985

Country/Piece of birth:

SINGAPORE

Sex:

M

S85103191




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg

PASS DATE: **05 Jun 2006**

NP 428A

Licence No: **S85103191**




Date of issue:

09-12-2015

Address:

**APT BLK 965 HOUGANG AVENUE 9
#09-646
SINGAPORE 530965**



NPIC No: **S85103191**

5539225

CERTIFICATE OF INSURANCE

AIG

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : SEOW DONG JIE, PATRICK (XIAO DONGJIE)
 Period of Insurance : 05 Feb 2018 To 04 Feb 2019
 Engine No. : CHZ 640416
 Chassis No. : WAUZZZ8V1JA072156

Vehicle No. : SLW2857T
 Policy No. : 1800012222
 Endorsement No. :
 Issued Date : 13 Feb 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sportback 1.0 TFSI S tronic
 Engine Capacity/Tonnage : 999.00 CC
 Driver Restriction : NA
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2018
 Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
 You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 30 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

SEOW DONG JIE, PATRICK (XIAO DONGJIE) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: OVERSEA-CHINESE BANKING CORPN LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125263

PREMIUM LEASING -NS
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.



Steffany Loh

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE Steffany Loh

AIG Asia Pacific Insurance Pte. Ltd.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0326/2018/CCS
Date	:	15-Mar-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Seow Dong Jie, Patrick
Address	:	Blk 965 Hougang Avenue 9 #09-646 Singapore 530965
Telephone	:	HP +65 82682791
Type of Claim	:	Own Damage Claim
Policy No.	:	1800012222
Vehicle No	:	SLW 2857 T
Model Code	:	Audi A3 SB 1.0 TFSI
Model / Year	:	Feb-18
Engine No	:	CHZ 640416
Chassis No	:	WAUZZZ8V1JA072156
Mileage	:	-
Date In	:	14-Mar-18
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	13-Mar-18
Place of Accident	:	Along CTE bef Ang Mo Kio Ave 1 exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2857 T.

S/N	Parts Description			Damage Parts & Prices	
				S/NETT	REMARKS
21	LED HEADLIGHT - LH/RH <i>Cancel</i>	2	\$	9,776.00	✓ 7820.80
22	MAIN LIGHT POWER MODULE <i>new</i>	2	\$	1,329.00	+
23	LIGHT CONTROL SYSTEM CONTROL UNIT <i>new</i>	2	\$	972.00	+
24	LED WITH HEAT SINK - LH/RH <i>new</i>	2	\$	1,250.00	+
25	HEADLIGHT HOSE - LH/RH <i>new</i>	2	\$	68.00	+
26	HEADLIGHT WASHER CYLINDER - LH/RH <i>new</i>	2	\$	246.00	?
27	HEADLIGHT WASHER HOSE <i>new</i>		\$	57.00	✓
28	BONNET <i>Disbald</i>		\$	2,378.00	✓ 1902.40
29	BONNET ATTACHMENT PARTS <i>new</i>		\$	141.00	✓ 112.80
30	BONNET HINGE - LH/RH <i>But</i>	2	\$	106.00	✓ 84.64
31	BONNET HINGE COVER - LH/RH <i>new</i>	2	\$	72.00	?
32	BONNET DAMPER <i>new</i>		\$	105.00	+
33	BONNET EDGE PROTECTION <i>new</i>		\$	24.00	✓ 18.88
34	BONNET CATCH HOOK - TOP <i>new</i>		\$	78.00	?
35	BONNET LOCK STRIKER - LH/RH <i>new</i>	2	\$	192.00	?
36	BONNET CATCH HOOK - BOTTOM <i>new</i>		\$	55.00	?
37	BONNET LOCK <i>new</i>	2	\$	353.00	?
38	BONNET LOCK BOWDEN CABLE <i>new</i>		\$	50.00	+
39	FRONT LOCK CARRIER <i>Cancel</i>		\$	638.00	✓ 510.00
40	LOCK CARRIER AIR GUIDE - LH/RH <i>new</i>	2	\$	40.00	?
SUB-TOTAL SPARE PARTS				\$ 17,930.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2857 T.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Dischd</i>	\$ 1,613.00 ✓	1290.40
2	FRONT BUMPER GUIDE - LH/RH <i>new</i>	2 \$ 66.00 +	} X
3	FRONT BUMPER GRILLE - LOWER <i>new</i>	\$ 140.00 +	
4	FRONT BUMPER CLOSING ELEMENT - LH/RH <i>new</i>	2 \$ 508.00 +	406.40
5	RADIATOR GRILLE <i>Crushed</i>	\$ 1,239.00 ✓	991.20
6	RADIATOR GRILLE CLOSING ELEMENT - UPPER <i>Engd</i>	\$ 167.00 ✓	133.20
7	STICKER FOR AIR CONDITIONER <i>m</i>	\$ 7.00 ✓	4.88
8	SIGN ' CAUTION ' STICKER <i>m</i>	\$ 12.00 ✓	9.28
9	FRONT BUMPER GRILLE - LH/RH <i>new</i>	2 \$ 328.00 +	} X
10	FRONT BUMPER FOAM COVER <i>Not New</i>	\$ 105.00 ?	
11	FRONT BUMPER FOAM <i>Not New</i>	\$ 162.00 ?	
12	FRONT BUMPER REINFORCEMENT BEAM <i>Not New</i>	\$ 633.00 ?	
13	REINFORCEMENT BEAM BOLT SET <i>Not New</i>	\$ 31.00 ?	
14	FRONT FENDER - LH/RH <i>Regr</i>	2 \$ 1,492.00 +	
15	FRONT FENDER RIVET SET <i>new</i>	\$ 48.00 +	
16	FRONT FENDER BRACKET - LH/RH REAR <i>2</i>	2 \$ 82.00 +	
17	FRONT FENDER BRACKET - LH/RH FRONT <i>2</i>	2 \$ 48.00 +	
18	FRONT FENDER BRACE - LH/RH <i>2</i>	2 \$ 168.00 +	
19	FRONT FENDER CLOSING ELEMENT - LH/RH <i>2</i>	2 \$ 106.00 +	
20	FRONT WHEEL HOUSING LINER - LH/RH <i>2</i>	2 \$ 302.00 +	
SUB-TOTAL SPARE PARTS		\$ 7,257.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 2857 T.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer Assy.	S/N \$ 360.00 ✓ /	
2	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system.	S/N \$ 1,000.00 ✓ /	
3	To dismantle front bumper, both front fenders, headlights and bonnet. Renew front lock carrier and align to position. Renew damaged panels. Reorganise front crash management components. Reinstall all parts removed.	\$ 5,400.00 3250 ✓	
4	To respray front bumper, both front fenders, bonnet hinges and both A-pillar. <i>Bonnet</i>	\$ 4,000.00 2500 ✓	
5	To renew intake manifold and attachment parts.	S/N \$ 900.00 ? } x	
6	To renew front windscreen.	S/N \$ 480.00 x }	
7	To carry out diagnostic check.	S/N \$ 192.00 ✓ /	
TOTAL LABOUR CHARGES		: \$ 12,332.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2857 T.

S/N	Parts Description	Damage Parts & Prices		REMARKS
		S/NETT		
41	LOCK CARRIER AIR GUIDE - UPPER <i>new</i>	\$	10.00	<i>x</i>
42	A/C CONDENSER <i>Not new</i>	\$	500.00	<i>?</i>
43	RADIATOR <i>Not new</i>	\$	828.00	<i>?</i>
44	ADDITIONAL RADIATOR <i>Not new</i>	\$	799.00	<i>?</i>
45	RADIATOR BRACKET - LH/RH <i>Not new</i>	2 \$	75.00	<i>?</i>
46	RADIATOR BUSH SET <i>Not new</i>	\$	17.00	<i>?</i>
47	COOLANT <i>new</i>	\$	133.00	<i>106.24</i>
48	RADIATOR FAN WITH FAN RING <i>Not new</i>	\$	1,425.00	<i>?</i>
49	AIR FILTER AIR GUIDE <i>Not new</i>	\$	59.00	<i>?</i>
50	AIR FILTER <i>Not new</i>	\$	242.00	<i>?</i>
51	CHARGE AIR COOLER <i>new</i>	\$	658.00	<i>x</i>
52	AIR COOLER SEAL <i>new</i>	2 \$	26.00	<i>+</i>
53	INTAKE MANIFOLD <i>new</i>	\$	551.00	<i>+</i>
54	WINDSCREEN TRIM - LOWER <i>new</i>	\$	156.00	<i>+</i>
55	WINDSCREEN <i>new</i>	\$	953.00	<i>+</i>
56	RAIN SENSOR GEL FOIL <i>new</i>	\$	127.00	<i>+</i>
57	GLASS PRIMER <i>new</i>	\$	19.00	<i>+</i>
58	FRONT NO. PLATE <i>Bent</i>	S/N \$	25.00	<i>25.00</i>
59	FRONT WINDSCREEN SEALANT <i>new</i>	S/N \$	200.00	<i>+</i>
60	SUNDRIES <i>new</i>	\$	500.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 32,490.00	
TOTAL LABOUR CHARGES		:	\$ 12,332.00	
GRAND TOTAL		:	\$ 44,822.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

66882.08

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

: Adrian Ly

Surveyed Date

: 15/03/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, as ays.

[Signature]
16/3/18

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0326/2018/CCS
27-Mar-18
CHANG
1 of 1
SLW 2857 T
Audi A3 SB 1.0 TFSI

		Unit Price	Amount
Quantity	Description		
<u>Parts</u>			
1	INTAKE AIR GUIDE {deformed.	\$ 50.00	39.76
2	INTAKE AIR GUIDE COVER	\$ 26.00	20.32
TOTAL PARTS :		\$ 76.00	
GRAND TOTAL :		\$ 76.00	

For Premium Automobiles Pte Ltd

Adrian Ling
28/03/18
SLS.



Authorised Signature

Janice Lee (LKKAuto)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Saturday, May 19, 2018 3:50 PM
To: Adrian Ling (LKKAuto); Janice Lee (LKKAuto); SUR; Carrine Leong; Nora Khai
Subject: FINAL REVISION - SLW2857T - OD AIG - SURVEYED 15 MAR 18
Attachments: PA03262018 - SLW 2857 T - A3 SB 1.0 TFSI - FRONT (AIG) + SUPP.xls

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$20,835.08 @ 8 days of repairs exclude 1 Sunday.

Some photographs were mailed to your office on 27 Mar 18 from Benoi.

your early closure is well appreciated.

Best regards - jb

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0326/2018/CCS
Date	:	15-Mar-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
8 days exclude 1 Sunday - ok -
jb - 19 May 18

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Seow Dong Jie, Patrick
Address	:	Blk 965 Hougang Avenue 9 #09-646 Singapore 530965
Telephone	:	HP +65 82682791
Type of Claim	:	Own Damage Claim
Policy No.	:	1800012222
Vehicle No	:	SLW 2857 T
Model Code	:	Audi A3 SB 1.0 TFSI
Model / Year	:	Feb-18
Engine No	:	CHZ 640416
Chassis No	:	WAUZZZ8V1JA072156
Mileage	:	-
Date In	:	14-Mar-18
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	13-Mar-18
Place of Accident	:	Along CTE bef Ang Mo Kio Ave 1 exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 2857 T.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	\$ 360.00
2	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system.	S/N \$ 1,000.00	\$ 1,000.00
3	To dismantle front bumper, both front fenders, headlights and bonnet. Renew front lock carrier and align to position. Renew damaged panels. Re-organise front crash management components. Reinstall all parts removed.	\$ 5,400.00	\$ 3,250.00
4	To respray front bumper, both front fenders, bonnet hinges and both A-pillar.	\$ 4,000.00	\$ 2,500.00
5	To renew intake manifold and attachment parts.	S/N \$ 900.00	
6	To renew front windscreen.	S/N \$ 480.00	
7	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 12,332.00	\$ 7,302.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2857 T.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
		\$ 1,613.00	\$ 1,290.40
1	FRONT BUMPER		
2	FRONT BUMPER GUIDE - LH/RH	2 \$ 66.00	
3	FRONT BUMPER GRILLE - LOWER	\$ 140.00	
4	FRONT BUMPER CLOSING ELEMENT - LH/RH	2 \$ 508.00	\$ 406.40
5	RADIATOR GRILLE	\$ 1,239.00	\$ 991.20
6	RADIATOR GRILLE CLOSING ELEMENT - UPPER	\$ 167.00	\$ 133.20
7	STICKER FOR AIR CONDITIONER	\$ 7.00	\$ 4.88
8	SIGN ' CAUTION ' STICKER	\$ 12.00	\$ 9.28
9	FRONT BUMPER GRILLE - LH/RH	2 \$ 328.00	
10	FRONT BUMPER FOAM COVER	\$ 105.00	
11	FRONT BUMPER FOAM	\$ 162.00	
12	FRONT BUMPER REINFORCEMENT BEAM	\$ 633.00	
13	REINFORCEMENT BEAM BOLT SET	\$ 31.00	
14	FRONT FENDER - LH/RH	2 \$ 1,492.00	
15	FRONT FENDER RIVET SET	\$ 48.00	
16	FRONT FENDER BRACKET - LH/RH REAR	2 \$ 82.00	
17	FRONT FENDER BRACKET - LH/RH FRONT	2 \$ 48.00	
18	FRONT FENDER BRACE - LH/RH	2 \$ 168.00	
19	FRONT FENDER CLOSING ELEMENT - LH/RH	2 \$ 106.00	
20	FRONT WHEEL HOUSING LINER - LH/RH	2 \$ 302.00	
	SUB-TOTAL SPARE PARTS	\$ 7,257.00	\$ 2,835.36

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2857 T.

S/N	Parts Description	c/f	Damage Parts & Prices		REMARKS
			S/NETT		
				\$	2,835.36
				\$	7,820.80
21	LED HEADLIGHT - LH/RH	2	\$ 9,776.00		
22	MAIN LIGHT POWER MODULE	2	\$ 1,329.00		
23	LIGHT CONTROL SYSTEM CONTROL UNIT	2	\$ 972.00		
24	LED WITH HEAT SINK - LH/RH	2	\$ 1,250.00		
25	HEADLIGHT HOSE - LH/RH	2	\$ 68.00		
26	HEADLIGHT WASHER CYLINDER - LH/RH	2	\$ 246.00		
27	HEADLIGHT WASHER HOSE		\$ 57.00		
28	BONNET		\$ 2,378.00	\$	1,902.40
29	BONNET ATTACHMENT PARTS		\$ 141.00	\$	112.80
30	BONNET HINGE - LH/RH	2	\$ 106.00	\$	84.64
31	BONNET HINGE COVER - LH/RH	2	\$ 72.00		
32	BONNET DAMPER		\$ 105.00		
33	BONNET EDGE PROTECTION		\$ 24.00	\$	18.88
34	BONNET CATCH HOOK - TOP		\$ 78.00		
35	BONNET LOCK STRIKER - LH/RH	2	\$ 192.00		
36	BONNET CATCH HOOK - BOTTOM		\$ 55.00		
37	BONNET LOCK	2	\$ 353.00		
38	BONNET LOCK BOWDEN CABLE		\$ 50.00		
39	FRONT LOCK CARRIER		\$ 638.00	\$	510.00
40	LOCK CARRIER AIR GUIDE - LH/RH	2	\$ 40.00		
SUB-TOTAL SPARE PARTS			\$ 17,930.00	\$	13,284.88

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2857 T.

S/N	Parts Description	c/f	Damage Parts & Prices		REMARKS
			S/NETT	\$	
					13,284.88
41	LOCK CARRIER AIR GUIDE - UPPER		\$	10.00	
42	A/C CONDENSER		\$	500.00	
43	RADIATOR		\$	828.00	
44	ADDITIONAL RADIATOR		\$	799.00	
45	RADIATOR BRACKET - LH/RH	2	\$	75.00	
46	RADIATOR BUSH SET		\$	17.00	
47	COOLANT		\$	133.00	\$ 106.24
48	RADIATOR FAN WITH FAN RING		\$	1,425.00	
49	AIR FILTER AIR GUIDE		\$	59.00	
50	AIR FILTER		\$	242.00	
51	CHARGE AIR COOLER		\$	658.00	
52	AIR COOLER SEAL	2	\$	26.00	
53	INTAKE MANIFOLD		\$	551.00	
54	WINDSCREEN TRIM - LOWER		\$	156.00	
55	WINDSCREEN		\$	953.00	
56	RAIN SENSOR GEL FOIL		\$	127.00	
57	GLASS PRIMER		\$	19.00	
58	FRONT NO. PLATE	S/N	\$	25.00	\$ 25.00
59	FRONT WINDSCREEN SEALANT	S/N	\$	200.00	
60	Added parts - see attached		\$	76.00	\$ 60.08
61	SUNDRIES		\$	500.00	\$ 56.88
	TOTAL SPARE PARTS		\$	32,566.00	\$ 13,533.08
	TOTAL LABOUR CHARGES		\$	12,332.00	\$ 7,302.00
	GRAND TOTAL		\$	44,898.00	\$ 20,835.08

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLW 2857 T

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0326/2018/MAS

28 June 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SLW 2857 T, Audi A3 SB 1.0 TFSI

With reference to the above-mentioned vehicle, no. **SLW 2857 T**, claimant, **Mr. Seow Dong Jie, Patrick**, please find the related document per attached.

1. A copy of the Original invoice no. 85012651 – S\$21,651.54
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLW 2857 T

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733
Page 1 09:56

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Telephone 6388 2223
Telefax 6841 1182

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

INSURANCE INVOICE
Company No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice: 85012651 Date : 26/06/2018 Order : SLW2857T Term : 30		Account: A0005 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120	
Regn No.: SLW2857T (V 36756) Model: A3 SPORTSBACK 1.0 TFSI 8V FANG USB No.: You have been assisted by :- UB-Jiayee (87)		Regn Date: 05/02/2018 Chassis: WAUZZZ8V1JA072156 Mileage: 2006 Engine: CHZ 540416		WIP No.: 58800 Dept: U	

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE.	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM	1000.00	1.00	1,000.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER, BOTH FRONT FENDERS, HEADLIGHTS AND BONNET, RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW DAMAGED PANELS, REORGANISE FRONT CRASH MANAGEMENT	3250.00	1.00	3,250.00
Sub-Total					
7% GST					
Grand Total					

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733
Page 2 09:56

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408693
Telephone 6388 2223
Telefax 6841 1183

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2223
9828 1233

INSURANCE INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85012651
Date: 26/06/2016
Order: SLW2857T
Term: 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLW2857T (V 36756) Regn Date: 05/02/2010 Mileage: 2006 WIP No.: 58800
Model: A3 SPORTSBACK 1.0 TFSI 8VFANG Chassis: WAUZZZ8V1JA072156 Engine: CHZ 6A0416 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (87)

		Details	Qty	Unit Price	Amount
S	BODYWORK	COMPONENTS, REINSTALL ALL PARTS REMOVED M:	2500.00	1.00	2,500.00
S	BODYWORK	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND HINGES M:	192.00	1.00	192.00
		TO CARRY OUT DIAGNOSTIC CHECKS			
X	ABV3807319	PLATE Less 020%	1.00	254.00	203.20
X	ABV3807320	PLATE Less 020%	1.00	254.00	203.20
X	AG A13A8JM1	COOLANT ADDITIVE Less 020%	4.00	33.20	106.24
X	ABV3853651AA3FZ	GRILLE Less 020%	1.00	1239.00	991.20
X	ABV0941773D	HEADLIGHT(A) Less 020%	1.00	4888.00	3,910.40
X	ABV0941774D	HEADLIGHT(A) Less 020%	1.00	4888.00	3,910.40
X	ABV0805588A	CARRIER Less 020%	1.00	637.50	510.00
X	ABV0823029D	HOOD (A) Less 020%	1.00	2378.00	1,902.40
X	ABV0807065R GRU	COVER(V) (G) Less 020%	1.00	1613.00	1,290.40
X	ABV0121205A	AIR DUCT Less 020%	1.00	9.60	7.68
X	ABV0823126B	EDGING Less 020%	1.00	23.60	18.88
X	ABV0823301G	HINGE (A) Less 020%	1.00	52.90	42.32
Sub-Total					
7% GST					
Grand Total					

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore

281 Alexandra Road
Singapore 159938
Main Telephone 6366 2223
Main Telefax 6471 3733

Page 3 09:56

Alexandra Service Centre

281 Alexandra Road
Singapore 159938
Telephone 6366 2223
Telefax 6475 1023

Ubi Service Centre

55 Ubi Road 1
Singapore 408699
Telephone 6366 2223
Telefax 6541 1183

Customer Service

Service Appointment
24 hour Breakdown Service
Email customer.care@premiumauto.com.sg

6366 2323
9828 1233

INSURANCE INVOICE

Company Reg. No. 199302271W

GST Reg. No. 199302271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85012651
Date : 26/06/2018
Order : SLW2857T
Term : 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLW2857T (V 36756) Regn Date: 05/02/2018 Mileage: 2006 WIP No.: 58800
Model: A3 SPORTSBACK 1.0 TFSI 8VFANG Chassis: WAUZZZ8V1JA072156 Engine: CHZ 640416 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (87)

		Details	Qty	Unit Price	Amount
X	ABV08233026	HINGE (A)	1.00	52.90	42.32
X	ABV4823485C	HOOK	1.00	54.80	43.84
X	ABV0823480A	HOOK	1.00	77.80	62.24
X	ABV0823531A	BOWD CABLE	1.00	50.00	40.00
X	ABK0010520A	PLATE	1.00	11.50	9.28
X	ABV0010515A	STICKER	1.00	6.10	4.88
X	ASQ00129254B	AIR DUCT	1.00	49.70	39.76
X	ABV0121283K	AIR DUCT	1.00	19.90	15.92
X	ABV3853949	PLATE (A)	1.00	166.50	133.20
X	ASQ00129954	COVER	1.00	25.40	20.32
Sub-Total					20,235.08
7% GST					1,416.46
Grand Total					21,651.54

Parts 13,508.08
Labour 0.00
Sublet 7,327.00
Menus 0.00
Lubricant 0.00



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLW 2857 T

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0326/2018/JT
2 APR 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 Sportsback 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8V1JA072156
Vehicle Regn No. : SLW 2857 T
Vehicle Mileage : 2006 KM
Vehicle Owner : Mr.Seow Dong Jie, Patrick
Certificate No : 1800012222
Policy Excess : S\$642.00(inclusive 7% GST)
Accident Date : 13th March 2018
Place : Along CTE before AMK
Repair Cost : \$ 21,651.54
WIP No. : 58800
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Patrick

Time

Date

07/04/2018

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number: **S85103191**

Name: **SEOW DONG JIE, PATRICK (XIAO DONGJIE)**

Birth Date: **01 Apr 1985**
Issue Date: **05 Jun 2006**



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S85103191**



Name: **SEOW DONG JIE, PATRICK (XIAO DONGJIE)**

Chinese Name: **蕭 东 杰**

Race: **CHINESE**

Date of birth: **01-04-1985**

Country/Place of birth: **SINGAPORE**


Sex: **M**

S85103191

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars ≤ 3000kg with ≤ 7 passengers, exclusive of the driver; and other motor vehicles ≤ 2500kg **05 Jun 2006**



License No: **S85103191**

NP 428A



5539225

NRIC No: **S85103191**



Date of issue: **09-12-2015**

Address: **APT BLK 965 HOUGANG AVENUE 9 #09-646 SINGAPORE 530965**

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : SEOW DONG JIE, PATRICK (XIAO DONGJIE)
Period of Insurance : 05 Feb 2018 To 04 Feb 2019
Engine No. : CHZ 640416
Chassis No. : WAUZZZ8V1JA072156

Vehicle No. : SLW2857T
Policy No. : 1800012222
Endorsement No. :
Issued Date : 13 Feb 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sportback 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 30 years old and above

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

SEOW DONG JIE, PATRICK (XIAO DONGJIE) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download 'AIG SG' from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: OVERSEA-CHINESE BANKING CORPN LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125263

PREMIUM LEASING -NS

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manik

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Mar 2018 11:35		15 Mar 2018 17:51 Edit Adj Rpt	S\$20,835.08 Edit Estimates	S\$20,835.08 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS [Created by insurer] Insured: SEOW DONG JIE, PATRICK, ID: S85103191, Tel: +6582682791, Email: AVANTIS01@GMAIL.COM Vehicle Reg. No.: SLW2857T Claim Type: OD / 3146515801SG Date of Loss: 13/03/2018 18:00 - :59 [1 Months and 8 Days From LTA Reg Date (Man Yr)] Policy/Cover Note No.: 1800012222 (Comprehensive) Coverage: 05/02/2018 - 04/02/2019 Excess: S\$600.00 Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911 Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Tr, Tinesh] Tinesh.Tr@aig.com Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/03/2018] Driver/Custodian: SEOW DONG JIE, PATRICK (32 / Male), NRIC: S85103191, Tel: +6582682791 View All Compose Case Mail																								
ASSOCIATED MAIL RECEIVED - AIG_SG (01/06/2018): Alert - Adj Mandate Approved (S\$30949.00) - SLW2857T - Claim Handler: Tr, Tinesh - AIG_SG (19/03/2018): Alert - Adj Mandate Approved (S\$23561.00) - SLW2857T - Claim Handler: Tr, Tinesh - AIG_SG (16/03/2018): SLW2857T / OD / 13/03/2018 / Coverage & Excess update																								
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Claim Documents

*SLW2857T (3146515801SG)
OD

Mar 13 2018 6:00PM
[SEOW DONG JIE, PATRICK]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View	View in Browser
			1 per page	☒
Assessment Reports			Thumbnail	Print
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	1	Load HTM
1	19/03/18 10:33	Adjuster Immediate Advice	1	Load HTM
2	31/05/18 14:58	Adjuster Immediate Advice		
			3 per page	☒
Photos/Images			Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1	Load JPG
1	19/03/18 10:34	General View	1	Load JPG
2	19/03/18 10:34	General View	1	Load JPG
3	19/03/18 10:35	General View	1	Load JPG
4	19/03/18 10:35	General View	1	Load JPG
5	19/03/18 10:35	General View	1	Load JPG
6	19/03/18 10:35	General View	1	Load JPG
7	19/03/18 10:35	General View	1	Load JPG
8	19/03/18 10:35	General View	1	Load JPG
9	19/03/18 10:35	General View	1	Load JPG
10	19/03/18 10:35	General View	1	Load JPG
11	19/03/18 10:35	General View	1	Load JPG
12	19/03/18 10:35	General View	1	Load JPG
13	19/03/18 10:35	General View	1	Load JPG
14	19/03/18 10:35	General View	1	Load JPG
15	19/03/18 10:35	General View	1	Load JPG
16	19/03/18 10:35	General View	1	Load JPG
17	19/03/18 10:35	General View	1	Load JPG
18	19/03/18 10:35	General View	1	Load JPG
19	19/03/18 10:35	General View	1	Load JPG
20	19/03/18 10:35	General View	1	Load JPG
21	19/03/18 10:35	General View	1	Load JPG
22	19/03/18 10:35	General View	1	Load JPG
23	19/03/18 10:35	General View	1	Load JPG
24	19/03/18 10:35	General View	1	Load JPG
25	19/03/18 10:35	General View	1	Load JPG
26	19/03/18 10:35	General View	1	Load JPG
27	19/03/18 10:35	General View	1	Load JPG
28	19/03/18 10:35	General View	1	Load JPG
29	19/03/18 10:35	General View	1	Load JPG
30	19/03/18 10:35	General View	1	Load JPG
31	19/03/18 10:35	General View	1	Load JPG
32	19/03/18 10:35	General View	1	Load JPG
33	19/03/18 10:35	General View	1	Load JPG
34	19/03/18 10:35	General View	1	Load JPG

Merimen e-Claims

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
35	31/05/18 14:53	Reinspection Photo	Load JPG	☒
36	31/05/18 14:53	Reinspection Photo	Load JPG	☒
37	31/05/18 14:53	Reinspection Photo	Load JPG	☒
38	31/05/18 14:53	Reinspection Photo	Load JPG	☒
39	31/05/18 14:53	Reinspection Photo	Load JPG	☒
40	31/05/18 14:53	Reinspection Photo	Load JPG	☒
41	31/05/18 14:53	Reinspection Photo	Load JPG	☒
42	31/05/18 14:53	Reinspection Photo	Load JPG	☒
43	31/05/18 14:53	Reinspection Photo	Load JPG	☒
44	31/05/18 14:53	Reinspection Photo	Load JPG	☒
45	31/05/18 14:53	Reinspection Photo	Load JPG	☒
46	31/05/18 14:53	Reinspection Photo	Load JPG	☒
47	31/05/18 14:53	Reinspection Photo	Load JPG	☒
48	31/05/18 14:53	Reinspection Photo	Load JPG	☒
49	31/05/18 14:53	Reinspection Photo	Load JPG	☒
50	31/05/18 14:53	Reinspection Photo	Load JPG	☒
51	31/05/18 14:53	Reinspection Photo	Load JPG	☒
52	31/05/18 14:53	Reinspection Photo	Load JPG	☒
53	31/05/18 14:53	Reinspection Photo	Load JPG	☒
54	31/05/18 14:53	Reinspection Photo	Load JPG	☒
55	31/05/18 14:53	Reinspection Photo	Load JPG	☒
56	31/05/18 14:53	Reinspection Photo	Load JPG	☒
57	31/05/18 14:53	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/03/18 10:44	Certificate of Insurance	Load PDF	
2	19/03/18 10:44	SLW 2857T ESTIMATE	Load PDF	
3	19/03/18 10:44	Singapore Accident Statement	Load PDF	
4	19/03/18 10:44	Insured Person's NRIC AND DL	Load PDF	
5	31/05/18 14:54	SLW 2857T SUPPLEMENTARY	Load PDF	
6	06/07/18 10:38	Workshop Invoice	Load PDF	
7	06/07/18 10:38	Discharge Voucher	Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	14/03/18 17:13	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	14/03/18 17:10	Accident Photo	Load JPG	☒
2	14/03/18 17:10	Accident Photo	Load JPG	☒
3	14/03/18 17:10	Accident Photo	Load JPG	☒
4	14/03/18 17:10	Accident Photo	Load JPG	☒
5	14/03/18 17:10	Accident Photo	Load JPG	☒
6	14/03/18 17:10	Accident Photo	Load JPG	☒
7	14/03/18 17:10	Accident Photo	Load JPG	☒
8	14/03/18 17:10	Accident Photo	Load JPG	☒
9	14/03/18 17:10	Accident Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
10	14/03/18 17:10	Accident Photo	Load JPG	☒
11	14/03/18 17:10	Accident Photo	Load JPG	☒
12	14/03/18 17:10	Accident Photo	Load JPG	☒
13	14/03/18 17:10	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	14/03/18 17:03	Sketch Plan	Load JPG	☒
2	14/03/18 17:03	Sketch Plan #2	Load JPG	☒

Documents Checklist

		Reset	Save	Print
DOCUMENTS CHECKLIST				
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18004981/ARBE2

Date: 06/07/2018

REFERENCE

Insured/Claimant: SEOW DONG JIE, PATRICK
Date of Loss: 13/03/2018Policy No: 1800012222
Nature of Claim: OD

Claim No: 3146515801SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW2857T**
Make & Model: AUDI A3, 999cc TFSI (A)
Reg. Date: 05/02/2018 (Man. Year: 2017)
Colour: Grey
Engine Capacity: 999 cc
Market Value/New Car Price: S\$125,000.00
Sum Insured (S\$): **Market Value/New Car Price**Engine No: CHZ640416
Chassis No: WAUZZZ8V1JA072156
Odometer: 2006 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):
Handbrake (Serviceable): Yes Engine Modification:Yes Footbrake (Serviceable): Yes
No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16
Front Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm
*The above values represent the remaining tyre treads depth*Rear Tyre Size: 205/55 R16
Rear Left Side: Bridgestone 6 mm
Rear Right Side: Bridgestone 6 mm

	Repairer's	Adjuster's	Difference	Diff %
COST OF CLAIMS				
Parts	32,550.08	13,533.08	19,017.00	58.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,332.00	7,302.00	5,030.00	40.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,882.08	20,835.08	24,047.00	53.58
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	44,282.08	20,235.08	24,047.00	54.30
+ GST 7.00/7.00% (S\$)	3,099.75	1,416.46	1,683.29	54.30
Nett Amount (S\$)	47,381.83	21,651.54	25,730.29	54.30

INSPECTION

Date of Assignment: 15/03/2018
Date Inspected: 15/03/2018 Inspected At:Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

Adjuster Report

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,613.00 FS	*1,290.40 FS
2	2		*FRONT BUMPER GUIDE - LH/RH	Not Necessary	66.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - LOWER	Not Necessary	140.00 FS	*- FS
4	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Necessary	508.00 FS	*406.40 FS
5	1		*RADIATOR GRILLE	Cracked	1,239.00 FS	*991.20 FS
6	1		*RADIATOR GRILLE CLOSING ELEMENT - UPPER	Damaged	167.00 FS	*133.20 FS
7	1		*STICKER FOR AIR CONDITIONER	Necessary	7.00 FS	*4.88 FS
8	1		*SIGN CAUTION STICKER	Necessary	12.00 FS	*9.28 FS
9	2		*FRONT BUMPER GRILLE - LH / RH	Not Necessary	328.00 FS	*- FS
10	1		*FRONT BUMPER FOAM COVER	Not Necessary	105.00 FS	*- FS
11	1		*FRONT BUMPER FOAM	Not Necessary	162.00 FS	*- FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	633.00 FS	*- FS
13	1		*SET REINFORCEMENT BEAM BOLT	Not Necessary	31.00 FS	*- FS
14	2		*FRONT FENDER - LH / RH	Repair	1,492.00 FS	*- FS
15	1		*SET FRONT FENDER RIVET	Not Necessary	48.00 FS	*- FS
16	2		*FRONT FENDER BRACKET - LH / RH REAR	Not Necessary	82.00 FS	*- FS
17	2		*FRONT FENDER BRACKET - LH / RH FRONT	Not Necessary	48.00 FS	*- FS
18	2		*FRONT FENDER BRACE - LH / RH	Not Necessary	168.00 FS	*- FS
19	2		*FRONT FENDER CLOSING ELEMENT - LH / RH	Not Necessary	106.00 FS	*- FS
20	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	302.00 FS	*- FS
21	2		*LED HEADLIGHT - LH / RH	Cracked	9,776.00 FS	*7,820.80 FS
22	2		*MAIN LIGHT POWER MODULE	Not Necessary	1,329.00 FS	*- FS
23	2		*LIGHT CONTROL SYSTEM CONTROL UNIT	Not Necessary	972.00 FS	*- FS
24	2		*LED WITH HEAT SINK - LH / RH	Not Necessary	1,250.00 FS	*- FS
25	2		*HEADLIGHT HOSE - LH / RH	Not Necessary	68.00 FS	*- FS
26	2		*HEADLIGHT WASHER CYLINDER - LH / RH	Not Necessary	246.00 FS	*- FS
27	1		*HEADLIGHT WASHER HOSE	Not Necessary	57.00 FS	*- FS
28	1		*BONNET	Distorted	2,378.00 FS	*1,902.40 FS
29	1		*BONNET ATTACHMENT PARTS	Necessary	141.00 FS	*112.80 FS
30	2		*BONNET HINGE - LH / RH	Bent	106.00 FS	*84.64 FS
31	2		*BONNET HINGE COVER - LH / RH	Not Necessary	72.00 FS	*- FS
32	1		*BONNET DAMPER	Not Necessary	105.00 FS	*- FS
33	1		*BONNET EDGE PROTECTION	Necessary	24.00 FS	*18.88 FS
34	1		*BONNET CATCH HOOK - TOP	Not Necessary	78.00 FS	*- FS
35	2		*BONNET LOCK STRIKER - LH / RH	Not Necessary	192.00 FS	*- FS
36	1		*BONNET CATCH HOOK - BOTTOM	Not Necessary	55.00 FS	*- FS
37	2		*BONNET LOCK	Not Necessary	353.00 FS	*- FS
38	1		*BONNET LOCK BOWDEN CABLE	Not Necessary	50.00 FS	*- FS
39	1		*FRONT LOCK CARRIER	Cracked	638.00 FS	*510.00 FS
40	2		*LOCK CARRIER AIR GUIDE - LH / RH	Not Necessary	40.00 FS	*- FS
41	1		*LOCK CARRIER AIR GUIDE - UPPER	Not Necessary	10.00 FS	*- FS
42	1		*A/C CONDENSER	Not Necessary	500.00 FS	*- FS
43	1		*RADIATOR	Not Necessary	828.00 FS	*- FS
44	1		*ADDITIONAL RADIATOR	Not Necessary	799.00 FS	*- FS
45	2		*RADIATOR BRACKET - LH / RH	Not Necessary	75.00 FS	*- FS
46	1		*SET RADIATOR BUSH	Not Necessary	17.00 FS	*- FS
47	1		*COOLANT	Necessary	133.00 FS	*106.24 FS
48	1		*RADIATOR FAN WITH FAN RING	Not Necessary	1,425.00 FS	*- FS
49	1		*AIR FILTER AIR GUIDE	Not Necessary	59.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*AIR FILTER	Not Necessary	242.00 FS	*- FS
51	1		*CHARGE AIR COOLER	Not Necessary	658.00 FS	*- FS
52	2		*AIR COOLER SEAL	Not Necessary	26.00 FS	*- FS
53	1		*WINDSCREEN TRIM - LOWER	Not Necessary	156.00 FS	*- FS
54	1		*WINDSCREEN	Not Necessary	953.00 FS	*- FS
55	1		*RAIN SENSOR GEL FOIL	Not Necessary	127.00 FS	*- FS
56	1		*GLASS PRIMER	Not Necessary	19.00 FS	*- FS
57	1		*FRONT NO. PLATE	Bent	25.00 FS	*25.00 FS
58	1		*FRONT WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
59	1		*SUNDRIES	Necessary	500.00 FS	*56.88 FS
60	1		*INTAKE AIR GUIDE	Deformed	39.76 FS	*39.76 FS
61	1		*INTAKE AIR GUIDE COVER	Deformed	20.32 FS	*20.32 FS
62	1		*INTAKE MANIFOLD	Not Necessary	551.00 FS	*- FS
F=Franchise part. S=SpcNett.					Total Parts (\$\$)	32,550.08 13,533.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONRTOL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,000.00	1,000.00
3	TO DISMANTLE FRONT BUMPER, BOTH FRONT FENDERS, HEADLIGHTS AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW DAMAGED PANELS. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,400.00	3,250.00
4	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES AND BOTH A-PILLAR	New	4,000.00	2,500.00
5	TO RENEW INTAKE MANIFOLD AND ATTACHMENT PARTS	New	900.00	0.00
6	TO RENEW FRONT WINDSCREEN	New	480.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			12,332.00	7,302.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >