



Your Ref : DMCFHQ17-000059

Date: 01<sup>st</sup> September 2018

Our Ref : CC4/EQI18004982/Kja3s2

**M/s EQ Insurance Company Ltd**

5 Maxwell Road  
#17-00 Tower Block  
MND Complex  
Singapore 069110  
(The Motor Claims Department)

Dear Sir/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE NO: SBN  
4063U ACCIDENT ON 08/03/2018 INSURED VEHICLE SJD 7595P**

Instruction was received to inspect the vehicle Reg. No. SBN 4063U. The inspection was conducted on 14/03/2018 at the premises of M/s: Loh Heng, Blk 176 #03-08 Sin Ming Drive Singapore 575721.

The following information were recorded: -

Registration Number	: SBN 4063U
Make & Model	: Mercedes Benz 200E Auto
Year of Registration	: 1990
Engine Capacity	: 1996 cc
Body Colour	: Metallic Dark Blue
Chassis Number	: WDB1240212B312308
Speedometer Reading	: 465915 km

The vehicle sustained damages at the rear portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$ 9,000.00
Less: LTA Reimbursement Value (RV)	(S\$ 717.00)
Nett Liability	<u>S\$ 8,283.00</u>

Vehicle Inspected By:



KONG SENG CHEONG  
*Licensed Appraiser*



K.K. LAU  
*MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),  
AM CATARI(CAN), M. MATA(USA), M. Mdata(USA),  
Licensed Appraiser*

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.