

ASS. REC. BY:

REF: CS/MSG18005006/T1qd3n2 Special Instruction:

Surveyor: Taufik Menmen ASSIGNMENT (Office)From (Person): Catherine Thia of MSIG Date/Time: 15/3/18 @ 4:19pm

Estimated Cost: _____ Bill to: _____

OD TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKQ 8772H Insured: SJV 2786Tat Workshop m/s Cycle & Carriage Industries Tel: 8332 0062of 188 Pandan LoopPolicy No: 27434318Mcy Claim No: 551574

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 07/03/18
(Client's Record)CA / REV / REP. / REV 24 HRS wp H.O.D. Endorsement: _____Date/Time: 9:14am @ 16/3/18 Person Contacted: Vincent Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKQ 8772H - NBA / MSG18004411/Y D.O.A: 7/03/2018
	SJV 2786T - NBA / MSG18004411/Y D.O.A: 7/03/18
20/3/18 @ 2:36pm	revised to Catherine Thia via Menmen.
24/3/18 @ 2:11pm	confirmed with Vincent final fig \$12309.13, 7 days. called \$ 6724.87, 35%.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18005006/T1qd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 16-03-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SVJ 2786T	Veh. Inspected	SKQ 8772H
Policy No.	27434318MCY	Coverage (\$)	0.00
Claim No.	551574	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	16/03/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	07/03/2018	Inspection Date	16/03/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 20 Mar 2018

Preliminary Advice

Insured Vehicle No	: SJV2786T	Accident Date	: 07/03/2018
TP Vehicle No	: SKQ8772H	Assignment Date	: 15/03/2018
Make	: MERCEDES-BENZ E250	Est. Duration of Repair	: 8.00
Date of Inspection	: 17/03/2018		
Inspection At	: CYCLE & CARRIAGE INDUSTRIES PTE LTD (PANDAN LOOP) 188 PANDAN LOOP SINGAPORE 128378		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,962.39
Revised Amount	:S\$	12,289.50
Check Items (Estimated)	:S\$	4,152.89
Total	:S\$	16,442.39

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Mar 2018		15 Mar 2018 16:19 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	M3 MARINE GROUP PTE LTD, Co. Reg. No.: 200509344C		
Main Claimant:	GOLDEN AGRI INTERNATIONAL PTE LTD, Co. Reg. No.: 199800781G		
Vehicle Reg. No.:	SKQ8772H	Date of Loss:	07/03/2018 08:00 - :59
Claim Type:	TP / 551574	Policy/Cover Note No.:	27434318MCY Coverage: 19/01/2018 - 18/01/2019
Vehicle Reg. No. (Insured):	SJV2786T	Policy No. (Claimant):	
		Excess:	
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/03/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Pang Xiu Shi

From: Woon Choo Kwok
Sent: Wednesday, 7 March, 2018 11:51 AM
To: Catherine Thia; Pang Xiu Shi
Cc: Christopher Chionh; Foo Ai Ngoh; Jason Sim
Subject: FW: SKQ8772H//SJV2786T= DIRECT SETTLEMENT
Attachments: img-307112001-0001.pdf; SAS2370037.PDF

Follow Up Flag: Follow up
Flag Status: Flagged

Dear CT & PXS

FYA

Best Regards

Kwok Woon Choo
Senior Administrative Officer, Claims Services Direct line +65 6643 1330 | Direct fax +65 6225 7402 |
woonchoo_kwok@sg.msig-asia.com

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

-----Original Message-----

From: Agnes Lee
Sent: Wednesday, March 07, 2018 11:42 AM
To: Woon Choo Kwok <WoonChoo_Kwok@sg.msig-asia.com>
Subject: FW: SKQ8772H//SJV2786T= DIRECT SETTLEMENT

-----Original Message-----

From: Eric Lee Ming Hui [mailto:eric.lee@cyclecarriage.com.sg]
Sent: 07 March 2018 11:30
To: Claims <claims@sg.msig-asia.com>
Cc: Vincent Seah Yong Kuan <vincent.seah@cyclecarriage.com.sg>
Subject: SKQ8772H//SJV2786T= DIRECT SETTLEMENT

Dear Officer In-Charge,

This email is with regards to the above accident which has been reported by our customer. We have been instructed by him/her (motor vehicle number SKQ8772H), to submit a claim on his/her behalf as we are the authorised repair workshop for his/her car.

We note that you are the insurer (3rd party) of the (motor vehicle number SJV2786T) involved. As such we are proposing for a Direct Settlement with regards to the repair costs and other consequential losses.

We appreciate your assistance in this matter and look forward to your agreement on this direct settlement.

I can be reached at Vincent.seah@cyclecarriage.com.sg

Thank You.

Your Sincerely,

Vincent Seah
Service Advisor - Body Care & Repair
Mercedes-Benz Body Care & Repair Center
83320062

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 24 May 2018 2:11 PM
To: 'Vincent Seah Yong Kuan'; Taufikh (LKKAUTO)
Cc: SUR
Subject: RE: SKQ8772H- FINALIZE

Dear Vincent,

Confirm final fig \$12,309.13 before GST and 7 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Vincent Seah Yong Kuan [<mailto:vincent.seah@cyclecarriage.com.sg>]

Sent: Tuesday, 17 April 2018 9:35 AM

To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>

Subject: SKQ8772H- FINALIZE

Hi

Finalize

Vincent Seah

Cycle & Carriage Ind. Pte Limited

Body Care & Repair - Pandan Loop Service Center

188 Pandan Loop Singapore 128378

Tel : 83320062 (H/P) DID: 6771 4401

Fax.: 6872 1272

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0781G
Vehicle Details	
Vehicle No.:	SKQ8772H
Vehicle to be Exported:	No
Intended De-registration Date:	20 Mar 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E250 SEDAN (R18)
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	27492030235569
Chassis No.:	WDD2120362B060046
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$49,580.00
Original Registration Date:	02 Jan 2015
First Registration Date:	02 Jan 2015
Transfer Count:	0
Actual ARF Paid:	\$56,412.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Jan 2025
PARF Rebate Amount:	\$42,309.00
Intended COE Rebate Details	
COE Expiry Date:	01 Jan 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$68,689.00
COE Rebate Amount:	\$46,586.00
Total Rebate Amount:	\$88,895.00

The information contained herein is correct as at 20 Mar 2018

OK

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view **Expired ads**

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used MERCEDES E250, MERCEDES E250 Singapore, used MERCEDES E250 Singapore, used MERCEDES E250, used vehicles Singapore or even buy used MERCEDES E250 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/03/2018 09:50
Date Of Accident	07/03/2018 08:15
Exact Location Of Accident	CLEMENTI ROAD TWDS AYE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKQ8772H
Insured/Policyholder	
Name Of Registered Owner	GOLDEN AGRI INTERNATIONAL PTE LTD
Co Reg No	199800781G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97607118

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E250
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B28863902MCY
Cover Note Number	

Driver

Name of Driver	CHEN SAU HUA
NRIC No	S6972966E
Date Of Birth	04/03/1969
Occupation	INDOOR
Date Of Driving Pass	28/04/1995
Driving Experience	22 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97607118
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	1 STIRLING ROAD
Postcode	148942
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : RYAN CHEN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

NEARBY THE TRAFFIC LIGHT, THE CAR INFRONT ME STOP ABRUPTLY AND I MANAGED TO STOP ON TIME HOWEVER CAR B (SVJ2786T) DRIVER FAILED TO STOP AND BANGED INTO MY REAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SVJ2786T
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ALEX
NRIC/Passport Number	
Contact Number	96717333
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


07/03/18 09:10am
Policyholder's Signature
Date & Time

07/03/18 09:10am
Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's
Name:
NRIC/FIN No.:

Vincent Seah
Cycle & Carriage Industries Pte Ltd
Cycle & Carriage Repair Center
4401 HP: 8332 0062 Fax: 8332 1272
Email: vincent.seah@cyclecarriage.com.sg
DID: 6778 4401

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Seeing the traffic light the car in front me
stop abruptly and I managed to stop on time
however SUV 2786T driver Failed to stop and
banged into my rear.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

Policyholder's Signature

Date & Time

Driver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre

Name:

NRIC/FIN No.:

DID: 671 4401
 Body Care & Repair Centre
 Email: vincent.seah@cyclecar.com.sg
 Vincent Seah
 Cycle & Carriage Industries Pte Ltd
 HP: 8332 0062 Fax: 6872 1272

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg 28 Apr 1995

NP 428A



Licence No: S6972966E



4471393

NRIC No: S6972966E



Date of issue
15-09-2009

1 STIRLING ROAD
SINGAPORE 148942

NRIC No: S6972966E

Date: 01/02/2015

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S6972966E

Name

CHEN SAU HUA

Birth Date: 04 Mar 1969

Issue Date: 15 Sep 2009



001783182C

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S6972966E



Name

CHEN SAU HUA

陳少華

Race

CHINESE

Date of birth

04-03-1969

Country of birth

INDONESIA

Sex

M

S6972966E

**MSIG**

MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way, #21-01, SCX Centre 2, Singapore 068807
 Tel +65 6827 7888, Fax +65 6827 7800
 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
 (REPUBLIC OF SINGAPORE)
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

Form M.X.4
 Company Ownership

MOTORMAX PLUS-COMMERCIAL
Comprehensive

Certificate No. B 28863902 MCY

Excess : SGD600
 Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
 SKQ8772H

2. Name of Policyholder
 Golden Agri International Pte Ltd

3. Effective Date of the Commencement of Insurance for the purposes of the Act
 02/01/2018

4. Date of Expiry of Insurance
 01/01/2019

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.
 The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
 Approved Insurers

for Chief Executive Officer



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKQ8772H

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information
WIP No 21833
Reg No/Reg Date SKQ8772H / 02/01/2015
Date In/Mileage / 0
Chassis No WDD2120362B060046
Engine No 27492030235569
Make/Model MB/E 250 2.0 CGI SEDAN (W212
Colour/Trim 021 197 Obsidian Bl/ 042 274 Leather Jav

Account No	Terms	Date/Time Printed	CSE	Operator				
W1000558	Credit	07/03/2018/ 13:59	VS	356 / Vincent Seah				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : B28863902MCY // 07.03.18 DRIVE IN/EXCESS : 08.03.18 // TP CAR NO: SJV2786T-MSIG DATE IN/DATE SURVEY: BY/AUTHORIZED ON :								
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT							0.10	✓ 380.00
A BPILAB REMOVE & REFIT LUGGAGE COMPARTMENT, TRIM, GARNISH-CARPET FOR NECESSARY REPAIR. NETT								✓ 960.00
A BPILAB DISASSEMBLE AND REPLACE REAR BUMPER, REAR BOOT, END PANEL								End Panel Repair - 3840X End Panel Replce. - 2880 ✓ 5760.00
A BPIRES RESPRAY ON REAR BUMPER, REAR BOOT, END PANEL								End 1800 ✓ 2400.00
A BPILAB DISASSEMBLE AND ADJUST HEAD REST & REFINISH. NETT								✓ 240.00
M REAR SWITCHING MODULE, CODE B					1.00	118.57	00.00	118.57
M REAR SWITCHING MODULE, CODE A					1.00	118.57	00.00	118.57
M REAR SWITCH MODULE BRACKET					1.00	46.06	00.00	46.06
M SPACER RING					3.00	6.42	00.00	19.26
M SPACER RING					3.00	6.42	00.00	19.26
M [STR] DISTANCE SENSOR					6.00	172.07	00.00	1032.42
M ELECTRICAL WIRING HARNESS					1.00	121.05	00.00	121.05
M CENTRE REAR BUMPER CHROME MOULDING					1.00	158.78	00.00	158.78
M RIGHT REAR BUMPER CHROME MOULDING					1.00	128.17	00.00	128.17
M LEFT REAR BUMPER CHROME MOULDING					1.00	128.17	00.00	128.17
M RIGHT BOTTOM BRACKET					1.00	17.36	00.00	17.36
M LEFT BOTTOM BRACKET					1.00	17.36	00.00	17.36
M CENTRE BASIC MOUNTING FOR BUMPER					1.00	211.58	00.00	211.58
M REAR BOTTOM BUMPER					1.00	241.49	00.00	241.49
M RIGHT BRACKET					1.00	34.78	00.00	34.78
M LEFT BRACKET					1.00	34.78	00.00	34.78

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKQ8772H

MSIG INSURANCE (S'PORE) PTE LTD
MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information
WIP No 21833
Reg No/Reg Date SKQ8772H / 02/01/2015
Date In/Mileage / 0
Chassis No WDD2120362B060046
Engine No 27492030235569
Make/Model MB/E 250 2.0 CGI SEDAN (W212)
Colour/Trim 021 197 Obsidian Bl/ 042 274 Leather Jav

Account No	Terms	Date/Time Printed	CSE	Operator
WI000558	Credit	07/03/2018/ 13:59	VS	356 / Vincent Seah
Description of Goods / Services				
	Qty	Unit Price	Disc%	Amount
M REAR BUMPER	1.00	1630.57	00.00	1630.57
M REAR BOOT WEATHERSTRIP	1.00	175.69	00.00	175.69
M TRUNK LID	1.00	2709.70	00.00	2709.70
M E250 MODEL PLATE	1.00	74.42	00.00	74.42
M GROMMET	3.00	2.23	00.00	6.69
M MERCEDES STAR	1.00	46.63	00.00	46.63
M REAR BOOT CHROME MOULDING	1.00	113.13	00.00	113.13
M REAR END PANEL	1.00	1228.45	00.00	1228.45
M REAR CROSS MEMBER	1.00	789.45	00.00	789.45

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanphk 97495749
16/3/18 1630
Resurvey before paint
sur @ lkkauto.com
tanphk@lkkauto.com
7-8 days

20/3/18

Confirmed & accepted by

Nett 18,962.39
7% GST on 18962.39 1327.37
Total Payable 20,289.76

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKQ8772H

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Vehicle & Document Information

21833
SKQ8772H / 02/01/2015
16/03/2018 / 29901
WDD2120362B060046
27492030235569
MB/E 250 2.0 CGI SEDAN (W212)
021 197 Obsidian Bl/ 042 274 Leather Jav

SKQ8772H

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WI000558	Credit	17/04/2018/ 09:31	VS	356 / Vincent Seah				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount

M. BPNSUN
POLICY NO/ACC DATE : B28863902MOY // 15.03.18
DRIVE IN/EXCESS : 08403.18 // TP CAR NO: SUV2786T-MSIG
DATE IN/DATE SURVEY: 15.03.18 // 16.03.18 TAUFIKH-LKK 16:00PM
DIRECT SETTLEMENT: CATHERINE THIA-MSIG// 12.03.18

A BPILAB
USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO
IDENTIFICATION STANDARD. NETT

A BPILAB
REMOVE & REFIT LUGGAGE COMPARTMENT, TRIM, GARNISH-
CARPET FOR NECESSARY REPAIR. NETT

A BPILAB
DISASSEMBLE AND REPLACE REAR BUMPER, REAR BOOT, END PANEL

A BPIRES
RESPRAY ON REAR BUMPER, REAR BOOT, END PANEL

A BPILAB
DISASSEMBLE AND ADJUST HEAD REST & REFINISH. NETT

X REAR SWITCHING MODULE, CODE A

X SPACER RING

X CENTRE REAR BUMPER CHROME MOULDING

X RIGHT REAR BUMPER CHROME MOULDING

X LEFT REAR BUMPER CHROME MOULDING

X RIGHT BOTTOM BRACKET

X LEFT BOTTOM BRACKET

X REAR BUMPER

X TRUNK LID

X E250 MODEL PLATE

X GROMMET

X MERCEDES STAR

X REAR BOOT CHROME MOULDING

X REAR CROSS MEMBER

X STOP

X RIVETED NUT

Finalization
7 days

0.10 380.00

960.00

2880.00

1800.00

240.00

1.00 118.57 00.00 118.57

6.00 6.42 00.00 38.52

1.00 158.78 00.00 158.78

1.00 128.17 00.00 128.17

1.00 128.17 00.00 128.17

1.00 17.36 00.00 17.36

1.00 17.36 00.00 17.36

1.00 1630.57 00.00 1630.57

1.00 2709.70 00.00 2709.70

1.00 74.42 00.00 74.42

3.00 2.23 00.00 6.69

1.00 46.63 00.00 46.63

1.00 113.13 00.00 113.13

1.00 789.45 00.00 789.45

2.00 9.41 00.00 18.82

4.00 3.66 00.00 14.64

all 18.82
all 14.64

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKQ8772H

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

WIP No

21833

Reg No/Reg Date

SKQ8772H / 02/01/2015

Date In/Mileage

16/03/2018 / 29901

Chassis No

WDD2120362B060046

Engine No

27492030235569

Make/Model

MB/E 250 2.0 CGI SEDAN (W212

Colour/Trim

021 197 Obsidian Bl/ 042 274 Leather Jav

Vehicle & Document Information

SKQ8772H

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WI000558	Credit	17/04/2018/ 09:31	VS	356 / Vincent Seah	1.00	38.15	00.00	38.15
Description of Goods / Services								

X COVER

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Finalization

Confirmed & accepted by

7% GST on **Nett 12,309.13**
861.64
Total Payable 13,170.77

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKQ8772H

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information
WIP No 21833
Reg No/Reg Date SKQ8772H / 02/01/2015
Date In/Mileage 16/03/2018 / 29901
Chassis No WDP2120362B060046
Engine No 27492030235569
Make/Model MB/E 250 2.0 CGI SEDAN (W212)
Colour/Trim 021 197 Obsidian Bl/ 042 274 Leather Jav

SKQ8772H

Account No	Terms	Date/Time Printed	CSE	Operator
W1000558	Credit	17/04/2018/ 09:31	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

M BPNSUN

POLICY NO/ACC DATE : 828805902M0Y // 07/03/18
DRIVE IN/EXCESS : 08/03/18 // TP CAR NO: SUV2786T-MSIG
DATE IN/DATE SURVEY: 15.03.18 // 16.03.18 TAUFIKH-LKK 16:00PM
DIRECT SETTLEMENT: CATHERINE THIA-MSIG// 12.03.18

X STOP
X RIVETED NUT
X COVER

2.00	9.41	00.00
4.00	3.66	00.00
1.00	38.15	00.00

18.82 net
14.64 net
38.15 de

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

	Nett	71.61
7% GST on	71.61	5.01
Total Payable		76.62

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 6388
Fax: 6779 5363
www.mercedes-benz.com.sg

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005006/T1QD3N2

Date: 28/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	27434318MCY
Claimant Vehicle No :	SKQ8772H	Insured Vehicle No :	SJV2786T
Date of Loss:	07/03/2018	Nature of Claim:	TP
		Claim No:	551574

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ8772H	Engine No:	27492030235569
Make & Model:	MERCEDES-BENZ E250, 2.0 SEDAN (R18) (A)	Chassis No:	WDD2120362B060046
Reg. Date:	02/01/2015 (Man. Year: 2014)	Odometer:	34394 km
Colour:	Black		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/35 R18	Rear Tyre Size:	265/35 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,294.00	6,049.13	3,244.87	34.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,740.00	6,260.00	3,480.00	35.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,034.00	12,309.13	6,724.87	35.33
+ GST 7.00/7.00% (S\$)	1,332.38	861.64	470.74	35.33
Nett Amount (S\$)	20,366.38	13,170.77	7,195.61	35.33

INSPECTION

Date of Assignment:	15/03/2018	
Date Inspected:	16/03/2018	Inspected At:
		Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 May 2018)
Parts:	143	MERCEDES-BENZ E250 2.0 SEDAN (R18) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ8772H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR SWITCHING MODULE, CODE B	Not Necessary	118.57 FS	*- FS
2	1		*REAR SWITCHING MODULE, CODE A	Distorted	118.57 FS	*118.57 FS
3	1		*REAR SWITCH MODULE BRACKET	Not Necessary	46.06 FS	*- FS
4	3		*SPACER RING	Necessary	19.26 FS	*19.26 FS
5	3		*SPACER RING	Necessary	19.26 FS	*19.26 FS
6	6		*(STR) DISTANCE SENSOR	Not Necessary	1,032.42 FS	*- FS
7	1		*ELECTRICAL WIRING HARNESS	Not Necessary	121.05 FS	*- FS
8	1		*CENTRE REAR BUMPER CHROME MOULDING	Cut	158.78 FS	*158.78 FS
9	1		*RIGHT REAR BUMPER CHROME MOULDING	Necessary	128.17 FS	*128.17 FS
10	1		*LEFT REAR BUMPER CHROME MOULDING	Necessary	128.17 FS	*128.17 FS
11	1		*RIGHT BOTTOM BRACKET	Cracked	17.36 FS	*17.36 FS
12	1		*LEFT BOTTOM BRACKET	Cracked	17.36 FS	*17.36 FS
13	1		*CENTRE BASIC MOUNTING FOR BUMPER	Not Necessary	211.58 FS	*- FS
14	1		*REAR BOTTOM BUMPER	Not Necessary	241.49 FS	*- FS
15	1		*RIGHT BRACKET	Not Necessary	34.78 FS	*- FS
16	1		*LEFT BRACKET	Not Necessary	34.78 FS	*- FS
17	1		*REAR BUMPER	Deformed	1,630.57 FS	*1,630.57 FS
18	1		*REAR BOOT WEATHERSTRIP	Not Necessary	175.69 FS	*- FS
19	1		*TRUNK LID	Bent	2,709.70 FS	*2,709.70 FS
20	1		*E250 MODEL PLATE	Necessary	74.42 FS	*74.42 FS
21	3		*GROMMET	Necessary	6.69 FS	*6.69 FS
22	1		*MERCEDES STAR	Necessary	46.63 FS	*46.63 FS
23	1		*REAR BOOT CHROME MOULDING	Necessary	113.13 FS	*113.13 FS
24	1		*REAR END PANEL	Not Necessary	1,228.45 FS	*- FS
25	1		*REAR CROSS MEMBER	Bent	789.45 FS	*789.45 FS
26	2		*STOP	Necessary	18.82 FS	*18.82 FS
27	4		*RIVETED NUT	Necessary	14.64 FS	*14.64 FS
28	1		*COVER	Deformed	38.15 FS	*38.15 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 9,294.00 6,049.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	380.00	380.00
2	REMOVE & REFIT LUGGAGE COMPARTMENT,TRIM,GARNISH-CARPET FOR NECESSARY REPAIR	New	960.00	960.00
3	DISASSEMBLE AND REPLACE REAR BUMPER,REAR BOOT,END PANEL	New	5,760.00	2,880.00
4	RESPRAY ON REAR BUMPER,REAR BOOT,END PANEL	New	2,400.00	1,800.00
5	DISASSEMBLE AND ADJUST HEAD REST & REFINISH	New	240.00	240.00
Gross Labour Cost (S\$)			9,740.00	6,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >