

ASS. REC. BY:

REF: CS/FCI18005008

Uvd3

n2

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

(WS)

From (Person): Aung Yin Min

of FCI

Date/Time: 15/3/18 @ 4:23pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJD 9339A

Insured: SHB 2316X

at Workshop m/s SME Motor

Tel: 67476106

of 1 Kaki Bkt Ave 6 # 02-15 Autobay

Policy No:

Claim No: D18002147MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14/03/2018

CA / REV / REP. / REV 24 HRSlop

H.O.D. Endorsement:

Date/Time: 9:27am @ 16/3/18

Person Contacted: Pei Ying

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJD 9339A - x

SHB 2316X - CS/MSG15016486/Hlqbd1

D.O.A: 26/4/15

22/3/18

Email preli revised to FCI

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

FCI/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: STD 9339Aat Workshop m/s SME 9.30of SKH

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STD 9339A Yr Regn: 9.14Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAIMake: Mer 5012 c.c. 2996Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 33659 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDC166562A344772Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/50 R19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 5 mmL/Bal. 5 mmD.O.A. 14/3/18

Survey held at _____

Rear

R/Bal. 5 mmL/Bal. 5 mmD.O.I. 21/3/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

10/5/18 no second hand parts.
Confirmed final by \$2081.50 with AHying (Red 2923, 580
Note: New parts replacement CR sum 14/05/18
(No LS)

RECEIVED 14 MAY 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 14/5 - typistDays Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: CWSLump Sum / I.B.I. (\$ 2081.50)

140

50

50

26

266



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18005008/Uvd3		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 16-03-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2316X	Veh. Inspected	SJD 9339A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002147MFSH	Excess (\$)	0.00	
Assign From	CWS (AUNG YIN MIN)	Assign Date	16/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/03/2018	Inspection Date		
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18002147MFSH

Our ref: CS/FCI18005008/Uvd3

DATE: 22/3/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. SJD 9339A


We thank for your instruction on 15/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 21/3/2018 at the premises of M/s SME MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$5,004.50
Revised Estimate Amount	: S\$2,081.50
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s body.



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	15-03-2018	Our Ref No. D18002147MFSH
Accident Date	14-03-2018	Claim Type. Third Party
Insured Vehicle	SHB2316X	Third Party Vehicle. SJD9339A
Survey Location	1 KAKI BUKIT AVE 6 BLK D #02-15/16/17/18AUTOBAY @ KAKI BUKIT	
Contact Person.	PEIYING	
Contact No.	67476106/ 0	Fax No. 67442368
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SME MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235983)



PRI Documents



Close X

PRI Header Details

Claim No	D18002147MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & SME MOTI
Workshop Name	SME MOTOR PTE LTD (Contact Person : PEIYING)	Survey Location & Contact Details	1 KAKI BUKIT AVE 6 BLK D #02-15/16/17/18AUTOBAY (Mobile: 0 , Phone: 67476106 , Fax: 67442368 EmailId: PEIYING@SMEMOTOR.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB2316X	TP Vehicle No	SJD9339A
PRI Recieved Date	15-03-2018 04:45:51 PM	Surveyor Appointed Date	15-03-2018 04:22:37 PM	Surveyor Accept Date	16-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	16-03-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 22 March 2018 3:31 PM
To: 'Claim Workflow System'
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002147MFSH/1, SJD 9339A
Attachments: SJD 9339A PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJD 9339A
Date of survey: 21/3/2018
Number of days:3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 16 March 2018 9:30 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002147MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 15 March 2018 4:22 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; AUNGYINMIN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002147MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 7019Z

Vehicle Details

Vehicle No.: SJD9339A
Vehicle to be Exported: No
Intended De-registration Date: 21 Mar 2018
Vehicle Make: MERCEDES BENZ
Vehicle Model: ML400 4MATIC (R19 BI)
Primary Colour: Grey
Manufacturing Year: 2013
Engine No.: 27682130024916
Chassis No.: WDC1660562A344772
Maximum Power Output: 245.0 kW (328 bhp)
Open Market Value: \$70,080.00
Original Registration Date: 09 Sep 2014
First Registration Date: 09 Sep 2014
Transfer Count: 0
Actual ARF Paid: \$98,144.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 08 Sep 2024
PARF Rebate Amount: \$73,608.00

Intended COE Rebate Details

COE Expiry Date: 08 Sep 2024
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$73,010.00
COE Rebate Amount: \$47,206.00
Total Rebate Amount: \$120,814.00

The information contained herein is correct as at 21 Mar 2018

OK

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S : FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD #16-01

CITY HOUSE

Singapore 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Your Ref No: 18/FC/TP-056 (03)

Claim Type: Third Party

Accident Date: 14/03/2018

TP Veh Reg No: SHB2316X

Estimate No: EST0004012

Date: 15 Mar 2018

Policy No: GA118571

Veh Reg No: SJD9339A

Make/Model: M.BENZ ML400

Chasis No: WDC1660562A344772

Engine No: 27682130024916

Reg. Date: 09/09/2014

Estimate Repair Cost to Vehicle No :SJD9339A

Description	Quantity	List Price	Amount
		SS	SS
Net Price			
1 FRT LH DOOR	1 PC	2,700.00	2,700.00
2 FRT LH DOOR INNER RUBBER	1 PC	270.00	270.00
3 LH SIDE STEP (TOP)	1 PC	1,160.00	1,160.00
4 LH SIDE STEP (LOWER)	1 PC	375.00	375.00
		4,505.00	4,505.00
	Less 10%	450.50	4,054.50
Labour			
5 WIRE CHECKING	1 UNIT	50.00	50.00
6 TRANSFER DOOR COMPONENT FROM OLD TO NEW	1 UNIT	150.00	150.00
7 LABOUR CHARGE	1 UNIT	450.00	450.00
8 SPRAY PAINTING	1 UNIT	300.00	300.00
		950.00	950.00
Total			SS 5,004.50
Add GST @ 7%			350.32
Total Amount Payable			SS 5,354.82

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND THREE HUNDRED FIFTY FOUR AND CENTS EIGHTY TWO ONLY

For SME Motor Pte Ltd

not signed
Lian
before & after repair
3 days
21/3/18
p/p @ 208/50

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18005008/Uvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 15-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2316X	Veh. Inspected	SJD 9339A	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18002147MFSH	Excess (\$)	0.00	
Assign From	AUNGYM	Assign Date	15/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ (A)	c.c	2996	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WDC1660562A344772	Colour	GREY	
Odometer	33659	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/50 R19	PIRELLI	5 mm	
L/H Front Tyre	255/50 R19	PIRELLI	5 mm	
R/H Rear Tyre	255/50 R19	PIRELLI	5 mm	
L/H Rear Tyre	255/50 R19	PIRELLI	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/03/2018	Inspection Date	21/03/2018	
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJD 9339A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT LH DOOR (N)	TO REPAIR SEE LABOUR	2,700.00	-
1	FRT LH DOOR INNER RUBBER (N)	NOT NECESSARY	270.00	-
1	LH SIDE STEP (TOP)(N)	DISTORTED	1,160.00	1,160.00
1	LH SIDE STEP (LOWER)(N)	DISTORTED	375.00	375.00
	LESS 10% DISCOUNT		-450.50	-153.50
			4,054.50	1,381.50
<u>LABOUR</u>				
	WIRE CHECKING.	NOT NECESSARY	50.00	20.00
	TRANSFER DOOR COMPONENT FROM OLD TO NEW.		150.00	-
	LABOUR CHARGE INCLUSIVE OF THE REPAIR OF FRT LH DOOR.		450.00	400.00
	SPRAY PAINTING.		300.00	280.00
			950.00	700.00
GRAND TOTAL			5,004.50	2,081.50
RECOMMENDED COST OF REPAIRS				2,081.50

Report Ref No. CS/FCI18005008/Uvd3n2

NOTE: NEW PARTS REPLACEMENT

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.