



ZOOM AUTOWERKS PTE LTD

832 Sims Avenue, Eunosville

#12-884 Singapore 400832

Tel: 9450 7920

* zoomautowerks@gmail.com

D.O.A : 15 March 2018

16 March 2018

OWNER : MUHAMMAD SALIM BIN BIN SAID

REG NO. : SGD 9381 L

MAKE/MODEL : TOYOTA VIOS

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear windscreen moulding	\$ 17 68.90 X
1	Rear boot lid	\$ 10/suc 596.50 ✓
2	Rear boot hinges	\$ 17 139.20 X
1	Rear boot inner trim	\$ 15 52.00 X
1	Rear boot lock	\$ 4m 49.50 ✓
1	Rear boot lock catch	\$ 17 38.30 X
1	Rear boot logo	\$ 1m 32.50 ✓
1	Rear boot rubber	\$ 1m 181.20 ✓
1	Rear boot "VIOS" emblem	\$ 1m 30.90 ✓
1	Rear boot "1.5" emblem	\$ 1m 31.20 ✓
1	Rear boot "E" emblem	\$ 1m 36.30 ✓
1	Rear boot "VVTi" emblem	\$ 1m 36.50 ✓
1	Rear boot number plate garnish	\$ 17 98.30 X
1	Rear number plate lamp (1 set)	\$ 17 84.40 X
2	Rear taillamps	\$ 15 641.00 X
2	Rear taillamp panels	\$ 17 316.40 X
1	Rear end panel	\$ 17 758.50 X
1	Rear end panel inner garnish	\$ 4m 89.50 ✓
1	Rear bumper	\$ 10/oc 485.60 ✓
2	Rear bumper brackets	\$ 34 50.00 ✓
2	Rear bumper side retainers	\$ 34 57.20 ✓
1	Rear floor panel	\$ 17 793.30 X
1	Rear floor board	\$ 17 123.80 X
2	Rear floor side boards	\$ 17 247.60 X
1	Rear exhaust silencer	\$ 17 754.20 X
2	Rear exhaust mountings	\$ 17 65.00 X
2	Rear fenders	\$ 17 1,764.40 X
2	Rear fender air gates	\$ 17 85.00 X
2	Rear fender inner trims	\$ 17 301.90 X
		\$ 8,009.10
Less 25%		\$ 2,002.28
		\$ 6,006.83

SPECIAL NETT ITEMS

1	Rear windscreen sealant	\$	11	80.00	X
1	Rear boot inner trim clip (1 set)	\$	11	35.00	X
1	Rear end panel sealant	\$	11	50.00	X
1	Rear bumper clip (1 set)	\$	11	45.00	X
1	Rear number plate	\$	11	50.00	X
1	Rear reverse sensor (1 set)	\$	11	350.00	200
				<u>610.00</u>	
					245

S/N**LABOUR CHARGES**

1	To remove, replaced damaged lamps and check up rear wiring.	\$		80.00	20
2	To remove and refit inner garnishes.	\$		150.00	60
3	To remove and refit rear reverse sensor.	\$		150.00	50
4	To transfer rear boot lid mechanism and wiring assembly.	\$		120.00	60
5	To remove and refit rear windscreen glass.	\$	11	180.00	X
6	To remove, refit and replace exhaust silencer and mountings.	\$	11	150.00	X
7	To apply undercoating.	\$		200.00	50
8	Panel beating.	\$		2,000.00	600
9	To re-spray painting on the affected areas.	\$		1,800.00	800
				<u>4,830.00</u>	
					1640

GRAND TOTAL :**\$ 11,446.83**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: