



## Auto Insure Pte. Ltd.

Bik 3, 391A Woodlands Road  
 Yew Tee Industrial Estate  
 Singapore (677964)  
 E: claims@autoinsure.com.sg  
 W: www.autoinsure.com.sg  
 T: 6368 2788 F: 6368 0081  
 GST No.: 201437380M

Page No.1

### AUTOMOBILE ASSESSMENT REPORT

Our Ref: SLM1174P  
 Your Ref: SHC3975G

Date: 15-Mar-18

BY EMAIL ONLY  
 (claims@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT  
 email: motorclaim@iii.com.sg

India International Insurance Pte Ltd  
 64 Cecil St,  
 #04-#05 IOB building,  
 49711

Assessed Vehicle No : SLM1174P  
 Car Make and Model : MAZDA3 1.5L SDN  
 Date of Accident : 14-Mar-18  
 Date of Assessment : 15-Mar-18

We have carried out a physical assessment of SLM1174P at our workshop Auto Insure Pte Ltd sustained damages to the REAR portion of the vehicle.


#### 4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the REAR portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : P/P  
 Adjusted Amount : \$ 6,500.00  
 Est. Repair Days : 4



\*\* Considering that our vehicle is less than 6 months old.  
 We will not agree to any repair of parts, only replacement will be done. \*\*

Pursuant to your instruction, we have NOT AUTHORIZED repair.  
 The assessment was conducted on a "WITHOUT PREJUDICE" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

#### Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.  
 No liability or responsibility whatsoever shall be held by  
 AUTO INSURE PTE LTD. For any reliance on this report by any third party.

2 days.

Sebastian  
 16/3/18.

- Part by part repair.  
 - Photo After repair.  
 70036121

sebastianyeang@lkkauto.com.

#### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1	2	REAR REVERSE SENSOR	✓ DMG	\$	280.00
2	1 SET	REAR BUMPER CLIPS	✓ NEC	\$	50.00
				SUB TOTAL	\$ 340.00
				TOTAL PARTS COST	\$ 3,190.72

200  
30

Our Ref: SLM1174P

Your Ref: SHC3975G

S/NO	DESCRIPTION	EST. BY WORKSHOP
<b>LABOUR &amp; PAINTWORK</b>		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ <del>1,000.00</del>
2	TOWING CHARGE	
3	TO CONDUCT HEADLAMP FOCUS	\$ -
4	TO REMOVE/REFIX A/C CONDENSOR & REFILL AIRCON GAS	\$ -
5	TO REMOVE/INSTALL REAR WINDSCREEN	\$ -
6	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	\$ 150.00
	TO CONDUCT WHEEL ALIGNMENT	\$ -
	LABOR FOR UNDERCARRIDGE	\$ -
7	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ 80.00
8	TO REMOVE / INSTALL REAR REVERSE SENSOR	\$ <del>150.00</del>
9	TO REMOVE / REFIX UPHOSTERY, GARNISH AND ATTACHMENT PARTS	\$ 180.00
10	TO REMOVE / REFIX REAR LUGGAGE COMPARTMENT	\$ <del>150.00</del>
11	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ <del>800.00</del>
12	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ 150.00
13	TO VACUUM, WAXING & CLEAN	\$ 100.00
14	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ 100.00
TOTAL BEFORE GST		\$ 6,050.72
GST 7%		\$ 423.55
TOTAL (PARTS & LABOUR):		\$ 6,474.27

200

X

X

40

X

30

200

X

X

#### Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$6,500.00 for direct settlement with the third party insurance.

Yours Faithfully,

Jason Heng  
Claims Director

Our Ref: SLM1174P  
 Your Ref: SHC3975G

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
<u>PARTS REPLACEMENT - LIST ITEMS</u>				
1	1	REAR BUMPER R		\$ 1,365.50
2	2	REAR BUMPER SIDE RETAINERS ?		\$ 118.00
3	1	REAR REINFORCEMENT ?		\$ 589.90
4	1	REAR END PANEL ?		\$ 885.00
5	1	REAR END PANEL TOP GARNISH ?		\$ 425.00
6	1	REAR BUMPER REFLECTOR RH Y		\$ 180.00
			SUB TOTAL	\$ 3,563.40
			LESS 20%	\$ 712.68
			TOTAL AMOUNT	\$ 2,850.72