

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
GREAT AMERICAN INSURANCE COMPANY				CS3/GAI18005017/R	1d3e2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190				28-06-2018		
			Code:	GAI		
1. Policy Particulars :- (THIRD PARTY CLAIM)						
	Insured Veh.	PC 4815J	Veh. In	spected	PC 9060L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.		Excess	s (\$)	0.00	
	Assign From	RACHEL TAN	Assign	n Date	16/03/2018	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA HIACE 3.0 (A)	c.c		2982	
	Engine No.	HIDDEN	Year o	f Reg.	2017	
	Chassis No.	KDH2230030491	Colour		WHITE	
	Odometer	66948 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modifie	cation	NIL	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15C	MICHE	LIN	6 mm	
	L/H Front Tyre	195 R15C	MICHEL	LIN	6 mm	
	R/H Rear Tyre	195 R15C	MICHEL	LIN	6 mm	
	L/H Rear Tyre	195 R15C	MICHEL	LIN	6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRO			RTION.		
5.	General Information					
	Accident Date	14/03/2018	Inspec	t Date / Time	16/03/2018 (02:46 PM)	
	Survey held at	160 SIN MING DRIVE #03-08				
	Repairer	Repairer MSM LOGISTICS PTE LTD				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500-\$5,300					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					

Report Ref No. CS3/GAI18005017/R1d3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

BEng(Hons), B. Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.