

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHF727K -

AAD1803-119

Not Authored
1/1/18 \$2450

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHF727K - CANDY
 VF1ABL15AUC281194
 RENAULT
 LATITUDE
 14.03.2018
AIG

PART		LIST
1	1 BUMPER COVER REAR	\$ <i>Buc/Red</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$ <i>Red/Wh</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$ <i>Sh</i> 113.47 X
4	1 BUMEP R BRACKET SIDE RH REAR	\$ <i>Sh</i> 135.97 X
5	1 BUMEP R RETAINER RH REAR	\$ <i>Sh</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$ <i>Sh</i> 43.61 X
7	1 BUMEP R BRACKET SIDE LH REAR	\$ <i>Sh</i> 135.97 X
8	1 BUMEP R RETAINER LH REAR	\$ <i>Sh</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$ <i>Sh</i> 43.61 X
10	1 BUMPER BEAM REAR	\$ <i>Bj</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$ <i>R</i> 225.95
12	1 BUMPER BEAM BRACKET RH REAR	\$ <i>R</i> 225.95
13	1 BOOT REAR	\$ <i>R</i> 2,872.68
14	1 BOOT FINISHER	\$ <i>Sh</i> 470.06
15	1 BOOT WHEATERSTRIP	\$ <i>Sh</i> 323.05
16	1 BOOT REFLECTOR LAMP LH	\$ <i>Sh</i> 493.35
17	1 BOOT REFLECTOR LAMP RH	\$ <i>Sh</i> 493.35
18	1 BOOT BADGE 'RENAULT'	\$ <i>nn</i> 225.36
19	1 BOOT BADGE	\$ <i>nn</i> 225.36
20	1 BOOT SWITCH	\$ <i>Sh</i> 168.13
21	1 BOOT LOCK	\$ <i>R</i> 202.67
22	1 BOOT LOCK CATCH	\$ <i>R</i> 74.40
23	2 LICENCE PLATE LAMP	\$ <i>Sh</i> 50.52
24	2 BOOT RUBBER PLUG	\$ <i>Sh</i> 221.81
25	1 FENDER PANEL REAR LH	\$ <i>R</i> 3,299.13
26	1 WHEELARCH REAR LH	\$ <i>Sh</i> 543.47
27	1 FENDER PANEL REAR RH	\$ <i>R</i> 3,299.13
28	1 WHEELARCH REAR RH	\$ <i>Sh</i> 543.47
29	1 TAILLAMP RH	\$ <i>Sh</i> 552.55
30	1 TAILLAMP PANEL RH	\$ <i>R</i> 986.70
31	1 TAILLAMP LH	\$ <i>Sh</i> 552.55
32	1 TAILLAMP PANEL LH	\$ <i>R</i> 986.70
33	1 OUTER PANEL REAR (End Panel)	\$ <i>R</i> 1,471.77
34	1 OUTER PANEL REAR (End Panel)TRIM	\$ <i>Sh</i> 404.56

X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1803-119

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF727K -

35	1	EXHAUST REAR	\$	R	7,489.05	X
36	1	EXHAUST CAP REAR	\$	R	230.49	X
TOTAL			\$		29,849.67	
10%			\$		2,984.97	
			\$		26,864.70	

Special Nett

1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	nn	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	nn	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	nn	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	nn	17.82	} X
11	1SET	BOOT FINISHER CLIP	\$	nn	24.20	
12	1	BOOT STICKER "Trans-cab"	\$	nn	30.00	
13	1	BOOT STICKER "6555-3333"	\$	nn	30.00	
14	1SET	FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	
15	1SET	FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	
16	1	TAILLAMP CLIP RH	\$	nn	5.00	
17	1	TAILLAMP CLIP LH	\$	nn	5.00	
18	2	REAR WINDSCREEN SELANT	\$	nn	80.00	
19	1	WINDSCREEN MOULDING	\$	nn	100.00	
20	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
21	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00	
22	1	SPARE TYRE	\$	Sn	330.00	
TOTAL			\$		2,124.02	
TOTAL PARTS			\$		28,988.72	

Putty And Spray Painting Of The Affected Portion.	\$	2201	3,000.00
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2001	2,800.00
To Rust-Proofing Of The Affected Areas.	\$	nn	170.00 X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1803-119

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF727K -

To reinstall rear bumper parking sensor.	\$	170.00 <i>60%</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nr</i> 170.00 X
To repair and realign rear exhaust pipe.	\$	<i>nr</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nr</i> 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nr</i> 170.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nr</i> 380.00 X
Towing Fees	\$	<i>nr</i> 120.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nr</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>nr</i> 220.00 X

TOTAL	\$	7,710.00
Over All Total	\$	36,698.72

**(PARTS BY PARTS)
Repair Days**

*10Days
2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: