

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 14 May 2018

To : LKK

By Fax: 6256-4315

Attn: Rasul

Tel : 90010068

VEHICLE NO : FBC 4679B

Honda Revo 400

ACCIDENT DATE: 8 March 2018

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Handle Bar	1	150.00 <i>MT</i>
2 Meter Assy	1	1,500.00 <i>Bto</i>
3 Handle Bar Bracket Holder	1	30 280.00 <i>scr</i>
4 Headlamp	1	300 540.00 <i>CRs</i>
5 Brake Lever	1	75.00 <i>scr</i>
6 Fork Tube	1 set	350.00 <i>Bt</i>
7 Front Rim	1	600 850.00 <i>pro</i>
8 Brake Disc	1	650.00 <i>scr</i>
9 Front Mudguard	1	200 280.00 <i>pro</i>
10 Fork Bracket	1	280.00 <i>Bt</i>
11 Fuel Tank	1	1300 1,400.00 <i>PA</i>
12 Crash Bar	1 set	150 400.00 <i>Bt</i>
13 Mirror	1 set	80 196.00 <i>Bto</i>
14 Front Signal Light LH	1	80 175.00 <i>pro</i>

Sub-Total 7,126.00

Less 10% 5745 712.60

Sub-Total 6,413.40

10%
5170.50

(1)

VEHICLE NO : FBC 4679B

Honda Revo 400

Nett items

- 1 IU unit
- 2 Rear box
- 3 Front tyre
- 4 Front number plate
- 5 Towing fee
- 6 Remove & replace necessary parts, align & etc
- 7 Remove & replace fork assy, top up fork oil, replace front rim, brake disc, & alignment
- 8 Putty & respray paint & design with 3 tone colour
- 9 Check electrical harness wiring

170.00 X mm
350.00 150 sur /
250.00 cut /
15 20.00 10 /
40 50.00
450.00 250
250.00 100
480.00 350
60.00 30

Sub-Total 2,080.00

Nett Total 8,493.40

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you

SG 98 MOTOR PTE LTD

:LG

Rasm
Hp 90010068
4 days
2/5
16/03/18 @ 1415

5170.50
1185.00
6355.50
209
5084.40

4/5 5,100
4 days

2