

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 620J

AAD1803-115

*Not Authorised
L1 Sing & 7850J*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 620J

VF1ABL15AUC278507

RENAULT

LATITUDE

14.3.2018

EQ

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>Bz</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>Bz</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Bzi</i> 113.47 X
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 X
5	1 BUMPER RETAINER RH REAR	\$	<i>Sn</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61 X
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 X
8	1 BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61 X
10	1 BUMPER BEAM REAR	\$	<i>Bz</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>OII</i> 225.95 ✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>Bz</i> 225.95 ✓
13	1 BOOT REAR	\$	<i>Prv</i> 2,872.68 ✓
14	1 BOOT FINISHER	\$	<i>Sn</i> 470.06 X
15	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05 X
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35 X
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35 X
18	1 BOOT BADGE 'RENAULT'	\$	<i>Prv</i> 225.36 ✓
19	1 BOOT BADGE	\$	<i>Prv</i> 225.36 ✓
20	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45 X
21	1 BOOT SWITCH	\$	<i>Sn</i> 168.13 X
22	1 BOOT LOCK	\$	<i>R</i> 202.67 X
23	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40 X
24	2 LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52 X
25	2 BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81 X
26	1 TAILLAMP RH	\$	<i>Sn</i> 552.55 X
27	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70 X
28	1 TAILLAMP LH	\$	<i>Sn</i> 552.55 X
29	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70 X
30	1 OUTER PANEL REAR (End Panel)	\$	<i>Bz</i> 1,471.77 ✓

Trans-cab Auto Services Pte Ltd

AAD1803-115

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 620J

31	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>cm</i> 404.56 ✓
32	1 EXHAUST REAR	\$	<i>n</i> 7,489.05 ✗
33	1 EXHAUST CAP REAR	\$	<i>n</i> 230.49 ✗

TOTAL	\$	22,750.91
10%	\$	3,586.89
	\$	32,282.05

Special Nett

1	1SET PARKING AID	\$	<i>scr</i> 600 ✓
2	1SET REAR BUMPER CLIP	\$	<i>nu</i> 700.00 ✓
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>nu</i> 66.00 ✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>nu</i> 33.00 ✓
5	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>nu</i> 10.00 ✗
6	1SET BUMPER RETAINER RH CLIP RR	\$	<i>nu</i> 20.00 ✗
7	1SET BUMPER RETAINER CLIP LH RR	\$	<i>nu</i> 10.00 ✗
8	1SET BUMPER RETAINER CLIP LH RR	\$	<i>nu</i> 20.00 ✗
9	1SET BUMPER LOWER REAR RIVET	\$	<i>nu</i> 22.00 ✗
10	1SET BUMPER LOWER REAR CLIP	\$	<i>nu</i> 66.00 ✓
11	1 EXHAUST MOUNTING REAR	\$	<i>sn</i> 17.82 ✗
12	1SET BOOT FINISHER CLIP	\$	<i>nu</i> 24.20 ✗
13	1 BOOT STICKER "Trans-cab"	\$	<i>nu</i> 30.00 ✓
14	1 BOOT STICKER "6555-3333"	\$	<i>nu</i> 30.00 ✓
	1 BOOT INNER TRIM CLIP	\$	<i>nu</i> 45.00 ✗

TOTAL	\$	1,094.02
--------------	----	-----------------

TOTAL PARTS	\$	33,376.07
--------------------	----	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,500.00 <i>6601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,200.00 <i>6001</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>601</i>

Trans-cab Auto Services Pte Ltd

AAD1803-115

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 620J

To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i> 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	↷ 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	↷ 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	↷ 170.00	X
To check steering geometry and computer wheel alignment	\$	↷ 220.00	X
TOTAL		\$	9,040.00

Over All Total \$ 42,416.07

PART BY PART

Repair Days **10-DAYS**

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: