

SMRT Accident Vehicle Repair Estimates

AXA

LIWA

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4670D
 Ref. No : TAX/03/18/2069
 Reg. Date : 04/03/2015
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : NG SIM HOCK
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 14/03/2018 03:07:00 PM
 Accident Reported Date / Time : 14/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095050
 Special Instruction to ARC,if any :
 SKW9477Y - AXA
 Prepared Date : 14/03/2018 04:32:04 PM



Sebastian
 16/3/18.
 - Lump Sum Repair
 - Question Mark Item
 Photo
 - Photo After Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U605759065

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,014.00	0.00
Total Spray Painting Charges :	1,116.00	0.00
Total Material Charges :	3,866.98	3,866.98
Other Charges :	488.44	0.00
TOTAL :	6,485.42	0.00
Lum Sum Total :	6,500.00	0.00
No. of Repair Days :	6.00	0.00
Prepared / Adjusted By :		4 days
Arc / Surveyor Sing Off Date :	15/03/2018 10:12:45 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 15/03/2018 10:11:42 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :
Quotation Date : Invoice Date :
Invoice Amount : Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	1,014.00	0.00 600
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0.00 ?
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 100
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
Total Spray Painting & Panel Beating	1,116.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	148.44	0.00 ✓
TO REPLACE SUNDRY PARTS	100.00	0.00 ✗
TO WASH AND VACUUM	60.00	0.00 ✗
Total Other Costs	488.44	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-17930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace	No ✓ Defect
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace	No ✓ N/C
52611-17080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace	No
52021-17023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace	No
57014-17030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Replace	No
52116-17040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace	No
51529-17060			BRACKET, FR TURN CENTER LH	1	58.20	25.00	43.65	Replace	Replace	No
51529-17050			BRACKET, FR TURN LOWER LH	1	26.00	25.00	19.50	Replace	Replace	No
51529-17040			BRACKET, FR TURN UPPER LH	1	24.40	25.00	18.30	Replace	Replace	No
51521-17050			LENS & BODY, FR TURN LH	1	511.80	10.00	460.62	Replace	Replace	No ✓ C&K
53102-17020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace	No
52618-17050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.77	Replace	Replace	No
52113-17180			WIRE, ENGINE ROOM, NO.3	1	242.00	10.00	217.80	Replace	Replace	No
53201-17902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace	No R
51170-17500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace	No
53802-17050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace	No R
5374-17051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No ✓ N/C
53876-17030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace	No ✓ TN
53852-17020			FENDER LINER PAD, FR WHEEL. LH	1	49.30	25.00	36.97	Replace	Replace	No
TOTAL MATERIALS								4,833.75	4,833.72	
TOTAL MATERIALS(Discounted)								3,866.98	3,866.98	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									