

27/03/2018

ASS. REC. BY:

REF: CS/EG18005037/Aqd3n2 Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Yee Pei Li of EGI Date/Time: 16/3/18 @ 2.19pm

Estimated Cost: Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SJF 1376J Insured: GBA 1456H

at Workshop m/s Fastech Auto Tel: 6746 5405

of 1 Kaki Bkt Ave 6 # 01-46 Autobay

Policy No: Claim No: GBA 1456H / SE / pl

Sum Insured: Excess:

Make of Veh: D.O.A. 15/03/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 2.40pm @ 16/3/18 Person Contacted: Nancy Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SJF 1376J - CS/AGI 18000821/Klqd3n2 D.O.A.: 12/01/18
	GBA 1456H - X.
14/3/18 @ 3.17pm	Informed Steve Lim, we are pending estimate from repairer.
16/3/18 @ 3.50pm	revised to Steve Lim by email.
	LS \$4900, 6 days (Red \$5896.68, 55%)

REF:

ASS. REC. BY: Adrian Ling**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJF1376J Yr Regn: 2008, MayType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Axi c.c. 1496Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 184319 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NZE1416079852Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/70 R14R: 185/70 R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or hing hong

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 16/03/18Survey held at FastechDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Ergo.

COE Expiry: 28/02/23.

RECEIVED 26 MAR 2018

Date/Time, File Pass to?

1) 26/3/18 Adrian Ling

Date/Time, File Return to?

2) _____

☐ : Preli. Report☐ : Final ReportDays Of Repair: 6Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

_____\$ + RS. ____\$ SI

Photos

Others

TOTAL

350

Report Format: TPLump Sum / B.I. (\$) 4900



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park , Singapore 408933

TEL : 6256 3561 FAX : 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18005037/Aqd3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 16-03-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 1456H	Veh. Inspected	SJF 1376J
Policy No.		Coverage (\$)	0.00
Claim No.	GBA 1456H/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	16/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/03/2018	Inspection Date	16/03/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GBA1456H/SE/pl

Date: 26th March 2018

Our Ref: CS/EG118005037/Aqd3

Without Prejudice

The Motor Claims Department
ERGO Insurance Pte Ltd

Attn: Siti

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SJF 1376J


We thank you for the instruction on 16/03/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16/03/2018 at the premises of M/s FASTECH AUTO and have the following to report:-

Workshop Estimate Amount	: S\$ <u>10,796.68</u>
Revised Estimate Amount	: S\$ <u>4,900.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
Salvage Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the o/s portion & undercarriage.



Comments/ Present Status:

Damages consistent.

Days of repair: 6 days.

We have NOT authorise repair.

Yours faithfully

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Friday, 16 March 2018 2:19 PM
To: 'admin-d@lkkauto.com'
Subject: OI : GBA1456H / TP : SJF1376J/LKK / DOA : 15/03/2018
Attachments: GBA1456H - SAS.pdf; SJF1376J - SAS.pdf; SJF1376J - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : NANCY LAM @ 6746 5405

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date:	16.03.2018
Our Reference:	GBA 1456H/SE/pl
Your Reference:	SJF 1376J
To:	FASTECH AUTO PTE LTD

Sent via Fax

or

Email

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection:	SJF 1376J
Insured's Vehicle:	GBA 1456H
Date Of Accident:	15.03.2018

We acknowledge receipt of your request for PRS on: **15.03.2018**

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

✓	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
	Your request for inspection does not have your client's GIA report, kindly forward a copy.
	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
	Our Insured's driver has not reported the accident to us todate.
✓	Others: OFFICER-IN-CHARGE - STEVE LIM

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Journal of Management Education, 20(1), 1-10
 Copyright © 1996 Sage Publications
 10.1177/0095647296200001001

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .



Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 19 March 2018 5:17 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'; assignments; 'Steve Lim'
Cc: SUR
Subject: RE: GBA1456H / TP : SJF1376J/LKK / DOA : 15/03/2018

Dear Steve,

Please be informed that we have inspected the vehicle SJF 1376J on 16/03/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 16 March 2018 2:42 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBA1456H / TP : SJF1376J/LKK / DOA : 15/03/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Friday, 16 March 2018 2:19 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : GBA1456H / TP : SJF1376J/LKK / DOA : 15/03/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 26 March 2018 3:50 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'; assignments; 'Steve Lim'
Cc: SUR
Subject: RE: GBA1456H / TP : SJF1376J/LKK / DOA : 15/03/2018
Attachments: CSEGI18005037Aqd3.pdf

Dear Steve,

Enclosed herewith preliminary advice of SJF 1376J.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 19 March 2018 5:17 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>; 'Steve Lim' <steve.lim@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBA1456H / TP : SJF1376J/LKK / DOA : 15/03/2018

Dear Steve,

Please be informed that we have inspected the vehicle SJF 1376J on 16/03/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 16 March 2018 2:42 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBA1456H / TP : SJF1376J/LKK / DOA : 15/03/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

FASTECH AUTO PTE LTD

page 1/2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate : 20199

Date : 16.03.2018

Vehicle Num : SJF 1376J

Make/Model : TOYOTA AXIO

Chassis/Engine no :

Accident Date : 15.03.2018

Claim No : 0118-20199

Reference :

Policy No :

TPEgo
Xiao Chen

Qty	Particular	Amount S\$
-----	------------	------------

List Item :

1 pc	Rear windscreen glass moulding <i>Del + new</i>	\$ 145.30 -
1 pc	Rear fender RH <i>Perked.</i>	\$ 1,123.60 <i>936.60</i>
1 pc	Rear door RH <i>Distorted</i>	\$ 1,210.20 <i>972.40</i>
1 pc	Rear door inner lock RH <i>Turned</i>	\$ 152.20 ✓
1 pc	Rear door top hinga RH <i>3 new</i>	\$ 65.00 +
1 pc	Rear door bottom hinga RH	\$ 65.00 +
1 pc	Rear door glass RH <i>Shattered</i>	\$ 275.20 ✓
1 pc	Rear door frame black tape RH <i>new</i>	\$ 64.00 ✓
1 pc	Rear door glass regulator RH <i>Prod.</i>	\$ 415.60 <i>227</i>
1 pc	Rear door glass regulator motor RH <i>new - 4921.10</i>	\$ 395.60 ✓
1 pc	Rear door glass outer moulding RH <i>Del +</i>	\$ 101.30 ✓
1 pc	Rear door board RH <i>cracked</i>	\$ 615.20 <i>3690.82 480.10</i>
1 pc	Rear door glass channel RH <i>new</i>	\$ 164.10 +
1 pc	Rear door check RH <i>new</i>	\$ 95.20 +
1 pc	Front door frame black tape RH <i>new</i>	\$ 64.00 ✓
1 pc	Rear door rubber RH <i>cut</i>	\$ 165.20 ✓
1 pc	Front door glass outer moulding RH <i>new</i>	\$ 104.10 +
1 pc	Rear shock absorber RH <i>new</i>	\$ 365.90 +
1 pc	Rear wheel bearing RH <i>new</i>	\$ 415.20 ✓
List Item Total :		\$ 6,001.90
Discount 25 %		\$ 1,500.48
		\$ 4,501.43

Rear Bumper
torn

527. ✓

FASTECH AUTO PTE LTD

page 2/2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate : 20199

Date : 16.03.2018

Vehicle Num : SJF 1376J

Make/Model : TOYOTA AXIO

Chassis/Engine no :

Accident Date : 15.03.2018

Claim No : 0118-20199

Reference :

Policy No :

Qty	Particular	Amount S\$
		B/F \$ 4,501.43
<u>Special Nett Item :</u>		
1 pc	Rear sport rim RH <i>cut</i>	\$ 1,200.00 <i>-40</i>
1 pc	Rear tyre RH <i>new</i>	\$ 450.00 <i>+</i>
1 set	Rear windscreen glass sealant <i>new</i>	\$ 120.00 <i>-60</i>
1 set	Rear bumper clip <i>new</i>	\$ 50.00 <i>+</i>
Special Nett Total :		\$ 1,820.00

Labour Charge :

To check wiring	\$ 100.00 <i>-30</i>
Apply anti dust chemical	\$ 150.00 <i>+</i>
Remove and refix suspension	\$ 450.00 <i>-120</i>
Check wheel alignment	\$ 80.00 <i>✓</i>
Remove and refix rear windscreen glass	\$ 150.00 <i>-120</i>
Remove and refix upholstery, cushion seat etc	\$ 150.00 <i>-60</i>
Labour charge knock dents on rear damage portion cut & welding & renew parts	\$ 1,500.00 <i>-750</i>
To spray paint affected portion	\$ 1,500.00 <i>-800</i>
Labour Charge Total :	\$ 4,080.00

Adrian Lj
 4/5 16/03/18
 06 hrs 10796.67

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

FASTECH AUTO PTE LTD

Acknowledged by Repairer

Signature:

Date:

E & O. E

Total Amount : \$ 10,401.43

total 6140.82

L/S: AAK

4:01/c



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18005037/Aqd3n2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 28-03-2018	
Code : EGI			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBA 1456H	Veh. Inspected	SJF 1376J
Policy No.		Coverage (\$)	0.00
Claim No.	GBA 1456H/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	16/03/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA AXIO	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	NZE1416079852	Colour	SILVER
Odometer	184319	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/70 R14	LING LONG	6 mm
L/H Front Tyre	185/70 R14	LING LONG	6 mm
R/H Rear Tyre	185/70 R14	LING LONG	6 mm
L/H Rear Tyre	185/70 R14	LING LONG	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/03/2018	Inspection Date	16/03/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJF 1376J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	145.30	145.30
1	REAR FENDER RH	DENTED	1,123.60	936.60
1	REAR DOOR RH	DISTORTED	1,210.20	972.40
1	REAR DOOR INNER LOCK RH	JAMMED	152.20	152.20
1	REAR DOOR TOP HINGA RH	NOT NECESSARY	65.00	-
1	REAR DOOR BOTTOM HINGA RH	NOT NECESSARY	65.00	-
1	REAR DOOR GLASS RH	SHATTERED	275.20	275.20
1	REAR DOOR FRAME BLACK TAPE RH	NECESSARY	64.00	64.00
1	REAR DOOR GLASS REGULATOR RH	DAMAGED	415.60	227.00
1	REAR DOOR GLASS REGULATOR MOTOR RH	DAMAGED	395.60	395.60
1	REAR DOOR GLASS OUTER MOULDING RH	DEFORMED	101.30	101.30
1	REAR DOOR BOARD RH	CRACKED	615.20	480.10
1	REAR DOOR GLASS CHANNEL RH	NOT NECESSARY	164.10	-
1	REAR DOOR CHECK RH	NOT NECESSARY	95.20	-
1	FRONT DOOR FRAME BLACK TAPE RH	NECESSARY	64.00	64.00
1	REAR DOOR RUBBER RH	CUT	165.20	165.20
1	FRONT DOOR GLASS OUTER MOULDING RH	NOT NECESSARY	104.10	-
1	REAR SHOCK ABSORBER RH	NOT NECESSARY	365.90	-
1	REAR WHEEL BEARING RH	DAMAGED	415.20	415.20
1	REAR BUMPER	TORN	527.00	527.00
	LESS 25% DISCOUNT		-1,632.23	-1,230.28
			4,896.67	3,690.82
SPECIAL NETT ITEMS				
1	REAR SPORT RIM RH (SN)	CUT	1,200.00	400.00
1	REAR TYRE RH (SN)	NOT NECESSARY	450.00	-
1	SET REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	120.00	60.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	30.00
			1,820.00	490.00
LABOUR				
	TO CHECK WIRING.		100.00	30.00

Report Ref No. CS/EGI18005037/Aqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	APPLY ANTI DUST CHEMICAL.	NOT NECESSARY	150.00	-
	REMOVE AND REFIX SUSPENSION.		450.00	120.00
	CHECK WHEEL ALIGNMENT.		80.00	80.00
	REMOVE AND REFIX REAR WINDSCREEN GLASS.		150.00	120.00
	REMOVE AND REFIX UPHOLSTERY, CUSHION SEAT ETC.		150.00	60.00
	LABOUR CHARGE KNOCK DENTS ON REAR DAMAGE PORTION CUT & WELDING & RENEW PARTS.		1,500.00	750.00
	TO SPRAY PAINT AFFECTED PORTION.		1,500.00	800.00
			4,080.00	1,960.00
GRAND TOTAL			10,796.67	6,140.82
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,900.00

Report Ref No. CS/EGI18005037/Aqd3n2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.