

22/03/2018

ASS. REC. BY:

REF: CS/SMO18005041 / Sgd3ⁿ²

Special Instruction:

Surveyor:

Sebastian

ASSIGNMENT (Office)

From (Person):

Irene Henry

of

SMO

Date/Time:

16/3/18 @ 4:33pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGY 4396S

Insured:

SJM 3001R

at Workshop m/s

Yew Tee Automobile

Tel:

6765 3373

of

Blk 6, Woodlands Rd 399F Yew Tee Ind. Est

Policy No:

Claim No:

CMTD1801175

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/03/2018

CA / REV / REP. / REV 24 HRS

'wp'

19/3/18 @ Morning

H.O.D. Endorsement:

Date/Time:

4:51pm @ 16/3/18

Person Contacted:

Yee Meng

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SGY 4396S -X

SJM 3001R -X

21/3/18 @ 4:50pm revised to Irene Henry by email -

21/5/18 @ 12:08pm Sebastian confirmed with Sky Toh US \$3550, 6 days.

(Check \$7355.07, 67%)

REF: SMO

2272

ASSIGNMENT

From:

Date: 19/3/18

Veh No:

SGY 4396S

Yr Regn:

26/9/2007

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SGY 4396S

Make:

Toyota Vios

c.c. 1497

at Workshop m/s

Yew Tee Automobile

Colour:

Silver

A/C: Insured / Std / NI / NA

of

Blk 6, woodlands Rd 399F Yew Tee Ind

Sp. Reading

150455

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

MK05314730 YOS1375

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Morning

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / SiRim / STD A/Rim or

(Policy Condition)


Tyre Size:

F: 18.5/60R15 Mic

R:

Fallon

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

6 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Vehicle: IN / OUT

Date:

Person Contacted:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

15/3/18

D.O.I.

19/3/18

Survey held at

Yew Tee Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 24 MAY 2018

Date/Time: File Pass to?

☐

Preli. Report

1) 24/5 Mavis

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech. Insp. (\$

☐

Weekend (\$

Survey Fee:

Transportation

) \$ - RS \$

) Photos

) Others

TOTAL

350

Report Format:

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18005041/Sqd3

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 16-03-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJM 3001R	Veh. Inspected	SGY 4396S
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801175	Excess (\$)	0.00
Assign From	IREN HENRY	Assign Date	16/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/03/2018	Inspection Date
Survey held at	YEW TEE AUTOMOBILE TECH PL (HQ) BLK 6 WOODLANDS ROAD 399F YEW TEE IND. ESTATE SINGAPORE 678006	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Nivitha (LKK Auto)

From: Henry, Irene James <irene.henry@sompo.com.sg>
Sent: Friday, 16 March 2018 4:33 PM
To: assignments
Cc: Nivitha (LKK Auto)
Subject: SOMPO REF: CMTD1801175/FW: Accident involving SGY4396S (NTUC) claiming against SJM3001R (SOMPO)
Attachments: SGY4396S Estimate.pdf; SGY4396S_15032018.pdf

Our Claim Reference: CMTD1801175

Dear LKK AUTO,

Kindly assist to arrange to conduct motor survey of the mentioned vehicle (SGY 4396S)

Please refer to the correspondence below.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: YT(HQ) [mailto:utauto@singnet.com.sg]
Sent: Friday, 16 March, 2018 4:25 PM
To: Henry, Irene James <irene.henry@sompo.com.sg>
Cc: Choo, Thelma <thelma.choo@sompo.com.sg>; info@yewteegroup.com
Subject: RE: Accident involving SGY4396S (NTUC) claiming against SJM3001R (SOMPO)

Hi Irene,

We choose LKK Auto Consultants.

Thanks.

Best Regards

Sky Teh

9747 1475

Website: www.yewteegroup.com

Email: info@yewteegroup.com

Like Us On Facebook

Director of

-YEW TEE AUTOMOBILE TECH PTE LTD



WEST HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 / 6762 2081 / 6764 9042

Fax: 6760 4895

Email: utauto@singnet.com.sg

EAST Branch Office:

Synergy@KB, 25 Kaki Bukit Road 4

Unit No #01-60/61

Singapore 417800

DID: 6702 3113 (3 Lines)

Fax: 6702 3773

Email: utauto2@singnet.com.sg

NORTH Branch:

Mega@Woodlands

39 Woodlands Close #01-12

Singapore 737856



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Henry, Irene James [<mailto:irene.henry@sompo.com.sg>]

Sent: Friday, 16 March, 2018 1:02 PM

To: YT(HQ)

Cc: Choo, Thelma

Subject: RE: Accident involving SGY4396S (NTUC) claiming against SJM3001R (SOMPO)

Our Reference: CMTD1801175

Your Reference: SGY 4396S

Date: 16th March 2018

Without Prejudice

BY EMAIL ONLY

Attention:

M/S YEW TEE AUTOMOBILE TECH PTE LTD

ACCIDENT INVOLVING SJM 3001R & SGY 4396S ON 15.03.2018

Dear Sir

We refer to your Notice of Accident via email dated 16/03/2018.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Ma Chin Fook (North area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: YT(HQ) [mailto:utauto@singnet.com.sg]
Sent: Friday, 16 March, 2018 11:40 AM
To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>
Cc: utauto@singnet.com.sg
Subject: Accident involving SGY4396S (NTUC) claiming against SJM3001R (SOMPO)

Hi Motor Claims Dept,

Attached estimate and report.

Kindly please arrange PRI at Yew Tee HQ.

Kindly let us have the list of surveyor to choose for conduct the pre-repair survey.

Thank You ☺

Best Regards

Ms Lai Yee Meng



Yew Tee Automobile Tech Pte Ltd

HQ:
Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:
Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

Shiau Chan (LKKAuto)

From: YT(HQ) <utauto@singnet.com.sg>
Sent: Monday, 21 May 2018 12:08 PM
To: Sebastian Yeang (LKK Auto)
Cc: info@yewteegroup.com; info@yewteegroup.com; info@yewteegroup.com; Shiau Chan (LKKAuto); info@yewteegroup.com
Subject: RE: SGY4396S

Hi Sebastian,

Ok confirm Lump Sum at \$3,550/- with 6 repair days.

Thanks.

Best Regards

Sky Teh

9747 1475

Website: www.yewteegroup.com

Email: info@yewteegroup.com

Like Us On Facebook

Director of

-YEW TEE AUTOMOBILE TECH PTE LTD



WEST HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 / 6762 2081 / 6764 9042

Fax: 6760 4895

Email: utauto@singnet.com.sg

EAST Branch Office:

Synergy@KB, 25 Kaki Bukit Road 4

Unit No #01-60/61

Singapore 417800

DID: 6702 3113 (3 Lines)

Fax: 6702 3773

Email: utauto2@singnet.com.sg

NORTH Branch:

Mega@Woodlands

39 Woodlands Close #01-12

Singapore 737856



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Sebastian Yeang (LKK Auto) [<mailto:SebastianYeang@lkkauto.com>]

Sent: Monday, 21 May, 2018 10:32 AM

To: YT(HQ)

Cc: info@yewteegroup.com; info@yewteegroup.com; info@yewteegroup.com; Shiau Chan (LKKAuto)

Subject: RE: SGY4396S

Dear Sky

Please refer to attachment for the finalization.

Thank You

CS/SMO18005041/Sqd3

Best Regards,

Sebastian | Automotive Assessor

LKK Auto Consultants

phone: 6256-3561 email: sebastianyeang@lkkauto.com fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: YT(HQ) [<mailto:utauto@singnet.com.sg>]
Sent: Friday, 18 May 2018 2:41 PM
To: Sebastian Yeang (LKK Auto)
Cc: info@yewteegroup.com; info@yewteegroup.com; info@yewteegroup.com
Subject: RE: SGY4396S

Hi Sebastian,

Kindly please finalise COR at lump sum \$3,700/- with 6 repair days.

Thanks.

Best Regards

Sky Teh

9747 1475
Website: www.yewteegroup.com
Email: info@yewteegroup.com
Like Us On Facebook

Director of
-YEW TEE AUTOMOBILE TECH PTE LTD



WEST HQ:
Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 / 6762 2081 / 6764 9042

EAST Branch Office:
Synergy@KB, 25 Kaki Bukit Road 4
Unit No #01-60/61
Singapore 417800
DID: 6702 3113 (3 Lines)

NORTH Branch:
Mega@Woodlands
39 Woodlands Close #01-12
Singapore 737856

Fax: 6760 4895

Email: utauto@singnet.com.sg

Fax: 6702 3773

Email: utauto2@singnet.com.sg

 please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: YT(HQ) [<mailto:utauto@singnet.com.sg>]
Sent: Wednesday, 18 April, 2018 6:16 PM
To: 'sebastianyeang@lkkauto.com'
Cc: 'info@yewteegroup.com'; info@yewteegroup.com
Subject: RE: SGY4396S

Resend.

Hi Sebastian,

Attached after repair photos.

Kindly please finalise COR at lump sum \$3,700/- with 6 repair days.

Thanks.

Best Regards

Sky Teh

9747 1475

Website: www.yewteegroup.com

Email: info@yewteegroup.com

Like Us On Facebook

Director of

-YEW TEE AUTOMOBILE TECH PTE LTD



WEST HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 / 6762 2081 / 6764 9042

Fax: 6760 4895

Email: utauto@singnet.com.sg

EAST Branch Office:

Synergy@KB, 25 Kaki Bukit Road 4

Unit No #01-60/61

Singapore 417800

DID: 6702 3113 (3 Lines)

Fax: 6702 3773

Email: utauto2@singnet.com.sg

NORTH Branch:

Mega@Woodlands

39 Woodlands Close #01-12

Singapore 737856

 please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: YT(HQ) [mailto:utauto@singnet.com.sg]
Sent: Monday, 26 March, 2018 12:16 PM
To: sebastianyeang@lkkauto.com
Cc: info@yewteegroup.com
Subject: SGY43965

Hi Sebastian,

Attached after repair photos.

Kindly please finalise COR at lump sum \$3,700/- with 6 repair days.

Thanks.

Best Regards

Sky Teh

9747 1475

Website: www.yewteegroup.com

Email: info@yewteegroup.com

Like Us On Facebook

Director of

-YEW TEE AUTOMOBILE TECH PTE LTD



WEST HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 / 6762 2081 / 6764 9042

Fax: 6760 4895

Email: utauto@singnet.com.sg

EAST Branch Office:

Synergy@KB, 25 Kaki Bukit Road 4

Unit No #01-60/61

Singapore 417800

DID: 6702 3113 (3 Lines)

Fax: 6702 3773

Email: utauto2@singnet.com.sg

NORTH Branch:

Mega@Woodlands

39 Woodlands Close #01-12

Singapore 737856



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 21 March 2018 4:50 PM
To: 'Henry, Irene James'; assignments
Cc: SUR
Subject: RE: SOMPO REF: CMTD1801175/FW: Accident involving SGY4396S (NTUC) claiming against SJM3001R (SOMPO)
Attachments: CSSMO18005041Sqd3.pdf

Dear Irene,

Enclosed herewith preliminary advice of SGY 4396S.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 16 March 2018 4:53 PM
To: 'Henry, Irene James' <irene.henry@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SOMPO REF: CMTD1801175/FW: Accident involving SGY4396S (NTUC) claiming against SJM3001R (SOMPO)

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Henry, Irene James [<mailto:irene.henry@sompo.com.sg>]
Sent: Friday, 16 March 2018 4:33 PM
To: assignments <assignments@lkkauto.com>
Cc: Nivitha (LKK Auto) <admin-d@lkkauto.com>
Subject: SOMPO REF: CMTD1801175/FW: Accident involving SGY4396S (NTUC) claiming against SJM3001R (SOMPO)

Our Claim Reference: CMTD1801175

Dear LKK AUTO,

Kindly assist to arrange to conduct motor survey of the mentioned vehicle (SGY 4396S)

Please refer to the correspondence below.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1801175/NSW

Date: 21st March 2018

Our Ref: CS/SMO18005041/Sqd3

Without Prejudice

The Motor Claims Department
Sompo Insurance

Attn: Irene

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SGY 4396S


We thank you for the instruction on 16/03/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/03/2018 at the premises of M/s YEW TEE AUTOMOBILE and have the following to report:-

Workshop Estimate Amount	: S\$ <u>10,905.07</u>
Revised Estimate Amount	: S\$ <u>3,725.74</u>
"Check" Items Amount	: S\$ <u>3,477.55</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 6 days.

We have not authorized repair.

Yours faithfully

Sebastian
Automobile Assessor



Toyota Vios 1.5M E (COE till 05/2021)

\$18,800

\$5,930 /yr

22-May-2006

1,497 cc

140,000 km

Sedan

Available

Cheapest In The Market! \$0 Down Payment. Famed For Excellent Fuel Efficiency And Low Maintenance, High Paper Value At \$14800, Absolute No Risks Buy, Bank Loan, In House, Loan Available With Monthly AT...

Heritage Auto Enterprise Pte Ltd

Posted: 21-Mar-2018 Tags: 2006 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Toyota Vios 1.5A E (COE till 03/2022)

\$24,800

\$6,210 /yr

19-Mar-2007

1,497 cc

Sedan

Available

\$0 Down Payment Available! In House Loan Or Bank Loan Available! No Need Guarantor Or Minimum Income! Fast And Easy Loan Approval! High Loan Or Trade In Welcome! Uber/Grab Usage Available Call Now Bef...

Posted: 21-Mar-2018 Tags: 2007 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Toyota Vios 1.5A E (COE till 06/2021)

\$22,800

\$6,950 /yr

04-Jul-2006

1,497 cc

Sedan

Available

Very Well-maintained COE Car. Regular Servicing. Low Depreciation. Best Selling Model! Clean And Neat Interior. No Repairs Needed. Inhouse Loan And Trade In Available. Hurry Call Now Before Its Gone.

Lay Auto Pte Ltd

Posted: 20-Mar-2018 Tags: 2006 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Toyota Vios 1.5A E (COE till 06/2021)

\$22,500

\$6,860 /yr

26-Jul-2006

1,497 cc

223,000 km

Sedan

Available

Very Well-maintained COE Car. Regular Servicing. Dashcam. New Seats. Neon Blue Leg Room Lights. Pioneer DVD Player. New Sound System. Fresh Spray Pearl White Painting. Tinting. Visor. New Rims. Recent...

Carro

Posted: 20-Mar-2018 Tags: 2006 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Caught On Camera

A picture says a thousand words and a video clip could get you 100% on your insurance claims. Every car needs a camera for those unexpected moments when things happen. A list of the best dash cams available with reviews.

Find out more!



Toyota Vios 1.5A E Sports (New 5-yr COE)

\$34,800

\$6,960 /yr

19-Feb-2008

1,497 cc

91,000 km

Sedan

Available

Previously "OPC" Converted, One Year In-House Warranty! Purchase With Official Warranty Certificate With Peace Of Mind, Fully Refurbished, New Paintwork, Accident Free, Wear And Tear Replaced, \$495 Lo...

Carway

Posted: 20-Mar-2018 Tags: 2008 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Toyota Vios 1.5A E (COE till 12/2022)

\$32,800

\$6,970 /yr

03-Dec-2007

1,497 cc

124,000 km

Sedan

Available

"One Year In-House Warranty!" Purchase With Official Warranty Certificate With Peace Of Mind, Our Company Renew COE Cars For Sale Base On Car Conditions Not On Ownership, Fully Refurbished, New Paintw...

Carway

Posted: 19-Mar-2018 Tags: 2007 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Toyota Vios 1.5A E (COE till 09/2022)

\$31,800

\$7,100 /yr

11-Sep-2007

1,497 cc

146,000 km

Sedan

Available

One Year In House Warranty! With Official Warranty Certificate For Peace Of Mind, Our Company Renew Coe Cars For Sale Base On Car Conditions Not On Ownership, Fully Refurbished New Paintwork, Accident...

Carway

Posted: 18-Mar-2018 Tags: 2007 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Toyota Vios 1.5A E (COE till 03/2023)

\$34,800

\$7,020 /yr

06-Mar-2008

1,497 cc

88,638 km

Sedan

Available

One Year In-House Warranty! Purchase With Official Warranty Certificate With Peace Of Mind, Fully Refurbished, New Paintwork, Accident Free, Wear And Tear Replaced, \$495 Low Monthly Installment, 10% D...

Carway

Posted: 18-Mar-2018 Tags: 2008 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Toyota Vios 1.5A E (COE till 12/2022)

\$33,800

\$7,150 /yr

12-Dec-2007

1,497 cc

138,000 km

Sedan

Available

"One Year In House Warranty!" With Official Warranty Certificate For Peace Of Mind, Our Company Renew COE Cars For Sale Base On Car Conditions Not On Ownership, Fully Refurbished, Accident Free, Wear ...

Carway

Posted: 18-Mar-2018 Tags: 2007 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota

Toyota Vios 1.5A E Sports (New 5-yr COE)

\$34,800

\$6,960 /yr

18-Feb-2008

1,497 cc

133,800 km

Sedan

Available



"One Year In House Warranty", Purchase With Official Warranty Certificate With Peace Of Mind, Fully Refurbished, New Paintwork, Accident Free, Wear And Tear Replaced, \$495 Low Monthly Installment, 10%...

Carway

Posted: 18-Mar-2018 Tags: 2008 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Toyota Vios 1.5A E (COE till 01/2023)

\$33,800

\$7,010 /yr

16-Jan-2008

1,497 cc

90,152 km

Sedan

Available

Toyota Reliability! Low Maintenance! Ultimate Fuel Saver! Excellent Condition, Comfortable And Practical With Ample Room Space And Boot Space. 1 Owner Genuine Mileage With Full Agent Borneo Motors Ser...

Posted: 18-Mar-2018 Tags: 2008 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Toyota Vios 1.5A E Sports (COE till 12/2022)

\$31,800

\$6,670 /yr

26-Dec-2007

1,497 cc

163,378 km

Sedan

Available

CNY Offer! Original Condition And Lowest Price In The Market, Accident Free, Very Well Maintained Interior And Exterior, Accident Free, With No Wear And Tear To Be Replace, Low Mileage, Brand New Rim ...

Posted: 17-Mar-2018 Tags: 2007 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Toyota Vios 1.5A E (New 5-yr COE)

\$35,777

\$7,150 /yr

18-Mar-2008

1,497 cc

-

Sedan

Available

Popular Toyota Vios 1.5A! New 5 Years COE! Low Mileage, Well Maintained, Regularly Serviced, Affordable Depreciation, Easy Financing, Reliable Engine, Most Fuel Efficient 1.5L Sedan. Call Us To Find O...

Posted: 17-Mar-2018 Tags: 2008 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota



Toyota Vios 1.5A E (COE till 02/2022)

\$24,500

\$6,220 /yr

27-Feb-2007

1,497 cc

-

Sedan

Available

EFIZZIG MOTOR TRADERS. \$3k All In Driveaway. No Financial Strain As We Provide In House Loans And Other Financial Services To Meet Your Needs. Attractive Insurance Rates To Cater For All Drivers. Call...

Posted: 17-Mar-2018 Tags: 2007 Toyota Vios, Toyota Vios, Toyota, Vios, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view [Expired ads](#)

« Back (1 2 3 4) Next »

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used VIOS, VIOS Singapore, used VIOS Singapore, used VIOS, used vehicles Singapore or even buy used VIOS Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	2277Z

Vehicle Details

Vehicle No.:	SGY43965
Vehicle to be Exported:	No
Intended De-registration Date:	20 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS J AUTO
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	1NZX634292
Chassis No.:	MR053HY9305031395
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,043.00
Original Registration Date:	26 Sep 2007
First Registration Date:	26 Sep 2007
Transfer Count:	0
Actual ARF Paid:	\$13,248.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	25 Sep 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$22,041.00
COE Rebate Amount:	\$19,898.00
Total Rebate Amount:	\$19,898.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 20 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/03/2018 16:43
Date Of Accident	15/03/2018 13:45
Exact Location Of Accident	SLIP RD CORNER OF PIONEER RD TURNING TO TUAS CRES
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGY4396S
Insured/Policyholder	
Name Of Registered Owner	POH YING HAU
NRIC No	S7642277Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81570237
Alternative Phone No	OFFICE-81570237
Vehicle Particulars	
Manufacturer	TOYOTA
Model	VIOS-1.5 J (A)
Exact Purpose for which vehicle was being used at time of accident	WORK USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5094794103
Cover Note Number	
Driver	
Name of Driver	POH YING HAU
NRIC No	S7642277Z
Date Of Birth	27/12/1976
Occupation	OUTDOOR
Date Of Driving Pass	28/01/2000
Driving Experience	18 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81570237
Fax Number	
Contact Number	OFFICE-81570237
Email Address	NOEMAIL

Address	BLK 38 UPPER BOON KENG ROAD #04-2402
Postcode	380038
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : MALE
Passenger 3	NAME: : UNKNOWN GENDER: : MALE
Passenger 4	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJM3001R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver

KOH TECK WEI

NRIC/Passport Number

S9030188H

Contact Number

93875081

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud;
 - (ii) to regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (iii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
(Name & Title)

Insurer's Signature
(Name of the Policyholder)
(Date & Time)

Insurer's Signature
(Name)
(Date & Time)

Sketch Plan #2

SKETCH PLAN

X, Y = 01/03/2018 14:45



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 15th Mar 2018, at around 1.45pm, I was travelling on Pioneer Rd and turning left towards Inas Crescent. I stopped before the give way line on the ~~left~~ left turn slip road to let other vehicles pass. While my car was stationary at the slip road, a car from behind (Sima 3001R) hit the back of my car from behind with the front of his car. I had come to a complete stop before the give way line and had been stationary for a few seconds before the collision occurred.

DECLARATION

I declare that the information provided is true and correct to the best of my knowledge.

[Signature]
 I declare that the information provided is true and correct to the best of my knowledge.
 Date & Time: _____

[Signature]
 I declare that the information provided is true and correct to the best of my knowledge.
 Date & Time: _____

[Signature]
 I declare that the information provided is true and correct to the best of my knowledge.
 Date & Time: _____

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

ON BEHALF OF OWNER :

Policy Particulars: - THIRD PARTY DAMAGED CLAIM

Insured veh.	SGY4396S	Excess.	\$ -
Policy No.	5094794103	Coverage.	Comprehensive
Claiming Against.	SJM3001R		SOMPO
Insured Under.	NTUC		

Vehicle Particulars & Condition

Make & Model	Toyota Vios
Engine No.	1NZX634292
Chassis No.	MR053HY9305031395
Odometer	
Engine CC.	1497
Year Of Reg.	2007
Colour.	Silver
Parf/COE Rebate.	\$ 19,959.00

Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

Description Of Damages

Rear portion damaged.

General Information

Accident Date. 15/3/2018

Survey held at

Yew Tee Automobile Tech Pte Ltd

SYNERGY@KB 25 KAKI BUKIT ROAD 4 #01-61 S(417800)

Remarks

A) THE SURVEY WAS CONDUCTED ON A "LUMP SUM" BASIS
KINDLY LET US HAVE THE LIABILITY SOON.

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR:

Days

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

Qty.	Description Of Parts	Pricing
1	Rear bumper ✓ DT	\$ 383.66
1	Boot lid R	\$ 554.60
1	Rear fender LH R	\$ 765.58
1	Rear fender RH X	\$ 765.58 <i>nn</i>
1	Rear end panel ? ✓ DT	\$ 595.85
1	Rear spare tyre panel ? X	\$ 635.45 <i>nn</i>
	List	\$ 3,700.72
	Less 25%	\$ 925.18
	Total	\$ 2,775.54
1	Rear bumper side retainer LH ✓ NEC	\$ 56.70
1	Rear bumper bracket LH ? ✓ CRK	\$ 95.90
1	Rear bumper reflector LH ✓ SCR	\$ 92.90
1	Boot lid hinges LH ✓ BT	\$ 49.20
1	Boot lid hinges RH ✓ BT	\$ 49.20
1	Boot lid rubber ✓ TN	\$ 175.40
1	Boot lid lock ✓ 3m	\$ 145.60
1	Boot lid lock catch ✓ BT	\$ 89.00
1	Boot lid logo ✓ NEC	\$ 32.60
1	Boot lid "VIOS" emblem ✓ NEC	\$ 50.55
1	Boot lid "J" emblem ✓ NEC	\$ 38.90
1	Rear taillamp LH ✓ ST	\$ 320.00
1	Rear taillamp RH ? X	\$ 320.00 <i>nn</i>
1	Rear taillamp panel LH ? ✓ DT	\$ 160.90
1	Rear taillamp panel RH ? X	Rpr <i>R</i>
1	Rear fender air gate LH ? ✓ CRK	\$ 42.15
1	Rear fender mudflap LH ✓ Deform	\$ 55.00
1	Rear fender inner trim board LH ? X	\$ 484.75 <i>nn</i>
1	Rear end panel inner garnish ? ✓ Deform	\$ 177.72
1	Rear spare tyre board ✓ chip off	\$ 330.50
1	Rear spare tyre sponge tray LH X	\$ 109.70 <i>nn</i>
1	Rear spare tyre sponge tray RH X	\$ 109.70 <i>nn</i>
1	Rear chassis member LH ? X	\$ 1,312.00 <i>nn</i>
	Nett	\$ 4,298.37
	Less 10%	\$ 429.84
	Total	\$ 3,868.53

25%

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

Qty.	Description Of Parts	Pricing
1	Rear bumper clips (1 set) ✓ NEC	\$ 45.00 30
1	Rear bumper reverse sensor (1 set) ✓ DMG	210 \$ 260.00 300
1	Rear number plate X	\$ 45.00 111
2	Rear taillamp clips ✓ NEC	\$ 16.00
2	Rear taillamp gasket ✓ LH Only. NEC	50 \$ 80.00 40
1	Rear end panel inner garnish clips (1 set) ✓ NEC	\$ 35.00 30
1	Rear windscreen sealant X	\$ 60.00 111
	S/N	\$ 541.00

LABOUR

To apply undercoating on the repaired and replaced panels for rust protection.

To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.

To supply spray terostat sealant on the cutting areas.

To dismantle and refit rear windscreen glass. ✓

To remove and refit rear bumper sensors.

Towing charges.

To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.

To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.

?	\$ 120.00 40 50
	\$ 80.00 30 40
?	\$ 100.00 60
	\$ 120.00 X
	\$ 80.00 30 40
	\$ 120.00 30
	\$ 1,800.00 700 800
	\$ 1,300.00 800

LABOUR \$ 3,720.00

Sub Total. \$ 10,905.07

7% GST \$ 763.36

Grand Total \$ 11,668.43

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Sebastian
19/5/18
- Lump Sum Repair
- Question Mark Item Photo
- Photo After Paint
90036124
sebastian@lkkauto.com

2/3/18

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: ytauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: ytauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

Qty.	Description Of Parts	Pricing
1	Rear bumper ✓ DT	\$ 383.66
1	Boot lid R	\$ 554.60
1	Rear fender LH R	\$ 765.58
1	Rear fender RH X	\$ 765.58
1	Rear end panel ? ✓ DT	\$ 595.85
1	Rear spare tyre panel ? X	\$ 635.45
	List	\$ 3,700.72
	Less 25%	\$ 925.18
	Total	\$ 2,775.54
1	Rear bumper side retainer LH ✓ NCC	\$ 56.70
1	Rear bumper bracket LH ? ✓ CRK	\$ 95.90
1	Rear bumper reflector LH ✓ SCR	\$ 92.90
1	Boot lid hinges LH ✓ DT	\$ 49.20
1	Boot lid hinges RH ✓ DT	\$ 49.20
1	Boot lid rubber ✓ TN	\$ 175.40
1	Boot lid lock ✓ JAL	\$ 145.60
1	Boot lid lock catch ✓ DT	\$ 89.00
1	Boot lid logo ✓ NCC	\$ 32.60
1	Boot lid "VIOS" emblem ✓ NCC	\$ 50.55
1	Boot lid "J" emblem ✓ NCC	\$ 38.90
1	Rear taillamp LH ✓ DT	\$ 320.00
1	Rear taillamp RH ? X	\$ 320.00
1	Rear taillamp panel LH ? ✓ DT	\$ 160.90
1	Rear taillamp panel RH ? X	Rpr
1	Rear fender air gate LH ? ✓ CRK	\$ 42.15
1	Rear fender mudflap LH ✓ Defon	\$ 55.00
1	Rear fender inner trim board LH ? X	\$ 484.75
1	Rear end panel inner garnish ? ✓ Defon	\$ 177.72
1	Rear spare tyre board ✓ CRK	\$ 330.50
1	Rear spare tyre sponge tray LH X	\$ 109.70
1	Rear spare tyre sponge tray RH X	\$ 109.70
1	Rear chassis member LH ? X	\$ 1,312.00
	Nett	\$ 4,298.37
	Less 10%	\$ 429.84
	Total	\$ 3,868.53

2941.73

-25%

2206.29

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: ytauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: ytauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

Qty.	Description Of Parts	Pricing
1	Rear bumper clips (1 set) ✓ N/E	\$ 45.00 30
1	Rear bumper reverse sensor (1 set) ✓ DATES	\$ 260.00 200 210
1	Rear number plate X	\$ 45.00
2	Rear taillamp clips ✓ N/E	\$ 16.00
2	Rear taillamp gasket ✓ LH Only. N/E	\$ 80.00 40 50
1	Rear end panel inner garnish clips (1 set) ✓ N/E	\$ 35.00 30
1	Rear windscreen sealant X	\$ 60.00
	S/N	\$ 541.00

LABOUR

To apply undercoating on the repaired and replaced panels for rust protection.

To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.

To supply spray terostat sealant on the cutting areas.

To dismantle and refit rear windscreen glass. ✓

To remove and refit rear bumper sensors.

Towing charges.

To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.

To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.

?	\$ 120.00 40 50
\$	80.00 30 40
\$	100.00 60
\$	120.00
\$	80.00 30 40
\$	120.00 30
\$	1,800.00 400 800
\$	1,300.00 500

LABOUR \$ 3,720.00

Sub Total. \$ 10,905.07

7% GST \$ 763.36

Grand Total \$ 11,668.43

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Sebastian
19/5/12.
- Lump Sum Repair.
- Question Mark Item Photo
- Photo After Paint
90036124
sebastianyang@lkkauto.com

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

ON BEHALF OF OWNER :

Policy Particulars: - THIRD PARTY DAMAGED CLAIM

Insured veh.	SGY4396S	Excess.	\$ -
Policy No.	5094794103	Coverage.	Comprehensive
Claiming Against.	SJM3001R	SOMPO	
Insured Under.	NTUC		

Vehicle Particulars & Condition

Make & Model	Toyota Vios
Engine No.	1NZX634292
Chassis No.	MR053HY9305031395
Odometer	
Engine CC.	1497
Year Of Reg.	2007
Colour.	Silver
Parf/COE Rebate.	\$ 19,959.00

Parts : \$ 2206.29
S/Nett : \$ 376.00 336
Labour : \$ 1840.00 1870
4422.29 4412.29

Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

Lump Sum - 20%
3537.83 3529.83
✓
L/S : \$ 3550

Description Of Damages

Rear portion damaged.

General Information

Accident Date: 15/3/2018

Survey held at

Yew Tee Automobile Tech Pte Ltd

SYNERGY@KB 25 KAKI BUKIT ROAD 4 #01-61 S(417800)

Remarks

A) THE SURVEY WAS CONDUCTED ON A "LUMPSUM" BASIS
KINDLY LET US HAVE THE LIABILITY SOON.

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR:

Days




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18005041/Sqd3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 28-05-2018		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJM 3001R	Veh. Inspected	SGY 4396S	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1801175	Excess (\$)	0.00	
Assign From	IREN HENRY	Assign Date	16/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	MR053HY9305031395	Colour	SILVER	
Odometer	150455	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	MICHELIN	6 mm	
L/H Front Tyre	185/60 R15	MICHELIN	6 mm	
R/H Rear Tyre	185/60 R15	FALKEN	6 mm	
L/H Rear Tyre	185/60 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/03/2018	Inspection Date	19/03/2018	
Survey held at	YEW TEE AUTOMOBILE TECH PL (HQ) BLK 6 WOODLANDS ROAD 399F YEW TEE IND. ESTATE SINGAPORE 678006			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGY 4396S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED	383.66	383.66
1	BOOT LID	TO REPAIR SEE LABOUR	554.60	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	765.58	-
1	REAR FENDER RH	NOT NECESSARY	765.58	-
1	REAR END PANEL	DENTED	595.85	595.85
1	REAR SPARE TYRE PANEL	NOT NECESSARY	635.45	-
	LESS 25% DISCOUNT		-925.18	-244.88
			2,775.54	734.63
1	REAR BUMPER SIDE RETAINER LH	NECESSARY	56.70	56.70
1	REAR BUMPER BRACKET LH	CRACKED	95.90	95.90
1	REAR BUMPER REFLECTOR LH	SCRATCHED	92.90	92.90
1	BOOT LID HINGES LH	BENT	49.20	49.20
1	BOOT LID HINGES RH	BENT	49.20	49.20
1	BOOT LID RUBBER	TORN	175.40	175.40
1	BOOT LID LOCK	JAMMED	145.60	145.60
1	BOOT LID LOCK CATCH	BENT	89.00	89.00
1	BOOT LID LOGO	NECESSARY	32.60	32.60
1	BOOT LID "VIOS" EMBLEM	NECESSARY	50.55	50.55
1	BOOT LID "J" EMBLEM	NECESSARY	38.90	38.90
1	REAR TAILLAMP LH	BENT	320.00	320.00
1	REAR TAILLAMP RH	NOT NECESSARY	320.00	-
1	REAR TAILLAMP PANEL LH	DENTED	160.90	160.90
1	REAR TAILLAMP PANEL RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR FENDER AIR GATE LH	CRACKED	42.15	42.15
1	REAR FENDER MUDFLAP LH	DEFORMED	55.00	55.00
1	REAR FENDER INNER TRIM BOARD LH	NOT NECESSARY	484.75	-
1	REAR END PANEL INNER GARNISH	DEFORMED	177.72	177.72
1	REAR SPARE TYRE BOARD	CHIPPED OFF	330.50	330.50
1	REAR SPARE TYRE SPONGE TRAY LH	NOT NECESSARY	109.70	-
1	REAR SPARE TYRE SPONGE TRAY RH	NOT NECESSARY	109.70	-

Report Ref No. CS/SMO18005041/Sqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR CHASSIS MEMBER LH	NOT NECESSARY	1,312.00	-
	LESS 10% DISCOUNT		-429.84	-
	LESS 25% DISCOUNT		-	-490.56
			3,868.53	1,471.66
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	45.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	260.00	210.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	45.00	-
2	REAR TAILLAMP CLIPS (SN)	NECESSARY	16.00	16.00
2	REAR TAILLAMP GASKET (SN)	N/S NECESSARY	80.00	50.00
1	SET REAR END PANEL INNER GARNISH CLIPS (SN)	NECESSARY	35.00	30.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-
			541.00	336.00
	<u>LABOUR</u>			
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		120.00	50.00
	TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS,REPLACE DAMAGED PARTS.		80.00	40.00
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.		100.00	60.00
	TO DISMANTLE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT REAR BUMPER SENSORS.		80.00	40.00
	TOWING CHARGES.		120.00	80.00
	TO REMOVE & REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN & REPAIR INCLUDING CUT & WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.INCLUSIVE OF THE REPAIR OF BOOT LID,REAR FENDER LH AND REAR TAILLAMP PANEL RH.		1,800.00	800.00
	TO SPRAY PAINTING ON THE REPLACED & REPAIR PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPERS,CLEANING & SANDING OF SURFACES,FINAL POLISHING & WAXING ARE ALSO AVAILABLE.		1,300.00	800.00
			3,720.00	1,870.00
	GRAND TOTAL		10,905.07	4,412.29
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,550.00

Report Ref No. CS/SMO18005041/Sqd3n2