

15/5/2018

INS. CASE OWNER:

CC 3/LPC18005067

1 K/m/302

LKK:

IDAC:

Surveyor:

KALVIN

DOI:

14/05/18

Date / Time:

16/05/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKV 27365

Name of Insured:

JAY MING HUI

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

15/05/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Ann 210 Jinh Yong

Driver Tel No.:

9666672

(V/L: YES / NO)

Claim No.:

15/18/18VP05/020476

Policy No.:

2/17VP05/015235-001

Make / Model:

M-BENZ

Place of Accident:

KAO I ORCHARD ROAD

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SHD 35142



INSRS:

WSP: CD66 (Lungs)

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

01/05/18

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

05-01-19

SHD 35142 - CC 3/LPC18002542/m/4/2/2 non-05/02/18

SKV 27365 - X

* 01 unit to life to accident photo.

FILE PASS TO TYPIST TO PREPARE REPORT.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

UTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time: 19/03/18

Sent By: Shirley Aiew

FINALIZATION

Date/Time:

Confirm with:

Confirm by: MWK

Repair Cost:

PIP

SS 1,401.08

(

2 days) Reduction:

49

%

Email ☒Call ☐

FINAL SETTLEMENT

Date/Time: 01-08-19

Confirm with: KAZALI

Email ☒Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

31

If NO or B 28. Ass. Lia:

Repair Cost:

w/bst

SS 1,499.16

Loss of Rental (LOR):

SS 409.50

(

3-5 days) x 117

Loss of Use (LOU):

SS -

(

5

x

days)

Loss of Income (LOI):

SS 115.00

(

50

x

3-5 days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LO ☒

[Tick only one]

GIA/LTA Search

SS 7.44

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 2,091.15

Global Sum SS 2,091.00

FINAL PAYMENT

Date/Time: 01-08-19

Confirm with: KAZALI

Email ☒Call ☐

Payee 1:

SS 2,091.00

Name 1:

COMFORTDESIGN ENGINEERING PTE LTD.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT 19/9/19

08/11/2018

Name: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimate of Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No _____

Claims No _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Vch: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHD35142

Yr Regn: 8 Sep 316

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 240

c.c

1685

Colour: Blue

A/C:

Insured / Std / NI / NA

Sp. Reading: 215333

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: 1CMH18414MH4093488

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modf: Nil / S/Rim / S/A/Rim or

Tyre Size: F: _____

R: _____

205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 15/12/18

D.O.I. 16/3/18

Survey held at

CDGE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear.

The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time	Action / Instruction
<u>28/3/18</u>	<u>Call PIP \$45000 / 28/3/18</u> <u>\$1401.08 / 28/3/18</u>

Loan-pac
PIP

(RED: 1.33x10 49%)

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair: _____

1)

☐

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Notes

: Interview (\$

Tech Insp (\$

Other (\$

Total (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC3/LPC18005067/K1ma3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 19-03-2018		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKV 2736B	Veh. Inspected	SHD 3514Z	
Policy No.	Z/17VP05/015235-001	Coverage (\$)	0.00	
Claim No.	17/18/18/VP05/020476	Excess (\$)	0.00	
Assign From		Assign Date	19/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	15/03/2018	Inspection Date	16/03/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

511 BELLEVUE 1, #02-25 PAYA LEBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/LPC18005067/K1ms3

Date: 19/03/2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD 3514Z


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16.03.2018 at the M/s ComfortDelGro Engineering Pte Ltd (Loyang) have the following to report:-

Workshop Estimate Amount	: S\$	2,732.18
Revised Estimate Amount	: S\$	1,401.08
"Check" Items Amount	: S\$	845.40
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2.0 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

JC NO. 305125687

REGN NO: SHD3514Z	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL: I-40	DATE/TIME IN: 16.03.2018 10:45
YR OF MANU: 08.09.2016	TARGET DATE
CHASSIS CODE: RMHLE41UMGU093488	COMPLETION DATE/TIME:

REGN NO: SHD3514Z	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL: I-40	DATE/TIME IN: 16.03.2018 10:45
YR OF MANU: 08.09.2016	TARGET DATE
CHASSIS CODE: RMHLE41UMGU093488	COMPLETION DATE/TIME:

REGN NO: SHD3514Z	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL: I-40	DATE/TIME IN: 16.03.2018 10:45
YR OF MANU: 08.09.2016	TARGET DATE
CHASSIS CODE: RMHLE41UMGU093488	COMPLETION DATE/TIME:

REGN NO: SHD3514Z	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL: I-40	DATE/TIME IN: 16.03.2018 10:45
YR OF MANU: 08.09.2016	TARGET DATE
CHASSIS CODE: RMHLE41UMGU093488	COMPLETION DATE/TIME:

REGN NO: SHD3514Z	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL: I-40	DATE/TIME IN: 16.03.2018 10:45
YR OF MANU: 08.09.2016	TARGET DATE
CHASSIS CODE: RMHLE41UMGU093488	COMPLETION DATE/TIME:

REGN NO: SHD3514Z	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL: I-40	DATE/TIME IN: 16.03.2018 10:45
YR OF MANU: 08.09.2016	TARGET DATE
CHASSIS CODE: RMHLE41UMGU093488	COMPLETION DATE/TIME:

(O)

(P)

COUNT CARD NO.

LONGAC

JOB DESCRIPTION

1/NO	LABOR CODE	DESCRIPTION
------	------------	-------------

RECEIVED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE _____

edgement Slip

Exit Pass

SHD3514Z LKE

Vehicle No.: SHD3514Z

Service Advisor

Signature/Date

Name of Service Advisor

Date _____

urned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHD 3514Z

DATE 16/3/2018 13:57

MAKE :

MODEL : HYUNDAI i40

LKK/Kalvin PbyP
 Like
 LONPAC

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 603.60	
	Rear Bumper Reinforcement ?			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket ?			\$ 49.00	
	Rear Bumper Clips ✓			\$ 22.00	
	Rear Bumper Sponge ?			\$ 143.40	
	Rear Bumper Under Cover ✓			\$ 225.00	
	Rear Bumper Reflector Lamp (LH) ✓			\$ 32.00	
	SUB TOTAL			\$ 1,939.35	
	LESS 20%			\$ 387.87	
	DISCOUNTED TOTAL			\$ 1,551.48	
	Rear No. Plate ✓			\$ 25.00	Nett
	License Plate cover X rep			\$ 100.00	Nett
	Rear Bumper Reverse Sensor X			\$ 135.70	Nett
	Rear Bumper Advertisement Logo ✓			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00	Nett
				\$ 510.70	
	Labour Charge				
	Panel Beating			\$ 250.00	200
	Spray Painting Charge			\$ 250.00	200
	Wiring Charge			\$ 50.00	X
	R/Refix Reverse Sensor			\$ 120.00	20
	TOTAL LABOUR			\$ 670.00	
	ESTIMATE TOTAL			\$ 2,732.18	
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before spray painting • To display damaged parts during resurvey • Parts prices are subject to information • Third party survey is on all without • No illegal modification(s) allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____				
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Kalvin LKK
 16/3/18 1500 hrs
 2 Dns
 P/P
 Before Paint job

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3514Z

DATE 16/3/2018 13:57

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>Deformed</i>			\$ 603.60
	Rear Bumper Reinforcement <i>Xsu</i>			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) <i>Xsu</i>		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket <i>Xsu</i>			\$ 49.00
	Rear Bumper Clips <i>me</i>			\$ 22.00
	Rear Bumper Sponge <i>Xsu</i>			\$ 143.40
	Rear Bumper Under Cover <i>me</i>			\$ 225.00
	Rear Bumper Reflector Lamp (LH) <i>me</i>			\$ 32.00
	SUB TOTAL			\$ 1,939.35
	LESS 20%			\$ 387.87
	DISCOUNTED TOTAL			\$ 1,551.48
	Rear No. Plate <i>me</i>			\$ 25.00
	License Plate cover <i>X repl</i>			\$ 100.00
	Rear Bumper Reverse Sensor <i>Xsu</i>			\$ 135.70
	Rear Bumper Advertisement Logo <i>me</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) <i>me</i>		\$ 100.00	\$ 200.00
				\$ 510.70
	Labour Charge			
	Panel Beating			\$ 250.00 <i>200</i>
	Spray Painting Charge			\$ 250.00 <i>200</i>
	Wiring Charge			\$ 50.00 <i>X 25</i>
	R/Refix Reverse Sensor			\$ 120.00 <i>20</i>
	TOTAL LABOUR			\$ 670.00
	ESTIMATE TOTAL			\$ 2,732.18

Kaliakky

16/3/18 *1500*

2 DTS

P/P
Before paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK/Kalwin

PhyP

LONPAC

Like

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305125687
 REGN NO : SHD3514Z
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 08.09.2016
 DATE/TIME IN : 16.03.2018 10:45
 ACCIDENT DATE : 15.03.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1 L	603.60	20.00	482.88
0002 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
0003 04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1 L	225.00	20.00	180.00
0004 04-01-0103-0851-G	I40VC REFLECTOR/REFLEX AS	1 L	32.00	20.00	25.60
0005 FNPS	NO PLATE(S)	1 N	25.00	2.00-	25.00

SUB-TOTAL : 731.08

JOB NATURE

0000 20-05	RENEW ADVERTISMENT STICKER-	250.00
0001 L	PANEL BEATING	200.00
0002 23-502	SPRAYPAINT ON AFFECTED AREA	200.00
0003 20-22	REMOVE/REFIX REVERSE SENSOR	20.00

SUB-TOTAL : 670.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305125687
REGN NO : SHD3514Z
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 08.09.2016
DATE/TIME IN : 16.03.2018 10:45
ACCIDENT DATE : 15.03.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,401.08

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305125687

Date : 26/03/18

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr KALVIN ANG

Vehicle Reg No : SHD3514Z CTPL

15.03.18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **LONPAC** --- **SKV2736B**
2. The finalized amount shall be:

(a) Spare Parts after List discount	\$731.08
(b) Labour Charges	\$670.00
Total for Part-By-Part Repair Cost	\$1,401.08
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: 20%	
Final Lumpsum Repair cost	

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : Calvin

Date : 28/3/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Mei Kwan (LKKAUTO)

From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 5 April, 2018 11:35 AM
To: Shirley Hiew (LKK Auto); Bevan Lim (LKK Auto)
Cc: MT_Claim_SG; Admin A; CS A Team
Subject: RE: Direct Settlement - Accident Involving SKV2736B (OI : LPC - 17/18/18/VP05/020476) AND SHD3514Z (TP : LKK REF - CC3/LPC18005067/K1ms3) on 15/03/2018
Attachments: SKV2736B 150318.PDF; Claim Reference: 17/18/18/VP05/020476
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Hi Shirley/Bevan

Attached are Insured's GIA report and photographs for your handling.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Monday, 19 March, 2018 5:59 PM
To: GERALD POH WEE BIN; Bevan Lim (LKK Auto)
Cc: MT_Claim_SG; ONG LI LI; ERIC WOO JUN KIAT; Admin A; CS A Team
Subject: RE: Direct Settlement - Accident Involving SKV2736B (OI : LPC - TBA) AND SHD3514Z (TP : LKK REF - CC3/LPC18005067/K1ms3) on 15/03/2018

Dear Gerald,

Thanks and noted.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]
Sent: Monday, 19 March 2018 5:43 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: Direct Settlement - Accident Involving SKV2736B (OI : LPC - TBA) AND SHD3514Z (TP : LKK REF - CC3/LPC18005067/K1ms3) on 15/03/2018

Our Ref :TBA



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933.

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC3/LPC18005067/K1ea3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 19-09-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKV 2736B	Veh. Inspected	SHD 3514Z	
Policy No.	Z/17VP05/015235-001	Coverage (\$)	0.00	
Claim No.	17/18/18/VP05/020476	Excess (\$)	0.00	
Assign From		Assign Date	16/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMGU093488	Colour	BLUE	
Odometer	215333	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	7 mm	
L/H Front Tyre	205/60 R16	HANKOOK	7 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	7 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/03/2018	Inspection Date	16/03/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3514Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	603.60	603.60
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	504.35	-
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$180.00	SERVICEABLE	360.00	-
1	REAR BUMPER SIDE BRACKET	SERVICEABLE	49.00	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER SPONGE	SERVICEABLE	143.40	-
1	REAR BUMPER UNDER COVER	CUT	225.00	225.00
1	REAR BUMPER REFLECTOR LAMP (LH)	CRACKED	32.00	32.00
	LESS 20% DISCOUNT		-387.87	-176.52
			1,551.48	706.08
SPECIAL NETT ITEMS				
1	REAR NO.PLATE (SN)	CRACKED	25.00	25.00
1	LICENSE PLATE COVER (SN)	TO REPAIR SEE LABOUR	100.00	-
1	REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	135.70	-
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
			510.70	275.00
LABOUR				
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF LICENSE PLATE COVER.		250.00	200.00
	SPRAY PAINTING CHARGE.		250.00	200.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	R/REFIX REVERSE SENSOR .		120.00	20.00
	-		-	-
	-		-	-
	-		-	-
			670.00	420.00
GRAND TOTAL			2,732.18	1,401.08



RECOMMENDED COST OF REPAIRS			1,401.08
-----------------------------	--	--	----------

Report Ref No. CC3/LPC18005067/K1ea3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.