

INS. CASE OWNER:

CC4/LPC18005069 / KUG302^a

LKK:
IDAC:

Surveyor: KENNETH DOI: 19/03/18 Date / Time: 11/03/18

Pre-assign / CCU / FTE

Insured Vehicle No.: SDS 82R Claim No.: 18/18/VP05/020438
 Name of Insured: AW YONG SIEW MENG Policy No.: 2/18/VP05/016223
 Insured Tel No.: _____ HP: 96907940 Make / Model: Honda Civic
 Excess Sec II : \$\$ D.O.A: 28/22/2 Place of Accident: Tankek Road
 Is driver the owner? (YES / NO) Nature of Accident: _____
 If NO, Driver Name / Age: _____ OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
 Driver Tel No.: _____ (VL: YES / NO) Insured Liability: % Final ? Yes / No

SLB 3415P

INSRS: WSP: Tong Luck Tel: _____ Liability: _____ RMKS: _____
 INSRS: WSP: _____ Tel: _____ Liability: _____ RMKS: _____
 INSRS: WSP: _____ Tel: _____ Liability: _____ RMKS: _____
 INSRS: WSP: _____ Tel: _____ Liability: _____ RMKS: _____

Date / Time	STAGE	DATE / PIC
<u>11/3/18</u>	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 21/03/18 Sent By: Shirley Hwee

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____
 Repair Cost: \$\$(_____ days) Reduction: % _____ Email Call

FINAL SETTLEMENT Date/Time: 18/5/18 Confirm with: Candy Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27 If NO or B 28. Ass. Lia: _____

Repair Cost: \$\$(2319.97)

Loss of Rental (LOR): \$\$(_____ days)

Loss of Use (LOU): \$\$(400.00) (\$ 80 x 5 days)

Loss of Income (LOI): \$\$(_____ x _____ days)

LOR only LOU only LOR + LOU LOR + LO [Tick only one]

GIA/LTA Search \$\$(7.45)

Medical: \$\$(_____)

Disbursement: \$\$(_____ (e.g. Tow/Independent))

Legal Cost \$\$(_____)

Total: \$\$(2727.42) Global Sum \$\$: _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$\$(2727.42) Name 1: TONG LUCK AUTO PTE LTD

Payee 2: (Strike if N.A.) \$\$(_____) Name 2: _____

Payee 3: (Strike if N.A.) \$\$(_____) Name 3: _____

RECEIVED 31 MAY 2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC18005068/Kua3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 19-03-2018	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SDS 82R	Veh. Inspected
	Policy No.	Z/18/VP05/016223	Coverage (\$)
	Claim No.	18/18/18/VP05/020438	Excess (\$)
	Assign From		Assign Date
			19/03/2018
2. Vehicle Particulars & Condition			
	Make & Model		c.c
	Engine No.	HIDDEN	Year of Reg.
	Chassis No.		Colour
	Odometer	-	Steering
	Brakes		Modification
	General		
3. Conditions of Tyres			
		Size	Make
	R/H Front Tyre		Balance
	L/H Front Tyre		mm
	R/H Rear Tyre		mm
	L/H Rear Tyre		mm
4. Description of Damages			
5. General Information			
	Accident Date	28/02/2018	Inspection Date
	Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722	
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVENUE 1, #02-25 PAVANURI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref: 18/18/18/VP05/020438
Our ref: CC4/LPC18005068/Kus3

Date: 21/03/2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLB 3415P

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19.03.2018 at the M/s Tong Luck Auto Pte Ltd (Sin Ming) have the following to report:-

Workshop Estimate Amount	: S\$	<u>7,275.20</u>
Revised Estimate Amount	: S\$	<u>1,524.70</u>
"Check" Items Amount	: S\$	<u>2,581.30</u>
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 16 March 2018 3:09 PM
To: Operation / Candy Ong; assignments@lkkauto.com; 'SUR' (sur@lkkauto.com)
Cc: tlauto@singnet.com.sg
Subject: RE: ACCIDENT INVOLVING VEHICLE NO.: SLB3415P & SDS82R ON 28/02/2018 ALONG BUKIT TIMAH ROAD (TURN LEFT TO FARRER ROAD) Our ref: 18/18/18/VP05/020438

Attachments: SLB3415P-NOA.PDF

3:31pm @ 16/3/18
person @ candy
vehicle in

Without Prejudice

Dear Candy

Thank you for your confirmation.

Dear Catherine (LKK)

Please arrange Kenneth Kong to attend to the TP survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Operation / Candy Ong [mailto:operation@tlauto.com.sg]
Sent: Friday, 16 March, 2018 3:03 PM
To: ONG LI LI
Cc: tlauto@singnet.com.sg
Subject: RE: ACCIDENT INVOLVING VEHICLE NO.: SLB3415P & SDS82R ON 28/02/2018 ALONG BUKIT TIMAH ROAD (TURN LEFT TO FARRER ROAD) Our ref: 18/18/18/VP05/020438

Dear Li Li,

We hereby confirm and agreed to nominate Kenneth Kong to conduct the pre-repair survey of the damages to our client's vehicle

Best Regards,
Candy Ong
Tong Luck Auto Pte Ltd

From: ONG LI LI [mailto:llong@lonpac.com]
Sent: Friday, March 16, 2018 2:39 PM
To: Operation / Candy Ong <operation@tlauto.com.sg>; MT_Claim_SG <mt_claim@lonpac.com>; assignments@lkkauto.com; 'SUR' (sur@lkkauto.com) <sur@lkkauto.com>
Cc: tlauto@singnet.com.sg
Subject: RE: ACCIDENT INVOLVING VEHICLE NO.: SLB3415P & SDS82R ON 28/02/2018 ALONG BUKIT TIMAH ROAD (TURN LEFT TO FARRER ROAD) Our ref: 18/18/18/VP05/020438

Without Prejudice
Save as to Costs

Dear Candy

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No	Name of Surveyor	<input type="checkbox"/> Please tick ✓
1	Wilson Teo	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Kalvin Ang	
5	Sebastian Yeang	
6	Adrian Ling	
7	Mohammed Rasul	
8	Marcus Chua	
9	Kenneth Kong	
10	Ma Chin Fook	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Operation / Candy Ong [mailto:operation@tlauto.com.sg]
Sent: Friday, 16 March, 2018 2:33 PM
To: MT_Claim_SG
Cc: tlauto@singnet.com.sg
Subject: ACCIDENT INVOLVING VEHICLE NO.: SLB3415P & SDS82R ON 28/02/2018 ALONG BUKIT TIMAH ROAD (TURN LEFT TO FARRER ROAD)

Dear All,

We have our client's instruction to notify you the above accident.

Please find attached documents for your information and necessary action

The vehicle is now garage at our workshop.

Kindly let us have your surveyor list and arrange for the vehicle to be inspect at an earlier date

Best Regards,
Candy Ong
Tong Luck Auto Pte Ltd

Mei Kwan (LKKAuto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 10 April, 2018 5:26 PM
To: Mei Kwan (LKKAuto); Thin Thin (LKKAuto)
Cc: MT_Claim_SG; Admin A; CS A Team
Subject: RE: ACCIDENT INVOLVING VEHICLE NO.: SLB3415P & SDS82R ON 28/02/2018 ALONG BUKIT TIMAH ROAD (TURN LEFT TO FARRER ROAD) Our ref: 18/18/18/VP05/020438

Attachments: SDS82R 280218.PDF

Categories: AGNES

Hi Mei Kwan

Please see attached for our Insured's GIA report.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Tuesday, 10 April, 2018 5:22 PM
To: ONG LI LI; Thin Thin (LKKAuto)
Cc: MT_Claim_SG; Admin A; CS A Team
Subject: RE: ACCIDENT INVOLVING VEHICLE NO.: SLB3415P & SDS82R ON 28/02/2018 ALONG BUKIT TIMAH ROAD (TURN LEFT TO FARRER ROAD) Our ref: 18/18/18/VP05/020438

Dear Li Li,

We refer to the below email and the contents were duly noted.

Kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [mailto:llong@lonpac.com]
Sent: Tuesday, 10 April, 2018 4:59 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: RE: ACCIDENT INVOLVING VEHICLE NO.: SLB3415P & SDS82R ON 28/02/2018 ALONG BUKIT TIMAH ROAD (TURN LEFT TO FARRER ROAD) Our ref: 18/18/18/VP05/020438

Hi Thin Thin

Please refer to the attached TP LOD and supporting documents and handle.

Subject: RE: ACCIDENT INVOLVING VEHICLE NO.: SLB3415P & SDS82R ON 28/02/2018 ALONG BUKIT TIMAH ROAD (TURN LEFT TO FARRER ROAD) Our ref: 18/18/18/VP05/020438

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:llong@lonpac.com>]

Sent: Friday, 16 March 2018 3:09 PM

To: Operation / Candy Ong <operation@tlauto.com.sg>; assignments@lkkauto.com; 'SUR' (sur@lkkauto.com) <sur@lkkauto.com>

Cc: tlauto@singnet.com.sg

Subject: RE: ACCIDENT INVOLVING VEHICLE NO.: SLB3415P & SDS82R ON 28/02/2018 ALONG BUKIT TIMAH ROAD (TURN LEFT TO FARRER ROAD) Our ref: 18/18/18/VP05/020438

Without Prejudice

Dear Candy

Thank you for your confirmation.

Dear Catherine (LKK)

Please arrange Kenneth Kong to attend to the TP survey.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Operation / Candy Ong [<mailto:operation@tlauto.com.sg>]

Sent: Friday, 16 March, 2018 3:03 PM

To: ONG LI LI

Cc: tlauto@singnet.com.sg

Subject: RE: ACCIDENT INVOLVING VEHICLE NO.: SLB3415P & SDS82R ON 28/02/2018 ALONG BUKIT TIMAH ROAD (TURN LEFT TO FARRER ROAD) Our ref: 18/18/18/VP05/020438

Dear Li Li,

We hereby confirm and agreed to nominate Kenneth Kong to conduct the pre-repair survey of the damages to our client's vehicle

Best Regards,

Candy Ong

Tong Luck Auto Pte Ltd

From: Operation / Candy Ong [<mailto:operation@tlauto.com.sg>]

Sent: Friday, 16 March, 2018 2:33 PM

To: MT_Claim_SG

Cc: tlauto@singnet.com.sg

Subject: ACCIDENT INVOLVING VEHICLE NO.: SLB3415P & SDS82R ON 28/02/2018 ALONG BUKIT TIMAH ROAD
(TURN LEFT TO FARRER ROAD)

Dear All,

We have our client's instruction to notify you the above accident.

Please find attached documents for your information and necessary action

The vehicle is now garage at our workshop.

Kindly let us have your surveyor list and arrange for the vehicle to be inspect at an earlier date

Best Regards,

Candy Ong

Tong Luck Auto Pte Ltd



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN :

YOUR REF NO : SDS82R

CLAIM TYPE : THIRD PARTY

TP INS. CO. : LONPAC INSURANCE BHD

ACCIDENT DATE : 28/02/2018

TP VEH REG NO : SDS82R

ESTIMATE

NO : QUOT201803-000059(00)

DATE : 16/03/2018

POLICY NO : 999995580

VEH REG NO : SLB3415P

MAKE/MODEL : MERCEDES BENZ GLA180 (R18 B)

CHASSIS NO : WDC1569422J222887

ENGINE NO : 27091030885298

REG. DATE : 2015

*Not Authorized
1. B1
Putty & Blayain
3 days @ 1130 hrs*

Estimate Repair Cost to Vehicle No : SLB3415P

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Rear end panel	1	887.00	887.00 X
2 Tallamp lower bracket - RH / LH	2	58.00	116.00 X
3 Rear bumper <i>Repair</i>	1	<i>But</i> 1,190.00	1,190.00 X
4 Rear bumper pad	1	<i>Sn</i> 417.00	417.00 X
5 Rear bumper inner frame	1	<i>Sn</i> 62.00	62.00 X
6 Rear bumper lower chrome	1	783.00	783.00 X
7 Rear bumper reinforcement	1	<i>But</i> 580.00	580.00 X
8 Rear bumper side retainer - RH / LH	2	38.00	76.00 X
9 Rear bumper top chrome	1	<i>Sn</i> 185.00	185.00 X
10 Rear bumper reverse sensor	4	185.00	740.00 X
11 Rear bumper sensor seals	6	<i>Sn</i> 12.00	72.00 X
12 Rear bumper clips <i>necessary</i>	15	<i>Sn</i> 9.00	135.00 X
13 Rear exhaust mounting - RH	1	285.00	285.00 X
			5,528.00
		Less 10%	552.80
			4,975.20
LABOUR			
14 To remove & refit rear bumper sensor	1	<i>nn</i> 100.00	100.00 X
15 To check and rectify wiring system	1	80.00	80.00 X
16 To panel beat and straighten floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 X
17 To putty and spray paint on affected areas	1	1,000.00	1,000.00 X
18 To apply rust proofing on replaced and repaired panels	1	120.00	120.00 X
			2,300.00
			820
			2,168.00
			7%
			151.77
			2,319.97
		TOTAL	S\$ 7,275.20
		ADD GST @ 7%	509.26
		GRAND TOTAL	S\$ 7,784.46

SINGAPORE DOLLAR SEVEN THOUSAND SEVEN HUNDRED EIGHTY-FOUR AND CENTS FORTY-SIX ONLY



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

Not Authorised

ATTN :

YOUR REF NO : SDS82R

CLAIM TYPE : THIRD PARTY

TP INS. CO. : LONPAC INSURANCE BHD

ACCIDENT DATE : 28/02/2018

TP VEH REG NO : SDS82R

*1. B1
Punery B4 gain*

3 days

ESTIMATE

NO : QUOT201803-000059(00)

DATE : 16/03/2018

POLICY NO : 999995580

VEH REG NO : SLB3415P

MAKE/MODEL : MERCEDES BENZ GLA180 (R18 B1)

CHASSIS NO : WDC1569422J222887

ENGINE NO : 27091030885298

REG. DATE : 2015

Estimate Repair Cost to Vehicle No : SLB3415P

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Rear end panel	1	887.00	887.00 <i>R</i>
2 Taillamp lower bracket - RH / LH	2	58.00	116.00 <i>7</i>
3 Rear bumper	1	1,190.00	1,190.00 <i>Bar</i>
4 Rear bumper pad	1	417.00	417.00 <i>7</i>
5 Rear bumper inner frame	1	62.00	62.00 <i>7</i>
6 Rear bumper lower chrome	1	783.00	783.00 <i>new</i>
7 Rear bumper reinforcement	1	580.00	580.00 <i>7</i>
8 Rear bumper side retainer - RH / LH	2	38.00	76.00 <i>Sm</i>
9 Rear bumper top chrome	1	185.00	185.00 <i>7</i>
10 Rear bumper reverse sensor	4	185.00	740.00 <i>Sm</i>
11 Rear bumper sensor seals	6	12.00	72.00 <i>7</i>
12 Rear bumper clips	15	9.00	135.00 <i>7</i>
13 Rear exhaust mounting - RH	1	285.00	285.00 <i>Sm</i>
			5,528.00
		Less 10%	552.80
			4,975.20
LABOUR			
14 To remove & refit rear bumper sensor	1	100.00	100.00 <i>7</i>
15 To check and rectify wiring system	1	80.00	80.00 <i>201</i>
16 To panel beat and straighten floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 <i>3501</i>
17 To putty and spray paint on affected areas	1	1,000.00	1,000.00 <i>4501</i>
18 To apply rust proofing on replaced and repaired panels	1	120.00	120.00 <i>new</i>
			2,300.00
		TOTAL	S\$ 7,275.20
		ADD GST @ 7%	509.26
		GRAND TOTAL	S\$ 7,784.46

SINGAPORE DOLLAR SEVEN THOUSAND SEVEN HUNDRED EIGHTY-FOUR AND CENTS FORTY-SIX ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey on "without prejudice" basis
- No illegal modifications allowed

Acknowledged by Repairer
Signature:
Date:



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN :

YOUR REF NO : SDS82R
CLAIM TYPE : THIRD PARTY
TP INS. CO. : LONPAC INSURANCE BHD
ACCIDENT DATE : 28/02/2018
TP VEH REG NO : SDS82R

ESTIMATE

NO : QUOT201803-000059(00)
DATE : 16/03/2018
POLICY NO : 999995580
VEH REG NO : **SLB3415P**
MAKE/MODEL : MERCEDES BENZ GLA180 (R18 B1)
CHASSIS NO : WDC1569422J222887
ENGINE NO : 27091030885298
REG. DATE : 2015

Estimate Repair Cost to Vehicle No : SLB3415P

Description	Quantity	Unit Price	Amount
		S\$	S\$

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18005068/Kua3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 01-06-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDS 82R	Veh. Inspected	SLB 3415P
Policy No.	Z/18/VP05/016223	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020438	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	16/03/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES GLA180 (A)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDC1569422J222887	Colour	METALLIC SILVER
Odometer	9354	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50 R18	YOKOHAMA	9 mm
L/H Front Tyre	235/50 R18	YOKOHAMA	9 mm
R/H Rear Tyre	235/50 R18	YOKOHAMA	9 mm
L/H Rear Tyre	235/50 R18	YOKOHAMA	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/02/2018	Inspection Date	19/03/2018
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 3415P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR END PANEL (N)	TO REPAIR SEE LABOUR	887.00	-
2	TAILLAMP LOWER BRACKET-RH/LH @\$58.00 (N)	TO REPAIR SEE LABOUR	116.00	-
1	REAR BUMPER (N)	TO REPAIR SEE LABOUR	1,190.00	-
1	REAR BUMPER PAD (N)	SERVICEABLE	417.00	-
1	REAR BUMPER INNER FRAME (N)	SERVICEABLE	62.00	-
1	REAR BUMPER LOWER CHROME (N)	DENTED	783.00	783.00
1	REAR BUMPER REINFORCEMENT (N)	BUCKLED	580.00	580.00
2	REAR BUMPER SIDE RETAINER-RH/LH @\$38.00 (N)	SERVICEABLE	76.00	-
1	REAR BUMPER TOP CHROME (N)	SERVICEABLE	185.00	-
4	REAR BUMPER REVERSE SENSOR @\$185.00 (N)	SERVICEABLE	740.00	-
6	REAR BUMPER SENSOR SEALS @\$12.00 (N)	SERVICEABLE	72.00	-
15	REAR BUMPER CLIPS @\$9.00 (N)	NECESSARY	135.00	135.00
1	REAR EXHAUST MOUNTING-RH (N)	SERVICEABLE	285.00	-
	LESS 10% DISCOUNT		-552.80	-149.80
			4,975.20	1,348.20
LABOUR				
	TO REMOVE & REFIT REAR BUMPER SENSOR.	NOT NECESSARY	100.00	-
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	20.00
	TO PANEL BEAT AND STRAIGHTEN FLOORBOARD PANEL, REAR CHASSIS FRAME, TO CUT AND WELD REAR END PANEL INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME. INCLUSIVE OF THE REPAIR OF REAR END PANEL, TAILLAMP LOWER BRACKET-RH/LH AND REAR BUMPER.		1,000.00	350.00
	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS.		1,000.00	450.00
	TO APPLY RUST PROOFING ON REPLACED AND REPAIRED PANELS.	NOT NECESSARY	120.00	-
			2,300.00	820.00
GRAND TOTAL			7,275.20	2,168.20

Report Ref No. CC4/LPC18005068/Kua3n2



RECOMMENDED COST OF REPAIRS			2,168.20
-----------------------------	--	--	----------

Report Ref No. CC4/LPC18005068/Kua3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.