



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN :

YOUR REF NO : SDS82R

CLAIM TYPE : THIRD PARTY

TP INS. CO. : LONPAC INSURANCE BHD

ACCIDENT DATE : 28/02/2018

TP VEH REG NO : SDS82R

ESTIMATE

NO : QUOT201803-000059(00)

DATE : 16/03/2018

POLICY NO : 999995580

VEH REG NO : **SLB3415P**

MAKE/MODEL : MERCEDES BENZ GLA180 (R18
B)

CHASSIS NO : WDC1569422J222887

ENGINE NO : 27091030885298

REG. DATE : 2015

Estimate Repair Cost to Vehicle No : SLB3415P

Description	Quantity	Unit Price	Amount
		S\$	S\$

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE