



**Main Office :** No. 22, Jalan Kilang, Singapore 159419  
Tel: 6476 3333 Fax: 6271 5891

**Service Centre :** Block 1008, Bukit Merah Lane 3,  
#01-04/06/08/115, Singapore 159722  
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314  
www.mova.com.sg  
GST Reg. No: M2-0088864-2

**Mova Spray Centre**  
2K Oven Spray Painting System

**Power-M Automotive Pte Ltd**  
Specialise In Car Air-con Services,  
Car Audio & Hi-Fi System.

**Hilton Car Rental Centre**

**Hilton Auto Trading**

Dealing In New/Used Cars, Hire Purchase & Insurance.



**TP INSURER:** India International Insurance Pte Ltd (HQ)  
**UNKNOWN**

Singapore

**Claimant Insurer:** NTUC Income Insurance Co-operative Ltd

#### PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	14/03/2018
Vehicle Reg. No.:	SFQ5770S	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHEN MEI YIN		
Make/Model:	NISSAN SYLPHY, 1.5 4AT (A)	Vehicle Reg. Date:	23/08/2007
Vehicle Colour:	CHOCOLATE	Chassis No:	JN1BAAG11Z0105193
Engine No:	HR15171526A		
Odometer:	0 KM		
Paint Type:		Nett Item Discount:	10.00 %
List Item Discount:	30.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss:	REFER TO SKETCH PLAN		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

Tanpin 97495749  
up 21/3/18 @ 8pm  
Lampiran  
Resurvey after repair  
Swee Chuan Koh.  
Foley.

COST OF CLAIMS	Amount
Parts	3,043.34
Miscellaneous Items	10.00
Labour	2,680.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>5,733.34</b>
<b>+ GST 7.00% (S\$)</b>	<b>401.33</b>
<b>Nett Amount (S\$)</b>	<b>6,134.67</b>

This claim is handled by: BILLY

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS**

**Reference**

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 14 Mar 2018)  
**Parts:** 143      NISSAN SYLPHY 1.5 4AT (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SFQ5770S)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT DOOR RH (REPAIR)	30.00	0.00	-
2	1		*REAR DOOR RH	10.00	0.00	bt ✓ *1,015.00 FN
3	1		*REAR DOOR STICKER RH	10.00	0.00	neu ✓ *108.00 FN
4	1		*REAR DOOR CHROME MOULDING RH	10.00	0.00	? *149.00 FN
5	1		*REAR DOOR LOCK RH	10.00	0.00	x ✓ *166.70 FN
6	1		*REAR DOOR WEATHERSTRIP RH	10.00	0.00	neu ✓ *106.70 FN
7	1		*REAR DOOR GLASS REGULATOR RH - CHECK	10.00	0.00	-
8	1		*REAR DOOR GLASS REGULATOR MOTOR RH - CHECK	10.00	0.00	-
9	1		*REAR QUATER MOULDING RH	10.00	0.00	? *570.00 FN <i>plumb</i>
10	1		*REAR QUATER GLASS SEALANT RH	0	0.00	neu ✓ *40.00 FS
11	1		*REAR W/S GLASS MOULDING	10.00	0.00	neu ✓ *157.30 FN
12	1		*REAR W/S GLASS SEALANT	0	0.00	neu ✓ *40.00 FS
13	1		*REAR FENDER RH	10.00	0.00	neu ✓ *996.40 FN
14	1		*REAR FENDER COWLING RH	10.00	0.00	x ✓ *23.50 FN
15	1		*REAR SPORT RIM RH - CHECK	10.00	0.00	-
16	1		*REAR AXLE - CHECK	10.00	0.00	-
17	1		*REAR WHEEL BEARING RH - CHECK	10.00	0.00	-
18	1		*REAR SHOCK ABSORBER RH - CHECK	10.00	0.00	-

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,372.60</b>
<b>- Nett Item Discount on N Items (\$\$)</b>	<b>329.26</b>
<b>Total Parts (\$\$)</b>	<b>3,043.34</b>

Report was unsubmitted during this print-out.  
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	10.00
<b>Sub Total (S\$)</b>			<b>10.00</b>

Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	TO CUT /WELD REAR FENDER RH. KNOCK AND STRAIGHTEN REAR FENDER INNER PANEL RH, CENTER PILLAR RH. FRONT DOOR RH. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION	New	<i>700</i> 1,000.00
2	SPRAY PAINT FRONT DOOR RH, CENTER PILLAR RH, REAR DOOR RH, REAR FENDER RH, REAR BUMPER , INNER PANEL	New	<i>700</i> 950.00
3	REMOVE & REPLACE REAR WINDSCREEN GLASS AND CHECK WATER LEAKAGE	New	<i>✓</i> 120.00
4	REMOVE & REPLACE REAR SPEAKER BOARD, REAR SEAT ASSY, REAR FLOOR CARPET, GARNISH, TRIM COVERING	New	<i>80</i> 160.00
5	REMOVE & REPLACE PETROL TANK PIPE, HOSE , GARNISH	New	<i>50</i> 80.00
6	REMOVE & REPLACE REAR DOOR MECHANISM AND CHECK LOCKING SYSTEM	New	<i>✓</i> 50.00
7	TO APPLY SEAL ON WELDING JOINT	New	<i>40</i> 80.00
8	REMOVE & REPLACE REAR UNDER CARRIAGE SUSPENSION	New	<i>phub? 120?</i> 180.00
9	RUST PROOF AFFECTED AREAS	New	<i>40</i> 60.00
<b>Gross Labour Cost (S\$)</b>			<b>2,680.00</b>

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >